

STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
DIVISION OF RESEARCH AND INNOVATION
OFFICE OF MATERIALS AND INFRASTRUCTURE

**DEVELOPMENT OF STAKING CONFIGURATIONS
FOR K-RAIL**



Principal Investigator John Jewell, P.E.

Report Prepared by Malinda Gallaher

Research Performed byRoadside Safety Research Group

STATE OF CALIFORNIA

DEPARTMENT OF TRANSPORTATION
DIVISION OF RESEARCH AND INNOVATION
OFFICE OF MATERIALS AND INFRASTRUCTURE

**DEVELOPMENT OF STAKING CONFIGURATIONS
FOR K-RAIL**

Supervised by Robert Meline, P.E.


Principal Investigator John Jewell, P.E.

Report Prepared by Malinda Gallaher


Research Performed by Roadside Safety Research Group



Robert Meline, P.E.
Chief
Roadside Safety Research Group



John Jewell, P.E.
Senior Transportation Engineer
Roadside Safety Research Group



Malinda Gallaher
Transportation Engineer
Roadside Safety Research Group

1. REPORT NO. FHWA/CA/MI-2006/21	2. GOVERNMENT ACCESSION NO.	3. RECIPIENT'S CATALOG NO.	
4. TITLE AND SUBTITLE DEVELOPMENT OF STAKING CONFIGURATIONS FOR K-RAIL		5. REPORT DATE December 2008	
		6. PERFORMING ORGANIZATION CODE	
7. AUTHOR(S) Malinda Gallaher		8. PERFORMING ORGANIZATION REPORT NO. 65-680928	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Roadside Safety Research Group California Department of Transportation 5900 Folsom Blvd., Sacramento, CA. 95819		10. WORK UNIT NO.	
		11. CONTRACT OR GRANT NO.	
12. SPONSORING AGENCY NAME AND ADDRESS California Department of Transportation 5900 Folsom Blvd., Sacramento CA. 95819		13. TYPE OF REPORT & PERIOD COVERED Final	
		14. SPONSORING AGENCY CODE	
15. SUPPLEMENTARY NOTES This project was performed in cooperation with the US Department of Transportation, Federal Highway Administration, under the research project titled "DEVELOPMENT OF STAKING CONFIGURATIONS FOR K-RAIL."			
16. ABSTRACT Full-scale crash testing was conducted on various staking configurations for pre-cast concrete barrier (California K-rail). The staking configurations tested were developed in effort to optimize cost and worker safety. Testing was conducted in accordance with NCHRP Report 350. The tested barriers consisted of twelve or thirteen concrete segments, each 6045 mm (20 ft) in length. The segments were placed on 125-mm (5-in) AC pavement and connected together with 31.8 x 660 - mm (1.25 x-26 in) pins. Each segment was secured to the ground using 25 x 610-mm (24-in) stakes either uncapped or capped. The tests were performed at the Caltrans Dynamic Test Facility in West Sacramento, California. A total of six crash tests were conducted under Report 350 Test Level 3-11. Two testing groups were established: K-rail as a median barrier and K-rail adjacent to an excavation. Each group was tested under three staking configurations. One test from the median barrier group and two tests from the excavation group were within the limits of Report 350 Test Level 3-11. It is recommended that staked K-rail be approved for use on California State highways when the following conditions are present: <ol style="list-style-type: none"> 1. When K-rail is placed as a semi-permanent median barrier with less than 610 mm (2 ft) from the edge of travel way in both directions, use four capped stakes per section every other section. 2. When K-rail is placed less than 610 mm (2 ft) from the edge of an excavation, use two capped stakes per section along the traffic side. The distance between the K-rail and excavation must be a minimum of 75 mm (3 in). 			
17. KEY WORDS K-rail, Type K, Type 50, Temporary Barriers, Safety Shape Barrier, Crash Test, Staking, Stake, New Jersey Shape, Temporary Railing, Tie-down, Anchored Barrier		18. DISTRIBUTION STATEMENT No Restrictions. This document is available through the National Technical Information Service, Springfield, VA 22161	
19. SECURITY CLASSIF. (OF THIS REPORT) Unclassified	20. SECURITY CLASSIF. (OF THIS PAGE) Unclassified	21. NO. OF PAGES 129	22. PRICE

NOTICE

The contents of this report reflect the views of Roadside Safety Research Group, which is responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the State of California or the Federal Highway Administration. This report does not constitute a standard specification or regulation.

Neither the State of California nor the United States Government endorses products or manufacturers. Trade or manufacturers' names appear herein only because they are considered essential to the object of this document.

English to Metric System (SI) of Measurement

SI CONVERSION FACTORS

<u>To Convert From</u>	<u>To</u>	<u>Multiply By</u>
ACCELERATION		
m/s ²	ft/s ²	3.281
AREA		
m ²	ft ²	10.764
ENERGY		
Joule (J)	ft.lb _f	0.7376
FORCE		
Newton (N)	lb _f	0.2248
LENGTH		
m	ft	3.281
m	in	39.37
cm	in	0.3937
mm	in	0.03937
MASS		
kg	lb _m	2.205
PRESSURE OR STRESS		
kPa	psi	0.1450
VELOCITY		
km/h	mph	0.6214
m/s	ft/s	3.281
km/h	ft/s	0.9113
VOLUME		
liters	gal	0.2642

ACKNOWLEDGMENTS

This work was accomplished in cooperation with the United States Department of Transportation, Federal Highway Administration.

Special appreciation is due to the following staff members of Materials Engineering and Testing Services (METS) and the Division of Research and Innovation (DRI) for their help on this project:

John Jewell, Robert Meline, Larry Moore, Mike O’Keeffe, David Whitesel, and Ali Zalekian - test preparation, data reduction, vehicle preparation, and film processing; Eric Jacobson, and Ed Ung - electronic instrumentation; and Bill Poroshin, Mike Said, and Martin Zanotti - machine shop services. Thanks also to Dave Bengel, Independent Camera Operator.

Other persons from Caltrans who made important contributions include:

Project Committee Members – Janice Benton (Traffic Operations), Greg Berry (HQ Construction), Ray Estakhri (Traffic Operations), Gary Gauthier (Roadside Safety and Research), Randy Hiatt (Traffic Operations), Celso Izquierdo (HQ Construction), Ken Kochevar (FHWA), and Matt Schmitz (FHWA).

From Headquarters Photography - Don Tateishi.

Engineering Student Assistants - Jon Nguyen, Ron Phoebus, Brian Icban, and Brent Norton.

TABLE OF CONTENTS

1. INTRODUCTION.....	1
1.1. Problem	1
1.2. Objective	1
1.3. Background and Significance of Work.....	1
1.4. Literature Search	2
1.5. Scope	2
2. TECHNICAL DISCUSSION	4
2.1. Test Conditions – Crash Tests	4
2.1.1. Test Facilities.....	4
2.1.2. Test Article Design	5
2.1.2.1. K-rail	5
2.1.2.2. Stakes	6
2.1.2.3. Stake Configurations	7
<i>Figure 2-5. Staking Configurations Layout</i>	<i>8</i>
2.1.3. Test Vehicles	9
2.1.4. Data Acquisition System	10
2.2. Test Results – Crash Tests.....	10
2.2.1. Test 671 – Median Layout: 2 Uncapped Stakes per Barrier.....	10
2.2.1.1. Impact Description/Vehicle Behavior	10
2.2.1.2. Barrier Damage	13
2.2.1.3. Vehicle Damage	15
2.2.1.4. Test 671 Data Summary Sheet	17
2.2.2. Test 672 – Median Layout: 4 Uncapped Stakes per Every Other Barrier.....	18
2.2.2.1. Impact Description/Vehicle Behavior	18
2.2.2.2. Barrier Damage	21
2.2.2.3. Vehicle Damage	23
2.2.2.4. Test 672 Data Summary Sheet	25
2.2.3. Test 673 - Median Layout: 4 Capped Stakes per Every Other Barrier.....	26
2.2.3.1. Impact Description/Vehicle Behavior	26
2.2.3.2. Barrier Damage	29
2.2.3.3. Vehicle Damage	31
2.2.3.4. Test 673 Data Summary Sheet	33
2.2.4. Test 674 – Excavation Layout: 4 Capped Stakes per Every Other Barrier	34
2.2.4.1. Impact Description/Vehicle Behavior	34
2.2.4.2. Barrier Damage	36
2.2.4.3. Vehicle Damage	40
2.2.4.4. Test 674 Data Summary Sheet	42
2.2.5. Test 675 – Excavation Layout: 2 Capped Stakes per Barrier on Traffic Side	43
2.2.5.1. Impact Description/Vehicle Behavior	43
2.2.5.2. Barrier Damage	45
2.2.5.3. Vehicle Damage	47
2.2.5.4. Test 675 Data Summary Sheet	49
2.2.6. Test 676 – 1 Capped Stake per Barrier.....	50
2.2.6.1. Impact Description/Vehicle Behavior	50
2.2.6.2. Barrier Damage	53
2.2.6.3. Vehicle Damage	54
2.2.6.4. Test 676 Data Summary Sheet	56
2.3. Discussion of Test Results.....	57
2.3.1. Structural Adequacy	57
2.3.1.1. Median Barrier Configurations	57
2.3.1.2. Adjacent to Excavation Configurations.....	57
2.3.2. Occupant Risk.....	58

2.3.2.1.	Median Barrier Configurations	58
2.3.2.2.	Adjacent to Excavation Configurations.....	58
2.3.3.	<i>Vehicle Trajectory</i>	58
2.3.3.1.	Median Barrier Configurations	58
2.3.3.2.	Adjacent to Excavation Configurations.....	58
3.	CONCLUSIONS	66
4.	RECOMMENDATIONS	67
5.	IMPLEMENTATION	68
6.	REFERENCES	69
7.	APPENDIX	70
7.1.	Test Vehicle.....	70
7.1.1.	<i>Equipment</i>	70
7.1.2.	<i>Vehicle Parameters</i>	71
7.2.	Guidance System	77
7.3.	Photo Instrumentation.....	78
7.4.	Video Analysis	81
7.5.	Detailed Drawings of Test Article	82
7.6.	Test Article Installation	86
7.7.	Electronic Instrumentation and Data	87
7.7.1.	<i>Instrumentation</i>	87
7.7.2.	<i>Data</i>	89

LIST OF FIGURES

Figure 2-1. Asphalt Concrete Thickness.....	4
Figure 2-2. K-rail Rebar Placement.....	5
Figure 2-3. Uncapped Stake	6
Figure 2-4. Capped Stake	6
Figure 2-5. Staking Configurations Layout	8
Figure 2-6. Test 671 - Side View of Vehicle Pre-Impact	11
Figure 2-7. Test 671 - Vehicle at Impact Location Pre-Impact	11
Figure 2-8. Test 671 - Close-up view of Vehicle at Impact Location Pre-Impact	12
Figure 2-9. Test 671 - Barrier Pre-Impact	12
Figure 2-10. Test 671 - Barrier Static Displacements [mm].....	13
Figure 2-11. Test 671 - Downstream View of Barrier Post-Impact.....	13
Figure 2-12. Test 671 - Impact Location Post-Impact	14
Figure 2-13. Test 671 - Section 6 Upstream Stake Post-Impact	14
Figure 2-14. Test 671 - Side View of Vehicle Post-Impact.....	15
Figure 2-15. Test 671 – Front-left View of Vehicle Post-Impact	16
Figure 2-16. Test 671 - Front-right View of Vehicle Post-Impact	16
Figure 2-17. Test 671 - Impact sequence and diagram	17
Figure 2-18. Test 672 - Side View of Vehicle Pre-Impact	18
Figure 2-19. Test 672 - Vehicle at Impact Location Pre-Impact	19
Figure 2-20. Test 672 - Close-up View of Vehicle at Impact Location.....	19
Figure 2-21. Test 672 - Barrier Pre-Impact	20
Figure 2-22. Test 672 - Stake #6B Pre-Impact	20
Figure 2-23. Test 672 - Barrier Static Displacements [mm].....	21
Figure 2-24. Test 672 - Downstream View of Barrier Post-Impact.....	21
Figure 2-25. Test 672 - Impact Point Post-Impact.....	22
Figure 2-26. Test 672 - Stake #6B Post-Impact.....	22
Figure 2-27. Test 672 - Scuffing on the Backside of the Barrier.....	23
Figure 2-28. Test 672 - Side View of Vehicle Post-Impact.....	23
Figure 2-29. Test 672 - Front-left View of Vehicle Post-Impact.....	24
Figure 2-30. Test 672 - Impact sequence and diagram	25
Figure 2-31. Test 673 - Side View of Vehicle Pre-Impact	26
Figure 2-32. Test 673 - Vehicle at Impact Location Pre-Impact	27
Figure 2-33. Test 673 - Close-up View of Vehicle at Impact Location Pre-Impact	27
Figure 2-34. Test 673 - Barrier Pre-Impact	28
Figure 2-35. Test 673 - Stake #6B Pre-Impact	28
Figure 2-36. Test 673 - Barrier Static Displacements [mm].....	29
Figure 2-37. Test 673 - Downstream View of Barrier Post-Impact.....	29
Figure 2-38. Test 673 - Impact Point Post-Impact.....	30
Figure 2-39. Test 673 - Stake #6B Post-Impact.....	30
Figure 2-40. Test 673 - Side View of Vehicle Post-Impact.....	31
Figure 2-41. Test 673 - Front-left View of Vehicle Post-Impact.....	32
Figure 2-42. Test 673 - Barrier Involved with Secondary Impact	32
Figure 2-43. Test 673 - Impact sequence and diagram	33
Figure 2-44. Test 674 - Side View of Vehicle Pre-Impact	34
Figure 2-45. Test 674 - Vehicle at Impact Location Pre-Impact	35
Figure 2-46. Test 674 - Close-up View of Vehicle at Impact Location.....	35
Figure 2-47. Test 674 - Barrier Pre-Impact	36
Figure 2-48. Test 674 - Overall View of Excavation.....	36
Figure 2-49. Test 674 - Barrier Static Displacements [mm].....	37
Figure 2-50. Test 674 - Downstream View of Barrier Post-Impact.....	37
Figure 2-51. Test 674 - Impact Point Post-Impact.....	38
Figure 2-52. Test 674 – Upstream, Impact-side Stake in Section 8 Post-Impact.....	38
Figure 2-53. Test 674 - Back of Barrier Post-Impact	39

Figure 2-54. Test 674 - Damaged Pavement from Rear Stake	39
Figure 2-55. Test 674 - Pavement Damage after Barrier Removal.....	40
Figure 2-56. Test 674 - Side View of Vehicle Post-Impact.....	40
Figure 2-57. Test 674 - Front-right View of Vehicle Post-Impact	41
Figure 2-58. Test 674 - Impact sequence and diagram	42
Figure 2-59. Test 675 - Side View of Vehicle Pre-Impact	43
Figure 2-60. Test 675 - Vehicle at Impact Location Pre-Impact	44
Figure 2-61. Test 675 - Close-up View of Vehicle at Impact Location.....	44
Figure 2-62. Test 675 - Barrier Pre-Impact	45
Figure 2-63. Test 675 - Barrier Static Displacements [mm].....	45
Figure 2-64. Test 675 - Downstream View of Barrier Post-Impact.....	46
Figure 2-65. Test 675 - Barrier over Excavation	46
Figure 2-66. Test 675 - Impact Point Post-Impact.....	47
Figure 2-67. Test 675 - Stake at Impact Point	47
Figure 2-68. Test 675 - Stake Downstream from Impact Point	47
Figure 2-69. Test 675 - Side View of Vehicle Post-Impact.....	48
Figure 2-70. Test 675 - Front-right View of Vehicle Post-Impact	48
Figure 2-71. Test 675 - Impact sequence and diagram	49
Figure 2-72. Test 676 - Side View of Vehicle Pre-Impact	51
Figure 2-73. Test 676 - Vehicle at Impact Location Pre-Impact	51
Figure 2-74. Test 676 - Close-up View of Vehicle at Impact Location.....	52
Figure 2-75. Test 676 - Barrier Pre-Impact	52
Figure 2-76. Test 676 - Barrier Static Displacements [mm].....	53
Figure 2-77. Test 676 - Downstream View of Barrier Post-Impact.....	53
Figure 2-78. Test 676 - Impact Point Post-Impact.....	54
Figure 2-79. Test 676 - Stake Downstream of Impact Point.....	54
Figure 2-80. Test 676 - Vehicle Post-Impact Front View.....	55
Figure 2-81. Test 676 - Vehicle Post-Impact Side View	55
Figure 2-82. Test 676 - Impact sequence and diagram	56
Figure 7-1. Guidance System	77
Figure 7-2. Typical Camera Locations and Labels.....	78
Figure 7-3. K-rail Standard Plan (2004).....	82
Figure 7-4. Typical Uncapped Stake Installation Layout	83
Figure 7-5. Typical Capped Stake Installation Layout	84
Figure 7-6. Capped Stake Dimensions [mm].....	85
Figure 7-7. Stake Installation.....	86
Figure 7-8. Forklift Carrying K-rail.....	86
Figure 7-9. Installed Uncapped Stake.....	86
Figure 7-10. Installed Capped Stake.....	86
Figure 7-11. Instrumentation Layout.....	87
Figure 7-12. Vehicle Accelerometer and Gyro Sign Convention	89
Figure 7-13. Test 671 Vehicle Accelerations Vs Time.....	90
Figure 7-14. Test 671 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time	91
Figure 7-15. Test 671 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time.....	92
Figure 7-16. Test 671 Acceleration Severity Index Vs Time	93
Figure 7-17. Test 671 Vehicle Roll, Pitch, and Yaw Vs Time	94
Figure 7-18. Test 672 Vehicle Accelerations Vs Time.....	95
Figure 7-19. Test 672 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time	96
Figure 7-20. Test 672 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time.....	97
Figure 7-21. Test 672 Vehicle Roll, Pitch, and Yaw Vs Time	98
Figure 7-22. Test 672 Acceleration Severity Index Vs Time	99
Figure 7-23. Test 673 Vehicle Accelerations Vs Time.....	100
Figure 7-24. Test 673 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time	101
Figure 7-25. Test 673 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time.....	102
Figure 7-26. Test 673 Vehicle Roll, Pitch, and Yaw Vs Time	103
Figure 7-27. Test 673 Acceleration Severity Index Vs Time	104

Figure 7-28. Test 674 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time	105
Figure 7-29. Test 674 Vehicle Accelerations Vs Time.....	106
Figure 7-30. Test 674 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time.....	107
Figure 7-31. Test 674 Vehicle Roll, Pitch, and Yaw Vs Time	108
Figure 7-32. Test 674 Acceleration Severity Index Vs Time	109
Figure 7-33. Test 675 Acceleration Severity Index Vs Time	110
Figure 7-34. Test 675 Vehicle Roll, Pitch, and Yaw Vs Time	111
Figure 7-35. Test 675 Vehicle Accelerations Vs Time.....	112
Figure 7-36. Test 675 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time.....	113
Figure 7-37. Test 675 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time	114
Figure 7-38. Test 676 Vehicle Accelerations Vs Time.....	115
Figure 7-39. Test 676 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time	116
Figure 7-40. Test 676 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time.....	117
Figure 7-41. Test 676 Vehicle Roll, Pitch, and Yaw Vs Time	118
Figure 7-42. Test 676 Acceleration Severity Index Vs Time	119

LIST OF TABLES

Table 1-1. Target Impact Conditions.....	3
Table 2-1. Test Vehicle Masses.....	9
Table 2-2. Test 671 Assessment Summary.....	59
Table 2-3. Test 672 Assessment Summary.....	60
Table 2-4. Test 673 Assessment Summary.....	61
Table 2-5. Test 674 Assessment Summary.....	62
Table 2-6. Test 675 Assessment Summary.....	63
Table 2-7. Test 676 Assessment Summary.....	64
Table 2-8. Vehicle Trajectory, Speed and Impact Severity	65
Table 2-9. Tolerances for Impact Angle, Velocity and Severity	65
Table 7-1. Test 671 Vehicle Dimensions.....	71
Table 7-2. Test 672 Vehicle Dimensions.....	72
Table 7-3. Test 673 Vehicle Dimensions.....	73
Table 7-4. Test 674 Vehicle Dimensions.....	74
Table 7-5. Test 675 Vehicle Dimensions.....	75
Table 7-6. Test 676 Vehicle Dimensions.....	76
Table 7-7. Camera Type	78
Table 7-8. Camera Locations for Test 671 through Test 673	79
Table 7-9. Camera Locations for Test 674 through Test 676	80
Table 7-10. Accelerometer and Gyro Specifications.....	88

1. INTRODUCTION

1.1. Problem

The current policy for the staking of K-rail is not consistent with the current understanding of how K-rail reacts during vehicular impacts. Efforts to develop a new policy for staking K-rail during construction have been met with concern over cost-effectiveness and crash-worthiness issues. A new configuration for staked K-rail that passes NCHRP Report 350 guidelines [1] must be developed to provide the safest alternative for the traveling public and construction personnel with minimal deployment cost.

1.2. Objective

This research project focuses on developing a cost-effective staking configuration for K-rail, which meets NCHRP Report 350 Test Level 3 for longitudinal barriers and the needs of Caltrans' Traffic Operations and Construction. Traffic Operations requested a staking configuration to use when K-rail is placed as a median barrier in narrow medians. Construction requested a configuration that meets two criteria: place K-rail near the edge of an excavation and minimize the distance between the K-rail and the excavation. In addition, both groups requested that the staking configurations minimize barrier movement, pavement damage, and worker exposure.

1.3. Background and Significance of Work

Caltrans' current standard for portable concrete barrier is K-rail. This barrier may be used in long-term installations when properly installed [2]. K-rail evolved from the Type 50 ("New Jersey shape") median barrier, which has been approved for use in California and other states since the mid-1960s. By 1971, substantial interest was expressed in California and other states to develop a movable barrier that could be used in work zones. In 1972, Caltrans ran a series of crash tests on K-rail. The test results led to the approval of K-rail for use as a temporary barrier in California. The K-rail that has become the standard consists of 6.1-m^a (20-ft) long sections with pin and loop connections, each weighing approximately 3630 kg (8000 lbs).

In 1999, Caltrans tested fully staked K-rail for temporary installations, and the results showed that fully staked K-rail greatly reduced lateral barrier movement [3]. Traffic Operations issued a Policy Directive on 1/18/2002 that required K-rail to be staked when it was placed near the edge of travel way and/or near the edge of an excavation. However, the policy was rescinded on 3/15/2002 due to the increased traffic exposure for construction workers during stake installation, damage to the pavement, and increased cost of traffic control.

This research project was established to address the concerns listed above. The results of this research will lead to new policy that outlines the minimum guidelines for temporary K-rail installations.

^a Metric units are used for measurements taken for NCHRP Report 350 evaluation criteria. Dual units (Metric followed by U.S. Customary) are used for measurements related to the test article.

1.4. Literature Search

A search for information about staked K-rail consisted of information contained in past crash test reports by Caltrans and other agencies. Information was found in:

- Compliance Crash Testing of K-rail Used in Semi-Permanent Installations, FHWA/CA/OR-99/07 [3]
- Dynamic Tests of Prestressed Concrete Median Barrier Type 50, Series XXVI, CA-HY-MR-6588-1-73-06 [4]
- Crash Test Results for the Idaho 6095-mm Concrete Barrier [5]
- “Tie-Downs and Transitions for Temporary Concrete Barriers,” Journal of the Transportation Research Board, No. 1984 [6]

1.5. Scope

A total of six tests were performed and evaluated in accordance to NCHRP Report 350. The first three tests evaluated K-rail when placed as a semi-permanent median barrier and the last three evaluated K-rail when placed adjacent to an excavation. The testing matrix established for this project is shown in Table 1-1 on the preceding page.

1 INTRODUCTION

Table 1-1. Target Impact Conditions

Test #	STAKE CONFIGURATION	Vehicle Mass [kg] (lbm)	Impact Speed [km/h] (mph)	Impact Angle [deg]	NCHRP REPORT 350	
					Test Designation	Vehicle
<i>K-RAIL PLACED AS A SEMI-PERMANENT BARRIER</i>						
671	2 uncapped stakes in opposite corners, upstream relative to the traffic flow.	2000 (4410)	100 (62.1)	25	3-11	2000P
672	4 uncapped stakes per section, every other section.	2000 (4410)	100 (62.1)	25	3-11	2000P
673	4 capped stakes per section, every other section.	2000 (4410)	100	25	3-11	2000P
<i>K-RAIL PLACED ADJACENT TO AN EXCAVATION</i>						
674	4 capped stakes per section, every other section with the barrier offset by 152mm (6 in) from the excavation's edge.	2000 (4410)	100 (62.1)	25	3-11	2000P
675	2 capped stakes per section, traffic side with the barrier offset by 76mm (3 in) from the excavation's edge.	2000 (4410)	100 (62.1)	25	3-11	2000P
676	1 capped stake per section, traffic side, upstream relative to traffic with the barrier offset by 76mm (3 in) from the excavation's edge.	2000 (4410)	100 (62.1)	25	3-11	2000P

2. TECHNICAL DISCUSSION

2.1. Test Conditions – Crash Tests

2.1.1. Test Facilities

All of the crash tests were conducted at the Caltrans Dynamic Test Facility in West Sacramento, California. The test area is a large, flat, asphalt concrete surface containing 2 overlays (Figure 2-1). Each overlay measured approximately 51 mm (2 in) thick. There were no obstructions near or within the testing area.



Figure 2-1. Asphalt Concrete Thickness

2.1.2. Test Article Design

2.1.2.1. *K-rail*

The K-rail was purchased new at Concrete Products in Tracy, CA. The K-rail was manufactured to Caltrans' Standard Plans and Specifications. Members of the Roadside Safety and Research Group visited the plant to inspect the K-rail. They evaluated the construction process, collected concrete samples for testing, measured the concrete temperature, performed a slump test, and checked the rebar placement (Figure 2-2).

Sampling cylinders were prepared for later testing of the compressive strength of the concrete. Three cylinders were sent for testing to the concrete testing section at the Caltrans Transportation Laboratory. The 28-day average compressive strength was found to be 29,160 kPa (4230 psi). The results from all tests and inspections met or exceeded Caltrans' 2004 Standard Specifications. The 2004 K-rail Standard Plan is located in Section 7.5 of the Appendix.



Figure 2-2. K-rail Rebar Placement

2.1.2.2. *Stakes*

2.1.2.2.1. *Stake Description*

The stakes originally selected were 610-mm (24-in) long, #25M (#8) deformed rebar of ASTM A615 Grade 60 material (Figure 2-3). These parameters were selected for the following reasons:

1. Deformed bar (vs. smooth bar) to increase the uplift resistance.
2. 610-mm (24-in) length allows for quick installation. A longer length would consume more installation time, and thus, would increase worker exposure. Additionally, a longer stake would not provide a significant amount of lateral resistance.
3. #25M (#8) rebar is the largest size that will fit through a K-rail staking slot. It provides greater to lateral displacement than smaller sizes.
4. ASTM A615 Grade 60 deformed rebar is a common material.



Figure 2-3. Uncapped Stake

For conservative results, the uncapped stakes were driven down until their heads were flush with the K-rail slot's horizontal surface. More details about the stakes and installation process are located in Sections 7.5 and 7.6.

Starting with Test 673, the stake design was modified to have a cap (Figure 2-4). This addition provided uplift resistance and prevented the K-rail from slipping over the stake when impacted. The uplift resistance was important since, without caps, the K-rail would rotate about the stakes opposite the impact side. The vehicle would then travel up the face of the barrier and be launched onto the top of the barrier.

The stake design changed to 610-mm (24-in) long, #25M (#8) deformed rebar of ASTM A706 Grade 60 material with a 70-mm (2.75-in) diameter by 13-mm (0.5-in) thick washer welded approximately 25 mm (1 in) below the top surface. Points were added to the stakes for Tests 674 – 676 for quicker installation. More information about stakes and the installation process is located in Sections 7.5 and 7.6.



Figure 2-4. Capped Stake

2.1.2.3. Stake Configurations

Two types of staking configurations were developed. The first configuration type is used when K-rail is placed as a temporary median barrier. The second configuration type is used when K-rail is placed adjacent to an excavation during construction.

2.1.2.3.1. Median Configurations (Tests 671-673)

The median configurations are symmetrically designed relative to the traffic flow. The configurations are shown in top section of Figure 2-5.

The staking configuration for Test 671 incorporated two uncapped stakes per barrier. The stakes were placed in opposing corners in the slot that was upstream relative to the traffic's flow. The critical impact point (CIP) was located 305 mm upstream from a joint to maximize the potential for vehicle roll and the barrier displacement.

The staking configuration for Test 672 incorporated four uncapped stakes in every other barrier. As in Test 671, the critical impact point was located 305 mm upstream from a joint on a staked section to maximize the vehicle's roll and the barrier's displacement.

The staking configuration for Test 673 incorporated four capped stakes in every other barrier. It was noted after Tests 671 and 672 that the uncapped stakes provided no uplift resistance for the barrier. Also, once the barrier lifted above the stake's top edge, the stake provided no lateral resistance. Therefore, the configuration for Test 673 is the same as it was for Test 672, but capped stakes replaced uncapped stakes. Again, the critical impact point was located 305 mm upstream from a joint on a staked section to maximize the vehicle roll and the barrier displacement.

2.1.2.3.2. Adjacent to an Excavation Configurations (Tests 674-676)

The adjacent-to-an-excavation configurations were designed to establish guidelines for the minimum distance between the K-rail and an excavation and to minimize the lateral barrier movement. The excavation was approximately 610 mm deep. The configurations are shown in lower section of Figure 2-5.

The staking configuration for Test 674 incorporated four capped stakes in every other barrier. Since this configuration had a favorable result for Test 673, it was the first choice for the adjacent-to-an-excavation testing series. The barrier was placed 150 mm from the edge of the excavation. The critical impact point was located 914 mm upstream from a joint on a non-staked barrier segment to evaluate for potential vehicle snagging and to maximize the barrier displacement.


The staking configuration for Test 675 incorporated two capped stakes per barrier on the traffic side. It was noted from previous tests that the stakes that were located opposite of the impact side created a pivot point when the barrier was impacted. The pivot point would cause the barrier to rollback, which led to vehicle roll. The barrier was placed 75 mm from the edge of the excavation versus at the edge to account for varying edge conditions. The critical impact point was located 914 mm upstream from a joint to evaluate for potential vehicle snagging and to maximize the barrier displacement.

The staking configuration for Test 676 incorporated one capped stake per barrier in the traffic side's upstream slot. It was designed to further reduce installation costs, pavement damage, and worker exposure. The barrier was placed 75 mm from the edge of the excavation

2 TECHNICAL DISCUSSION

versus at the edge to account for varying edge conditions. The critical impact point was located 305 mm upstream from a joint to maximize the barrier's displacement.

MEDIAN BARRIER CONFIGURATIONS



ADJACENT TO AN EXCAVATION CONFIGURATIONS




Figure 2-5. Staking Configurations Layout

2.1.3. Test Vehicles

Most test vehicles complied with NCHRP Report 350 Test Designation 3-11 guidelines. One vehicle was below the recommended test inertial mass^b. For all tests, the vehicles were ¾-ton pickups in good condition, free of major body damage and not missing any structural parts. All of the vehicles had front-mounted engines and standard equipment.

Table 2-1. Test Vehicle Masses

Test No.	Vehicle		Test Inertial
<i>Units</i>	<i>Model</i>	<i>Year Manufactured</i> ^c	<i>Kg (lbm)</i>
671	GMC Sierra 2500	1992	1986.7 (4379.9)
672	GMC Sierra 2500	1993	1987.4 (4381.5)
673	Chevrolet 2500	1997	2016.3 (4445.2)
674	GMC Cheyenne	1989	1929.7 ^b (4254.3)
675	Chevrolet Silverado	1994	2005.9 (4422.2)
676	Chevrolet Silverado	1988	1981.0 (4367.4)

The test vehicles were self-powered and used a speed control device to limit acceleration once the impact speed had been reached. Remote braking was possible at any time during all tests via a radio-linked, remote-controlled braking setup. A short distance before the point of

^b The test inertial mass was less than the recommended test inertial mass range (2000 +/- 45 kg). The same conclusion for this test would have been made with a vehicle that was within the recommended test inertial mass range.

^c NCHRP Report 350 recommends that test vehicles be less than six years old at the time of testing. Although all of the vehicles were older than the recommended age limit, the body style of the 2500 pickup was the same from 1988 – 1998. In 1999 and 2000 the older body style was still available for new purchase.

impact each vehicle was released from the guidance rail and the ignition system was deactivated. A detailed description of the test vehicle equipment and guidance system is contained in Sections 7.1 and 7.2 (located in the Appendix).

2.1.4. Data Acquisition System

All tests were recorded with high-speed digital video cameras, one normal speed digital video camera, and one digital SLR camera. The test vehicles and test articles were photographed before and after impact with a digital video camera and a digital SLR camera. A film report of this project was assembled using edited portions of the digital film and camera coverage. More detailed information on the cameras is located in Section 7.3.

Two sets of orthogonal accelerometers were mounted in the center of gravity of each vehicle. One set of rate gyro transducers was placed 191 mm (7.5 in) behind the set of accelerometers (along the X-axis) to measure the roll, pitch, and yaw rates. These data were used in calculating the occupant impact velocities, ridedown accelerations, and maximum vehicle rotation. More information on instrumentation is located in Section 7.7.1.

Two separate digital transient data recorders, manufactured by GMH Engineering (Model II), were used to record electronic data during all tests. The digital data were analyzed with custom DADiSP workbooks using a personal computer. The test data is located in the Appendix.

2.2. Test Results – Crash Tests

2.2.1. Test 671 – Median Layout: 2 Uncapped Stakes per Barrier

2.2.1.1. Impact Description/Vehicle Behavior

The intended impact angle of 25° and impact location on the vehicle's left-front corner was set by the placement of the guide rail (Figure 2-7). Film analysis indicated that the actual impact angle was 28.3°, and the actual impact location was 93 mm upstream from the intended Critical Impact Point (CIP). The impact speed of 101.4 km/h (63.0 mph) was obtained by averaging the output from two independent speed traps located just upstream from the impact point. This speed was confirmed via film analysis. Upon impact the vehicle's left front corner was crushed while the barrier rocked back and shifted laterally away from the impact. The vehicle rode upwards on the barrier during impact and stayed in contact for 3.2 m (10.5 ft). Approximately 0.29 s after impact the left rear tire lost contact with the barrier, and the vehicle was in the air. The vehicle rolled to the right (positive), and its right front tire landed on the ground 14.1 m (46.3 ft) from the CIP and 0.61 s after the initial impact. The vehicle's undercarriage landed on top of the barrier 19.1 m (62.7 ft) from the CIP and 1.12 s after the initial impact. The vehicle remained in contact with the top of the barrier until reaching the end of the last segment, at which point it dropped to the ground. The brakes were applied 1.22 s after the initial impact as indicated by the data recorder's event channel. The vehicle came to rest 76 m (250 ft) from the CIP. Figure 2-6 through Figure 2-16 show the pre-test and post-test condition of the test vehicle and test article. Sequence photographs of the impact for Test 671 are shown as Figure 2-17 on the data summary sheet on page 17.

The longitudinal occupant impact velocity was 5.25 m/s (17.2 ft/s), which was below the allowable maximum of 12 m/s (39 ft/s) specified in NCHRP Report 350. The longitudinal

2 TECHNICAL DISCUSSION

occupant ridedown acceleration, 3.96 g, was below the allowed maximum of 20 g. Test results are summarized in Table 2-2 on page 59.



Figure 2-6. Test 671 - Side View of Vehicle Pre-Impact



Figure 2-7. Test 671 - Vehicle at Impact Location Pre-Impact



Figure 2-8. Test 671 - Close-up view of Vehicle at Impact Location Pre-Impact



Figure 2-9. Test 671 - Barrier Pre-Impact

2.2.1.2. Barrier Damage

The barrier underwent some permanent displacement as seen in the figure below (segments that did not have any measurable movement are not shown).




Figure 2-10. Test 671 - Barrier Static Displacements [mm]

The pin and loop connection between sections 5 & 6, 6 & 7 (nearest to the impact point) and 7 & 8 bent and caused spalling at the joint. Sections 6 through 12 had scuffmarks. Sections 10 and 11 had minor scuffing on the top, which occurred when the vehicle rode on top of the barrier. The upstream stake in Section 6 & both stakes in Section 7 were bent. The staked, upstream slot in Section 6 had spalling. The maximum lateral static displacement was 370 mm (14.6 in), and the maximum lateral dynamic displacement was 389 mm (15.3 in) at the toe. Static measurements were taken with a tape measure and dynamic measurements were obtained via film analysis. After impact, segments 6 and 7 maintained a backward lean due to obstructions under the K-rail.



Figure 2-11. Test 671 - Downstream View of Barrier Post-Impact



Figure 2-12. Test 671 - Impact Location Post-Impact



Figure 2-13. Test 671 - Section 6 Upstream Stake Post-Impact

2.2.1.3. *Vehicle Damage*

The initial impact damaged the left front corner of the vehicle. The left front quarter panel and bumper were crushed. The floorboard intruded into the occupant compartment by 2.5 cm (1 in). The floorboard deformation area was approximately 140 cm² (0.15 ft²) and was located at the left front corner. The tire partially slipped off of the rim. The secondary impact occurred when the vehicle contacted the ground while it was rolling. The right front quarter panel and bumper were damaged. The hub guidance assembly was slightly damaged.



Figure 2-14. Test 671 - Side View of Vehicle Post-Impact



Figure 2-15. Test 671 – Front-left View of Vehicle Post-Impact



Figure 2-16. Test 671 - Front-right View of Vehicle Post-Impact

2.2.1.4. Test 671 Data Summary Sheet




Figure 2-17. Test 671 - Impact sequence and diagram

General Information

Testing Agency..... California DOT
 Test Number 671
 Test Date June 9, 2005

Test Article

Type.....Semi-permanent K-rail in a median barrier configuration
 Staking Configuration
 2 uncapped stakes in opposite corners, upstream relative to the traffic flow.
 Installation Length..... 73.1 m (239.8 ft)
 Element Length 6.1 m (20 ft)
 Element Height..... 0.8 m (32 in)
 Element Weight..... 3540 kg (7805.7 lb)

Test Vehicle

Type..... Production Model
 Designation..... 2000P
 Model 1992 GMC Sierra
 Mass: Curb 1984.9 kg (4375.9 lbm)
 Test Inertial..... 1986.7 kg (4380.0 lbm)

Impact Conditions

Impact Velocity 101.4 km/h (63.0 mph)
 Impact Angle 28.3°

Exit Conditions

Exit Velocity..... n/a
 Exit Angle 0°

Test Data

Occupant Impact Velocity
 Long 5.25 m/s (17.2 ft/s)
 Lat -5.33 m/s (-17.5 ft/s)
 Ridedown Acceleration
 Long 3.96 g
 Lat -5.50 g
 ASI 1.41
 OCDI LF0010000

Post-Impact Vehicular Behavior

(Data Analysis/Video Analysis)

Maximum Roll Angle..... 33.93° / 63°
 Maximum Pitch Angle 14.30° / 16°
 Maximum Yaw Angle 24.22° / n/a

Test Article Deflections

Dynamic 389 mm (15.3 in)
 Permanent..... 370 mm (14.6 in)

2.2.2. Test 672 – Median Layout: 4 Uncapped Stakes per Every Other Barrier

2.2.2.1. Impact Description/Vehicle Behavior

The intended impact angle of 25° and impact location on the vehicle’s left-front corner was set by the placement of the guide rail (Figure 2-19). Film analysis indicated that the actual impact angle was 26.0°, and the actual impact location was 127 mm (5 in) upstream from the intended CIP. The impact speed of 99.1 km/h (61.6 mph) was obtained by averaging the output from two independent speed traps located just upstream from the impact point. This speed was confirmed via film analysis. Upon impact the vehicle’s left front corner was crushed. The vehicle rode upwards on the barrier during impact and stayed in contact for 3.0 m (9.8 ft). Approximately 0.29 s after impact the left rear tire lost contact with the barrier and the vehicle was in the air. The vehicle rolled to the right before its right front tire landed on the ground 13.3 m (43.6 ft) from the CIP and 0.59 s after the initial impact. The vehicle’s undercarriage landed on top of the barrier 23.8 m (78.1 ft) from the CIP and 1.23 s after the initial impact. The vehicle remained in contact with the top of the barrier until the end of the last segment was passed. The brakes were applied 0.82 s after the initial impact as indicated by the data recorder’s event channel. The vehicle came to rest 53 m (174 ft) from the CIP.

The longitudinal occupant impact velocity was 4.60 m/s (15.1 ft/s), which was above the allowable maximum of 12 m/s (39 ft/s) specified in NCHRP Report 350. The longitudinal occupant ridedown acceleration, -4.57 g, was below the allowed maximum of 20 g. Test results are summarized in Table 2-3 on page 60.

Figure 2-18 through Figure 2-29 show pre-test and post-test condition of the test vehicle and test article. Sequence photographs of the impact for Test 672 are shown as Figure 2-30 on the data summary sheet on page 25.



Figure 2-18. Test 672 - Side View of Vehicle Pre-Impact



Figure 2-19. Test 672 - Vehicle at Impact Location Pre-Impact



Figure 2-20. Test 672 - Close-up View of Vehicle at Impact Location



Figure 2-21. Test 672 - Barrier Pre-Impact




Figure 2-22. Test 672 - Stake #6B Pre-Impact

2.2.2.2. Barrier Damage

The barrier underwent some permanent displacement as seen in the figure below.




Figure 2-23. Test 672 - Barrier Static Displacements [mm]

The pin and loop connection between sections 5 & 6, 6 & 7 (nearest to the impact point) and 7 & 8 bent and caused spalling at the joint. Some stakes in Section 6 were bent and the slots they were in had spalling. Sections 6 and 7 had scuffmarks from the impact. Sections 10 through 12 had minor scuffing on the top, which occurred when the vehicle rode on top of the barrier. Section 7 underwent the most movement with a maximum lateral static displacement of 205 mm (8.1 in) and maximum lateral dynamic displacement of 256 mm (10 in) at the toe. Static measurements were taken with a tape measure and dynamic measurements were obtained via film analysis.



Figure 2-24. Test 672 - Downstream View of Barrier Post-Impact



Figure 2-25. Test 672 - Impact Point Post-Impact



Figure 2-26. Test 672 - Stake #6B Post-Impact



Figure 2-27. Test 672 - Scuffing on the Backside of the Barrier

2.2.2.3. *Vehicle Damage*

The initial impact damaged the left front corner of the vehicle. The left front quarter panel and bumper were crushed. Both rims on the left side were bent. The secondary impact occurred when the right side of the vehicle contacted the ground and rode along the top of the barrier. The right front quarter panel and bumper were damaged. The vehicle's left mid-section was damaged when it landed on top of the barrier. The hub guidance assembly was slightly damaged.



Figure 2-28. Test 672 - Side View of Vehicle Post-Impact



Figure 2-29. Test 672 - Front-left View of Vehicle Post-Impact

2.2.2.4. Test 672 Data Summary Sheet




Figure 2-30. Test 672 - Impact sequence and diagram

General Information

Testing Agency..... California DOT
 Test Number 672
 Test Date June 23, 2005

Test Article

Type.....Semi-permanent K-rail in a median barrier configuration
 Staking Configuration
 4 uncapped stakes per section, every other element.
 Installation Length..... 73.1 m (239.8 ft)
 Elements Length..... 6.1 m (20 ft)
 Elements Height 0.8 m (32 in)
 Elements Weight 3540 kg (7805.7 lb)

Test Vehicle

Type..... Production Model
 Designation..... 2000P
 Model 1993 GMC Sierra
 Mass: Curb 1967.6 kg (4337.8 lbm)
 Test Inertial..... 1987.4 kg (4381.5 lbm)

Impact Conditions

Impact Velocity 99.1 km/h (61.6 mph)
 Impact Angle 26.0°

Exit Conditions

Exit Velocity..... n/a
 Exit Angle 0°

Test Data

Occupant Impact Velocity
 Long 4.60 m/s (15.1 ft/s)
 Lat 7.91 m/s (25.9 ft/s)
 Ridedown Acceleration
 Long -4.57 g
 Lat -6.78 g
 ASI 1.50
 OCDI LF0011000

Post-Impact Vehicular Behavior

(Data Analysis/Video Analysis)

Maximum Roll Angle..... 56.66°/65°
 Maximum Pitch Angle 14.28°/14°
 Maximum Yaw Angle 35.34°/ ---

Test Article Deflections

Dynamic 256 mm (8.1 in)
 Permanent..... 205 mm (10.1 in)

2.2.3. Test 673 - Median Layout: 4 Capped Stakes per Every Other Barrier

2.2.3.1. Impact Description/Vehicle Behavior

The intended impact angle of 25° and impact location on the vehicle's left-front corner was set by the placement of the guide rail (Figure 2-32). Film analysis indicated that the actual impact angle was 26.2°, and the actual impact location was 112 mm (4.4 in) upstream from the intended CIP. The impact speed of 100.8 km/h (62.6 mph) was obtained by averaging the output from two independent speed traps located just upstream from the impact point. This speed was confirmed via film analysis. Upon impact the vehicle's left front corner was crushed. The vehicle rode upwards on the barrier during impact and stayed in contact for 4.0 m (13 ft). Approximately 0.31 s after impact the left rear tire lost contact with the barrier and the vehicle was in the air. The vehicle pitched forward (negative) and its right front tire landed on the ground 13.0 m (42.7 ft) from the CIP and 0.64 s after the initial impact. The brakes were applied 1.87 s after the initial impact as indicated by the data recorder's event channel. The vehicle had a secondary impact at its left front corner with a barrier protecting the downstream camera. The vehicle came to rest 82 m (269 ft) from the CIP.

The longitudinal occupant impact velocity was 5.31 m/s (17.4 ft/s), which was above the allowable maximum of 12 m/s (39 ft/s) specified in NCHRP Report 350. The longitudinal occupant ridedown acceleration, 4.51 g, was below the allowed maximum of 20 g. Test results are summarized in Table 2-4 on page 61.

Figure 2-31 through Figure 2-42 show the pre-test and post-test condition of the test vehicle and test article. Sequence photographs of the impact for Test 673 are shown as Figure 2-43 on the data summary sheet on page 33.



Figure 2-31. Test 673 - Side View of Vehicle Pre-Impact



Figure 2-32. Test 673 - Vehicle at Impact Location Pre-Impact



Figure 2-33. Test 673 - Close-up View of Vehicle at Impact Location Pre-Impact



Figure 2-34. Test 673 - Barrier Pre-Impact



Figure 2-35. Test 673 - Stake #6B Pre-Impact

2.2.3.2. Barrier Damage

The barrier underwent some permanent displacement as seen in the figure below.




Figure 2-36. Test 673 - Barrier Static Displacements [mm]

The pin and loop connection between sections 6 & 7 (nearest to the impact point) and 7 & 8 bent and caused spalling at the joint. Section 6 had a large, vertical crack on the impact side near the impact point. Sections 6 and 7 had scuffmarks from the initial impact. Some of the stakes lifted due to the barrier rotation. The maximum lateral static displacement was 163 mm (6.4 in) with a maximum lateral dynamic displacement of 200 mm (7.9 in) at the toe. Static measurements were taken with a tape measure, and dynamic measurements were obtained via film analysis.



Figure 2-37. Test 673 - Downstream View of Barrier Post-Impact



Figure 2-38. Test 673 - Impact Point Post-Impact



Figure 2-39. Test 673 - Stake #6B Post-Impact

2.2.3.3. *Vehicle Damage*

The initial impact damaged the left front corner of the vehicle. The left front quarter panel and bumper were crushed. A secondary impact occurred when the vehicle impacted a barrier protecting a camera. The impact was located at the left front corner again and further damaged the area. The hood was crushed inwards and the left front tire and rim were damaged. The maximum floorboard intruded^d into the occupant compartment by 3 cm (1.2 in). The floorboard deformation area was approximately 3275 cm² (3.5 ft²) and was located at the left front corner.

For Test 673, the vehicle impacted a K-rail section that had greater lateral and uplift resistance from the stakes than previous tests (due to the number of stakes and the caps); thus, Test 673's vehicle was damaged more than previous tests.



Figure 2-40. Test 673 - Side View of Vehicle Post-Impact

^d The floorboard deformation was greater for this test than the previous test since the vehicle impacted a fully staked section of K-rail. Upon impact, some of the vehicle's kinetic energy is absorbed by the barrier (causing the barrier to typically move) and reduces damage to the vehicle. For this project, the amount of energy transferred to the barrier was dependent on:

1. Lateral resistance from the stakes
2. Uplift resistance along the impact side from the stakes

When the resistances in items 1 and 2 are increased, the kinetic energy absorbed by the barrier is reduced, and barrier displacement is decreased.



Figure 2-41. Test 673 - Front-left View of Vehicle Post-Impact



Figure 2-42. Test 673 - Barrier Involved with Secondary Impact

2.2.3.4. Test 673 Data Summary Sheet




Figure 2-43. Test 673 - Impact sequence and diagram

General Information

Testing Agency..... California DOT
 Test Number 673
 Test Date August 24, 2005

Test Article

Type.....Semi-permanent K-rail in a median barrier configuration
 Staking Configuration
 K-rail as a temporary median divider with 4 capped stakes per section, every other section.
 Installation Length..... 79.2 m (259.8 ft)
 Element Length 6.1 m (20 ft)
 Element Height..... 0.8 m (32 in)
 Element Weight..... 3540 kg (7805.7 lb)

Test Vehicle

Type..... Production Model
 Designation..... 2000P
 Model 1997 Chevy 2500
 Mass: Curb 1951.2 kg (4301.7 kg)
 Test Inertial..... 2016.3 kg (4445.2 kg)

Impact Conditions

Impact Velocity 100.8 km/h (62.6 mph)
 Impact Angle 26.2°

Exit Conditions

Exit Velocity..... 84 km/h (52 mph)
 Exit Angle >5°

Test Data

Occupant Impact Velocity
 Long 5.31 m/s (17.4 ft/s)
 Lat -7.25 m/s (23.8 ft/s)
 Ridedown Acceleration
 Long 4.51 g
 Lat 11.21 g
 ASI 1.73
 OCDI LF0011001

Post-Impact Vehicular Behavior

(Data Analysis/Video Analysis)

Maximum Roll Angle..... 33.26°/39°
 Maximum Pitch Angle 19.48°/30°
 Maximum Yaw Angle 65.80°/ n/a

Test Article Deflections

Dynamic 207 mm (8.1 in)
 Permanent..... 163 mm (6.4 in)

2.2.4. Test 674 – Excavation Layout: 4 Capped Stakes per Every Other Barrier

2.2.4.1. Impact Description/Vehicle Behavior

The intended impact angle of 25° and impact location on the vehicle's right-front corner was set by the placement of the guide rail (Figure 2-45). Film analysis indicated that the actual impact angle was 26.5°, and the actual impact location was 130 mm (5.1 in) upstream from the intended CIP, resulting in an impact point 783 mm (30.8 in) upstream from a joint. The impact speed of 98.9 km/h (61.4 mph) was obtained by averaging the output from two independent speed traps located just upstream from the impact point. This speed was confirmed via film analysis. Upon impact the vehicle's right front corner was crushed. The vehicle rode upwards on the barrier face during impact and stayed in contact for 4.5 m (15 ft). Approximately 0.37 s after impact the right rear tire lost contact with the barrier and the vehicle was in the air. The vehicle pitched forward and its left front tire landed on the ground 13.0 m (42.7 ft) from the CIP and 0.59 s after the initial impact. The brakes were applied 1.30 s after the initial impact as indicated by the data recorder's event channel. The vehicle came to rest 51 m (170 ft) from the CIP.

The longitudinal occupant impact velocity was -3.80 m/s (-12.5 ft/s), which was below the allowable maximum of 12 m/s (39 ft/s) specified in NCHRP Report 350. The longitudinal occupant ridedown acceleration, -5.66 g, was below the allowed maximum of 20 g. Test results are summarized in Table 2-5 on page 62.

Figure 2-44 through Figure 2-57 show the pre-test and post-test condition of the test vehicle and test article. Sequence photographs of the impact for Test 674 are shown in Figure 2-58 on the data summary sheet.



Figure 2-44. Test 674 - Side View of Vehicle Pre-Impact



Figure 2-45. Test 674 - Vehicle at Impact Location Pre-Impact



Figure 2-46. Test 674 - Close-up View of Vehicle at Impact Location



Figure 2-47. Test 674 - Barrier Pre-Impact



Figure 2-48. Test 674 - Overall View of Excavation

2.2.4.2. Barrier Damage

The barrier underwent some permanent displacement as shown in the figure below.




Figure 2-49. Test 674 - Barrier Static Displacements [mm]

The pin and loop connection between sections 7 & 8 (nearest to the impact point) and 8 & 9 bent and caused spalling at the joint. Section 8 had spalling at the upstream, impact-side slot due to the stake bending. The upstream, excavation-side stake in Section 8 broke through the AC. The maximum lateral static displacement was 670 mm (26.3 in). Static measurements were taken with a tape measure. Due to the angle between the vehicle targets and the camera, the dynamic displacement could not be accurately measured.



Figure 2-50. Test 674 - Downstream View of Barrier Post-Impact



Figure 2-51. Test 674 - Impact Point Post-Impact



Figure 2-52. Test 674 - Upstream, Impact-side Stake in Section 8 Post-Impact



Figure 2-53. Test 674 - Back of Barrier Post-Impact



Figure 2-54. Test 674 - Damaged Pavement from Rear Stake



Figure 2-55. Test 674 - Pavement Damage after Barrier Removal

2.2.4.3. *Vehicle Damage*

The impact damaged the right front corner of the vehicle. The right front quarter panel and bumper were crushed. Both front tires were damaged. The body on the right side had minor body damage from scraping against the barrier. The bottom of the tailgate detached from the bed and was held in place by the upper hinges.



Figure 2-56. Test 674 - Side View of Vehicle Post-Impact



Figure 2-57. Test 674 - Front-right View of Vehicle Post-Impact

2.2.4.4. Test 674 Data Summary Sheet




Figure 2-58. Test 674 - Impact sequence and diagram

General Information

Testing Agency..... California DOT
 Test Number 674
 Test Date October 5, 2005

Test Article

Type.....Longitudinal Barrier /Temporary
 Barrier, with excavation 152 mm
 behind back of K-rail
 Staking Configuration
 4 capped stakes per section, every other
 section.
 Installation Length..... 79.2 m (259.8 ft)
 Element Length 6.1 m (20 ft)
 Element Height..... 0.8 m (32 in)
 Element Weight..... 3540 kg (7805.7 lb)

Test Vehicle

Type.....Production Model
 Designation..... 2000P
 Model 1989 GMC Cheyenne
 Mass Curb 1901.8 kg (4192.7 lbm)
 Test Inertial..... 1929.7 kg (4254.3 lbm)

Impact Conditions

Impact Velocity 98.9 km/h (61.4 mph)
 Impact Angle 26.5°

Exit Conditions

Exit Velocity..... 86 km/h (53 mph)
 Exit Angle 5°

Test Data

Occupant Impact Velocity
 Long -3.80 m/s (-12.5 ft/s)
 Lat -9.55 m/s (-31.3 ft/s)
 Ridedown Acceleration
 Long -5.66 g
 Lat 8.74 g
 ASI 2.11
 OCDI RF0001000

Post-Impact Vehicular Behavior

(Data Analysis/Video Analysis)

Maximum Roll Angle..... -29.71°/-10°
 Maximum Pitch Angle -27.98°/ 25°
 Maximum Yaw Angle -46.96°/ ---

Test Article Deflections

Dynamic n/a
 Permanent..... 670 mm (26.4 in)

2.2.5. Test 675 – Excavation Layout: 2 Capped Stakes per Barrier on Traffic Side

2.2.5.1. Impact Description/Vehicle Behavior

The intended impact angle of 25° and impact location on the vehicle's right-front corner was set by the placement of the guide rail (Figure 2-60). Film analysis indicated that the actual impact angle was 26.4°, and the actual impact location was 170 mm (6.7 in) downstream from the intended CIP. The impact speed of 100.6 km/h (62.5 mph) was obtained by averaging the output from two independent speed traps located just upstream from the impact point. This speed was confirmed via film analysis. Upon impact the vehicle's right front corner was crushed. The vehicle rode upward on the barrier during impact and stayed in contact for 4.5 m (14 ft). Approximately 0.29 s after impact the right rear tire lost contact with the barrier and the vehicle was in the air. The vehicle rolled to the left and its left front tire landed on the ground 12.9 m (42.3 ft) from the CIP and 0.58 s after the initial impact. The brakes were applied 1.17 s after the initial impact as indicated by video analysis using the brake flash. The vehicle came to rest 61 m (200 ft) from the CIP.

The longitudinal occupant impact velocity was 4.66 m/s (15.3 ft/s), which was above the allowable maximum of 12 m/s (39 ft/s) specified in NCHRP Report 350. The longitudinal occupant ridedown acceleration, -3.68 g, was below the allowed maximum of 20 g. Test results are summarized in Table 2-6 on page 63.

Figure 2-59 through Figure 2-70 show the pre-test and post-test condition of the test vehicle and test article. Sequence photographs of the impact for Test 675 are shown as Figure 2-71 on the data summary sheet on page 49.



Figure 2-59. Test 675 - Side View of Vehicle Pre-Impact



Figure 2-60. Test 675 - Vehicle at Impact Location Pre-Impact



Figure 2-61. Test 675 - Close-up View of Vehicle at Impact Location



Figure 2-62. Test 675 - Barrier Pre-Impact

2.2.5.2. Barrier Damage

The barrier underwent some permanent displacement as seen in the figure below.




Figure 2-63. Test 675 - Barrier Static Displacements [mm]

The pin and loop connection between sections 5 & 6 (nearest to the impact point) and 6 & 7 bent and caused spalling at the joint. The slots located in the upstream end of Section 5 and downstream end of Section 6 had spalling. Sections 5 and 6 had scuffmarks on the surface from the impact. The barriers' maximum lateral static displacement was 350 mm (13.8 in) and the maximum lateral dynamic displacement was 350 mm (13.8 in) at the toe. The barrier extended over the excavation by approximately 280 mm (11.0 in). Static measurements were taken with a tape measure, and dynamic measurements were obtained via film analysis.



Figure 2-64. Test 675 - Downstream View of Barrier Post-Impact



Figure 2-65. Test 675 - Barrier over Excavation



Figure 2-66. Test 675 - Impact Point Post-Impact



Figure 2-67. Test 675 - Stake at Impact Point



Figure 2-68. Test 675 - Stake Downstream from Impact Point

2.2.5.3. *Vehicle Damage*

The impact damaged the right front corner of the vehicle. The right front quarter panel and bumper were crushed. The tire slipped off the rim. The suspension and steering assemblies were damaged. The tie rod sheered off the spindle. The hub guidance assembly was slightly damaged.



Figure 2-69. Test 675 - Side View of Vehicle Post-Impact




Figure 2-70. Test 675 - Front-right View of Vehicle Post-Impact

2.2.5.4. Test 675 Data Summary Sheet





Figure 2-71. Test 675 - Impact sequence and diagram

General Information

Testing Agency..... California DOT
 Test Number..... 675
 Test Date October 25, 2005

Test Article

Type.....Longitudinal Barrier /Temporary
 Barrier with excavation 76 mm behind
 back of K-rail
 Staking Configuration
 2 capped stakes per section, traffic side.
 Installation Length..... 73.2 m (239.8 ft)
 Element Length 6.1 m (20 ft)
 Element Height..... 0.8 m (32 in)
 Element Weight..... 3540 kg (7805.7 lb)

Test Vehicle

Type.....Production Model
 Designation..... 2000P
 Model 1994 Chevy Silverado
 Mass: Curb 1970.9 kg (4345.1 lbm)
 Test Inertial..... 2005.9 kg (4422.2 lbm)

Impact Conditions

Impact Velocity 100.6 km/h (62.5 mph)
 Impact Angle 26.4°

Exit Conditions

Exit Velocity..... 84 km/h (52.2 mph)
 Exit Angle 12°

Test Data

Occupant Impact Velocity
 Long 4.66 m/s (15.3 ft/s)
 Lat -5.86 m/s (-19.2 ft/s)
 Ridedown Acceleration
 Long -3.68 g
 Lat 7.10 g
 ASI 1.32
 OCDI RF0001000

Post-Impact Vehicular Behavior

(Data Analysis/Video Analysis)

Maximum Roll Angle..... -56.92°/-64°
 Maximum Pitch Angle 16.78°/11°
 Maximum Yaw Angle -34.64°/ ---

Test Article Deflections

Dynamic 350 mm (13.8 in)
 Permanent..... 350 mm (13.8 in)

2.2.6. Test 676 – 1 Capped Stake per Barrier

2.2.6.1. *Impact Description/Vehicle Behavior*

The intended impact angle of 25° and impact location on the vehicle's right-front corner was set by the placement of the guide rail (Figure 2-73). Film analysis indicated that the actual impact angle was 25.1° and the actual impact location was 12 mm (0.5 in) downstream from the intended CIP. The impact speed of 101.8 km/h (63.3 mph) was obtained by averaging the output from two independent speed traps located just upstream from the impact point. This speed was confirmed via film analysis. Upon impact the vehicle's right front corner was crushed. The vehicle rode upwards on the barrier during impact and stayed in contact for 3.4 m (11 ft). Approximately 0.29 s after impact the right rear tire lost contact with the barrier and the vehicle was in the air. The vehicle rolled to its left and its left front tire landed on the ground and barrier simultaneously 13.7 m (44.9 ft) from the CIP and 0.63 s after the initial impact. The rear of the vehicle's undercarriage landed on top of the barrier 48.7 m (160 ft) from the CIP. The vehicle remained in contact with the top of the barrier almost to the end. Approximately 1 m (3 ft) before the barrier's end, the vehicle separated from the barrier and proceeded to rollover. Since the event channel was damaged and the vehicle rolled out of the camera's view, the brake application time is not available. The vehicle came to rest 64 m (210 ft) from the CIP.

The longitudinal occupant impact velocity was 3.63 m/s (11.9 ft/s), which was below the allowable maximum of 12 m/s (39 ft/s) specified in NCHRP Report 350. The longitudinal occupant ridedown acceleration, -3.86 g, was below the allowed maximum of 20 g. Test results are summarized in Table 2-7 on page 64.

Figure 2-72 through

Figure 2-80 show the pre-test and post-test condition of the test vehicle and test article. Sequence photographs of the impact for Test 676 are shown in Figure 2-82 on the data summary sheet.



Figure 2-72. Test 676 - Side View of Vehicle Pre-Impact



Figure 2-73. Test 676 - Vehicle at Impact Location Pre-Impact



Figure 2-74. Test 676 - Close-up View of Vehicle at Impact Location



Figure 2-75. Test 676 - Barrier Pre-Impact

2.2.6.2. Barrier Damage

The barrier underwent some permanent displacement as seen in the figure below.




Figure 2-76. Test 676 - Barrier Static Displacements [mm]

The pin and loop connections between sections 5 & 6 (nearest to the impact point) and 6 & 7 were bent and caused spalling at the joint. Section 5 had spalling at the stake location. Sections 5 and 6 had scuffmarks from the impact. Sections 9 through 12 had minor scuffing on the top, which occurred when the vehicle rode on top of the barrier.

The maximum lateral static displacement was 505 mm (20.0 in). Due to the angle between the vehicle targets and the camera, the dynamic displacement could not be accurately measured.



Figure 2-77. Test 676 - Downstream View of Barrier Post-Impact



Figure 2-78. Test 676 - Impact Point Post-Impact



Figure 2-79. Test 676 - Stake Downstream of Impact Point

2.2.6.3. Vehicle Damage

The initial impact damaged the right front corner of the vehicle. The right front quarter panel and bumper were crushed inwards. The right front tire and right side rims were damaged. The right body panel was crushed when the vehicle rode on top of the barrier. The windshield was damaged during the rollover, but remained in place. The rear window shattered.



Figure 2-80. Test 676 - Vehicle Post-Impact Front View




Figure 2-81. Test 676 - Vehicle Post-Impact Side View

2.2.6.4. Test 676 Data Summary Sheet





Figure 2-82. Test 676 - Impact sequence and diagram

General Information

Testing Agency..... California DOT
 Test Number 676
 Test Date May 16, 2006

Test Article

Type.....Longitudinal Barrier /Temporary
 Barrier with excavation 76 mm behind
 back of K-rail
 Staking Configuration
 1 capped stake per section, traffic side,
 upstream relative to traffic.
 Installation Length..... 73.1 m (239.8 ft)
 Element Length 6.1 m (20 ft)
 Height Length..... 0.8 m (32 in)
 Weight Length..... 3540 kg (7805.7 lb)

Test Vehicle

Type..... Production Model
 Designation..... 2000P
 Model 1988 Chevy Silverado
 Mass: Curb 1923.5 kg (4240.6 lbm)
 Test Inertial..... 1981.0 kg (4367.4 lbm)

Impact Conditions

Impact Velocity 101.8 km/h (63.3 mph)
 Impact Angle 25.1°

Exit Conditions

Exit Velocity..... n/a
 Exit Angle 0°

Test Data

Occupant Impact Velocity
 Long 3.63 m/s (11.9 ft/s)
 Lat -5.96 m/s (-19.6 ft/s)
 Ridedown Acceleration
 Long -3.86 g
 Lat 5.35 g
 ASI 1.16
 OCDI RF0011010

Post-Impact Vehicular Behavior

(Data Analysis/Video Analysis)

Maximum Roll Angle..... -57.41°/ -55°
 Maximum Pitch Angle 14.10°/ 25°
 Maximum Yaw Angle -52.45°/ n/a

Test Article Deflections

Dynamic n/a mm
 Permanent..... 505 mm (20.0 in)

2.3. Discussion of Test Results

NCHRP Report 350 stipulates that crash test performance is assessed according to three evaluation factors: 1) Structural Adequacy, 2) Occupant Risk, and 3) Vehicle Trajectory. These evaluation factors are further defined by evaluation criteria and are shown for each test designation in Table 5.1 of NCHRP Report 350. The NCHRP Report 350 Test Designation is 3-11 (2000P vehicle) for all tests conducted during this research.

2.3.1. Structural Adequacy

2.3.1.1. Median Barrier Configurations

Of the three tests conducted in the median barrier configuration, only Test 673 demonstrated acceptable structural adequacy. Tests 671 and 672 failed to safely redirect the test vehicle, demonstrating an inadequate structural integrity.

Test 671, with each K-rail element being held in position by two uncapped stakes in a staggered configuration, resulted in launching the vehicle up, over, and onto the top of the barrier. This was an unstable result, which could have led to a rollover or impact with oncoming traffic.

Test 672, with four uncapped stakes in every other K-rail element, yielded the same result as Test 671. The K-rail element leaned back and lifted off of the uncapped stake, resulting in a vehicle riding up the face and resting on the top of the barrier.

Test 673, with four capped stakes in every other K-rail element, resulted in one cracked K-rail element, a permanent lateral displacement of 163 mm (6.04 in), and some damage to the K-rail interconnects at the impact point. However, the damage to the barrier was not unexpected and the vehicle stability was much better in this test than it had been in the previous two. The vehicle did not vault onto the top of the barrier. The structural adequacy was acceptable for test configuration 673.

2.3.1.2. Adjacent to Excavation Configurations

Since this configuration involves an excavation, the K-rail Staking Committee added an additional criterion for evaluation in the Structural Adequacy category. The Committee asked that the lateral penetration of the K-rail into the excavation be kept to a minimum and that the Committee review the test results. Based on the additional Structural Adequacy Criteria, the configuration in Test 675 demonstrated acceptable structural adequacy, while the configurations in tests 674 and 676 did not.

Tests 674 (which was the same configuration as 673 except with the excavation), resulted in an acceptable redirection of the test vehicle but produced excessive penetration of the barrier into the excavation, posing an unacceptable risk to workers. Additionally, the failure of the AC pavement behind the rear stakes would require additional exposure of workers during pavement repair efforts at a later date.

Test 675, with capped stakes placed in every stake hole on the traffic-side of the K-rail but none on the excavation side, resulted in minimal lateral deflation and good vehicle redirection. There was no damage to the pavement. The review by the Committee resulted in the assessment that the 280 mm (11 in) of overlap into the excavation was acceptable. The structural adequacy of configuration 675 is acceptable.

Test 676, with a single capped stake on the downstream traffic side of each K-rail, resulted in excessive barrier movement and a rollover of the test vehicle. This test was a clear failure of the Structural Adequacy criteria.

A detailed assessment summary of structural adequacy for each test is shown in Table 2-2 through Table 2-7.

2.3.2. Occupant Risk

2.3.2.1. Median Barrier Configurations

All three of the median configuration tests passed the criteria for occupant risk. However, it should be noted that tests 671 and 672 resulted in the test vehicles straddling the barrier, which could result in secondary impacts and greater occupant risk. The occupant deformations were considered acceptable for all of the median configuration tests.

2.3.2.2. Adjacent to Excavation Configurations

Of the three tests conducted on excavation configurations, only test 675 concluded with acceptable results. The other configurations presented undue hazards to either the vehicle occupants or the work zone personnel.

Although Test 674 resulted in acceptable conditions for the vehicle occupants, there were undue hazards to the work zone personnel. Failure of the AC to hold the rear stake caused a large chunk of the AC to break loose and fall into the excavation. Additionally, the barrier penetrated 670 mm (26 in) into the excavation. The Committee considered the pavement failure and the deflection as unacceptable to the work zone safety.

Test 675 resulted in acceptable occupant risk. There was lateral deflection of barrier. However, the AC did not fail and the barrier deflection was acceptable to the Committee.

Test 676 failed several criterion of the Occupant Risk. There was excessive barrier penetration into the work zone. After impact the vehicle slid along the top of the barrier, presenting addition risk to the work zone. After losing contact with the barrier the vehicle rolled over.

A detailed assessment summary of occupant risk for each test is shown in Table 2-2 through Table 2-7.

2.3.3. Vehicle Trajectory

2.3.3.1. Median Barrier Configurations

The vehicle trajectory was considered marginal for tests 671 and 672 because the vehicle ended up straddling the barrier. Test 673 was considered to have acceptable post-impact trajectory.

2.3.3.2. Adjacent to Excavation Configurations

Test 674 and Test 675 had acceptable vehicle trajectory. The vehicle for Test 674, however, ended with a high degree of yaw toward the barrier shortly after impact.

The vehicle trajectory for Test 676 was not acceptable due to the rollover.

A detailed assessment summary of vehicle trajectory for each test is shown in Table 2-2 through Table 2-7.

2 TECHNICAL DISCUSSION

Table 2-2. Test 671 Assessment Summary

Test No. 671 – Temporary Railing (Type K) with 2000P
 Date June 5, 2005
 Test agency California Dept. of Transportation

Evaluation Criteria	Test Results	Assessment
<p>Structural Adequacy</p> <p>A. The Test article should contain and redirect the vehicle; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection on the test article is acceptable</p>	<p>Vehicle landed on top of the barrier and intruded into opposing traffic.</p>	<p>Fail</p>
<p>Occupant Risk</p> <p>D. Detached elements, fragments or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment that could cause serious injuries should not be permitted.</p> <p>F. The vehicle should remain upright during and after collision although moderate roll, pitching, and yawing are acceptable.</p>	<p>There were minor penetrations into the passenger compartment. Deformation was well within Report 350 guidelines.</p> <p>Vehicle remained upright and stable throughout the test and had a moderate roll.</p>	<p>Pass</p> <p>Pass</p>
<p>Vehicle Trajectory</p> <p>K. After collision it is preferable that the vehicle's trajectory not intrude into adjacent traffic lanes.</p> <p>L. The occupant impact velocity in the longitudinal direction should not exceed 12 m/s and the occupant ridedown acceleration in the longitudinal direction should not exceed 20 G's.</p> <p>M. The exit angle from the test article preferably should be less than 60% of the test impact angle, measured at time of the vehicle loss contact with the test article.</p>	<p>The vehicle straddled the barrier, but maintained a relatively straight course after exiting the barrier.</p> <p>Long. Occ. Impact Vel. = 5.25 m/s Long. Occ. Ridedown = 3.96 g</p> <p>The vehicle remained within the preferred limit.</p>	<p>Marginal Pass</p> <p>Pass</p> <p>Pass</p>

2 TECHNICAL DISCUSSION

Table 2-3. Test 672 Assessment Summary

Test No. 672 – Temporary Railing (Type K) with 2000P
 Date June 23, 2005
 Test agency California Dept. of Transportation

Evaluation Criteria	Test Results	Assessment
<p>Structural Adequacy</p> <p>A. The Test article should contain and redirect the vehicle; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection on the test article is acceptable</p>	<p>Vehicle landed on top of the barrier and intruded into opposing traffic.</p>	<p>Fail</p>
<p>Occupant Risk</p> <p>D. Detached elements, fragments or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment that could cause serious injuries should not be permitted.</p> <p>F. The vehicle should remain upright during and after collision although moderate roll, pitching, and yawing are acceptable.</p>	<p>There were minor penetrations into the passenger compartment. Deformation was well within Report 350 guidelines.</p> <p>Vehicle remained upright and stable throughout the test and had a moderate roll.</p>	<p>Pass</p> <p>Pass</p>
<p>Vehicle Trajectory</p> <p>K. After collision it is preferable that the vehicle's trajectory not intrude into adjacent traffic lanes.</p> <p>L. The occupant impact velocity in the longitudinal direction should not exceed 12 m/s and the occupant ridedown acceleration in the longitudinal direction should not exceed 20 G's.</p> <p>M. The exit angle from the test article preferably should be less than 60% of the test impact angle, measured at time of the vehicle loss contact with the test article.</p>	<p>The vehicle straddled the barrier, but maintained a relatively straight course after exiting the barrier.</p> <p>Long. Occ. Impact Vel. = 4.60 m/s Long. Occ. Ridedown = -4.57 g</p> <p>The vehicle remained within the preferred limit.</p>	<p>Marginal Pass</p> <p>Pass</p> <p>Pass</p>

2 TECHNICAL DISCUSSION

Table 2-4. Test 673 Assessment Summary

Test No. 673 – Temporary Railing (Type K) with 2000P
 Date August 24, 2005
 Test agency California Dept. of Transportation

Evaluation Criteria	Test Results	Assessment
<p>Structural Adequacy</p> <p>A. The Test article should contain and redirect the vehicle; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection on the test article is acceptable</p>	Vehicle contained and redirected.	Pass
<p>Occupant Risk</p> <p>D. Detached elements, fragments or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment that could cause serious injuries should not be permitted.</p> <p>F. The vehicle should remain upright during and after collision although moderate roll, pitching, and yawing are acceptable.</p>	<p>There were minor penetrations into the passenger compartment. Deformation was well within Report 350 guidelines.</p> <p>Vehicle remained upright and stable throughout the test.</p>	<p>Pass</p> <p>Pass</p>
<p>Vehicle Trajectory</p> <p>K. After collision it is preferable that the vehicle's trajectory not intrude into adjacent traffic lanes.</p> <p>L. The occupant impact velocity in the longitudinal direction should not exceed 12 m/s and the occupant ridedown acceleration in the longitudinal direction should not exceed 20 G's.</p> <p>M. The exit angle from the test article preferably should be less than 60% of the test impact angle, measured at time of the vehicle loss contact with the test article.</p>	<p>The vehicle maintained a relatively straight course after exiting the barrier.</p> <p>Long. Occ. Impact Vel. = 5.25 m/s Long. Occ. Ridedown = 3.96 g</p> <p>The vehicle remained within the preferred limit.</p>	<p>Pass</p> <p>Pass</p> <p>Pass</p>

2 TECHNICAL DISCUSSION

Table 2-5. Test 674 Assessment Summary

Test No. 674 – Temporary Railing (Type K) with 2000P
 Date October 5, 2005
 Test agency California Dept. of Transportation

Evaluation Criteria	Test Results	Assessment
<p>Structural Adequacy</p> <p>A. The Test article should contain and redirect the vehicle; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection on the test article is acceptable</p>	<p>Although the vehicle was contained and redirected, the AC supporting the rear stakes failed, resulting in an uncontrolled lateral deflection of the barrier.</p>	<p>Failure</p>
<p>Occupant Risk</p> <p>D. Detached elements, fragments or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment that could cause serious injuries should not be permitted.</p> <p>F. The vehicle should remain upright during and after collision although moderate roll, pitching, and yawing are acceptable.</p>	<p>There were minor penetrations into the passenger compartment. Deformation was well within Report 350 guidelines. However, the level of lateral translation of the barrier and debris from the failing AC posed an undue risk the work zone personnel.</p> <p>Vehicle remained upright and stable throughout the test.</p>	<p>Maginal Failure</p> <p>Pass</p>
<p>Vehicle Trajectory</p> <p>K. After collision it is preferable that the vehicle's trajectory not intrude into adjacent traffic lanes.</p> <p>L. The occupant impact velocity in the longitudinal direction should not exceed 12 m/s and the occupant ridedown acceleration in the longitudinal direction should not exceed 20 G's.</p> <p>M. The exit angle from the test article preferably should be less than 60% of the test impact angle, measured at time of the vehicle loss contact with the test article.</p>	<p>The vehicle maintained a relatively straight course after exiting the barrier.</p> <p>Long. Occ. Impact Vel. = 3.80 m/s Long. Occ. Ridedown = -5.66 g</p> <p>The vehicle remained within the preferred limit.</p>	<p>Pass</p> <p>Pass</p> <p>Pass</p>

2 TECHNICAL DISCUSSION

Table 2-6. Test 675 Assessment Summary

Test No. 675 – Temporary Railing (Type K) with 2000P
 Date October 25, 2005
 Test agency California Dept. of Transportation

Evaluation Criteria	Test Results	Assessment
<p>Structural Adequacy</p> <p>A. The Test article should contain and redirect the vehicle; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection on the test article is acceptable</p>	Vehicle contained and redirected.	Pass
<p>Occupant Risk</p> <p>D. Detached elements, fragments or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment that could cause serious injuries should not be permitted.</p> <p>F. The vehicle should remain upright during and after collision although moderate roll, pitching, and yawing are acceptable.</p>	<p>There were minor penetrations into the passenger compartment. Deformation was well within Report 350 guidelines.</p> <p>Vehicle remained upright and stable throughout the test and had a moderate roll.</p>	<p>Pass</p> <p>Pass</p>
<p>Vehicle Trajectory</p> <p>K. After collision it is preferable that the vehicle's trajectory not intrude into adjacent traffic lanes.</p> <p>L. The occupant impact velocity in the longitudinal direction should not exceed 12 m/s and the occupant ridedown acceleration in the longitudinal direction should not exceed 20 G's.</p> <p>M. The exit angle from the test article preferably should be less than 60% of the test impact angle, measured at time of the vehicle loss contact with the test article.</p>	<p>The vehicle maintained a relatively straight course after exiting the barrier.</p> <p>Long. Occ. Impact Vel. = 4.66 m/s Long. Occ. Ridedown = -3.68 g</p> <p>The vehicle remained within the preferred limit.</p>	<p>Pass</p> <p>Pass</p> <p>Pass</p>

2 TECHNICAL DISCUSSION

Table 2-7. Test 676 Assessment Summary

Test No. 676 – Temporary Railing (Type K) with 2000P
 Date May 16, 2006
 Test agency California Dept. of Transportation

Evaluation Criteria	Test Results	Assessment
<p>Structural Adequacy</p> <p>A. The Test article should contain and redirect the vehicle; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection on the test article is acceptable</p>	<p>Vehicle rode on top of the barrier and intruded into construction zone.</p>	<p>Fail</p>
<p>Occupant Risk</p> <p>D. Detached elements, fragments or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment that could cause serious injuries should not be permitted.</p> <p>F. The vehicle should remain upright during and after collision although moderate roll, pitching, and yawing are acceptable.</p>	<p>There were minor penetrations into the passenger compartment. Deformation was well within Report 350 guidelines. However, the level of lateral translation of the barrier posed added risk the work zone personnel.</p> <p>Vehicle rolled-over after losing contact with the barrier.</p>	<p>Marginal Pass</p> <p>Fail</p>
<p>Vehicle Trajectory</p> <p>K. After collision it is preferable that the vehicle's trajectory not intrude into adjacent traffic lanes.</p> <p>L. The occupant impact velocity in the longitudinal direction should not exceed 12 m/s and the occupant ridedown acceleration in the longitudinal direction should not exceed 20 G's.</p> <p>M. The exit angle from the test article preferably should be less than 60% of the test impact angle, measured at time of the vehicle loss contact with the test article.</p>	<p>The vehicle did not maintained a relatively straight course after exiting the barrier.</p> <p>Long. Occ. Impact Vel. = 3.63 m/s Long. Occ. Ridedown = -3.86 g</p> <p>The vehicle remained within the preferred limit.</p>	<p>Fail</p> <p>Pass</p> <p>Pass</p>

2 TECHNICAL DISCUSSION

Table 2-8. Vehicle Trajectory, Speed and Impact Severity

Test Number	Impact Angle	60% of Impact Angle	Exit Angle	Impact Speed, V_i	Exit Speed, V_e	Speed Change $V_i - V_e$	Impact Severity
<i>Units</i>	<i>deg</i>	<i>deg</i>	<i>deg</i>	<i>km/h</i> <i>(mph)</i>	<i>km/h</i> <i>(mph)</i>	<i>km/h</i> <i>(mph)</i>	<i>kJ</i> <i>(ft.lbf)</i>
671	28.3	17.0	0*	101.4 (63.1)	NA	NA	177.1 (130600)
672	26.0	15.6	0*	99.1 (61.6)	NA	NA	144.7 (106700)
673	26.2	15.7	5	100.8 (62.6)	84 (52)	16	154.1 (113700)
674	26.5	15.9	3	98.9 (61.5)	86 (53)	13	145.0 (107000)
675	26.4	15.8	12	100.6 (62.5)	84 (52)	17	154.8 (114200)
676	25.1	15.1	0*	101.8 (63.3)	NA	NA	142.5 (105100)

* Vehicle rode on top of the barrier until the last section.

Table 2-9. Tolerances for Impact Angle, Velocity and Severity

	Nominal	Negative Tolerance	Positive Tolerance
Impact Angle - deg	25	23.5	26.5
Impact Velocity - km/h (mph)	100 (62.1)	96 (60)	104 (65)
Impact Severity – Kj (ft.lbf)	138.1 (102000)	127.3 (94000)	149.4 (110000)

3. CONCLUSIONS

Based on the testing of the K-rail as described in this report, the following conclusions can be drawn:

1. The staking configurations in Tests 671 and 672 resulted in the test vehicles overriding the barrier into opposing traffic and are unacceptable as longitudinal TL-3 median barrier configurations. It was concluded that additional testing would have to balance the need for minimal lateral deflection with minimal barrier leaning. The front of the barrier would have to be kept down.
2. The staking configuration in Test 673 successfully contained and redirected a 2000-kg (4410-lbm) pickup truck impacting at 25° and 100 km/h (62.1 mph) and is a good staking configuration for use in TL-3 median applications.
3. Although the staking configuration in Test 674 successfully contained and redirected a 2000-kg (4410-lbm) pickup truck impacting at 25° and 100 km/h (62.1 mph), damage to the pavement and the high lateral deflection make this configuration a danger to work zone personnel. Therefore this configuration is unacceptable for use adjacent to an excavation.
4. The staking configuration in Test 675 placed stakes only on the traffic side of the barrier to maximize the amount of ground resistance behind the stake and to minimize the amount of barrier lean. This configuration successfully contained and redirected a 2000-kg (4410-lbm) pickup truck impacting at 25° and 100 km/h (62.1 mph) and is a good staking configuration for use in TL-3 applications where placing K-rail adjacent to an excavation is necessary.
5. The staking configuration in Test 676 resulted in the vehicle overriding the barrier and rolling over. This configuration is unacceptable in a TL-3 application. After Test 676, it was concluded that the least number of capped stakes that could be used to safely restrain K-rail is two stakes per segment.
6. Damage to installations of K-rail in crashes similar to the tests conducted for this project will result in small to moderate amounts of scraping and spalling of the rail and deformation to the connection loops and pins.
7. Damage to the asphalt concrete from the stakes was minimal before and after impact with the exception of Test 674. The hole in the asphalt concrete after a stake was removed measured approximately 25 mm x 380 mm (1 in x 15 in)
8. Capped stakes provided uplift resistance and greater lateral resistance than uncapped stakes.
9. The K-rail stakes on the side opposite of impact, while adding shear strength, also create a pivot point upon impact. However, stakes within 305 mm (12 in) of the excavation tear out and add little shear strength as in test 674

4. RECOMMENDATIONS

Based on the conclusions, the following are recommended:

1. When K-rail is placed as a semi-permanent median barrier on low and high-speed highways with less than 610 mm (24 in) from the edge of travel way, using four capped stakes per every other segment is an acceptable option where the first and last segments are staked.
2. When K-rail is placed between 75 and 610 mm (3 and 24 in) from the edge of an excavation on low and high-speed highways, use two capped stakes per segment along the traffic side.
3. Placing K-rail less than 75 mm (3 in) from an excavation is not recommended even with staking.
4. The minimum recommended depth for the asphalt concrete supporting staked K-rail is 100 mm (4 in).
5. The staking of K-rail is not recommended for permanent installations due to concern for decreasing performance of the stakes over time.
6. The stakes should be capped in a manor similar to what was used in this testing.

5. IMPLEMENTATION

The Caltrans Division of Traffic Operations and Construction will be responsible for creating and distributing a policy memo dictating the appropriate staking configuration for any future K-rail installations.

6. REFERENCES

1. H.E. Ross, D.L. Sicking, R.A. Zimmer, and J.D. Michie. "Recommended Procedures for the Safety Performance Evaluation of Highway Features," Transportation Research Board (NCHRP), National Cooperative Highway Research Program Report 350, 1993.
2. Department of Transportation, Division of Traffic Operations. "Long-Term Installations of K-rail." Memo to All District Division Chiefs, State of California, California. 28 November 1994.
3. Rich Peter and John Jewell. "Compliance Crash Testing of K-rail Used in Semi-Permanent Installations," California Department of Transportation, October 1999.
4. E.F. Nordlin, W.R. Juergens, J.R. Stoker, R.L. Stoughton, R.N. Doty, E.J. Tye, R.A. Pelkey, and W.F. Crozier. "Dynamic Tests of Prestressed Concrete Median Barrier Type 50, Series XXVI," Materials and Research Department, California Division of Highways, 1973.
5. "NCHRP Report 350 Crash Test Results for the Idaho 6095-mm Concrete Barrier," E-TECH Testing Services Inc, April 2000.
6. Bob W. Bielenberg, John D. Reid, Ronald K. Faller, John R. Rohde, and Dean L. Sicking. "Tie-Downs and Transitions for Temporary Concrete Barriers," Journal of the Transportation Research Board, No.1984, Transportation Research Board, Highway Facility Design 2006.

7. APPENDIX

7.1. Test Vehicle

7.1.1. Equipment

The test vehicles were modified as follows for the crash tests:

- The gas tanks on the test vehicles were disconnected from the fuel supply line and drained. A 12-liter (3.2-gal) safety gas tank was installed in the truck bed or rear cargo area and connected to the fuel supply line. The stock fuel tanks had dry ice or gaseous CO₂ added to purge fuel vapors.
- One 12-volt, deep-cycle, gel cell motorcycle storage battery was mounted in the vehicle. The battery operated the solenoid-valve braking/accelerator system, rate gyros, and the electronic control box. Two additional 12-volt, deep-cycle, gel cell battery powered the transient data recorder.
- A 1700-kPa (250-psi) CO₂ system, actuated by a solenoid valve, controlled remote braking after impact and emergency braking if necessary. This system included a pneumatic ram that was attached to the brake pedal. The operating pressure for the ram was adjusted through a pressure regulator during a series of trial runs prior to the actual test. Adjustments were made to assure the shortest stopping distance without locking up the wheels. When activated, the brakes could be applied in less than 100 milliseconds.
- The remote brakes were controlled via a radio link transmitter. When the brakes were applied by remote control from the console trailer, the ignition was also automatically rendered inoperable by removing power to the coil.
- For all self-propelled vehicle tests, an accelerator switch was located on the rear of the vehicle. The switch opened an electric solenoid, which in turn released compressed CO₂ from a reservoir into a pneumatic ram that had been attached to the accelerator pedal. The CO₂ pressure for the accelerator ram was regulated to the same pressure of the remote braking system. The speed at which the ram extended was adjusted via a needle valve.
- For all self-propelled vehicle tests a speed control device, connected in-line with the primary winding of the coil, was used to regulate the speed of the test vehicle based on the signal from a speed sensor output from the vehicle transmission. This device was calibrated prior to all tests by conducting a series of trial runs through a speed trap comprised of two tape switches set a specified distance apart and a digital timer. When the speed control device was not compatible with the vehicle, a series of tests were performed to acquire the distance for the vehicle to reach a specified speed. During the tests, a driver would immediately press the accelerator pedal to the floorboard to simulate the pneumatic ram. The vehicle would start at a set distance from the tape switches. Depending on the speed result, the vehicle would be shifted closer or further away from the tape switches. After the vehicle reached the specified speed from a location three consecutive times, the starting distance was determined for the actual test.
- For all self-propelled vehicle tests a micro switch was mounted below the front bumper and connected to the ignition system. A trip plate on the ground near the impact point triggered the switch as the car passed over it. The switch would open the ignition circuit and shut off the vehicle's engine prior to impact.

7.1.2. Vehicle Parameters


Table 7-1 through Table 7-6 gives specific information regarding vehicle dimensions and weights for Tests 671 through 676.

Table 7-1. Test 671 Vehicle Dimensions

VEHICLE DIMENSIONS

Test #: 671

DATE: 04-04-04 TEST NO: 671 VIN: 1GTFC24K2NE532112 MAKE: GMC
 MODEL: 2500 SIERRA YEAR: 1992 ODOMETER: 176177 mi TIRE SIZE: LT 225/75R16
 TIRE INFLATION PRESSURE (psig): NOT RECORDED
 MASS DISTRIBUTION (kg): LF 543.8 RF 551.3 LR 437.1 RR 454.5
 DESCRIBE ANY DAMAGE TO VEHICLE PRIOR TO TEST: none



ENGINE TYPE: V8
 ENGINE CID: 350
 TRANSMISSION TYPE:
 AUTO
 MANUAL
 OPTIONAL EQUIPMENT:
none
 DUMMY DATA:
 TYPE: N/A
 MASS: N/A
 SEAT POSITION: N/A

GEOMETRY (mm):

A	1900	D	1790	G	1497	K	632	N	1558	Q	445
B	900	E	1330	H		L	77	O	1612		
C	3335	F	5560	J	1045	M		P	745		


MASS (kg)	CURB	TEST INERTIAL	GROSS STATIC
M1	1110.2	1095.1	1095.1
M2	874.7	891.6	891.6
MT	1984.9	1986.7	1986.7

Table 7-2. Test 672 Vehicle Dimensions

VEHICLE DIMENSIONS

Test #: 672

DATE: 06-14-05 TEST NO: 672 VIN: 1GTFC24K5P2550390 MAKE: GMC
 MODEL: 2500 SIERRA YEAR: 1993 ODOMETER: 157414 mi TIRE SIZE: LT 225/75R16
 TIRE INFLATION PRESSURE (psig): FRONT 31-33 REAR 42-45
 MASS DISTRIBUTION (kg): LF 554.5 RF 547.6 LR 443.1 RR 442.5
 DESCRIBE ANY DAMAGE TO VEHICLE PRIOR TO TEST: none



ENGINE TYPE: V8
 ENGINE CID: 350
 TRANSMISSION TYPE:
 AUTO
 MANUAL
 OPTIONAL EQUIPMENT:
none
 DUMMY DATA:
 TYPE: N/A
 MASS: N/A
 SEAT POSITION: N/A

GEOMETRY (mm):

A	1915	D	1785	G	1488	K	605	N	1580	Q	443
B	927	E	1360	H		L	100	O	1620		
C	3345	F	5610	J	1030	M	395	P	760		


MASS (kg)	CURB	TEST INERTIAL	GROSS STATIC
M1	1108.3	1102.1	1102.1
M2	859.3	885.25	885.25
MT	1967.6	1987.4	1987.4

Table 7-3. Test 673 Vehicle Dimensions

VEHICLE DIMENSIONS

Test #: 673

DATE: 08-08-05 TEST NO: 673 VIN: 1GCFC24MIVZ136702 MAKE: CHEVY
 MODEL: 2500 YEAR: 1997 ODOMETER: 131456 mi TIRE SIZE: LT 245/75R16
 TIRE INFLATION PRESSURE (psig): 50
 MASS DISTRIBUTION (kg): LF 589.3 RF 558.4 LR 425.9 RR 442.5
 DESCRIBE ANY DAMAGE TO VEHICLE PRIOR TO TEST: none



ENGINE TYPE: V8
 ENGINE CID: 350
 TRANSMISSION TYPE:
 AUTO
 MANUAL
 OPTIONAL EQUIPMENT:
none
 DUMMY DATA:
 TYPE: N/A
 MASS: N/A
 SEAT POSITION: N/A

GEOMETRY (mm):

A	<u>1900</u>	D	<u>1760</u>	G	<u>1489</u>	K	<u>630</u>	N	<u>1555</u>	Q	<u>440</u>
B	<u>910</u>	E	<u>1250</u>	H		L	<u>95</u>	O	<u>1610</u>		
C	<u>1760</u>	F	<u>5550</u>	J	<u>990</u>	M	<u>410</u>	P	<u>760</u>		


MASS (kg)	CURB	TEST INERTIAL	GROSS STATIC
M1	<u>1138.6</u>	<u>1147.9</u>	<u>1147.9</u>
M2	<u>812.6</u>	<u>868.4</u>	<u>868.4</u>
MT	<u>1951.2</u>	<u>2016.3</u>	<u>2016.3</u>

Table 7-4. Test 674 Vehicle Dimensions

VEHICLE DIMENSIONS

Test #: 674

DATE: 09-16-05 TEST NO: 674 VIN: 1GCFC24HAKE227696 MAKE: GMC
 MODEL: CHEYENNE YEAR: 1989 ODOMETER: 104344 mi TIRE SIZE: LT 225/75R16
 TIRE INFLATION PRESSURE (psig): 50
 MASS DISTRIBUTION (kg): LF 560.2 RF 528.5 LR 420.1 RR 421.1
 DESCRIBE ANY DAMAGE TO VEHICLE PRIOR TO TEST: none



ENGINE TYPE: V8
 ENGINE CID: 305
 TRANSMISSION TYPE:
 AUTO
 MANUAL
 OPTIONAL EQUIPMENT:
none
 DUMMY DATA:
 TYPE: N/A
 MASS: N/A
 SEAT POSITION: N/A

GEOMETRY (mm):

A	<u>1880</u>	D	<u>1760</u>	G	<u>1460.2</u>	K	<u>590</u>	N	<u>1575</u>	Q	<u>440</u>
B	<u>890</u>	E	<u>1275</u>	H	<u> </u>	L	<u>90</u>	O	<u>1615</u>		
C	<u>3350</u>	F	<u>5530</u>	J	<u>965</u>	M	<u>375</u>	P	<u>720</u>		


MASS (kg)	CURB	TEST INERTIAL	GROSS STATIC
M1	<u>1094.5</u>	<u>1088.6</u>	<u>1088.6</u>
M2	<u>807.3</u>	<u>841.1</u>	<u>841.1</u>
MT	<u>1901.8</u>	<u>1929.7</u>	<u>1929.7</u>

Table 7-5. Test 675 Vehicle Dimensions

VEHICLE DIMENSIONS

Test #: 675

DATE: 10-18-05 TEST NO: 675 VIN: 1GCGC24K2RE107690 MAKE: CHEVROLET
 MODEL: SILVERADO YEAR: 1994 ODOMETER: 119490 mi TIRE SIZE: LT 245/75R16
 TIRE INFLATION PRESSURE (psig): 45
 MASS DISTRIBUTION (kg): LF 566 RF 544.3 LR 447.8 RR 447.8
 DESCRIBE ANY DAMAGE TO VEHICLE PRIOR TO TEST: none



ENGINE TYPE: V8
 ENGINE CID: 350
 TRANSMISSION TYPE:
 AUTO
 MANUAL
 OPTIONAL EQUIPMENT:
none
 DUMMY DATA:
 TYPE: N/A
 MASS: N/A
 SEAT POSITION: N/A

GEOMETRY (mm):

A	1880	D	1800	G	1495.8	K	630	N	1590	Q	445
B	890	E	1280	H		L	110	O	1620		
C	3350	F	5480	J	1100	M	420	P	755		


MASS (kg)	CURB	TEST INERTIAL	GROSS STATIC
M1	1118.1	1110.3	1110.3
M2	852.8	895.6	895.6
MT	1970.9	2005.9	2005.9

Table 7-6. Test 676 Vehicle Dimensions

VEHICLE DIMENSIONS

Test #: 676

DATE: 03-22-06 TEST NO: 676 VIN: 1GCFC24K8J2326361 MAKE: CHEVY
 MODEL: SILVERADO YEAR: 1988 ODOMETER: 139955 mi TIRE SIZE: LT 245/75R16
 TIRE INFLATION PRESSURE (psig): 50
 MASS DISTRIBUTION (kg): LF 554.5 RF 542.4 LR 443.6 RR 440.6
 DESCRIBE ANY DAMAGE TO VEHICLE PRIOR TO TEST: none



ENGINE TYPE: V8
 ENGINE CID: 350
 TRANSMISSION TYPE:
 AUTO
 MANUAL
 OPTIONAL EQUIPMENT:
none
 DUMMY DATA:
 TYPE: N/A
 MASS: N/A
 SEAT POSITION: N/A

GEOMETRY (mm):

A	<u>1860</u>	D	<u>1780</u>	G	<u>1493.3</u>	K	<u>625</u>	N	<u>1830</u>	Q	<u>440</u>
B	<u>845</u>	E	<u>1310</u>	H		L	<u>85</u>	O	<u>1595</u>		
C	<u>3345</u>	F	<u>5500</u>	J	<u>1045</u>	M	<u>405</u>	P	<u>770</u>		

MASS (kg)	CURB	TEST INERTIAL	GROSS STATIC
M1	<u>1095.2</u>	<u>1096.8</u>	<u>1096.8</u>
M2	<u>837.3</u>	<u>884.2</u>	<u>884.2</u>
MT	<u>1932.5</u>	<u>1981.0</u>	<u>1981.0</u>

7.2. Guidance System

A rail guidance system directed all vehicles into the test articles. The guidance rail, anchored at 3.8-m (12-ft) intervals along its length, was used to guide a mechanical arm that was attached to the vehicle's front wheel (Figure 7-1). A 10-mm (0.4-in) nylon rope was used to trigger the release mechanism on the guidance arm, thereby releasing the vehicle from the guidance system before impact.



Figure 7-1. Guidance System

7.3. Photo Instrumentation

Several high-speed digital cameras recorded the impact during the crash tests. Figure 7-2 shows a diagram of the camera locations. The types of cameras used are shown in Table 7-7 and their locations are shown in Table 7-8 and Table 7-9.

All of these cameras were mounted on tripods except the three that were mounted on a 10.7-m (35.1-ft) high tower directly over the impact location.

A video camera and a digital SLR camera were turned on by hand and used to obtain pan shots during the test. A switch on a console trailer near the impact area remotely triggered the other cameras. The test vehicle and test article were photographed before and after impact with digital video camera and a digital SLR camera. A film report of this project has been assembled using edited portions of the crash testing coverage.




Figure 7-2. Typical Camera Locations and Labels

Table 7-7. Camera Type

Camera Location	Figure 7-2 Label	Camera
Upstream	A	Weinberger SpeedCam Visario 1500
Downstream	B	Weinberger SpeedCam Visario 1500
Across	C	Weinberger SpeedCam Visario 1500
Behind	D	Weinberger SpeedCam Visario 1500
Upstream Overhead	E	Weinberger SpeedCam Visario 1500
Center Overhead	F	Weinberger SpeedCam Visario 1500
Downstream Overhead	G	Weinberger SpeedCam Visario 1500
Pan Digital Camera	H	Canon XL-1
Digital SLR Camera	J	Nikon D2X
Ground Camera	K	Weinberger SpeedCam Visario 1500
Ground Pan Camera	L	Canon XL-1

Table 7-8. Camera Locations for Test 671 through Test 673
(Relative to the Critical Impact Point)

Camera Location	Figure 7-2 Label	Test #671			Test #672			Test #673		
		x	y	z	x	y	z	x	y	z
Upstream	A	-35.7 mm	-330 mm	1 m	-36.6 m	0 m	1 m	-37 m	0 m	1 m
Downstream	B	65.2 m	145 mm	1 m	75.3 m	0 m	1 m	508 mm	74 m	1 m
Across	C	-2.6 m	-19.4 m	1 m	-711 mm	-17.3 m	1 m	2 m	-18.8 m	1 m
Behind	D	22.5 m	9.8 m	1 m	28.8 m	10.7 m	1 m	27.3 m	10.9 m	1 m
Upstream Overhead	E	-457 mm	0 m	9.1 m	-457 mm	0 mm	9.1 m	-457 mm	0 mm	9.1 m
Center Overhead	F	0 mm	0 mm	9.1 m	0 mm	0 mm	9.1 m	0 mm	0 mm	9.1 m
Downstream Overhead	G	457 mm	0 mm	9.1 m	457 mm	0 mm	9.1 m	457 mm	0 mm	9.1 m
Pan Digital Camera	H	-2.5 m	-21.6 m	5 m	3.5 m	-20.4 m	5 m	4.6 m	-19.6 m	5 m
Digital SLR Camera	J	-1575 mm	-21.6 m	5 m	4.5 m	-20.4 m	5 m	3.5 m	-20 m	5 m
Ground Camera	K	-	-	-	-3.8 m	2 m	-	-	-	-
Ground Pan Camera	L	-	-	-	-	-	-	-	-	-

Table 7-9. Camera Locations for Test 674 through Test 676
(Relative to the Critical Impact Point)

Camera Location	Figure 7-2 Label	Test #674			Test #675			Test #676			
		x	y	z	x	y	z	x	y	z	
Upstream	A	-42.4 m	0 m	1 m	Locations not recorded				-30.8 m	0 m	1 m
Downstream	B	85 m	0 m	1 m					74.6 m	0 m	1 m
Across	C	-1092 mm	-14.7 m	1 m					-1.4 m	-16.4 m	1 m
Behind	D	28.3 m	10.7 m	1 m					4.2 m	18.2 m	1 m
Upstream Overhead	E	-457 mm	0 mm	9.1 m					-457 mm	0 mm	9.1 m
Center Overhead	F	0 mm	0 mm	9.1 m					0 mm	0 mm	9.1 m
Downstream Overhead	G	457 mm	0 mm	9.1 m					457 mm	0 mm	9.1 m
Pan Digital Camera	H	4.5 m	-15.7 m	5 m					4.5 m	-15.7 m	5 m
Digital SLR Camera	J	6.3 m	-15.8 m	5 m					6.3 m	-15.8 m	5 m
Ground Camera	K	-	-	-					-	-	-
Ground Pan Camera	L	2 m	-14.8 m	305 mm					-	-	-

7.4. Video Analysis

Visual Fusion, video analysis software, was used to verify the impact speed and to obtain the impact angle, exit angle, exit speed, brake application time, and the maximum yaw, pitch, and roll angles.

The following are the pretest procedures that are completed to enable film data analysis:

1. Butterfly targets were attached to the top and sides of each test vehicle. The targets were located on the vehicle at intervals of 0.5 and 1.0 meters (1.64 and 3.28 ft). The targets established scale factors and horizontal and vertical alignment.
2. Flashbulbs, mounted on the test vehicle, were electronically triggered to establish 1) initial vehicle-to-article contact, and 2) the time of the application of the vehicle brakes. The impact flashbulbs begin to glow immediately upon activation, but have a delay of several milliseconds before lighting up to full intensity.




Figure 7-4. Typical Uncapped Stake Installation Layout




Figure 7-5. Typical Capped Stake Installation Layout




Figure 7-6. Capped Stake Dimensions [mm]

7.6. Test Article Installation

The K-rail barrier was placed on a surveyed line using a forklift with lifting hooks. The pins were placed in the pin-and-loop connection by hand. The barrier was not pull tight to maintain some of the slack in the joints. Holes in the asphalt concrete were drilled by using the K-rail stake holes as guides for a roto-hammer and 7/8-in drill bit. The stakes were installed in the pre-drilled holes using a 60-lb (27-kg) jackhammer with a stake-driving attachment. They were driven in until the head of the stakes cleared the barrier face to prevent wheel snagging (Figure 7-4 and Figure 7-10).



Figure 7-7. Stake Installation



Figure 7-8. Forklift Carrying K-rail



Figure 7-9. Installed Uncapped Stake



Figure 7-10. Installed Capped Stake

7.7. Electronic Instrumentation and Data

7.7.1. Instrumentation

Transducer data were recorded on two separate GMH Engineering, Data Brick, Model II, digital transient data recorders (TDR) that were mounted in the vehicle for all tests. The transducers mounted on the vehicle include two sets of accelerometers and one set of rate gyros at the center of gravity. The TDR data were reduced using a desktop personal computer running DADiSP 4.1.

Beginning at Test 674, a new set of gyros was installed. The previous set of gyros had malfunctioned and could not be repaired. The gyro and accelerometer specifications are shown in Table 7-10. The vehicle accelerometer and gyro sign convention used throughout this report is the same as that described in NCHRP Report 350 and is shown in Figure 7-12.

A rigid stand with three retro-reflective 90° polarizing tape strips was placed on the ground near the test article and alongside the path of the test vehicle (Figure 7-11). The strips were spaced at carefully measured intervals of 1.000-m (3.281-ft). The test vehicle had an onboard optical sensor that produced sequential impulses or “event blips” that were recorded concurrently with the accelerometer signals on the TDR, serving as “event markers”. The impact velocity of the vehicle could be determined from these sensor impulses and timing cycles and the known distance between the tape strips. A pressure-sensitive tape switch on the front bumper of the vehicle closed at the instant of impact and triggered two events: 1) an “event marker” was added to the recorded data, and 2) a flashbulb mounted on the top of the vehicle was activated. Two other pressure-sensitive tape switches, connected to a speed trap, were placed 4.000-m (13.124-ft) apart just upstream of the test article specifically to establish the impact speed of the test vehicle. The layout for all of the pressure-sensitive tape switches is shown in Figure 7-11.

The data curves are shown in Figure 7-13 through Figure 7-42 and include the accelerometer and rate gyro records from the test vehicles. They also show the velocity and displacement curves for the longitudinal and lateral components. These plots were needed to calculate the occupant impact velocity defined in NCHRP Report 350. All data were analyzed using software written by DADiSP and modified by Caltrans.




Figure 7-11. Instrumentation Layout

Table 7-10. Accelerometer and Gyro Specifications

MANUFACTURER	LOCATION	RANGE	ORIENTATION	TEST NUMBER
Endevco	Vehicle's C.G.	100 G	Longitudinal (primary)	ALL
Endevco	Vehicle's C.G.	100 G	Lateral (primary)	ALL
Endevco	Vehicle's C.G.	100 G	Vertical (primary)	ALL
Endevco	Vehicle's C.G.	100 G	Longitudinal (secondary)	ALL
Endevco	Vehicle's C.G.	100 G	Lateral (secondary)	ALL
Endevco	Vehicle's C.G.	100 G	Vertical (secondary)	ALL
Humphrey	191 mm (7.5-in) behind the C.G. (along the X-axis)	180 DEG/SEC	Roll	671, 672, 673
Humphrey	191 mm (7.5-in) behind the C.G. (along the X-axis)	90 DEG/SEC	Pitch	671, 672, 673
Humphrey	191 mm (7.5-in) behind the C.G. (along the X-axis)	180 DEG/SEC	Yaw	671, 672, 673
BEI Systron Donner Inertial	191 mm (7.5-in) behind the C.G. (along the X-axis)	500 deg/sec	Roll	674, 675, 676
BEI Systron Donner Inertial	191 mm (7.5-in) behind the C.G. (along the X-axis)	500 deg/sec	Pitch	674, 675, 676
BEI Systron Donner Inertial	191 mm (7.5-in) behind the C.G. (along the X-axis)	500 deg/sec	Yaw	674, 675, 676




Figure 7-12. Vehicle Accelerometer and Gyro Sign Convention

7.7.2. Data

Figure 7-13 through Figure 7-42 show the data for Tests 671 through 676.




Figure 7-13. Test 671 Vehicle Accelerations Vs Time




Figure 7-14. Test 671 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time




Figure 7-15. Test 671 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time

W22: Gxd=12.0; Gyd=9.0; Gzd=10.0; SQRT((W19/Gxd)^2+(W20/Gyd)^2+(W21/Gzd)^2); ASI=max;;fmax;asitime=curpos*dx-0.025;setylabel("g*0.5");setxlabel("TIME (seconds)");TxASI




Figure 7-16. Test 671 Acceleration Severity Index Vs Time




Figure 7-17. Test 671 Vehicle Roll, Pitch, and Yaw Vs Time




Figure 7-18. Test 672 Vehicle Accelerations Vs Time




Figure 7-19. Test 672 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time




Figure 7-20. Test 672 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time




Figure 7-21. Test 672 Vehicle Roll, Pitch, and Yaw Vs Time

W22: Gxd=12.0; Gyd=9.0; Gzd=10.0; Sqrt((W19/Gxd)^2+(W20/Gyd)^2+(W21/Gzd)^2); ASI=max;;fmax;asitime=curpos*dx-0.025;setylabel("g^0.5");setxlabel("TIME (seconds)");TxASI




Figure 7-22. Test 672 Acceleration Severity Index Vs Time




Figure 7-23. Test 673 Vehicle Accelerations Vs Time




Figure 7-24. Test 673 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time




Figure 7-25. Test 673 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time




Figure 7-26. Test 673 Vehicle Roll, Pitch, and Yaw Vs Time

W22: Gxd=12.0; Gyd=9.0; Gzd=10.0; SQRT((W19/Gxd)^2+(W20/Gyd)^2+(W21/Gzd)^2); ASI=max;fmax;asitime=curpos*dx-0.025;setylabel("g^0.5");setxlabel("TIME (seconds)");TxASI




Figure 7-27. Test 673 Acceleration Severity Index Vs Time




Figure 7-28. Test 674 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time




Figure 7-29. Test 674 Vehicle Accelerations Vs Time




Figure 7-30. Test 674 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time




Figure 7-31. Test 674 Vehicle Roll, Pitch, and Yaw Vs Time

W22: Gxd=12.0; Gyd=9.0; Gzd=10.0; Sqrt((W19/Gxd)^2+(W20/Gyd)^2+(W21/Gzd)^2); ASI=max;;fmax;asitime=curpos*dx-0.025;setylabel("g^0.5");setxlabel("TIME (seconds)");TxASI




Figure 7-32. Test 674 Acceleration Severity Index Vs Time

W22: Gxd=12.0; Gyd=9.0; Gzd=10.0; SQRT((W19/Gxd)^2+(W20/Gyd)^2+(W21/Gzd)^2); ASI=max;;fmax;asitime=curpos*dx-0.025;setylabel("g^0.5");setxlabel("TIME (seconds)");TxASI




Figure 7-33. Test 675 Acceleration Severity Index Vs Time




Figure 7-34. Test 675 Vehicle Roll, Pitch, and Yaw Vs Time




Figure 7-35. Test 675 Vehicle Accelerations Vs Time




Figure 7-36. Test 675 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time




Figure 7-37. Test 675 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time




Figure 7-38. Test 676 Vehicle Accelerations Vs Time




Figure 7-39. Test 676 Vehicle Longitudinal Acceleration, Velocity, and Distance Vs Time




Figure 7-40. Test 676 Vehicle Lateral Acceleration, Velocity, and Distance Vs Time




Figure 7-41. Test 676 Vehicle Roll, Pitch, and Yaw Vs Time

W22: Gxd=12.0; Gyd=9.0; Gzd=10.0; SORT((W19/Gxd)^2+(W20/Gyd)^2+(W21/Gzd)^2); ASI=max;fmax;asitime=curpos'dx-0.025;setylabel("g^0.5");setxlabel("TIME (seconds)");TxASI




Figure 7-42. Test 676 Acceleration Severity Index Vs Time