District		Project Title Dr. Fine Bridge Replacement	Output Bridge Rehabilitation and Replacement	Unit Bridge(s)	Approved Quantity
	0154T	Pudding Creek CAPM	Pavement Rehabilitation	Lane mile(s)	32.6
1	1055 1072	DN-199 Culverts Hunter/Panther Creek Bridge Replacement	Drainage System Restoration Bridge Seismic Restoration	Culvert(s) (ea) Bridge(s)	15
1	1095	CRESCENT CITY ADA	ADA - New Curb Ramps	Curb ramp(s)	94
1	1110	Ehlers Left Turn Pocket	Non-Capacity Increasing Operational Improvements	Daily Vehicle Hour(s) of Delay (DVHD)	0.2
1	1112	LAST CHANCE GRADE Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	1
	1113	Dominie Creek Fish Passage	Bridge Rehabilitation	Bridge(s)	1
1	1113M 1115	Dominie Fish Passage Mitigation Collier Tunnel Electrical Upgrade	Bridge Rehabilitation and Replacement Signs and Lighting Rehabilitation	Bridge(s) Lighting fixture(s)	238
1	1117	REHAB IDLEWILD MAINT STATION	Maintenance Facilities	Location(s)]
1	1121 1122	DN-199 Safety Improvements Permanent Restoration at Cushing Creek	Safety Improvements Major Damage (Permanent Restoration)	Collision(s) reduced Location(s)	20
i	1129	KLAMATH CAPM	Pavement Preservation (CAPM)	Lane mile(s)	50.1
1	1130	INSIDE PARK CULVERTS	Drainage System Restoration	Culvert(s) (ea)	9
1	1132 1134	Collier Tunnel Safety Repairs REPAIR DRAINAGE	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	3
i	1135	REPAIR CULVERT	Major Damage (Emergency Opening)	Location(s)	1
1	1137M 1138	Hunter-Panther Mitigation Wilson Creek Restoration & SPGA Wall	Bridge Seismic Restoration Major Damage (Permanent Restoration)	Bridge(s) Location(s)	C
	1141	Middle Fork Smith River Curve Improvement	Safety Improvements	Collision(s) reduced	20
	1142 1143	Culvert Rehabilitation & Fish Passage SLATER FIRE	Drainage System Restoration	Culvert(s) (ea) Location(s)	30
	1143	Damnation Creek Safety	Major Damage (Emergency Opening) Safety Improvements	Annual fatal and serious	0.68
		,		injury collision(s)	
1	1145	LCG Landslide Repair	Major Damage (Emergency Restoration)	Location(s)	1
i	1147M	Smith River Bridge On Site Mitigation	Bridge Rehabilitation and Replacement	Bridge(s)	C
	1148M	Smith River BR/HAMBRO Off Site Mitigation	Bridge Rehabilitation and Replacement	Bridge(s)	0.11
1	1152	Timbers Blvd Safety	Safety Improvements	Annual fatal and serious injury collision(s)	0.11
				7- 7	
1	1154	DN 199 Roundabout	Safety Improvements	Annual fatal and serious	0.28
				injury collision(s)	<u> </u>
1	1156	Mill Creek Safety	Safety Improvements	Annual fatal and serious	0.19
				injury collision(s)	
1	1157	Rowdy Creek Road Left Turn Channelization	Safety Improvements	Annual fatal and serious	0.07
				injury collision(s)	
1	1161	Del Norte STAA Improvements	Operational Improvements	Daily vehicle hour(s) of	20.1
	0051			delay (DVHD)	
- 1	2251	US101 STAA Operational Improvement Project	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	C
	2270	Avenue Culvert Rehab	Drainage System Restoration	Culvert(s) (ea)	7
	2301 2301B	South Fork Eel River Bridge #04-123 EEL RIVER BRIDGE SEISMIC	Bridge Seismic Restoration Bridge Formula Program	Bridge(s) Bridge(s)	1
	23016	Three HUM Bridges	Bridge Seismic Restoration	Bridge(s)	3
1	2346	Broadway ADA	ADA - Pedestrian Infrastructure	Curb ramp(s)	31
1	2355 2363	Construct New Materials Lab Bridge Rail Replacement - 3 bridges	Materials Laboratories Bridge Rail Replacement and Upgrade	Location(s) Linear feet rail	1026
1	2363M	3 Bridges Mitigation HUM-36	Bridge Rail Replacement and Upgrade	Annual fatal and serious	020
				injury collision(s)	
1	2366	Little Golden Gate Storm-Water	Storm Water Mitigation	Acre(s)	5.5
				treated/pollutant	
	2375 2375M	Eureka/Arcata Corridor MBGR Eureka-Arcata Corridor MBGR Mitigation	Safety Enhancements Safety Enhancements	Collision(s) reduced Collision(s) reduced	46
i	2376	Corridor Bridge Rails	Bridge Rail Replacement/Upgrade	Linear feet rail	
1	2376M 2378	Corridor Bridge Rails Mitigation Slope Repair and Drainage Improvements	Bridge Rail Replacement/Upgrade Storm Water Mitigation	Linear feet Acre(s)	14.3
,	23/6	зоре керан ана Банаде трочетенз	Sionn water Miligation	treated/pollutant	14.3
1	2378M	Environmental Mitigation	Storm Water Mitigation	Acre(s)	C
1	2379	Alton 015 Shoulder Widening	Collision Severity Reduction	treated/pollutant Collision(s) reduced	14
i	2380	Eureka CAPM	Pavement Rehabilitation	Lane mile(s)	7
	2382	King Salmon Rehab 2R	Pavement Preservation	Lane mile(s)	20.6
	2393 2397	4th Street Safety HUM-299 OFF RAMP IMPROVEMENT	Safety Improvements Safety Enhancements	Collision(s) reduced Collision(s) reduced	503
1	2400	HUM-101 Strengthen 2 Bridges	Trans Permit Requirements for Bridges	Bridge(s)	2
1	2403	CONSTRUCT FISH CREEK BRIDGE	Storm Water Mitigation	Acre(s) treated/pollutant	70.5
1	2403M	FISH CREEK BRIDGE MITIGATION	Storm Water Mitigation	Acre(s)	C
,	2415	Carlotta Curve Improvement	Safety Improvements	treated/pollutant Collision(s) reduced	20
	2415	Eureka Slough Bridges	Bridge Seismic Restoration	Bridge(s)	1
	2418	Arcata Acceleration/Deceleration Lanes	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	98.2
1	2418M	Arcata Accel/Decel Mitigation	Improvements Non-Capacity Increasing Operational	Delay (DVHD) Daily Vehicle Hour(s) of	C
			Improvements	Delay (DVHD)	
	2422	Redcrest CAPM	Pavement Rehabilitation	Lane mile(s)	35.9 36
	2424	ARCATA 101 Merge Improvements	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	
1	2426	Willow Creek Widen & Rumble	Safety Improvements	Collision(s) reduced	118
1	2426M 2427	Willow Creek Widen & Rumble Mitigation HUM-299 Blue Lake Widen & Rumble	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	4C
i	2429	4 BRIDGES DECK PRESERVATION	Capital Bridge Preventative Maintenance Program	Bridge(s)	4
1	2430	200/299 SEPARATION	Trans Permit Requirements for Bridges	Bridge(s)	1
	2433	HUM-299 Culverts	Drainage System Restoration	Culvert(s) (ea)	44
1	2433M	Culvert Revegetation Child	Drainage System Restoration	Culvert(s) (ea)	(
	2434 2435	HUM-299 Widen Shoulders Widen Shoulders & Install Rumble	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	30
1	2439	TRINIDAD CAPM	Pavement Preservation (CAPM)	Lane mile(s)	76.9
	2447 2449	Little Lost Man Fish Passage	Bridge Rehabilitation	Bridge(s)	2508
	2449 2452	HUM 96-169 5 BRIDGES Rail Upgrade Buck Mountain Combine	Bridge Rail Replacement and Upgrade Drainage System Restoration	Linear feet rail Culvert(s) (ea)	2508
1	2452	Buck Mountain Combine	Roadway Rehabilitation	Lane mile(s)	
1	2452	Buck Mountain Combine	Storm Water Mitigation	Acre(s)	
1	2456	Eureka Sidewalks & Curbs	ADA - New Curb Ramps	treated/pollutant Curb ramp(s)	31
1	2460	GUARDRAIL NEAR ARCATA	Safety Enhancements	Collision(s) reduced	9
1	2461 2461M	Fortuna Median Roadside Safety Project Fortuna Median Long ENV Monitoring	Roadside Safety Improvements Roadside Safety Improvements	Location(s) Location(s)	150
		promotion modified body Entry Modified High	SHOPP - Misc	Location(s)	,

1 2481	5th STREET SAFETY	Safety Improvements	Collision(s) reduced	
1 2484	HUM-254 Culvert Rehab	SHOPP - Sustainability and Miscellaneous	Location(s)	
1 2487 1 2488	REHAB HUM-169 CULVERTS BRIDGEVILLE WALL	Drainage System Restoration Major Damage (Permanent Restoration)	Culvert(s) (ea) Location(s)	
1 2489	BLUFF CREEK WALL	Major Damage (Permanent Restoration)	Location(s)	
1 2492	KORBEL WALLS	Major Damage (Permanent Restoration)	Location(s)	
1 2493 1 2494	Arcata to Blue Lake CAPM HUM-299 CAPM	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	2
1 2495	HUM-36 CAPM 201.121	Pavement Preservation (CAPM)	Lane mile(s)	4
1 2497M	HUM-101 Drainage South Mitigation	Drainage System Restoration	Culvert(s) (ea)	
1 2498	HUM-101 Drainage North	Drainage System Restoration	Culvert(s) (ea)	
1 2501 1 2502	HUM-169 Restoration MYERS FLAT PERMANENT RESTORATION	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
1 2502M	Myers Flat Long-Term Mitigation	Major Damage (Permanent Restoration)	Location(s)	
1 2517	BRIDGE CLEANUP	Major Damage (Emergency Opening)	Location(s)	
1 2518	HUM-254 culverts	Drainage System Restoration	Culvert(s) (ea)	
1 2518M 1 2522	Hum-254 culverts revegetation HUM-299 CURVE IMPROVEMENT	Drainage System Restoration	Culvert(s) (ea) Collision(s) reduced	
1 2522 1 2522M	HUM-299 Curve Improve Mitigation	Safety Improvements Safety Improvements	Annual fatal and serious	
ZOZZIVI	TION 277 Corve Improve Miligation	salety improvements	injury collision(s)	
1 2523 1 2524	REPAIR STRUCTURE Avenue Culvert Rehab Revegetation	Major Damage (Emergency Opening) Drainage System Restoration	Location(s) Culvert(s) (ea)	
1 2525	CARLOTTA SHOULDER WIDEN	Safety Improvements	Annual fatal and serious	(
. 2020	O WES IN COLOUR MISER	salot, improvements	injury collision(s)	,
1 2525M	Carlotta Shoulder Widen Mitigation	Safety Improvements	Annual fatal and serious	
			injury collision(s)	
2527	4th Street Safety and CAPM	Pavement Rehabilitation	Lane mile(s)	
1 2527	4th Street Safety and CAPM	Safety Improvements	Collision(s) reduced	
2528	Bridgeville Grade Slips	Major Damage (Emergency Opening)	Location(s)	-
2529	Weitchpec Slip-Out Repair	Major Damage (Emergency Opening)	Location(s)	
2530 2531	Loleta Slide Blue Lake Sink	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
2535	Blue Lake Landslide Repair	Major Damage (Emergency Opening) Major Damage (Permanent Restoration)	Location(s)	
2536	Prairie Creek Curve Improvement	Safety Improvements	Annual fatal and serious	
			injury collision(s)	
1 2537	DED AID CHILVEDT NEAD DIO DELL	Major Damage (Emergency Opening)	La antion (a)	
1 2537	REPAIR CULVERT NEAR RIO DELL Eureka-Arcata Corridor Combined Mitigation	# Sign(s), light(s), greenway, or other safety /	Location(s) Each	
2000	Edicka Weala Comadi Combined Willigation	beautification	Eddii	
1 2538	Eureka-Arcata Corridor Combined Mitigation	Bridge Rail Replacement and Upgrade	Linear feet rail	
1 2538	Eureka-Arcata Corridor Combined Mitigation	Collision Severity Reduction	Collision(s) reduced	
2538	Eureka-Arcata Corridor Combined Mitigation	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	
1 2541	Repair Culvert	Major Damage (Emergency Opening)	Location(s)	
2543	REPAIR DRAINAGE	Major Damage (Emergency Opening)	Location(s)	
2544	Broadway Complete Streets	SHOPP - Complete Streets	Bicycle and pedestrian	1
			infrastructure (linear	
			feet)	
1 2549	HUM-36 Drainage	Drainage System Restoration	Culvert(s) (ea)	
1 2550	Garcia Bridge Scour	Bridge Scour	Bridge(s)	
2551	Benbow CAPM	Pavement Preservation (CAPM)	Lane mile(s)	
1 2568	Orleans MS and Buckhorn CVEF	Maintenance Facilities	Location(s)	
1 2569	Broadway CS - Shared Path	SHOPP - Complete Streets	Bicycle and pedestrian infrastructure (linear	2
			feet)	
			,	
	HUM-299 East CAPM	Pavement Preservation (CAPM)	Lane mile(s)	
2572	HUM-299 Snow Storm Damage	Major Damage (Emergency Restoration)	Location(s)	
2572 2578	HUM-299 Snow Storm Damage 5th Street Combine	Major Damage (Emergency Restoration) ADA - New Curb Ramps	Location(s) Curb ramp(s)	
2572 2578 2578	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements	Location(s)	
2572 2578 2578 2592 2597	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration	Location(s) Curb ramp(s) Collision(s) reduced Location(s) Culvert(s) (ea)	
2572 2578 2578 2578 2592 2597 2598	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration)	Location(s) Curb ramp(s) Collision(s) reduced Location(s) Culvert(s) (ea) Location(s)	
2572 2578 2578 2578 2592 2597 2598 2599	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fernbridge Bridge Repair Earthquake Bridge Repair	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Curb ramp(s) Collision(s) reduced Location(s) Culverf(s) (ea) Location(s) Location(s)	
2572 2578 2578 2578 2592 2597 2598 2599 2600	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration	Location(s) Curb ramp(s) Cullision(s) reduced Location(s) Cuvert(s) (ea) Location(s) Location(s) Bridge(s)	
2572 2578 2578 2578 2592 2597 2598 2599 2600	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fernbridge Bridge Repair Earthquake Bridge Repair	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Curb ramp(s) Collision(s) reduced Location(s) Culverf(s) (ea) Location(s) Location(s)	
2572 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Bridge Seismic Restoration Major Damage (Emeraency Restoration)	Location(s) Curb ramp(s) Cullision(s) reduced Location(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	
2572 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604 2609	HUM-299 Snow Storm Damaae Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passaae Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Negarir	Maior Damage (Emergency Restoration) ADA - New Gurb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration Major Damage (Emergency Restoration)	Location(s) Curb ramp(s) Cullision(s) reduced Location(s) Cuver(s) (ea) Location(s) Location(s) Location(s) Location(s) Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	
2572 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604 2609 2611	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Horn 299	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration Major Damage (Emergency Restoration)	Location(s) Curb ramp(s) Cullision(s) reduced Location(s)	
2572 2578 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604 2609 2611 2613	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Stough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Silpout Repair Storm Damage Negarit Repair Storm Damage Negarit Repair Storm Damage Hum 299 Slide Repair	Major Damage (Emergency Restoration) ADA - New Gurb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration Major Damage (Emergency Restoration)	Location(s) Curb ramp(s) Cultision(s) reduced Location(s)	
2572 2578 2578 2578 2597 2597 2598 2599 2600 2602 2603 2604 2609 2611 2613 3047B 3098	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hortsook Creek Fish Passage Fembridge Bridge Repair Earthauake Bridge Repair Earthauake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass	Maior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration Major Damage (Emergency Restoration) Dainage System Restoration Bridge Rail Replacement/Uparade	Location(s) Curb ramp(s) Cultision(s) reduced Location(s)	
2572 2578 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604 2609 2611 2613 3047B 3098	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Stough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Silpout Repair Storm Damage Repair Hum 101 Silpout Repair Storm Damage Hum 299 Silde Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety	Major Damage (Emeraency Restoration) ADA - New Gurb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culvert(s) (ea) Linear feet Collision(s) reduced	
2572 2578 2578 2578 2592 2592 2597 2598 2599 2600 2602 2603 2604 2604 2611 2613 3047B 3099 3099M	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthauake Bridae Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Gulvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined militigartion	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration Major Damage (Emergency Restoration) Drainage System Restoration Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow Iane-mile(s) constructed	Location(s) Curb ramp(s) Cullision(s) reduced Location(s) Location	
2572 2578 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604 2609 2611 2613 30478 3099 3099 3099M	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Silpout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation	Major Damage (Emeraency Restoration) ADA - New Curb Ramins Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Bridge Seismic Restoration Major Damage (Emeraency Restoration) Bridge Rail Replacement/Upgrade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements	Location(s) Curb ramp(s) Cullision(s) reduced Location(s) Culvert(s) (ea) Location(s) Loca	
2572 2578 2578 2578 2592 2597 2598 2599 2600 2602 2603 2604 2604 2609 2611 2613 3047B 3099 3099M 3099M 3102	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthauake Bridae Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Gulvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined militigartion	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Seismic Restoration Major Damage (Emergency Restoration) Drainage System Restoration Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow Iane-mile(s) constructed	Location(s) Curb ramp(s) Cullision(s) reduced Location(s) Location	
2572 2578 2578 2578 2592 2597 2597 2599 2600 2603 2604 2603 2604 2611 2613 30478 3098 3099 3099 3102	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Stough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 96 Storm Damage Repair HUM 97 Storm Damage Repair HUM 98 Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Silide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS	Maior Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Bridge Seismic Restoration Major Damage (Emeraency Restoration) Bridge Roil Replacement/Uparade Safety Improvements Mixed flow Iane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment)	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culver(s) (ea) Linear feet Collision(s) reduced Miles Collision(s) reduced Collision(s) reduced Field element(s)	
2572 2578 2578 2578 2592 2597 2597 2600 2602 2603 2604 2609 2611 2613 3047B 3099 3099M 3102 3104	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 91 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Iransportation Management (TMC's & Field Equipment) Bridge Rehabilitation	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) Culter(s) Culter(s) Cultision(s) reduced Miles Collision(s) reduced Field element(s) Bridge(s)	
2572 2578 2578 2578 2592 2597 2597 2599 2600 2602 2603 2604 2603 2604 2613 30478 3098 3099M 3099M 3102 3107	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Possage Fembridae Bridae Repair Earthauake Bridae Repair Earthauake Bridae Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Slipout Repair Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-27 combined mitigation LAK-27 combined mitigation Coyote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge Bachelor Creek Bridge Bachelor Creek Bridge	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Bridge Seismic Restoration Major Damage (Emeraency Restoration) Drainage System Restoration) Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culver(s) (ea) Linear feet Collision(s) reduced Miles Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s)	
2572 2578 2578 2578 2592 2597 2599 2599 2600 2602 2603 2604 2609 2611 2613 3047B 3099 3099M 3102 3104	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 91 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Iransportation Management (TMC's & Field Equipment) Bridge Rehabilitation	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) Culter(s) Culter(s) Cultision(s) reduced Miles Collision(s) reduced Field element(s) Bridge(s)	
2572 2578 2578 2578 2592 2592 2597 2599 2600 2602 2603 2604 2609 2611 2613 30478 3099 3099M 3102 3104 3112 3118	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 96 Storm Damage Repair HUM 101 Silpout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation Coyote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge Bachelor Creek Bridge Mitigation Clearlake Oaks Charaina Station LAK-175 Curve Improvement BUE LAKES SAFETY	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Bridge Seismic Restoration Major Damage (Emeraency Restoration) Bridge Rail Replacement/Upgrade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation and Replacement SHOPP - Misc Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Enduced Miles Collision(s) reduced Field element(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced	
2572 2578 2578 2578 2597 2592 2597 2599 2600 2602 2602 2603 2604 2609 2611 2613 3047B 3098 3099M 3099M 3104 3107 31107 31118 31123 3124	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Gulvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Safety Improvements Safety Improvements Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) Culter(s) Cultision(s) reduced Miles Collision(s) reduced Field element(s) Bridge(s) Bridge(s) Bridge(s) Location(s) Collision(s) reduced Miles	
2572 2578 2578 2578 2592 2592 2597 2599 2600 2602 2604 2609 2611 2613 30478 3099 3099 3102 31107 31107 3112 31123	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthauake Bridge Repair Earthauake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Slipout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-19 combined mitigation Covote Grade Shoulder Widenina EAST LAKE CO TMS Bachelor Creek Bridge Bulle LAKES SAFETY LAK-29 COMBINED	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Mixed flow lane-mile(s) constructed	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Cultision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Miles Collision(s) reduced Miles Collision(s) reduced	
2572 2578 2578 2578 2592 2592 2592 2592 2600 2602 2602 2604 2603 2604 2613 30478 3099 3099M 3099M 3102 3112 3118 3124 3124	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm	Moior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Upargade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) Culter(s) Cultision(s) reduced Miles Collision(s) reduced Field element(s) Bridge(s) Bridge(s) Bridge(s) Location(s) Collision(s) reduced Miles	
2572 2578 2578 2578 2578 2592 2592 2597 2598 2599 2600 2602 2603 2604 2609 2611 2611 2613 3047B 3099 3099 3102 3107 3112 3112 3124 3124 3124 3124 3124 3126	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthauake Bridge Repair Earthauake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Slipout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-19 combined mitigation Covote Grade Shoulder Widenina EAST LAKE CO TMS Bachelor Creek Bridge Bulle LAKES SAFETY LAK-29 COMBINED	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Mixed flow lane-mile(s) constructed	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) reduced Miles Collision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Collision(s) reduced Collision(s) reduced Miles Collision(s) reduced Miles Collision(s) reduced Miles Collision(s) reduced Miles Collision(s) reduced	
2572 2578 2578 2578 2578 2592 2592 2597 2598 2599 2600 2602 2603 2604 2609 2611 2611 2613 3047B 3099 3099 3102 3107 3112 3112 3124 3124 3124 3124 3124 3126	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthauake Bridae Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 36 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridae	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Ubarade Safety Improvements Mixed flow lane-milets) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) reduced Miles Collision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Collision(s) reduced	
2572 2578 2578 2578 2597 2592 2597 2599 2600 2602 2603 2604 2609 2611 2613 3047B 3099 3099 3099 3102 31107 3112 3124 3124 3124 3124 3124 3126	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Possage Fembridae Bridae Repair Earthauake Bridae Repair Earthauake Bridae Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Slipout Repair Storm Domage Near Willits Repair Storm Domage Near Near Near Near Near Near Near Nea	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Drainage System Restoration Bridage Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridage Rehabilitation Bridage Rehabilitation Bridage Rehabilitation Bridage Rehabilitation Bridage Rehabilitation Maga Rehabilitation Mixed flow lane-mile(s) constructed Safety Improvements	Location(s) Curb ramp(s) Curb ramp(s) Cullision(s) reduced Location(s) Cullision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Collision(s) reduced	
2572 2578 2578 2578 2592 2597 2597 2598 2600 2602 2602 2603 2604 2611 2613 30478 3098 3099 3099M 3099M 3102 3112 3118 3124 3124 3124 3124 3124 3126 3128	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 95 Storm Damage Repair HUM 95 Storm Damage Repair HUM 95 Storm Damage Repair HUM 96 Storm Damage Repair Hum 101 Slipout Repair Storm Damage Hum 299 Slide Repair Lok 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Coyote Grade Shoulder Widenina EAST LAKE CO TMS Bachelor Creek Bridge	Moior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) reduced Miles Collision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Collision(s) reduced	
2572 2578 2578 2578 2597 2592 2597 2599 2600 2602 2602 2604 2609 2611 2613 30478 3099 3099 3099M 3102 31107 3112 31124 3124 3124 3128 3129 3130	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthauake Bridae Repair Eureka Stough Bridges Replacement HUM 36 Storm Damage Repair HUM 36 Storm Damage Repair HUM 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge Bachelor C	Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-milets) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Bridge Rail Replacement and Upgrade	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Cultision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Bridge(s) Bridge(s) Location(s) Location(s) Collision(s) reduced Collision(s) re	
2572 2578 2578 2578 2592 2597 2597 2599 2600 2602 2603 2604 2603 2604 2603 2604 2609 2611 2611 2613 3047B 3099 3099 3102 3112 3112 3124 3124 3124 3124 3126 3129 3129	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Possage Fembridge Bridge Repair Earthquake Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 96 Storm Damage Repair HUM 10 Slipout Repair Storm Domage Near Willits Repair Storm Domage Near Willits Repair Storm Domage Near Willits Repair Storm Domage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Manning & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge Bachelor Creek Bridge Bachelor Creek Bridge Mitigation Clearlake Oaks Charaina Station LAK-175 Curve Improvement BLUE LAKES SAFETY LAK-29 COMBINED Child mitigation SHOPP Kelsey Creek L Turn Channelization MDDLETOWN MITIGATION Bottle Rock Safety Morrison, Robinson & Kelsey Creek Twin Lakes CAPM Morrison, Robinson & Kelsey Creek	Moior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) reduced Miles Collision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Collision(s) reduced	
2572 2578 2578 2578 2597 2592 2597 2592 2600 2602 2602 2604 2609 2611 2613 3047B 3098 3099 3099 3102 31107 3112 3124 3124 3124 3124 3128 3129 3130 3132 3133	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Sith Street Combine Sith Street Combine Three Chop Road Culvert Repair Hortsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 36 Storm Damage Repair HUM 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widenina EAST LAKE CO TMS Bachelor Creek Bridge	Maior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Maior Damage (Emergency Restoration) Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) reduced Collision(s) reduced Lollision(s) reduced	
2572 2578 2578 2578 2578 2592 2592 2597 2599 2602 2602 2602 2603 2604 2611 2613 30478 3098 3099M 3099M 3104 3112 3112 3112 3124 3124 3124 3124 3126 3129 3133 3133 3133 3133 3133 3133 3133	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridae Bridae Repair Earthauake Bridae Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 95 Storm Damage Repair HUM 95 Storm Damage Repair HUM 95 Storm Damage Repair HUM 96 Storm Damage HUM 299 Slide Repair Lok 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Loke 29 Expressway - Safety LAK-29 Combined mitigation Covote Grade Shoulder Widenina EAST LAKE CO TMS Bachelor Creek Bridge Bachelo	Molor Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emergency Restoration) Drainage System Restoration Major Damage (Emergency Restoration) Drainage System Restoration Bridge Rail Replacement/Upargade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Cultision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Collision(s) reduced Location(s) Linear feet rail Lane mile(s) Bridae(s) Collision(s) reduced Collision(s)	
2572 2578 2578 2578 2597 2592 2597 2599 2600 2602 2602 2604 2609 2613 30478 3098 3099 3099M 3102 3104 3112 3118 3123 3124 3124 3128 3129 3130 3132 3133 3133 3133 3133	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Sith Street Combine Sith Street Combine Inree Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Stough Bridges Replacement HUM 36 Storm Damage Repair HUM 36 Storm Damage Repair HUM 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Gulvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge B	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) Reduced Collision(s) reduced Field element(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s)	
1 2600 1 2600 1 2602 1 2603 1 2604 1 2604 1 2607 1 2611 1 2613 1 3047B 1 3099 1 3099M 1 3102 1 3104 1 3107 1 3112 1 3112 1 3124 1 3124 1 3124 1 3124 1 3126 1 3129	HUM-299 Snow Storm Damage 5th Street Combine 5th Street Combine Three Chop Road Culvert Repair Hortsook Creek Fish Possage Fembridge Bridge Repair Earthquake Bridge Repair Earthquake Bridge Repair Eureka Slough Bridges Replacement HUM 36 Storm Damage Repair HUM 10 Stipout Repair Storm Damage Repair Hum 101 Stipout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Stide Repair Lak 20/29/53 Culvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widenina EAST LAKE CO TMS Bachelor Creek Bridge Bachelor Creek Bridg	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Drainage System Restoration Bridage Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Safety Improvements Transportation Management (TMC's & Field Equipment) Bridage Rehabilitation Bridage Rehabilitation Bridage Rehabilitation Bridage Rehabilitation Safety Improvements	Location(s) Curb ramp(s) Curb ramp(s) Cullision(s) reduced Location(s) Cullision(s) reduced Cullision(s) reduced Field element(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Location(s) Cullision(s) reduced Location(s) Linear feet rail Lone mille(s) Bridae(s) Cullision(s) reduced Location(s)	
12572 12578 12578 12578 12578 12592 12597 12599 12602 12602 12602 12602 12603 12604 12604 12604 12603 12613 13047B 13047B 13047B 13047B 1307M 13107M 13107M 131124 13124 13124 13128 13128 13129 13130 131313 13133 13133 13133 13133 13134 13133 13133 13134 13133 13133 13133 13133 13134	HUM-299 Snow Storm Damage Sith Street Combine Sith Street Combine Sith Street Combine Sith Street Combine Inree Chop Road Culvert Repair Hartsook Creek Fish Passage Fembridge Bridge Repair Earthquake Bridge Repair Eureka Stough Bridges Replacement HUM 36 Storm Damage Repair HUM 36 Storm Damage Repair HUM 101 Slipout Repair Storm Damage Near Willits Repair Storm Damage Near Willits Repair Storm Damage Hum 299 Slide Repair Lak 20/29/53 Gulvert Rehab Mannina & Polk Jones Cattle Pass Lake 29 Expressway - Safety LAK-29 combined mitigation LAK-29 combined mitigation Covote Grade Shoulder Widening EAST LAKE CO TMS Bachelor Creek Bridge B	Major Damage (Emeraency Restoration) ADA - New Curb Ramps Safety Improvements Major Damage (Emeraency Restoration) Drainage System Restoration Major Damage (Emeraency Restoration) Drainage System Restoration Bridge Rail Replacement/Uparade Safety Improvements Mixed flow lane-mile(s) constructed Safety Improvements Transportation Management (TMC's & Field Equipment) Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Safety Improvements	Location(s) Curb ramp(s) Cultision(s) reduced Location(s) Culter(s) Reduced Collision(s) reduced Field element(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s)	

1 3	3216	Lak-29/C St Left Turn Channelization	Safety Improvements	Annual fatal and serious injury collision(s)	0.09
1 3	3217	Abbot Mine Curve Improvement	Safety Improvements	Annual fatal and serious injury collision(s)	0.31
1 3	3218	Middletown North Safety	Safety Improvements	Annual fatal and serious injury collision(s)	0.2
1	4442	Hopland CAPM	Pavement Rehabilitation	Lane mile(s)	35.2
	4490	Albion River Bridge	Bridge Rehabilitation and Replacement	Bridge(s)	33.2
	4491	Salmon Creek Bridge	Bridge Rehabilitation	Bridge(s)	i
	4507	Pudding Creek Bridge	Bridge Rail Replacement/Upgrade	Linear feet	361
	4545	McCoy Creek Bridge Replacement	Bridge Rehabilitation	Bridge(s)	1
	4546 4553	Fort Bragg ADA Rodeo Creek Slide II	ADA - New Curb Ramps Major Damage (Permanent Restoration)	Curb ramp(s) Location(s)	36
	4574	Moss Cove, Irvine Lodge & Empire Camp SRRA's	Roadside Safety Improvements	Location(s)	3
		Navarro Ridge Safety Project	Safety Improvements	Collision(s) reduced	16
	4587	Calpella 2 Bridge Replacements	Bridge Rehabilitation and Replacement	Bridge(s)	2
	4587M 4588	Landscape Mitigation Elk Creek Bridge Replacement	Bridge Rehabilitation and Replacement Bridge Rail Replacement and Upgrade	Bridge(s) Linear feet rail	0 532
		Hare Creek Bridge	Bridge Rail Replacement/Upgrade	Linear feet rail	868
1 4	4588M	Elk Creek Bridge LTM	Bridge Rail Replacement and Upgrade	Bridge(s)	0
	4598	Flynn Creek CAPM & Tapered Edge	Pavement Rehabilitation	Lane mile(s)	35.7
	4613 4616	CAMP 20 SAFETY PROJECT Navarro Drainage	Safety Improvements Roadway Protective Betterments	Collision(s) reduced Location(s)	24
	4626	POINT ARENA CAPM	Pavement Rehabilitation	Lane mile(s)	29.5
1 4	4627	South Fork Eel River Bridge Seismic	Bridge Seismic Restoration	Bridge(s)	1
	4629	MEN-1 Fish Passage	SHOPP - Sustainability and Miscellaneous	Location(s)	2
1 4	4630	Gualala Shoulders	Safety Improvements	Annual fatal and serious injury collision(s)	0.08
1 4	4630M	Widen Shoulders & Install Rumble Strips	Safety Improvements	Annual fatal and serious injury collision(s)	0
1	4636	RUSSIAN GULCH BRIDGE	Bridge Rail Replacement/Upgrade	Linear feet	1134
1 4	4639	Abalobadiah Creek Safety	Safety Improvements	Collision(s) reduced	16
1 4	4647	LAKE 20 SHOULDERS	Safety Improvements	Collision(s) reduced	14
	4647M 4650	LAKE 20 Shoulders ENV Mitigation Shoulder Widening near Willits	Safety Improvements	Collision(s) reduced	<u>0</u> 8
		Shoulder Widening near Willits MEN-162 Super El Improvement	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	<u>8</u> 14
	4656	MEN-1 Widen Shoulders	Safety Improvements	Collision(s) reduced	11
1 4	4675	Hopland ADA	ADA - New Curb Ramps	Curb ramp(s)	18
	4676	COVELO PAVEMENT	Roadway Rehabilitation (3R)	Lane mile(s)	50.7
	4677 4678	Ridgewood Class 1 Pavement OILWELL Class 1 Pavement	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	37.5 14.1
	4682	Jack Peters Cr Bridge	Bridge Rail Replacement and Upgrade	Linear feet rail	563
	4682M	Jack Peters Long Term Mitigation	Bridge Rail Replacement and Upgrade	Bridge(s)	0
	4691	James Creek West Safety	Safety Improvements	Collision(s) reduced	14
	4692 4692M	Eel River Bridge Replacement Eel River Bridge Child	Bridge Seismic Restoration Bridge Seismic Restoration	Bridge(s) Bridge(s)	I
	4693	Navarro Mitigation	Roadside Enhancement (Mitigation Site	Location(s)	7
		-	Relinauishments)	1.	
	4694	LONGVALE REHAB UKIAH REHAB	Roadway Rehabilitation (2R)	Lane mile(s)	37.4
		Rockport to Leggett CAPM	Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	25 30.9
		Elk to Mendocino CAPM	Pavement Preservation (CAPM)	Lane mile(s)	34.4
	4698	Ridgewood Weigh In Motion	Weight Stations & Weight-In-Motion Facilities	Location(s)	1
1 4	4699	Manchester Mitigation	Roadside Enhancement (Mitigation Site	Location(s)	4
1	4702	McCOY CREEK SINKS	Relinauishments) Major Damage (Permanent Restoration)	Location(s)	1
	4705	Comminsky Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	1
1 4	4710	McCoy Creek Revegetation	Bridge Rehabilitation and Replacement	Bridge(s)	0
	4717	James Creek East Safety	Safety Improvements	Collision(s) reduced	30
	4719 4725	REPAIR UKIAH CULVERT LOG JAM REMOVAL	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	2
	4727	SOUTH FORK EEL SLIDE & DRAINAGE	Major Damage (Emergency Opening)	Location(s)	1
	4728	Point Arena Repair Culvert	Major Damage (Emergency Opening)	Location(s)	1
	4729	Howling Wolf South Slip-Out	Major Damage (Emergency Opening)	Location(s)	1
	4730 4731	Walker Road Slip-out Ridgewood Grade South	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	1
1 4	4733	ELK CREEK SCOUR	Major Damage (Emergency Opening)	Location(s)	5
	4734	Repair Slip-out and MBGR	Major Damage (Emergency Opening)	Location(s)	1
	4737 4738	MEN-128 SLIP OUT North Point Arena CAPM	Major Damage (Emergency Opening) Pavement Preservation (CAPM)	Lane mile(s)	1 36
	4742	Cummings CAPM	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s)	43.5
1 4	4743	Cook's Valley CAPM	Pavement Preservation (CAPM)	Lane mile(s)	38.9
		BOONVILLE CAPM	Pavement Preservation (CAPM)	Lane mile(s)	25.3
	4745 4745M	Reconstruct Drainage Piercy Culvert Revegetation	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	23 0
1 4	4747	Soda Creek Wall	Major Damage (Permanent Restoration)	Location(s)	1
	4748	Oilwell Hill Safety	Safety Improvements	Annual fatal and serious injury collision(s)	0.71
				1	
	4751 4752	Calpella Cable Median Barrier South Willits Median	Safety Improvements Safety Improvements	Collision(s) reduced Annual fatal and serious	30 0.56
1 4	4752	South Willits Median	Safety Improvements	Annual fatal and serious injury collision(s)	
1 4	4752 4753	South Willits Median Salmon Creek Sandblast Waste Abatement	Safety Improvements Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridge(s)	0.56
1 4	4752 4753 4754	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea)	
1 4	4752 4753	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Ook Fire Damage Repair	Safety Improvements Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridge(s)	0.56 0 123
1 4	4752 4753 4754 4757 4760 4761	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLIET STREETS FCCO Tree Removal & Snow Damage Repairs	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage [Emergency Openina] SHOPP - Sustainability and Miscellaneous Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridge(s) Culvert(s) (ea) Location(s) Centerline mile(s) Location(s)	0.56 C 123 1 1.5
1 4	4752 4753 4754 4757 4760	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Centerline mile(s)	0.56 0.56
1 4	4752 4753 4754 4757 4760 4761 4763	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilifation & Fish Possage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) SHOPP - Sustainability and Miscellaneous Major Damage (Emergency Openina) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced	0.56 (123 1 1.5 1 0.43
1 4	4752 4753 4754 4757 4760 4761 4763	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Maior Damage (Emergency Opening) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s)	0.56 (123 1 1.5 1 0.43
1 4	4752 4753 4754 4757 4760 4761 4763 4766 4766 4768	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety MEN-1 DRAINAGE	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Maior Damage [Emergency Openina] SHOPP - Sustainability and Miscellaneous Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Drainage System Restoration	Annual fatal and serious injury collision(s) Bridge(s) Culvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced Culvert(s) (ea)	0.56 (123
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	4752 4753 4754 4757 4760 4761 4763 4766 4768 4771 4772	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Ook Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety MEN-1 DRAINAGE DeHaven to Rockport CAPM Ridgewood Grade Safety	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emeraency Openina) SHOPP - Sustainability and Miscellaneous Maior Damage (Emeraency Openina) Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s)	0.56 (123
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	4752 4753 4754 4757 4760 4761 4763 4766 4768 4771 4772	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLIES STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety MEN-1 DRAINAGE DeHaven to Rockport CAPM Ridgewood Grade Safety Bridge Repair and Cleanup	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) SHOPP - Sustainability and Miscellaneous Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Restoration)	Annual fatal and serious injury collision(s) Bridge(s) Colvert(s) (ea) Location(s) Centertline mille(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s)	0.56 (123
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	4752 4753 4754 4757 4760 4761 4763 4766 4768 4771 4772 4773 4774	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety MEN-1 DRAINAGE DeHaven to Rockport CAPM Ridgewood Grade Safety Bridge Repair and Cleanup Ridgewood Emergency Road Repair	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Major Damage (Emergency Opening) Safety Improvements Safety Improvements Drainage System Restoration Povement Preservation (CAPM) Safety Improvements Major Damage (Emergency Restoration) Major Damage (Emergency Opening)	Annual fatal and serious injury collision(s) Bridge(s). Culvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Location(s)	0.56 C 123 1 1.5.5 1 0.43 A44 130 16.9
	4752 4753 4754 4757 4760 4761 4763 4766 4768 4771 4772 4773 4774 4775 4775	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety MEN-1 DRAINAGE DeHaven to Rockport CAPM Ridgewood Grade Safety Bridge Repair and Cleanup Ridgewood Emergency Road Repair Landslide Repair near Commisky REPAIR SLIDE	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emergency Openina) SHOPP - Sustainability and Miscellaneous Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridge(s) Coulvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced Culvert(s) (ea) Lone mile(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Location(s)	0.56 C 123 1 1.5. 1 0.43 444 130 16.9 0.34
	4752 4753 4754 4757 4760 4761 4763 4766 4768 4771 4772 4773 4774 4775 4781 4781	South Willits Median Salmon Creek Sandblast Waste Abatement Culvert Rehabilitation & Fish Passage Oak Fire Damage Repair COVELO COMPLETE STREETS FCO Tree Removal & Snow Damage Repairs LAFRANCHI SAFETY James Creek East & West Safety MEN-1 DRAINAGE DeHaven to Rockport CAPM Ridgewood Grade Safety Bridge Repair and Cleanup Ridgewood Emergency Road Repair Landslide Repair near Commisky	Safety Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) SHOPP - Sustainability and Miscellaneous Major Damage (Emergency Openina) Safety Improvements Safety Improvements Drainage System Restoration Povement Preservation (CAPM) Safety Improvements Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Centerline mile(s) Location(s) Annual fatal and serious injury collision(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s)	0.56 C 123 1 1.5.5 1 0.43 A44 130 16.9

1 4794	Westport Slide Complex	Major Damage (Permanent Restoration)	Location(s)	1
1 4796	Walker Fire	Major Damage (Emergency Restoration)	Location(s)	ì
1 4799	Elk Creek Bridge Replacement & BMMN	Bridge Rail Replacement and Upgrade	Linear feet rail	532
1 4803 1 4806	Men 253 Emergency Storm Damage Repairs Snow Storm Damage in Men and Lake County	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	90
1 4807	Navarro Combined	Protective Betterments	Location(s)	1
1 4807	Navarro Combined	Safety Improvements	Collision(s) reduced	16
1 4808	Salmon Creek Bridge	Bridge Rehabilitation and Replacement	Bridge(s)	1
1 4816	Ocean Drive Left Turn Pocket	Collision Severity Reduction	Annual fatal and serious injury collision(s)	0.01
			ii ijoi y Collisioi i(s)	
1 4839	Culvert Repairs	Major Damage (Emergency Restoration)	Location(s)	2
1 4842	Culvert Repairs	Major Damage (Emergency Restoration)	Location(s)	
1 4845 1 4846	Westport Repair Landslide Repair Storm Damage HUM 36	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
1 4855	Fire Damage Repairs	Major Damage (Emergency Restoration)	Location(s)	1
1 4856	Annie & Mary Trail (Segment 3) FCO Funds	SHOPP - Complete Streets	Bicycle and pedestrian	1850
			infrastructure (linear	
			feet)	
1 4891	Emergency Landslide Repair	Major Damage (Emergency Restoration)	Location(s)	1
1 4898	Loleta Repair Culvert	Major Damage (Emergency Restoration)	Location(s)	1
1 4899	REPAIR LANDSLIDE	Major Damage (Emergency Restoration)	Location(s)	
1 4901 1 4902	Repair Storm Damage Repair Landslide	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
1 4905	Maintenance Station Security Improvements	Maintenance Facilities	Location(s)	
1 4906	Multiple Location Slipout Repairs	Major Damage (Emergency Restoration)	Location(s)	2
1 4907	SLIDE REPAIR	Major Damage (Emergency Restoration)	Location(s)	
1 4908 1 4917	Repair Slide Damage Repair Storm Damage	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	1
1 4918	Repair Sink	Major Damage (Emergency Restoration)	Location(s)	
1 4919	Repair Storm Damage	Major Damage (Emergency Restoration)	Location(s)	1
1 4921	Repair Sink	Major Damage (Emergency Restoration)	Location(s)	3
1 4922 1 4926	Repair Slipout Repair Sinkhole	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
1 4935	Emergency Bridge Deck Repair	Major Damage (Emergency Restoration)	Location(s)	1
1 4949	Fire Damage Repair	Major Damage (Emergency Restoration)	Location(s)	1
1 4950	Lucerne Complete Streets	SHOPP - Complete Streets	Bicycle and pedestrian	21395
			infrastructure (linear feet)	
			1001)	
1 7002	HUM-101/MEN-271 Culverts	Drainage System Restoration	Culvert(s) (ea)	25
1 7017	MT KONOCTI TMS	Transportation Management (TMC's & Field	Field element(s)	21
1 7018	LaDicino Guardrail	Equipment) Safety Enhancements	Collision(s) reduced	174
1 7022	District Wide Curve Warning	Safety Enhancements	Collision(s) reduced	30
1 7024	4 LOC HFST & MGS	Safety Improvements	Collision(s) reduced	30
1 7025	LAK-MEN Fire Damage Repairs	Major Damage (Emergency Opening)	Location(s)	1
1 7027 1 7028	DN to HUM-101 CAPM Rehab Transportation Related Facilities	Pavement Preservation (CAPM) Maintenance Facilities	Lane mile(s) Location(s)	33
1 7029	COMBINED TMS	Transportation Management (TMC's & Field	Field element(s)	24
		Equipment)		
1 7032	Emergency Hazard Tree Removal	Major Damage (Emergency Opening)	Location(s)	4
1 8503 1 8504	Ridgewood Grade ELB Wall REPAIR SLIDE NEAR BRIDGEVILLE	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	1
1 8507	REPAIR SEIDE NEAR BRIDGEVILLE REPAIR AIRPORT ROAD TIDEGATE	Major Damage (Emergency Opening)	Location(s)	i
1 8508	HEARN GULCH SLIPOUT	Major Damage (Emergency Opening)	Location(s)	1
1 8510	Anderson Creek Slip	Major Damage (Emergency Opening)	Location(s)	3
1 8511 2 2711	MEN-1 BRIDGE SCOUR REPAIR Lake Boulevard Pavement	Maior Damage (Emergency Opening) Pavement Preservation (CAPM)	Lane mile(s)	20.4
2 3314	96 Culverts	Drainage System Restoration	Culvert(s) (ea)	28
2 3346	Sidehill & Dog Creek Seismic Retrofit	Bridge Seismic Restoration	Bridge(s)	2
2 3424	263 Klamath River Bridge	Bridge Rehabilitation	Bridge(s)	1
2 3445A 2 3445A	Redding to Anderson Six Lane - Phase 1 & 2 Redding to Anderson Six Lane - Phase 1 & 2	Mixed flow lane-mile(s) constructed Modified/Reconstructed bridge(s)	Miles Each	15
2 3445A	Redding to Anderson Six Lane - Phase 1 & 2	New bridge(s)	Each	2
2 3445A	Redding to Anderson Six Lane - Phase 1 & 2	Operational improvement(s)	Each	6
2 3453	East Red Bluff CAPM	Pavement Rehabilitation	Lane mile(s)	13.6
2 3456 2 3467	Dri Whiskey Bieber to Adin Pavement	Pavement Rehabilitation Roadway Rehabilitation	Lane mile(s) Lane mile(s)	21 16.6
2 3468	Good Fred	Roadway Rehabilitation	Lane mile(s)	20.9
2 3483	Hat Creek Bridge Replacement	Bridge Rehabilitation	Bridge(s)	1
2 3484	Butte & Ash Creek Bridge Replacement	Bridge Rehabilitation	Bridge(s)	2
2 3507 2 3509	Siskiyou 5 CRZ Black Butte OH Br replacement	Safety Enhancements Bridge Rehabilitation	Collision(s) reduced Bridge(s)	
2 3515	Sacramento River Bridge Seismic	Bridge Seismic Restoration	Bridge(s)	2
2 3516	Sis Tri Deck Rehab	Capital Bridge Preventative Maintenance Program	Bridge(s)	9
2 3522	Caldwell Bridgeway	Bridge Scour	Bridge(s)	1
2 3522	Caldwell Bridgeway Caldwell Bridgeway	Roadway Rehabilitation	Lane mile(s)	18.7
2 3543	Sims Crag Combine	Bridge Rehabilitation	Bridge(s)	2
2 3544	Route 273 Gaps	Pavement Rehabilitation Bridge Rehabilitation	Lane mile(s)	20.4
2 3546 2 3548	Lower Moffett Creek Scour Pit River Deck Improvements	Capital Bridge Preventative Maintenance Program	Bridge(s) Bridge(s)	1
	,			
2 3549	District Wide Scour Counter-Measures	Capital Bridge Preventative Maintenance Program	Bridge(s)	
0.0550	Pod Pluff Drainage	Drainaga System Bastasation	Culvort(e) (==)	
2 3550 2 3552	Red Bluff Drainage O'Brien SRRA Waters	Drainage System Restoration Roadside Safety Improvements	Culvert(s) (ea) Location(s)	27
2 3555	Trinity Workers Safety	Roadside Safety Improvements	Location(s)	12
2 3556	North Canyon TMS Improvement	Transportation Management (TMC's & Field	Field element(s)	16
2 3557	South Fork Mine CRZ	Equipment) Safety Enhancements	Collision(s) reduced	
2 3558	West Red Bluff CAPM	Pavement Rehabilitation	Lane mile(s)	10.1
2 3559	Francis B. Mathews Rest Area	Roadside Safety Improvements	Location(s)	1
2 3579	Burnt Ranch Curtains	Roadway Protective Betterments	Bridge(s)	
2 3586 2 3587	Trinity 3 Drainage Plumas 70 Drainage	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	44
2 3587	Butte 70 Drainage	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea)	42
2 3589	Modoc 139 Drainage	Drainage System Restoration	Culvert(s) (ea)	8
2 3592	Burnt Junction Drapery	Roadway Protective Betterments	Bridge(s)	2
2 3599 2 3600	Chilcoot 2R Adin Maintenance Facility-DES Brokered Project	Pavement Preservation L&B Maintenance Facilities	Lane mile(s) Location(s)	18
2 3600	Ukonom 3 Drainage	Drainage System Restoration	Culvert(s) (ea)	21
2 3606	Los Molinos ADA	ADA - Pedestrian Infrastructure	Curb ramp(s)	28
2 3607	East Cedar Pass Safety	Safety Improvements	Collision(s) reduced	18
2 3609	Worley Ranch Curve Improvement	Safety Improvements	Collision(s) reduced	16
2 3611	SB Cottonwood Scales	Commercial Vehicle Enforcement Facilities & Weigh In-Motion Scales	- Localion(s)	
		m. monori scaros		

2/2/14	Can Diver DOLL Deals Deplacement	Deidas Dahahilitatian	Driedera (a)	1
2 3614 2 3618	Sac River BOH Deck Replacement Burney CAPM	Bridge Rehabilitation Pavement Preservation (CAPM)	Bridge(s) Lane mile(s)	21.3
2 3619	Cromberg Rehab	Roadway Rehabilitation	Lane mile(s)	45.1
2 3619A 2 3619A	Cromberg Combined Cromberg Combined	Operational improvement(s) Roadway Rehabilitation (3R)	Each Lane mile(s)	45.1
2 3620	Portuguese and Cade Creek	Bridge Rehabilitation and Replacement	Bridge(s)	43.1
2 3622	Stanshaw Creek and Sandy Bar	Bridge Rehabilitation	Bridge(s)	2
2 3626 2 3627	South Market Street ADA Advance Mitigation Credit Purchase	ADA - Pedestrian Infrastructure Roadside Enhancement (Mitigation Site	Curb ramp(s) Location(s)	19
2 3627	Advance Miligation Credit Forchase	Relinquishments)	Eocanom(s)	0
2 3629	Horse Creek Bridge Replacement	Bridge Scour	Bridge(s)	1
2 3630	O Brien Deck and Rail Rehab	Bridge Rehabilitation	Bridge(s)	
2 3631 2 3632	Azalea Deck and Rail Rehab Tehama CRZ	Bridge Rehabilitation Safety Enhancements	Bridge(s) Collision(s) reduced	7
2 3633	Trinity Four Bridges	Bridge Preventative Maintenance	Bridge(s)	4
2 3637	Tidy Waters	Drainage System Restoration	Culvert(s) (ea)	5
2 3639 2 3640	Butterfly Two Wolf Creek Rock Fence Ward Curves	Roadside Safety Improvements Safety Improvements	Location(s) Collision(s) reduced	20
2 3641	Morgan Summit Curve Combined	Safety Improvements	Collision(s) reduced	24
2 3642	Champlin Slough	Bridge Scour	Bridge(s)	1
2 3643 2 3644	Yreka Rehab Yreka Maintenance Station Shop	Roadway Rehabilitation (3R) Equipment Facilities	Lane mile(s) Location(s)	11.2
2 3653	Toyota Barrel Curve	Safety Improvements	Collision(s) reduced	12
2 3657	Weed SRRA	Roadside Safety Improvements	Location(s)	2
2 3660 2 3663	Scott River Bridge Diamond Star Curve	Bridge Rehabilitation and Replacement Safety Improvements	Bridge(s) Collision(s) reduced	16
2 3668	Trinity Culverts	Drainage System Restoration	Culvert(s) (ea)	20
2 3673	Eskimo Hill Superelevation Improvement	Safety Improvements	Collision(s) reduced	14
2 3680	Whiskey Creek Rehabilitation Long Lead	Roadway Rehabilitation	Lane mile(s)	14.4
2 3685 2 3685A	Dunsmuir GAP Sac Gap Combined	Pavement Preservation Bridge Rehabilitation and Replacement	Lane mile(s) Bridge(s)	27.8 1
2 3685A	Sac Gap Combined	Roadway Rehabilitation (2R)	Lane mile(s)	27.8
2 3696	I 5 Big and Tall Grenada Payement	Trans Permit Requirements for Bridges	Bridge(s)	53.1
2 3697 2 3699	Grenada Pavement O Brien CAPM	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	59
2 3700	Almanor West Rehab	Roadway Rehabilitation (3R)	Lane mile(s)	25.8
2 3701	Del Loma Pavement	Pavement Preservation (CAPM)	Lane mile(s)	21.3
2 3706 2 3706A	Shalas CAPM Poison Lake Shalas Combine	Pavement Rehabilitation Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	75.5 75.5
2 3706A	Poison Lake Shalas Combine	Safety Improvements	Collision(s) reduced	20
2 3707	VP2	Pavement Preservation (CAPM)	Lane mile(s)	24.1
2 3709 2 3712	Graeagle Cap & Flood Dorris CAPM	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	17.1 21.3
2 3712	Beckwourth CAPM	Pavement Preservation (CAPM)	Lane mile(s)	23.6
2 3714	Crescent Mills CAPM	Pavement Preservation (CAPM)	Lane mile(s)	16.4
2 3718 2 3719	139 Susanville Paving Dibble Creek CAPM	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s)	20.5 37.8
2 3720	Near China Slide PR	Major Damage (Permanent Restoration)	Lane mile(s) Location(s)	37.0
2 3721	Somes Bar CAPM	Pavement Preservation (CAPM)	Lane mile(s)	18.8
2 3722	Chester Causeway Rehab	Pavement Preservation (CAPM)	Lane mile(s)	31.5
2 3723 2 3726	Plumas 70 Permanent Restoration Tehama 32 Wall Permanent Restoration	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	8
2 3728	Big French Creek PR	Major Damage (Permanent Restoration)	Location(s)	0
2 3732	SIS Worker Safety	Roadside Safety Improvements	Location(s)	64
2 3733	Red Bluff Bridges	Bridge Seismic Restoration	Bridge(s)	- 3
				2
2 3734 2 3735	Secret Valley SRRA Poker Bar Culverts	Safety Roadside Rest Area Restoration Drainage System Restoration	Location(s) Culvert(s) (ea)	2 71
2 3734 2 3735 2 3737	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Culvert(s) (ea) Lane mile(s)	21.3
2 3734 2 3735 2 3737 2 3738	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klomathon Fire Restoration	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Opening)	Location(s) Culvert(s) (ea) Lane mile(s) Location(s)	
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Culvert(s) (ea) Lane mile(s)	
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Ingol Curve Improvement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Opening) Safety Improvements	Location(s) Culvert(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced	21.3 1 1 2 38
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced	21.3 1 1 2
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Ingat Curve Improvement South Ave Safety Power Slide	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Opening) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Location(s) Culvert(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s)	21.3 1 1 2 38
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Uncol Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Opening) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Location(s) Cuiver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s)	21.3 1 1 2 38
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3747	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Ingat Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina)	Location(s) Culvert(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	21.3 1 1 2 38
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Silp-out Forest Dump Slide	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	21.3 1 1 2 38
2 3734 2 3735 2 3737 2 3738 2 3739 2 3739 2 3741 2 3742 2 3744 2 3745 2 3747 2 3747 2 3748 2 3750 2 3750	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaat Curve Improvement South Ave Safety Power Slide Helestide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Burnt Ranch CAPM	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM)	Location(s) Culvert(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s)	21.3 1 1 2 38
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3750 2 3750 2 3750	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Bumit Ranch CAPM Montaque CAPM	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s)	21.3 1 1 2 38 20 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3752 2 3752 2 3752	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Ingot Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montague CAPM Klomath Loke Rehob 2R	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R)	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Locatio	21.3 1 1 2 38 20 1 1 1 1 1 1 1 1 38 20 6.3 9
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3746 2 3747 2 3748 2 3750 2 3752 2 3752 2 3752 2 3753 2 3753	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Ingat Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Altar	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) teduced Location(s) Collision(s) Lane mile(s) Lane mile(s) Collision(s) reduced	21.3 1 1 2 38 20 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3750 2 3750 2 3752 2 3753 2 3753 2 3758 2 3759 2 3759 2 3759 2 3759	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klomathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaot Curve Improvement South Ave Safety Power Slide Helestide Deer Creek Canwall Dubackella Slia-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klomath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane	21.3 1 1 2 38 20 21 1 1 1 1 1 1 1 3.2 6.3 9 33.8
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3749 2 3750 2 3750 2 3752 2 3753 2 3753 2 3753 2 3753 2 3753 2 3753 2 3753 2 3753 2 3753	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Sip-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al3 at Route 36 Safety Potatio Curt	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Lane mile(s) Lane mi	21.3 1 1 2 38 20 1 1 1 1 1 1 1 1 1 3 6 3 3 3 3 3 4 2 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3750 2 3752 2 3753 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3755 2 3754 2 3755 2 3754 2 3756 2 3764	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Carro Fire Restoration Courte Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Altar CAPM Altar CAPM Altar CAPM Altar CAPM Altar CAPM Altar CAPM Buckhorn New Disposal Sites PR Potato Cut Crowded Bench	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservotion (CAPM) Pavement Preservotion (CAPM) Roadway Rehabilitation (2R) Povement Preservotion (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s)	21.3 1 1 2 388 20 1 1 1 1 1 1 1 1 3.2 6.3 9 33.8 12 1 1 0.4
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3750 2 3750 2 3752 2 3753 2 3753 2 3753 2 3753 2 3753 2 3754 2 3756 2 3763	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaat Curve Improvement South Ave Safety Power Slide Helestide Deer Creek Canwall Dubackella Slia-out Forest Dump Slide Itwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhorn New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane docation(s) Location(s) Location(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Lane mile(s) Lane mile(s)	21.3 1 2 38 20 21 1 1 1 1 1 1 3 6 5 3 3 8 3 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3750 2 3752 2 3753 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3755 2 3754 2 3755 2 3754 2 3756 2 3764	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Carro Fire Restoration Courte Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Altar CAPM Altar CAPM Altar CAPM Altar CAPM Altar CAPM Altar CAPM Buckhorn New Disposal Sites PR Potato Cut Crowded Bench	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservotion (CAPM) Pavement Preservotion (CAPM) Roadway Rehabilitation (2R) Povement Preservotion (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s)	21.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3749 2 3750 2 3750 2 3750 2 3753 2 3753 2 3754 2 3759 2 3759 2 3759 2 3759 2 3759 2 3759 2 3759 2 3761 2 3764 2 3764 2 3764 2 3764 2 3766 2 3766 2 3767	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleside Deer Creek Canwall Dubakella Silp-ouf Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Potation Curve Cardaville Abha and CAPM Potation CAPM Cardaville Abha and CAPM Weaverville Fishwalk Ianale Blue CAPM Weaverville Fishwalk Ianale Blue CAPM MecCloud CAPM Mecloud CAPM MecCloud CAPM Mecloud CAPM Media	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) L	21.3 1 2 38 38 30 20 20 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3750 2 3752 2 3753 2 3754 2 3753 2 3754 2 3755 2 3754 2 3755 2 3754 2 3755 2 3754 2 3755 2 3754 2 3755 2 3755 2 3755 2 3756 2 3756 2 3766 2 3766 2 3766 2 3767 2 3768 2 3773 2 3773	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Bunt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Iangle Blue CAPM McCloud CAPM McCloud CAPM Meaververille Fishwalk Iangle Blue CAPM McCloud CAPM	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Pavement Preservation (CAPM) Roadside Protection and Restoration	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	21.3 21.3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3752 2 3752 2 3753 2 3752 2 3753 2 3754 2 3764 2 3763 2 3763 2 3763 2 3763	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klomathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Helestide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klomath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM Mecloud CAPM Cottonwood Excess Land Transfer Wolf Creek Pavement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s) Lane mile(s) Lane mile(s	21.3 1 2 3 3 3 3 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3745 2 3747 2 3748 2 3750 2 3750 2 3752 2 3753 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3755 2	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Ingal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al3 at Roule 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tlandle Blue CAPM McCloud CAPM Fredonyer Slip Out	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM)	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fotal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s)	21.3 1 2 38 38 30 20 20 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3744 2 3744 2 3745 2 3746 2 3749 2 3750 2	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Sila-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM Fredonyer Slip Out Fress Street Schiap Index	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lone and serious injury collision(s) Location(s) Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Location(s) Lone mile(s) Lone mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	21.3 1 2 3 3 3 3 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3752 2 3753 2 3753 2 3754 2 3753 2 3754 2 3764 2 3763 2 3763 2 3763 2 3764 2 3764 2 3765 2 3767 2 3768	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhon New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM McCloud CAPM Fredonyer Slip Out PSPS Streetllicht Backing plates Filme Creek CAPM Fredonyer Slip Out PSPS Streetllicht Backing plates Fil One Grade Rockfall Mitigation	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	21.3 1 2 3 3 3 3 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3744 2 3744 2 3745 2 3746 2 3747 2 3748 2 3752 2 3752 2 3753 2 3754 2 3755 2 3754 2 3754 2 3754 2 3755 2 3756 2 3757 2 3777 2 3781 2 3777 2 3781 2 3786 2 3786 2 3786 2 3786 2 3777 2 3786 2 3777 2 3786 2 3777 2 3786 2 3786 2 3786 2 3786 2 3786 2 3777 2 3786 2 3786	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Sila-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM Fredonyer Slip Out Fress Street Schiap Index	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lone and serious injury collision(s) Location(s) Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Location(s) Lone mile(s) Lone mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	21.3 1 2 3 3 3 3 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3734 2 3735 2 3737 2 3738 2 3737 2 3738 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3752 2 3753 2 3754 2 3753 2 3754 2 3752 2 3753 2 3754 2 3764 2 3765 2 3764 2 3766 2 3777 2 3781 2 3783 2 3774 2 3775 2 3774 2 3775 2 3774 2 3775 2 3776 2 3768 2 3768 2 3776 2 3768 2 3776 2 3768 2 3777 2 3781 2 3788 2 37881 2 37881 2 37886	Secret Valley SRRA Poker Bar Culverts Burney Falls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Ivain Sinkhole Bunt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Meaververille Fishwalk Ianale Blue CAPM McCloud CAPM Fredonyer Slip Out PSPS Streetllight Backing plates Pit One Grade Rockfall Mitigation Sis 263 Bridae Repairs Pit Rivers Seismic Red Rock Pavement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Bridae(s) Bridae(s) Lane mile(s) Lan	21 23.33 24 24 25 26 27 28 28 28 29 29 20
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3744 2 3744 2 3745 2 3746 2 3747 2 3748 2 3752 2 3752 2 3753 2 3754 2 3755 2 3754 2 3755 2 3754 2 3755 2 3754 2 3755 2 3775 2 3775 2 3775 2 3775 2 3775 2 3775 2 3775 2 3775 2 3755 2 3777 2 3781 2 3785 2 3755 2 3755 2 3755 2 3755 2 3755 2 3755 2 3775 2 3755 2	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Insact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-ouf Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potatio Curl Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek Pavement Flume Creek CAPM Fredonver Slip Out PSPS Sires Sesimic Pit One Grade Rockfall Mitigation SIS 263 Bridge Repairs Pit Rivers Sesimic Pit Rivers Sesimic	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Locatio	21 33 34 20 20 1 1 1 1 1 2 1 4 5 5 6 7 2 7 2 1 2 1 2 1 8 4 5 9 3 3 9 3 3 9 4 5 9 4 5 9 5 9 6 9 6 9 7 1 1 2 1 9 7 1 2 1 2 9 7 1 2 .
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3750 2 3750 2 3752 2 3753 2 3753 2 3753 2 3753 2 3754 2 3764 2 3764 2 3765 2 3763 2 3763 2 3763 2 3764 2 3766 2 3767 2 3768 2 3777 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3769 2 3778 2 3788 2 3788 2 3789 2 3789 2 3790	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaot Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Itwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckban New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Mecarville Fishwalk Tanale Blue CAPM McCloud CAPM McCloud CAPM McCloud CAPM McCroek Safety Buckban New Disposal Sites PR Potato Cut Proving McCloud Fishwalk Tanale Blue CAPM McCloud CAPM McCloud CAPM McCloud CAPM Fredonyer Slip Out PSPS Streetllicht Backing plates Pit One Grade Rockfall Mitigation Sis 263 Bridge Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Cascade SHOPP Shinale Station Paving and Drainage	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Ridae(s) Ridae(s) Ridae(s) Ridae(s) Ridae(s) Ridae(s) Lane mile(s) Location(s) Ridae(s) Rid	21 33.4 33.3 33.3 33.3 33.3 33.3 33.3
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3749 2 3750 2 3752 2 3752 2 3753 2 3753 2 3759 2 3750 2 3761 2 3764 2 3766 2 3767 2 3768 2 3777 2 3788 2 3789 2 3780 2 3790 2	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaot Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Silo-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 3s Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM Fredonyer Silo Out Fisher Silo Safety Silo Safety Red Report Safety Silo Safety Filo One Grade Rockfall Mitigation Silo Safety Silo Safety Silo Safety Silo Safety Fredonyer Silo Out Fisher Safety Silo	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Prevement Preservation (CAPM) Prevement Preservation (CAPM) Prevement Preservation (CAPM) Pavement Preservation (CAPM)	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fotal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Lone mile(s) Location(s) Location(s	21 33.4 33.3 33.3 33.3 33.3 33.3 33.3
2 3734 2 3735 2 3737 2 3738 2 3737 2 3738 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3750 2 3752 2 3753 2 3754 2 3754 2 3754 2 3754 2 3758 2 3754 2 3758 2 3754 2 3758 2 3758 2 3758 2 3758 2 3766 2 3766 2 3766 2 3768 2 3778 2 3788 2 3778 2 3788 2 3779 2 3781 2 3788 2 3789 2 3789 2 3790 2 3791	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Iwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM McCloud CAPM Cathomy Sireet Inaal Fisher Cape Fish Cape Pit One Grade Rockfall Midigation Sis 263 Bridge Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Red Rock Pavement Diddy Roost Culverts Red Rock Pavement Diddy Roost Culverts Cascade SHOPP Shinale Station Paving and Drainage Fawndale Culverts Red Rock Polipour	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Protective Betterments Bridge Resimic Restoration Roadway Rehabilitation (3R) Drainage System Restoration Collision Severity Reduction Pavement Preservation (CAPM) Drainage System Restoration Roadway Rehabilitation (3R) Drainage System Restoration Collision Severity Reduction	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Lane mile(s) Location(s)	21.3 33 33 33 33 33 33 34 32 32 32 32 32 32 33 33 33 33 33 33 33
2 3734 2 3735 2 3737 2 3738 2 3737 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3752 2 3753 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3753 2 3754 2 3758 2 3759 2 3761 2 3763 2 3764 2 3765 2 3768 2 3777 2 3781 2 3777 2 3781 2 3778 2 3785 2 3786 2 3787 2 3788 2 3789 2 3790 2 3790	Secret Valley SRRA Poker Bar Culverts Bumey Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaat Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Twain Sinkhole Bumt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al3 at Route 36 Safety Potato Cut Crowded Bench Cadarville Fishwalk Tanale Blue CAPM Weaverville Fishwalk Tanale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek Pavement Flume Creek CAPM Fredonyer Slip Out PSPS Streetingth Backing plates Pit One Grade Rockfall Mitigation Sis 283 Bridge Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Cascarde Station Paving and Drainage Foward Be Cappe Shingle Station Paving and Drainage Foward Be Culverts Cascard Scaley Shingle Station Paving and Drainage Foward Be Culverts Cascard Selfour Polson Lake Curve Improvement Polson Lake Curve Improvement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Roadside Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Restoration Collision Severity Reduction Pavement Preservation (CAPM) Pavement Preservation (CAPM) Drainage System Restoration Collision Severity Reduction	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lone mile(s) Lane mile(s) Lone mile(s) Location(s) Collision(s) reduced Collision(s) reduced	21 33.1 13 45 45 21 21 21 21 22 21 22 23 33.1 24 26 26 27 28 29 20 20 20 20 20 20
2 3734 2 3735 2 3737 2 3738 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3747 2 3750 2 3750 2 3750 2 3750 2 3750 2 3750 2 3750 2 3750 2 3761 2 3764 2 3767 2 3768 2 3777 2 3788 2 3777 2 3781 2 3784 2 3785 2 3786 2 3777 2 3781 2 3786 2 3777 2 3781 2 3786 2 3787 2 3777 2 3781 2 3786 2 3786 2 3777 2 3781 2 3786 2 3787 2 3777 2 3781 2 3786 2 3786 2 3787 2 3777 2 3781 2 3786 2 3787 2 3777 2 3781 2 3786 2 3787 2 3787 2 3789 2 3790 2 3790 2 3790 2 3791 2 3792 2 3795 2 3796 2 3893 2 3796 2 3796 2 3796 2 3796 2 37976 2 3796 2 37976 2 37976 2 37976 2 37976 2 37976 2 3893	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Itwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckban New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Mecarville Fishwalk Tanale Blue CAPM McCloud CAPM McCloud CAPM McCloud CAPM McCroek Pavement Flume Creek CAPM Fredonver Slip Out PSPS Streetllicht Backing plates Pft One Grade Rockfall Mitiagation Sis 263 Bridge Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Near BFC Slipout Poison Lake Curve Improvement Devil's Corral Safety Poison Lake Curve Improvement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Ferergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Pavement Preservation (C	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Location	21 33.1 13 45 45 21 21 21 21 22 21 22 23 33.1 24 26 26 27 28 29 20 20 20 20 20 20
2 3734 2 3735 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3750 2 3761 2 3764 2 3764 2 3766 2 3766 2 3767 2 3775 2 3786 2 3786 2 3786 2 3786 2 3786 2 3786 2 3786 2 3786 2 3786 2 3787 2 3789 2 3790 2 3790 2 3791 2 3792 2 3795 2 3796 2 3796 2 3792 2 3795 2 3796 2 3796 2 3796 2 3796 2 3799 2 3790 2	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Restoration Delta Fire Restoration Inaot Curve Improvement South Ave Safety Power Slide Helestide Deer Creek Canwall Dubakella Silia-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 3s Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weverville Fishwalk Tanale Blue CAPM McCloud CAPM Cottonwood Excess Land Transfer Wolf Creek CAPM Fredonyer Silia Out Fredonyer S	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Pave	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Location(s)	21 21 23.33.22.22.23.33.33.8.22.23.33.33.22.23.33.33.22.23.33.33.22.23.33.3
2 3734 2 3735 2 3737 2 3738 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3747 2 3750 2 3750 2 3750 2 3750 2 3750 2 3750 2 3750 2 3750 2 3761 2 3764 2 3767 2 3768 2 3777 2 3788 2 3777 2 3781 2 3784 2 3785 2 3786 2 3777 2 3781 2 3786 2 3777 2 3781 2 3786 2 3787 2 3777 2 3781 2 3786 2 3786 2 3777 2 3781 2 3786 2 3787 2 3777 2 3781 2 3786 2 3786 2 3787 2 3777 2 3781 2 3786 2 3787 2 3777 2 3781 2 3786 2 3787 2 3787 2 3789 2 3790 2 3790 2 3790 2 3791 2 3792 2 3795 2 3796 2 3893 2 3796 2 3796 2 3796 2 3796 2 37976 2 3796 2 37976 2 37976 2 37976 2 37976 2 37976 2 3893	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inaal Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Slip-out Forest Dump Slide Itwain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckban New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Mecarville Fishwalk Tanale Blue CAPM McCloud CAPM McCloud CAPM McCloud CAPM McCroek Pavement Flume Creek CAPM Fredonver Slip Out PSPS Streetllicht Backing plates Pft One Grade Rockfall Mitiagation Sis 263 Bridge Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Near BFC Slipout Poison Lake Curve Improvement Devil's Corral Safety Poison Lake Curve Improvement	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Ferergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Pavement Preservation (C	Location(s) Culver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Location	21 21 23.33.22.22.23.33.33.8.22.23.33.33.22.23.33.33.22.23.33.33.22.23.33.3
2 3734 2 3735 2 3737 2 3738 2 3737 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3750 2 3750 2 3751 2 3752 2 3753 2 3754 2 3758 2 3759 2 3759 2 3761 2 3763 2 3764 2 3776 2 3768 2 3777 2 3781 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3779 2 3781 2 3785 2 3786 2 3787 2 3787 2 3789 2 3790 2 3790 2 3790 2 3791 2 3792 2 3796 2 3796 2 3796 2 3790 2 3791 2 3785 2 3786 2 3787 2 3787 2 3788 2 3787 2 3789 2 3790 2 3790 2 3791 2 3792 2 3796 2 3804 2 3806 2 3806 2 3806 2 3806	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Silp-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al3 at Route 36 Safety Buckhorn New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Ianale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek Pavement Flume Creek CAPM Fredonyer Slip Out PSPS Streetlight Backing plates Pit One Grade Rockfall Mitigation Sis 263 Bridae Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Cascade SHOPP Shingle Station Paving and Drainage Fawndale Culverts Near BFC Slipout Pokins Jorden Station Lake Shasta Viaducts Lassen County fires damage repairs Lovation and Claremont Fires Corates County Fires damage repairs Lovation and Claremont Fires Condon Slick Black Maintenance Station Lake Shasta Viaducts Lassen County fires damage repairs Lovation and Claremont Fires	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Bridge Rehabilitation and Replacement Major Damage (Emergency Openina)	Location(s) Culver(s) (ea) Luan mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Location(s	21 21 23.33.22.22.23.33.33.8.22.23.33.33.22.23.33.33.22.23.33.33.22.23.33.3
2 3734 2 3735 2 3737 2 3738 2 3737 2 3738 2 3739 2 3741 2 3742 2 3744 2 3745 2 3747 2 3750 2 3750 2 3750 2 3750 2 3753 2 3753 2 3754 2 3761 2 3763 2 3763 2 3763 2 3764 2 3767 2 3777 2 3781 2 3777 2 3781 2 3785 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3796 2 3796 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3790 2 3800 2 3800 2 3806 2 3806 2 3806 2 3806 2 3806	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Helestide Deer Creek Canwall Dubackella Slin-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al 3 at Route 36 Safety Buckhom New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Tanale Blue CAPM McCloud CAPM Cottonwood Excess Land Transfer Wolf Creek Pavement Flume Creek CAPM Fredonver Slip Out PSPS Streetlicht Backing plates Pit One Grade Rockfall Mitigation Sis 263 Bridge Reports Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Cascade SHoPP Shincel Station Paving and Drainage Fawndale Culverts Near BFC Slipout Poison Lake Curve Improvement Devils Corrol Safety Shincel Station Paving and Drainage Fawndale Culverts Cascade SHoPP Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Paving and Drainage Fawndale Culverts Cascade Shopp Shincel Station Lake Shasta Valedades Shincel Station Lake Shasta Valedades Shincel Shincel Shin	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (ZR) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Femergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM	Location(s) Cutver(s) (ea) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Locati	21.3 1 1 2 2 3 3 4 3 4 3 4 3 4 4 5 4 5 4 5 4 5 4 5 4
2 3734 2 3735 2 3737 2 3738 2 3737 2 3739 2 3741 2 3742 2 3744 2 3745 2 3746 2 3747 2 3748 2 3749 2 3750 2 3750 2 3751 2 3752 2 3753 2 3754 2 3758 2 3759 2 3759 2 3761 2 3763 2 3764 2 3776 2 3768 2 3777 2 3781 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3778 2 3779 2 3781 2 3785 2 3786 2 3787 2 3787 2 3789 2 3790 2 3790 2 3790 2 3791 2 3792 2 3796 2 3796 2 3796 2 3790 2 3791 2 3785 2 3786 2 3787 2 3787 2 3788 2 3787 2 3789 2 3790 2 3790 2 3791 2 3792 2 3796 2 3804 2 3806 2 3806 2 3806 2 3806	Secret Valley SRRA Poker Bar Culverts Burney Folls Pavement Klamathon Fire Restoration CARR Fire Reconstruction Delta Fire Restoration Inact Curve Improvement South Ave Safety Power Slide Heleslide Deer Creek Canwall Dubakella Silp-out Forest Dump Slide Twain Sinkhole Burnt Ranch CAPM Montaque CAPM Klamath Lake Rehab 2R Alturas CAPM Al3 at Route 36 Safety Buckhorn New Disposal Sites PR Potato Cut Crowded Bench Cedarville ADA and CAPM Weaverville Fishwalk Ianale Blue CAPM Cottonwood Excess Land Transfer Wolf Creek Pavement Flume Creek CAPM Fredonyer Slip Out PSPS Streetlight Backing plates Pit One Grade Rockfall Mitigation Sis 263 Bridae Repairs Pit Rivers Seismic Red Rock Pavement Diddy Roost Culverts Cascade SHOPP Shingle Station Paving and Drainage Fawndale Culverts Near BFC Slipout Pokins Jorden Station Lake Shasta Viaducts Lassen County fires damage repairs Lovation and Claremont Fires Corates County Fires damage repairs Lovation and Claremont Fires Condon Slick Black Maintenance Station Lake Shasta Viaducts Lassen County fires damage repairs Lovation and Claremont Fires	Safety Roadside Rest Area Restoration Drainage System Restoration Pavement Preservotion (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Roadside Protection and Restoration Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Bridge Rehabilitation and Replacement Major Damage (Emergency Openina)	Location(s) Culver(s) (ea) Luan mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Location(s	21 21 23.33.22.22.23.33.33.8.22.23.33.33.22.23.33.33.22.23.33.33.22.23.33.3

2 3815	Curve Warning Signs	Collision Severity Reduction	Annual fatal and serious	0.08
	Curve warning signs	Collision Severify Reduction	injury collision(s)	0.08
2 3817	Hilt Pavement Rehab	Roadway Rehabilitation (2R)	Lane mile(s)	45.8
2 3818	August Fire Slide DO	Major Damage (Emergency Opening)	Location(s)	
2 3820 2 3821	Lake Britton Bridge Rail DO Rattlesnake Slide DO	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	1
2 3822	Burnt Ranch Rockfall DO	Major Damage (Emergency Opening)	Location(s)	
2 3825 2 3826	Thompson Creek Bridge Downtown Redding CAPM	Bridge Rehabilitation and Replacement Pavement Preservation (CAPM)	Bridge(s) Lane mile(s)	24.8
2 3827	Quincy Pavement	Pavement Preservation (CAPM)	Lane mile(s)	36.5
2 3828	Bartle CAPM Gray Creek Bridge	Pavement Preservation (CAPM) Bridge Rehabilitation and Replacement	Lane mile(s) Bridge(s)	41.9
2 3830	Weed Blvd Pavement	Roadway Rehabilitation (3R)	Lane mile(s)	27.2
2 3831 2 3835	Tehama Plumas Scour Mitigation	Bridge Scour Transportation Management Systems	Bridge(s)	32
2 3835	Sac Valley ITS Sac Canyon ITS	Transportation Management Systems Transportation Management Systems	Field element(s) Field element(s)	27
2 3837	Lassen County ITS	Transportation Management Systems	Field element(s)	16
2 3838 2 3839	Trinity Dam Pavement Goose Lake Pavement	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	13.1
2 3840	Susan River Pavement	Roadway Rehabilitation (3R)	Lane mile(s)	13.3
2 3841 2 3842	Crowder Flat Pavement Hayfork Pavement	Roadway Rehabilitation (3R) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	11.9
2 3843	Far North TMS	Transportation Management Systems	Field element(s)	19
2 3844	Highway Curve Warning Signs	Collision Severity Reduction	Annual fatal and serious	0.2
			injury collision(s)	
2 3846	Sweetbrier Deck Replacement	Bridge Rehabilitation and Replacement	Bridge(s)	
2 3848 2 3849	Whiskey Creek Deck Replacement Herbert Miles SRRA Water Wastewater	Bridge Rehabilitation and Replacement New Safety Roadside Rest Areas	Bridge(s) Location(s)	
2 3850	Turnaround Snow Job DO	Major Damage (Emergency Opening)	Location(s)	14
2 3851 2 3852	Lava and Tennant Fires DO Dixie Fire South	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
2 3853	Elephant Butte Tunnel	Major Damage (Emergency Opening)	Location(s)	
2 3854	Beckwourth Fire	Major Damage (Emergency Opening)	Location(s)	17
2 3856 2 3857	Monument Fire Salt Creek ELB DO	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	43
2 3860	LAS 395 Dixie Fire	Major Damage (Emergency Opening)	Location(s)	40
2 3861 2 3862	Thomes Creek Bridge MTCE Horse Gulch Curve	Bridge Preventative Maintenance Safety Improvements	Bridge(s) Annual fatal and serious	0.13
2 0002	Horse collen collec	salety improvements	injury collision(s)	0.10
2 3863	Flume Creek Leftover Culverts	Drainage System Restoration	Culvert(s) (ea)	31
2 3864	East Palisades Class I Path	SHOPP - Complete Streets	Bicycle and pedestrian	7675
			infrastructure (linear	
			feet)	
2 3866	Rattlesnake 2 DO	Major Damage (Emergency Opening)	Location(s)	1
2 3867 2 3869	Salt Creek Part 2 ELB Las 70 Embankment Repair	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	2
2 3871	SIS 96 Wild fire repair	Major Damage (Emergency Opening)	Location(s)	105
2 3872	SIS 97 Whitney Cr Var Loc	Major Damage (Emergency Opening)	Location(s)	(
2 3876 2 3877	BUT/PLU 70 Corridor Slides SIS 96 Corridor Slides	Major Damage (Emergency Restoration) Major Damage (Emergency Opening)	Location(s) Location(s)	103
2 3877	SIS 96 Corridor Slides	Major Damage (Emergency Opening)	Location(s)	100
2 3885 2 3887	PLU 70 PM 81.82 California Cycle Track FCO	Major Damage (Emergency Opening) SHOPP - Complete Streets	Location(s) Bicycle and pedestrian	792
2 0007	California Cycle mack rec	Short Complete shoets	infrastructure (linear	,,,
			feet)	
2 3889	Wildlife Crossing Structure	SHOPP - Sustainability and Miscellaneous		1
2 3899	SIS 96 PM 0 to 103	Major Damage (Emergency Restoration)	feet) Location(s) Location(s)	3
			feet) Location(s) Location(s) Bicycle and pedestrian	1 3 8050
2 3899	SIS 96 PM 0 to 103	Major Damage (Emergency Restoration)	feet) Location(s) Location(s)	1 3 8050
2 3899 2 3902	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders	Major Damage (Emergency Restoration) SHOPP - Complete Streets	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet)	
2 3899	SIS 96 PM 0 to 103	Major Damage (Emergency Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear	
2 3899 2 3902 2 3903 2 3903 2 3904	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Wills Arlington LTL Combine	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lone mille(s) Each Each	21.3 2 1
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM)	feet) Location(s) Location(s) Bicycle and pedestrian infrostructure (linear feet) Lane mille(s) Each Lane mille(s)	
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Miligation Devil's Corrol Safety Combine	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced	21.3 2 16.4 (
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3914	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corral Safety Combine Maintenance Station Security Improvements	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s)	21.3 2 16.4 (
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3914 2 3918 2 3920	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Silde and Provide Traffic control PLU 70 Stabilization	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced	21.3 2 16.4 (
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3914 2 3918 2 3920 2 3922	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitication Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Slip- Out Repair	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lone mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s)	21.3 2 16.4 (
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3914 2 3918 2 3920 2 3922	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Silde and Provide Traffic control PLU 70 Stabilization	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s)	21.3 2 16.4 (
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3922 2 3922 2 3922 2 3928	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Lona-Term Militaation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO	Major Damage [Emergency Restoration] SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bitidae Scour Safety Improvements Maintenance Facilities Major Damage [Emergency Restoration] Major Damage [Emergency Restoration] Major Damage [Emergency Restoration] Bitidae Formula Program Bridae Formula Program Major Damage (Emergency Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s)	21.3 16.4 (22 27
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3920 2 3922 2 3922 2 3922 2 3929 2 3929 3 2112	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Sip- Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Curb ramp(s)	21.3 16.6 (20 27 21 11
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3920 2 3922 2 3922 2 3922 2 3929 3 2112 3 2114	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Side and Provide Traffic control PLU 70 Stabilization SIS Silp-Out Repair North Mount Shasta Separator Rehab Modac 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT 32 Intersection Improvements	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lone mile(s) Biddes(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Briddes(s) Briddes(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Briddes(s) Briddes(s) Briddes(s) Location(s) Curb ramp(s) Curb ramp(s) Culision(s) reduced Lone mile(s)	21.5 16.0 () 20 21 21 21 4 122 21 18.6
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3914 2 3918 2 3920 2 3922 2 3922 2 3922 2 3929 3 2112 3 2114 3 2115	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Sip- Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab But-32 Chico Rehab But-64 County Rehabilitation	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Sofety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Cocation(s) Location(s) Location(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Curb ramp(s) Collision(s) reduced Lane mile(s) Lone mile(s)	21.3 16.4 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3920 2 3922 2 3922 2 3922 2 3929 3 2112 3 2114	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Side and Provide Traffic control PLU 70 Stabilization SIS Silp-Out Repair North Mount Shasta Separator Rehab Modac 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT 32 Intersection Improvements	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lone mile(s) Biddes(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Briddes(s) Briddes(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Briddes(s) Briddes(s) Briddes(s) Location(s) Curb ramp(s) Curb ramp(s) Culision(s) reduced Lone mile(s)	21.3 16.4 (c) 22 22 23 1 1 1 1 1 1 1 1 1 1 1 1 1
2 3899 2 3902 2 3903 2 3904 2 3904 2 3904 2 3905 2 3914 2 3918 2 3920 2 3922 2 3922 2 3927 3 2112 3 2115A 3 2115A 3 2115A	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Milliadition Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shasta Separator Rehab Madac 299 Pit River Bridae Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety Project Gianella-Muir Safety & Meridian Rd Signal Combined	Maior Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Lane mile(s) Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3922 2 3922 3 2112 3 2115 3 2115 3 2116 3 2116 3 2116	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Lona-Ferm Mitication Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Side and Provide Traffic control PLU 70 Stabilization SIS Silip-Out Repair North Mount Shosta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bidge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Lone mile(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Curb ramp(s) Collision(s) reduced Lone mile(s) Collision(s) reduced	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3922 2 3922 3 2115 3 2115 3 2115 3 2116 3 2116 3 2116 3 2116	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Militaation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Station Security Improvements Remove Station Security Improvements Is Slip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall	Major Damage [Emergency Restoration] SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage [Emergency Restoration] Major Damage [Emergency Restoration] Major Damage [Emergency Restoration] Bidae Formula Program Bidae Formula Program Major Damage [Emergency Restoration] Program Bidae Formula Program Major Damage [Emergency Restoration] ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage [Permanent Restoration] Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Courb ramp(s) Courb ramp(s) Courb ramp(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3912 2 3922 2 3922 2 3922 2 3922 3 2112 3 2115 3 2115 3 2115 3 2115 3 2116 3 2116 3 2116 3 2117 3 2117 3 2117	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Miltigation Devil's Corral Safely Combine Maintenance Station Security Improvements Remove Silde and Provide Traffic control PLU 70 Stabilization SIS Silp-Out Repair North Mount Shasta Separator Rehab Modac 299 Pit River Bridge Rehab D2 Park Fire DO Chica ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safely & Meridian Rd Signal Combined Gianella-Muir Safely & Meridian Rd Signal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall BUT 32 Pedestrian Improvements SR 32 at Meridian Road Traffic Signalization	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Safety Improvements Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lone mile(s) Bidde(s) Collision(s) reduced Location(s) Location(s) Location(s) Bidde(s) Bidde(s) Cocation(s) Location(s) Location(s) Cuctor and solution (s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Lone mile(s) Location(s) Curb ramp(s) Collision(s) reduced Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Collision(s) reduced	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3904 2 3904 2 3904 2 3905 2 3914 2 3918 2 3929 3 2112 3 2115A	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Militaation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Station Security Improvements Remove Station Security Improvements Is Slip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall	Major Damage [Emergency Restoration] SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage [Emergency Restoration] Major Damage [Emergency Restoration] Major Damage [Emergency Restoration] Bidae Formula Program Bidae Formula Program Major Damage [Emergency Restoration] Program Bidae Formula Program Major Damage [Emergency Restoration] ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage [Permanent Restoration] Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Courb ramp(s) Courb ramp(s) Courb ramp(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3904 2 3918 2 3910 2 3918 2 3920 2 3922 2 3922 2 3922 2 3922 3 2112 3 2115 3 2115 3 2115 3 2116 3 2116 3 2116 3 2116 3 2116 3 2116 3 2116 3 2117 3 2120 3 2120 3 2120	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Miltigation Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Silde and Provide Traffic control PLU 70 Stabilization SIS Silp-Out Repair North Mount Shasta Separator Rehab Modac 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Sianal Combined Gianella-Muir Safety & Meridian Rd Sianal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall BUT-32 Pedestrian Improvements SR 32 at Meridian Road Traffic Sianalization SR 32 at Meridian Road Traffic Sianalization SR 32 at Meridian Road Traffic Sianalization BUT 32 Snow Damage Park Fire	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Fireffic signal interconnect project(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Sidae(s) Bridae(s) Curb ramp(s) Collision(s) reduced Lane mile(s) Curb ramp(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Each Location(s) Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) Location(s)	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3927 2 3928 3 2115 3 2115 3 2115 3 2116 3 2126 3	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Militaation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety Rehabilitation Gianella-Muir Safety & Meridian Rd Sianal Combined Gianella-Muir Safety & Meridian Rd Sianal Combined Gianella-Muir Safety & Meridian Rd Sianal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall SUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall SUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall SUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bidae Formula Program Bidae Formula Program Bidae Formula Program ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements	feet) Location(s) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Courb ramp(s) Courb ramp(s) Courb ramp(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lone mile(s) Location(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s)	21.3 16.0 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3904 2 3904 2 3904 2 3905 2 3914 2 3918 2 3929 3 2112 3 2115 3 2115 3 2115 3 2115 3 2115 3 2115 3 2115 3 2115 3 2115 3 2115 3 2120 3 2293 3 2293	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Miltigation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shosta Separator Rehab Madac 299 Pit River Bridae Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rad Signal Combined Gianella-Muir Safety & Meridian Rad Signal Combined Gianella-Muir Safety & Meridian Rad Signal Combined BUT-32 Soldier Pile Wall DATE Soldier Pile Wall BUT-32 Soldier Pile Wall DATE Soldier Pile Wall DATE SOLDIER Pile Wall DATE SOLDIER Pile Wall DATE SOLDIER PILE PILE Pulga 70 Profile Change Envir Milication for Pulga Ophir Palermo Safety, (Sea 1 SHOPP)	Maior Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidace Scour Safety Improvements Maintenance Facilities Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Bidae Formula Program Bidae Formula Program Maior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Maior Damage (Permanent Restoration) Safety Improvements Safety Improvements Traffic signal interconnect project(s) Maior Damage (Permanent Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lone mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Lone mile(s) Location(s) Curb ramp(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) Location(21.5 ((22.2)
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3927 2 3922 2 3927 2 3928 3 2112 3 2114 3 2115 3 2115 3 2116 3 2116 3 2116 3 2116 3 2116 3 2116 3 2120 3 2124 3 2120 3 2124 3 2125 3 2293 3 2293 3 2293	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Militaation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Side and Provide Traffic control PLU 70 Stabilization SIS Silp-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridae Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety Project Gianella-Muir Safety & Meridian Rd Sianal Combined Gianella-Muir Safety & Meridian Rd Sianal Combined BUT-32 Soldier Pile Wall BUT 32 Pedestrian Improvements SR 32 at Meridian Road Traffic Sianalization SR 32 at Meridian Road Traffic Sianalization BUT 32 Profile Change Envir Militaation for Pulaa Ophir Palermo Safety, ISea 1 SHOPP) Polermo Cox Safety, ISea 1 SHOPP) Polermo Cox Safety, ISea 1 SHOPP)	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bidae Formula Program Bridae Formula Program Bridae Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Gafety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridge(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridge(s) Bridge(s) Coulision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Collision(s) reduced Lane mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Location(s) Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) Loc	21.5 ((22.2)
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3920 2 3922 2 3922 2 3922 2 3922 3 2115 3 2115 3 2115 3 2115 3 2115 3 2116 3 2116 3 2116 3 2116 3 2120 3 2120 3 2124 3 2293 3 2293 3 2293 3 2293 3 2293 3 2295	SiS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Miltigation Devil's Corrol Safety Combine Maintenance Station Security Improvements Remove Side and Provide Traffic control PLU 70 Stabilization SiS Sip-Out Repoir North Mount Shasta Separator Rehab Modac 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT 32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety Project Gianella-Muir Safety Project Gianella-Muir Safety New Indian Rd Signal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wall BUT-32 Saldier Pile Wall SUT-32 Saldier Pile Wall SUT-32 Saldier Pile Wall SUT-32 Saldier Pile Wall SUT-32 Sand Meridian Road Traffic Signalization SR 32 at Meridian Road Traffic Signalization Deriv Miltigation for Pulca Ophir Palermo Safety, (Sea 1 SHOPP) Polermo Cox Safety (Sea 2 SHOPP) Hwy 70 Segment 2 Combined	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnoul(s) Channelization Pavement Preservation (CAPM) Bridge Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridge Formula Program Bridge Formula Program Bridge Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project (s) Major Damage (Permanent Restoration) Safety Improvements Traffic signal interconnect project (s) Major Damage (Permanent Restoration) Safety Improvements Firaffic signal interconnect project (s) Major Damage (Permanent Restoration) Safety Improvements Safety Improvements Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Sidae(s) Curb ramp(s) Collision(s) reduced Lane mile(s) Curb ramp(s) Collision(s) reduced Location(s) Curb ramp(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) L	21 16 12 12 12 18 18 18 19 10
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3922 2 3922 3 2115 3 2115 3 2115 3 2116 3 2116 3 2116 3 2116 3 2116 3 2120 3 2120 3 2120 3 2124 3 2125 3 2293 3 2293 3 2295 3 2295 3 2295 3 2295	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Sitide and Provide Traffic control PLU 70 Stabilization SIS Silip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Sianal Combined Gianella-Muir Safety & Meridian Rd Sianal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wa	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridae Formula Program Bridae Formula Program Bridae Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Firaffic signal interconnect project(s) Major Damage (Permanent Restoration) Major Damage (Emergency Openina) Major Damage (Fmergency Openina) Major Damage (Fmergency Restoration) Major Damage (Permanent Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridae(s) Corb ramp(s) Collision(s) reduced Lane mile(s) Lone mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s)	21
2 3899 2 3902 2 3903 2 3904 2 3904 2 3904 2 3905 2 3910 2 3914 2 3918 2 3922 2 3928 2 3922 2 3928 2 3929 3 2112 3 2115A 3 2115A 3 2116A 3 2116A 3 2116A 3 2116A 3 2117 3 2120 3 2120 3 2124 3 2125 3 2293 3 2293 3 2293 3 2294 3 2295A 3 2295A 3 2295A 3 2295A 3 2295A	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Lama Combine Del Lama Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Slide and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shosta Separator Rehab Madac 299 Pit River Bridae Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined BUT-32 Solider Pile Wall D2 Park Fire Pulga 70 Profile Change Envir Milication for Pulga Ophir Palemo Safety, (Sea 1 SHOPP) Palemo Cox Safety (Sea 2 SHOPP) Hwy 70 Segment 2 Combined Hwy 70 Segment 3 Combined	Maior Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidge Scour Safety Improvements Maintenance Facilities Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Bidge Formula Program Bidge Formula Program Maior Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Maior Damage (Permanent Restoration) Safety Improvements Traffic signal interconnect project(s) Maior Damage (Permanent Restoration) Safety Improvements Safety Improvements Safety Improvements Firaffic signal interconnect project(s) Maior Damage (Fermanent Restoration) Safety Improvements	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lone mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Collision(s) reduced Lone mile(s) Location(s) Location(s) Location(s) Curb ramp(s) Collision(s) reduced Location(s) Location(s) Location(s) Collision(s) reduced Lone mile(s) Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) L	21
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3922 2 3922 3 2115 3 2115 3 2115 3 2116 3 2116 3 2116 3 2116 3 2116 3 2120 3 2120 3 2120 3 2124 3 2125 3 2293 3 2293 3 2295 3 2295 3 2295 3 2295	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Mitigation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Sitide and Provide Traffic control PLU 70 Stabilization SIS Silip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Sianal Combined Gianella-Muir Safety & Meridian Rd Sianal Combined BUT-32 Soldier Pile Wall BUT-32 Soldier Pile Wa	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridae Formula Program Bridae Formula Program Bridae Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Firaffic signal interconnect project(s) Major Damage (Permanent Restoration) Major Damage (Emergency Openina) Major Damage (Fmergency Openina) Major Damage (Fmergency Restoration) Major Damage (Permanent Restoration)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Bridae(s) Corb ramp(s) Collision(s) reduced Lane mile(s) Lone mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s)	21 16 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3927 2 3922 2 3927 2 3928 3 2112 3 2115 3 2115 3 2115 3 2116A 3 2116A 3 2116A 3 2116A 3 2116 3 2120 3 2124 3 2129 3 2293 3 2293 3 2293 3 2293 3 2293 3 2295 3 2295 3 2295 3 2296 3 2297 3 2297 3 2297	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Milisation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Sitole and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined BUT-32 Soldier Pile Wall BUT 32 Padestrian Improvements SR 32 at Meridian Road Traffic Signalization SR 32 at Meridian Road Traffic Signalization BUT-32 Sonow Damage Park Fire Pulga 70 Profile Change Envir Militgation for Pulga Ophir Palermo Safety, (Sea 1 SHOPP) Pelermo Cox Safety (Sea 1 SHOPP) Pelermo Cox Safety (Sea 1 SHOPP) Pelermo Cox Safety (Sea 2 SHOPP) Hwy 70 Segment 2 Combined Butte Safety - (Sea Denbined Hwy 70 Segment 2 Combined	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bidae Formula Program Bidae Formula Program Bidae Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Dependent Safety Opening Major Damage (Emergency Opening)	feet) Location(s) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Corb ramp(s) Curb ramp(s) Corb ramp(s) Collision(s) reduced Lane mile(s) Lone mile(s) Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) Collision(s) reduced Collision(s) Collision(s) reduced Collision(s) Location(s)	21 16 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3922 2 3922 2 3922 2 3922 3 2112 3 2114 3 2115 3 2116 3 2116 3 2116 3 2116 3 2116 3 2116 3 2120 3 2124 3 2125 3 2293 3 2293 3 2295 3 2295 3 2295 3 2295 3 2296 3 2297 3 2298 3 2298 3 2298 3 2298	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Lona-Ferm Mitication Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Sidie and Provide Traffic control PLU 70 Stabilization SIS Silip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADAl Infrastructure BUT 32 Intersection Improvements BUT 32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined BUT 32 Pedestrian Improvements SR 32 at Meridian Road Traffic Signalization SR 32 at Meridian Road Traffic Signalization BUT 32 Show Damage Park Fire Pulga 70 Profile Change Envir Millication for Pulga Ophir Palermo Safety, (Seg 1 SHOPP) Pelermo Cox Safety (Seg 2 SHOPP) Hwy 70 Seament 2 Combined Butty 37 Seament 2 Combined Butty Sofety - Iseament 3 SHOPP) Camp Fire Fire Femeraency Butty Sy Traffic Signal @ Liberty Ln Camp Fire Fire Femeraency Butty Parfiel Signal @ Liberty Ln Camp Fire Fire Femeraency Butty Parfiel Signal Subter 70 CAPM	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnouf(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bridae Formula Program Bridae Formula Program Bridae Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Fraffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Fraffic signal interconnect project(s) Major Damage (Permanent Restoration) Major Damage (Fmergency Openina) Major Damage (Fmergency Restoration) Major Damage (Fmergency Restoration) Major Damage (Permanent Restoration) Safety Improvements Safety Improvements Safety Improvement Restoration) Major Damage (Fmergency Openina) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Fmergency Openina) Major Damage (Fmergency Openina) Major Damage (Emergency Openina)	feet) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Location(s) Collision(s) reduced Location(s) Curb ramp(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Each Location(s) Locat	21 16 () () () () () () () () () ()
2 3899 2 3902 2 3903 2 3903 2 3904 2 3904 2 3905 2 3910 2 3918 2 3922 2 3927 2 3922 2 3927 2 3928 3 2112 3 2115 3 2115 3 2115 3 2116A 3 2116A 3 2116A 3 2116A 3 2116 3 2120 3 2124 3 2129 3 2293 3 2293 3 2293 3 2293 3 2293 3 2295 3 2295 3 2295 3 2296 3 2297 3 2297 3 2297	SIS 96 PM 0 to 103 Mineral Multi-Use Path and Shoulders Del Loma Combine Del Loma Combine Crescent Mills Arlington LTL Combine Crescent Mills Arlington LTL Combine Horse Creek Long-Term Milisation Devil's Corral Safety Combine Maintenance Station Security Improvements Remove Sitole and Provide Traffic control PLU 70 Stabilization SIS Slip-Out Repair North Mount Shasta Separator Rehab Modoc 299 Pit River Bridge Rehab D2 Park Fire DO Chico ADA Infrastructure BUT 32 Intersection Improvements BUT-32 Chico Rehab Butte County Rehabilitation Butte County Rehabilitation Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined Gianella-Muir Safety & Meridian Rd Signal Combined BUT-32 Soldier Pile Wall BUT 32 Padestrian Improvements SR 32 at Meridian Road Traffic Signalization SR 32 at Meridian Road Traffic Signalization BUT-32 Sonow Damage Park Fire Pulga 70 Profile Change Envir Militgation for Pulga Ophir Palermo Safety, (Sea 1 SHOPP) Pelermo Cox Safety (Sea 1 SHOPP) Pelermo Cox Safety (Sea 1 SHOPP) Pelermo Cox Safety (Sea 2 SHOPP) Hwy 70 Segment 2 Combined Butte Safety - (Sea Denbined Hwy 70 Segment 2 Combined	Major Damage (Emergency Restoration) SHOPP - Complete Streets Pavement Preservation (CAPM) Turnout(s) Channelization Pavement Preservation (CAPM) Bidae Scour Safety Improvements Maintenance Facilities Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Bidae Formula Program Bidae Formula Program Bidae Formula Program Major Damage (Emergency Restoration) ADA - New Curb Ramps Safety Improvements Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Traffic signal interconnect project(s) Major Damage (Permanent Restoration) Safety Improvements Dependent Safety Opening Major Damage (Emergency Opening)	feet) Location(s) Location(s) Location(s) Bicycle and pedestrian infrastructure (linear feet) Lane mile(s) Each Lane mile(s) Bridae(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Corb ramp(s) Curb ramp(s) Corb ramp(s) Collision(s) reduced Lane mile(s) Lone mile(s) Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Each Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) Collision(s) reduced Collision(s) Collision(s) reduced Collision(s) Location(s)	21.3 2 1

3 2305	BUT/YUB 70 Seg 3 Combined	Passing lane mile(s) constructed	Miles	
3 2305	BUT/YUB 70 Seg 3 Combined	Safety Improvements	Collision(s) reduced	35
3 2306 3 2308	Butte 70 Girders Repair BUT 70 Slip Out	Major Damage (Emergency Opening)	Location(s)	
3 2310	BUT 70 Garden Drive OC Hit	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
3 2425	Cottonwood Creek Bridge Replacement	Bridge Scour	Bridge(s)	
3 2433	But 99 Bridge Rail Replacement	Bridge Rail Replacement/Upgrade	Linear feet rail	1028
3 2435	Butte 99 Road Rehab in Gridley	Pavement Preservation (CAPM)	Lane mile(s)	6.8
3 2435 3 2437	Butte 99 Road Rehab in Gridley Chico ITS	Roadway Iane mile(s) - new Transportation Management (Fiber Optic Cable)	Mile(s) of cable	6.7 5.6
3 2438	Habitat Advanced Mitigation	Roadside Enhancement (Mitigation Site	Location(s)	3.6
		Relinguishments)	()	
3 2439	Butte Neal Road Pavement	Major Damage (Emergency Opening)	Location(s)	1
3 2441 3 2442	Butte 99 Keefer Slough	Major Damage (Permanent Restoration)	Location(s)	
3 2442	Bridge Deck Preservation BUT 99 Sinkhole	Bridge Preventative Maintenance Major Damage (Emergency Opening)	Bridge(s) Location(s)	
3 2633	Butte City Bridge Replacement	Bridge Seismic Restoration	Bridge(s)	
3 2635	162 Road Widening	Safety Improvements	Collision(s) reduced	50
3 2638 3 2639	Oroville CAPM BUT 162 Sinkhole	Pavement Preservation (CAPM) Major Damage (Emergency Opening)	Lane mile(s) Location(s)	7.0
3 2640	North Complex Fire	Major Damage (Emergency Opening)	Location(s)	
3 2642	BUT 162 Ward Blvd Culvert	Major Damage (Emergency Opening)	Location(s)	
3 2694	Salt Creek Canyon	Safety Improvements	Annual fatal and serious injury collision(s)	0.37
3 2706	Camp Fire Debris Removal & Pavement Repair	Major Damage (Emergency Opening)	Location(s)	1
3 2707	BUT 191 Widening	Major Damage (Permanent Restoration)	Location(s)	
3 2710	Durham Pentz Intersection	Safety Improvements	Annual fatal and serious	0.14
			injury collision(s)	
3 2777	COL 5 Flooding/Channel Clearing	Major Damage (Emergency Opening)	Location(s)	
3 2793	Maxwell SRRA	Roadside Safety Improvements	Location(s)	
3 2794	SAC 99/51/160 Five Pump Plant Project	Drainage System Restoration	Pump plant(s) (ea)	
3 2796	Lynch Canyon	Safety Improvements	Collision(s) reduced	1
3 2797 3 2803	COL 5 Pavement Storm Damage Maxwell SB SRRA Rehab	Major Damage (Emergency Restoration) Safety Roadside Rest Area Restoration	Location(s)	
3 2855	LNU Fire Restoration	Major Damage (Emergency Opening)	Location(s)	
3 2950	Colusa Rehab	Roadway Rehabilitation	Lane mile(s)	
3 2951	Colusa Shoulder Widening & CRZ	Safety Enhancements	Collision(s) reduced	14
3 2953	COL 20 Shoulder Washouts	Major Damage (Emergency Opening)	Location(s)	
3 2975 3 3157	Maxwell SRRA Rehab Placerville 49 CAPM	Safety Roadside Rest Area Restoration Pavement Preservation (CAPM)	Lane mile(s)	4.4
3 3167	ED Storm Damage	Major Damage (Emergency Restoration)	Location(s)	4.4
3 3168	Safety Reactive Improvement at Various Locations	Safety Improvements	Annual fatal and serious	1.17
			injury collision(s)	
3 3290	Camino Safety Project	Safety Improvements	Collision(s) reduced	117
3 3290A	Camino Safety Project Combined	Drainage System Restoration	Culvert(s) (ea)	117
3 3290A	Camino Safety Project Combined	Safety Improvements	Collision(s) reduced	117
3 3304	Sidehill Viaduct Bridge (Echo Summit)	Bridge Rehabilitation	Bridge(s)	
3 3311 3 3312	ED 50 MBGR Upgrade to current standards ED 50 Advance Warning & ITS	Safety Enhancements Transportation Management (TMC's & Field	Collision(s) reduced	25
3 3312	ED 30 Advance Walning & 113	Equipment)	Field element(s)	3/
3 3313	D3 ADIEM and Sand Barrel upgrade	Safety Enhancements	Collision(s) reduced	3
3 3315	ED 50 Culverts	Drainage System Restoration	Culvert(s) (ea)	28
3 3315A	ED 50 Culvert Rehab	Drainage System Restoration	Culvert(s) (ea)	54
3 3316 3 3317	Cameron Park Safety ED 50 Culvert Rehab	Safety Improvements Drainage System Restoration	Collision(s) reduced Culvert(s) (ea)	32
3 3318	US 50 MBGR Upgrade	Safety Enhancements	Collision(s) reduced	
3 3326	Fresh Pond Slipout	Major Damage (Permanent Restoration)	Location(s)	
3 3327	Alder Creek Slide	Major Damage (Permanent Restoration)	Location(s)	
3 3330 3 3335	Bridal Veil Slipout Culvert Rehab and Wildlife Crossing	Major Damage (Permanent Restoration) Drainage System Restoration	Location(s) Culvert(s) (ea)	
3 3337	Placerville CAPM	Pavement Preservation (CAPM)	Lane mile(s)	29.8
3 3338	South Tahoe CAPM	Pavement Preservation (CAPM)	Lane mile(s)	12.0
3 3339	ED-50 Down Drain	Major Damage (Permanent Restoration)	Location(s)	
3 3340 3 3341	ED 50 Upper Truckee River Br Fire Repairs ED 50 CAPM	Major Damage (Emergency Opening)	Lane mile(s)	42.7
3 3347	Caldor Fire 1 SR50	Pavement Preservation (CAPM) Major Damage (Emergency Restoration)	Location(s)	2
3 3348	Caldor Fire 2 SR50	Major Damage (Emergency Opening)	Location(s)	-
3 3351	ED 50 Forni Culvert	Major Damage (Emergency Opening)	Location(s)	•
3 3352	ED 50 Tree Removal	Major Damage (Emergency Restoration)	Location(s)	25
3 3356 3 3365	ED 50 SLT Pavement ED 50 Rockfall - Slope Stabilization	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	20
3 3469	S. Lake Tahoe Safety Project	Safety Improvements	Collision(s) reduced	10
3 3470	ED 49 Sinkhole/Culvert Replacement	Major Damage (Emergency Opening)	Location(s)	
3 3473	Meeks Creek Bridge Replacement	SHOPP - Sustainability and Miscellaneous	Location(s)	
3 3631 3 3636	ED 193 Slipout Placerville Slide Repair	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
3 3709	Glenn 5 Roadside Safety	Roadside Safety Improvements	Location(s)	64
3 3710	Willows SRRA	Roadside Safety Improvements	Location(s)	
3 3712	GLE-5 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	34.4
3 3713	County Road OC Hit	Major Damage (Emergency Opening) ADA - New Curb Ramps	Location(s) Curb ramp(s)	110
3 3788		Payement Preservation (CAPM)	Lane mile(s)	20.7
3 3788 3 3790	Orland ADA Infrastructure GLE 32 CAPM	Tavement reservation (CALM)		
		Safety Improvements	Annual fatal and serious injury collision(s)	0.26
3 3790 3 3803	GLE 32 CAPM County Road P	Safety Improvements	injury collision(s)	
3 3790	GLE 32 CAPM			12
3 3790 3 3803 3 3855 3 3918 3 3994	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud)	Safety Improvements Safety Improvements Povement Preservation (CAPM) Safety Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced	12 5. 4
3 3790 3 3803 3 3855 3 3918	GLE 32 CAPM County Road P Safety Improvements Willows CAPM	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of	12 5. 4
3 3790 3 3803 3 3855 3 3918 3 3994 3 3996	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops)	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD)	12 5. 4 2
3 3790 3 3803 3 3855 3 3918 3 3994	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud)	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of	12 5. 4 2
3 3790 3 3803 3 3855 3 3918 3 3994 3 3996	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops)	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Sofety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of	12 5, 4 2
3 3790 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts)	Safety Improvements Povement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Detay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD)	12 5. 4 2 2
3 3790 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997 3 3999	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts) Omega Curves (Lowell Hill)	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Sofety Improvements Safety Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced	12 5. 4 2 2
3 3790 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts)	Safety Improvements Povement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Doily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced	12 5. 4 2 2
3 3790 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997 3 4000 3 4000A	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts) Omega Curves (Lowell Hill) Omega Curves Omega Curves	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Operational Improvements Safety Improvements Safety Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Daily vehicle hour(s) of delay (DVHD) Collision(s) reduced Daily vehicle hour(s) of delay (DVHD) Collision(s) reduced	12: 5 4. 2: 2: 1: 5: 9.
3 3790 3 3803 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997 3 4000 3 4000A 3 4000A	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts) Omega Curves (Lowell Hill) Omega Curves Omega Curves Rumble Stri	Safety Improvements Safety Improvements Povement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Operational Improvements Safety Improvements Safety Improvements Safety Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Daily vehicle hour(s) of delay (DVHD) Collision(s) reduced Collision(s) reduced Collision(s) reduced	12: 5.3: 4.4 20 21 10 5: 9.4
3 3790 3 3803 3 3803 3 3918 3 3994 3 3996 3 3997 3 3997 3 4000 3 4000A 3 4000A 3 4001A	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts) Omega Curves (Lowell Hill) Omega Curves Omega Curves Omega Curves Rumble Strips Gold Nugaet	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Operational Improvements Safety Improvements Operational Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Daily vehicle hour(s) of Delay (DVHD) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Lane mile(s)	12: 5.5. 4: 20 20 10 5: 9.0 9!
3 3790 3 3803 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997 3 4000 3 4000A 3 4000A	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts) Omega Curves (Lowell Hill) Omega Curves Comega Curves Rumble Strips Gold Nugaet Nev/Pla 20 CAPM	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Sofety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Sofety Improvements Safety Improvements Operational Improvements Safety Improvements Safety Improvements Povement Preservation (CAPM) Pavement Preservation (CAPM)	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Daily vehicle hour(s) of delay (DVHD) Collision(s) reduced Collision(s) reduced Collision(s) reduced	12: 5.9. 44 26 21 10 5: 9.6
3 3790 3 3803 3 3803 3 3855 3 3918 3 3994 3 3996 3 3997 3 3999 3 4000 3 4000A 3 4000A 3 4001 3 4002	GLE 32 CAPM County Road P Safety Improvements Willows CAPM Omega Curves (White Cloud) Omega Curves (Special Ops) NEV/PLA Turnouts Omega Curves (Turnouts) Omega Curves (Lowell Hill) Omega Curves Omega Curves Omega Curves Rumble Strips Gold Nugaet	Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Non-Capacity Increasing Operational Improvements Operational Improvements Safety Improvements Operational Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements	injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Daily vehicle hour(s) of delay (DVHD) Collision(s) reduced Collision(s) reduced Collision(s) reduced Lane mile(s)	12: 5.3: 44 2(2(11) 5: 9. 9. 9. 11: 22: 44.4

		_		
3 4123	Nev-49 Culvert Rehab (North)	Drainage System Restoration	Culvert(s) (ea)	31
3 4124 3 4125	Nev-49 Culvert Rehab (South) Count Station Repair & Install	Drainage System Restoration Transportation Management (TMC's & Field	Culvert(s) (ea) Field element(s)	3'
3 4123	Court station Repair & Install	Equipment)	rield element(s)	
3 4136	Nev-49 Corridor Improvement Project (Safety)	Collision Severity Reduction	Annual fatal and serious	0.3
			injury collision(s)	
3 4137	Nev-49 Wolf/Combie	Safaty Improvements	Callisian(s) raduced	2
3 4138	Nev-49 Round Valley/Quail Creek	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	1
3 4139	Nev/Yub 49 slide removal/slope repair	Major Damage (Emergency Opening)	Location(s)	
3 4143	Grass Valley Wildfire Evacuation Route (IIJA)	SHOPP - Sustainability and Miscellaneous	Centerline mile(s)	7.
3 4146	Nev-49 Vision Zero Shoulder Widening	Safety Improvements	Annual fatal and serious	0.
			injury collision(s)	
3 4287	Farad Ditch Slope Stabilization	Roadway Protective Betterments	Bridge(s)	
3 4288	Replace MBGR	Safety Enhancements	Collision(s) reduced	9
3 4291	UPGRADE EMS SIGNS	Transportation Management (TMC's & Field	Field element(s)	
2 4002	Anid Flet Dealifell Deatablish	Equipment) Roadway Protective Betterments	Landian(s)	
3 4293 3 4294	Acid Flat Rockfall Protection Donner Park to Trout Creek Road Rehab	Pavement Preservation	Location(s) Lane mile(s)	2.
3 4297	Nev 80 Concrete Barrier	Safety Enhancements	Collision(s) reduced	1
3 4298	Mystic Rockfall Protection	Roadway Protective Betterments	Bridge(s)	
3 4299	County Line Rockfall Protection	Roadway Protective Betterments	Bridge(s)	
3 4305 3 4306	Yuba Pass SOH Bridge Replacement Acid Flats	Bridge Formula Program Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s)	
3 4309	Kingvale/Soda Springs Gutter	Major Damage (Permanent Restoration)	Location(s)	
3 4318	NEV 80 Accel & Aux Lanes	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	
		Improvements	Delay (DVHD)	
3 4319	Nev 80 Rehab Pavement	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	22
2 4210	Nev 80 Rehab Pavement	Improvements Pavement Preservation	Delay (DVHD) Lane mile(s)	
3 4319 3 4322	Floriston Safety Improvement	Safety Improvements	Collision(s) reduced	2
3 4325	Donner Summit SRRA ACP Replacement	Safety Roadside Rest Area Restoration	Location(s)	
3 4329	NEV 80 Rutting 1	Major Damage (Emergency Restoration)	Location(s)	3
3 4330	NEV 80 Rutting 2"	Major Damage (Emergency Restoration)	Location(s)	3
3 4331	NEV 80 Rutting 1 NEV 80 Rutting 2	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	1
3 4332	Nev-174 Relinquishment	Relinauishments	Centerline mile(s)	1 0
3 4451	SR-174 Safety Improvement Project	Safety Improvements	Collision(s) reduced	7
3 4453	NEV 174 Henderson Sinkhole	Major Damage (Emergency Opening)	Location(s)	
3 4454	2023 Snow Tree Damage	Major Damage (Emergency Opening)	Location(s)	1
3 4681	PLA-28 Rehab	Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	20
3 4681A 3 4681A	PLA-28 Rehab Combine PLA-28 Rehab Combine	Pavement Preservation (CAPM) Safety Improvements	Collision(s) reduced	20
3 4683	Truckee Storm Damaged Pavement	Major Damage (Emergency Restoration)	Location(s)	11
3 4781	Pla-49 Rehab Project	Roadway Rehabilitation	Lane mile(s)	18
3 4785	American Canyon Roundabout	Safety Improvements	Collision(s) reduced	- 8
3 4787	Placer 49 Safety Barrier	Safety Improvements Roadway Rehabilitation (2R)	Collision(s) reduced	7
3 4788 3 4803	Placer 49 2R ED 49 CAPM	Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	
3 4899	PLA 65 Ranch	Roadside Enhancement (Mitigation Site	Location(s)	
		Relinauishments)	(-)	
3 4901	High Friction and Open Grade Surface Treatments	Safety Improvements	Collision(s) reduced	1.5
3 4902 3 4943	Pla 65 South Ingram Slough Slide Repair SAC 99 Storm Damage.	Major Damage (Permanent Restoration) Major Damage (Emergency Restoration)	Location(s)	
3 5026	Placer MBGR Upgrade	Safety Enhancements	Collision(s) reduced	
3 5079	Colfax Culvert Rehabilitation	Drainage System Restoration	Culvert(s) (ea)	3
3 5097	PLA 80 Bridge Replacement	Bridge Rehabilitation	Bridge(s)	
3 5105	Culvert Rehab	Drainage System Restoration	Culvert(s) (ea)	3 10
3 5111	Soda Springs Pavement Rehabilitation Atlantic On-ramp Widening	Roadway Rehabilitation (2R) Non-Capacity Increasing Operational	Lane mile(s) Daily Vehicle Hour(s) of	56
			Delay (DVHD)	J
3 5113	Allarine of famp Maching	Improvements		
3 5113	Secret Town Culvert Rehabilitation	Improvements Drainage System Restoration	Culvert(s) (ea)	
3 5114 3 5131	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation	Drainage System Restoration Roadway Rehabilitation (2R)	Culvert(s) (ea) Lane mile(s)	13
3 5114 3 5131 3 5133	Secret Town Culvert Rehabilitation Blue Canvon Pavement Rehabilitation Monte Vista Pavement Rehabilitation	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R)	Culvert(s) (ea) Lane mile(s) Lane mile(s)	13 13
3 5114 3 5131 3 5133 3 5140	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s)	13 13
3 5114 3 5131 3 5133 3 5140 3 5141	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	13 13 31
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142	Secret Town Culvert Rehabilitation Blue Canvon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s)	13 13 31
3 5114 3 5131 3 5133 3 5140 3 5141	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea)	13 13 31
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5145 3 5149 3 5150	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation 1-80 CAPM Antelope to Sierra College	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damaae (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s)	13 13 31 35
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5145 3 5149 3 5150 3 5153	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation I-80 CAPM Antelope to Sierra College SAC 5 Slabs	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Opening)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	13 13 31 31 55 51
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5145 3 5145 3 5150 3 5153 3 5154	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation 1.80 CAPM Antelope to Sierra College SAC 5 Slabs Winter 2021 Debris and Tree Removal	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s)	13 13 31 31 55 51
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5145 3 5149 3 5150 3 5153	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rack Retention Fencina Placer 80 Rehabilitation I-80 CAPM Antelope to Sierra College SAC 5 Slobs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Opening)	Cuiver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Cuiver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Location(s)	13 13 31 31 55 51
3 5114 3 5131 3 5131 3 5131 3 5140 3 5141 3 5142 3 5145 3 5150 3 5154 3 5154 3 5157 3 5157 3 5157 3 5158 3 5159 3 5159	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Milimore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Rehabilitation Placer 80 Rehabilitation Placer 80 Rehabilitation Blacer 80 Rehabilitation Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Major Damage (Emergency Openina)	Cuiver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Cuiver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Location(s) Location(s) Location(s) Location(s) Location(s)	13 13 31 31 55 51
3 5114 3 5133 3 5133 3 5140 3 5141 3 5142 3 5145 3 5145 3 5149 3 5150 3 5153 3 5153 3 5154 3 5157 3 5158 3 5158 3 5159 3 5163	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Rehabilit	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration)	Cuivert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Cuivert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Location(s)	13 13 31 31 55 51
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5145 3 5154 3 5155 3 5155 3 5155 3 5155 3 5155 3 5155 3 5156 3 5163 3 5163	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation I-80 CAPM Antelope to Sierra College SAC 5 Slobs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Rutting 1 PLA 80 Rutting 1 PLA 80 Rutting 1 PLA 80 Rutting 1	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	13 13 31 55 55 51
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5145 3 5154 3 5155 3 5155 3 5155 3 5155 3 5155 3 5155 3 5156 3 5163 3 5163	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Rehabilit	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration)	Cuivert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Cuivert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Location(s)	13 13 31 55 51
3 5114 3 5131 3 5133 3 5140 3 5140 3 5142 3 5142 3 5153 3 5154 3 5157 3 5158 3 5159 3 5159 3 5163 3 5164 3 5165 3 5166	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Resource 80 Rehabilitation Placer 80 Rehabilitation Resource 80 Rehabilitation Placer 80 Rehabilitation Resource 80 Rehabilitation Placer 80 Storb Rehabilitation Resource 80 Rehabilitation Placer 80 Storb Rehabilitation Resource 80 Rehabilitation Placer 80 Storb Rehabilitation Placer 80 Storb Rehabilitation Placer 80 Storb Rehabilitation Placer 80 Rehabilitation Placer 80 Rehabilitation Rehabilitation Placer 80 Rehabilitation	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openinal) Maior Damage (Emergency Openinal) Maior Damage (Emergency Openinal) Maior Damage (Emergency Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration)	Cuiver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Cuiver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lacation(s) Lane mile(s) Lane mile(s) Lacation(s) Location(s)	133 133 31 555 51
3 5114 3 5131 3 5133 3 5140 3 5142 3 5145 3 5145 3 5153 3 5153 3 5153 3 5153 3 5153 3 5163 3 5164 3 5164 3 5166 3 5166	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Roberts and Tree Removal Roseville MS Structure Replacements Placer 80 Structure Replacements Placer 80 Open-Graded Placer 80 Ruttina 1 Placer 80 Ruttina 2 Placer 80 Ruttina 3 Placer 80 Ruttina 9 Placer 8	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Major Damace (Emeraency Openina) Major Damace (Emeraency Openina) Major Damace (Emeraency Openina) Major Damace (Emeraency Restoration) Major Damace (Permanent Restoration)	Cuivert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Cuivert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lacation(s) Location(s)	13 13 13 13 13 13 13 13 13 13 13 13 13 1
3 5114 3 5131 3 5133 3 5133 3 5141 3 5142 3 5145 3 5150 3 5155 3 5155 3 5157 3 5157 3 5156 3 5164 3 5164 3 5165 3 5164 3 5165 3 5165 3 5165	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Mante Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation I-80 CAPM Antelope to Sierra College SAC 5 Slobs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Strom Damage PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Sirkhina 3 PLA 80 Sirkhole & Culvert PLA/ED 89 Drainage Repairs	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Permanent Restoration) Maior Damage (Emergency Pestoration) Maior Damage (Emergency Pestoration) Maior Damage (Emergency Pestoration) Maior Damage (Emergency Opening)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	13 13 13 13 13 13 13 13 13 13 13 13 13 1
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5153 3 5153 3 5154 3 5153 3 5155 3 5156 3 5164 3 5164 3 5165 3 5165 3 5166 3 5171 3 5289	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Resource 80 Rehabilitation Placer 80 Structure Replacements Placer 80 Structure Replacements Placer 80 Structure Replacements Placer 80 Rehabilitation Placer 80 Rehabili	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Permanent Restoration) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina)	Cuiver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Cuiver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	133 133 131 131 131 131 131 131 131 131
3 5114 3 5131 3 5133 3 5134 3 5142 3 5142 3 5143 3 5153 3 5153 3 5153 3 5155 3 5158 3 5159 3 5164 3 5164 3 5165 3 5165 3 5166 3 5167 3 5167 3 5289 3 5299	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Place Sock Placer 80 Rehabilitation Place 80 Replacements Placer 80 Storm Damage Placer 80 Storm Damage Placer 80 Open-Graded Placer 80 Rutting 1 Placer 80 Rutting 1 Placer 80 Rutting 3 Placer 80 Rutting 40	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femeranent) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Restoration) Maior Damace (Emeranency Restoration) Maior Damace (Emeranency Restoration) Maior Damace (Emeranency Restoration) Maior Damace (Femeranent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emeranency Openina) Maior Pamace (Emeranency Openina) Maior Pamace (Emeranency Openina) Maior Pamace (Emeranency Openina)	Cuivert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Cuivert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	133 133 131 131 131 131 131 131 131 131
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5153 3 5153 3 5154 3 5159 3 5159 3 5164 3 5166 3 5167 3 5166 3 5167 3 5289 3 5292	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Rothina 1 Placer 80 Rothina 1 Placer 80 Ruttina 3 Plac	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damace (Fermanent Restoration) Maior Damace (Emeraency Openina) Maior Damace (Emeraency Openina) Maior Damace (Emeraency Openina) Maior Damace (Emeraency Restoration) Maior Damace (Emeraency Restoration) Maior Damace (Emeraency Restoration) Maior Damace (Emeraency Restoration) Maior Damace (Fermanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Fermanent Restoration) Maior Damace (Fermanent Restoration) Maior Damace (Emergency Openina) Pavement Preservation (CAPM) Maior Damaent Preservation (CAPM)	Cuivert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Cuivert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Location(s)	133 133 31 55 55 51 13
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5149 3 5150 3 5150 3 5155 3 5158 3 5159 3 5159 3 5159 3 5164 3 5165 3 5165 3 5165 3 5167 3 5167 3 5289 3 5290 3 5294 3 5728	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Place 80 Robert 80 Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Ruttina 3 PLA 80 Ruttina 3 PLA 80 Suttina 8 PLA	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Pavement Preservation (CAPM)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	13 13 31 55 55 51 12
3 5114 3 5131 3 5133 3 5143 3 5142 3 5142 3 5144 3 5145	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Isla CAPM Antelope to Siera College SAC 5 Slabs Winter 2021 Debris and Tree Removal Rosseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Ruttina 3 PLA 80 Sinkhole & Culvert PLA/ED 89 Drainage Repairs Tahoe Citly Housina Replacement SR 89 CAPM PLA 98 GAPM PLA 98 GACKfall PLA 267 CAPM Paintersville & Mokelumne Seismic Retrofit Yol Curb Ramp Upgrades	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Femeraency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Femergency Openina) Pavement Preservation (CAPM) Maior Damage (Femergency Openina) Pavement Preservation (CAPM) Bridge Seismic Restoration	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Loca	133 133 31 55 51 13
3 5114 3 5131 3 5133 3 5140 3 5141 3 5142 3 5149 3 5150 3 5150 3 5153 3 5153 3 5154 3 5155 3 5158 3 5159 3 5164 3 5165 3 5165 3 5167 3 5289 3 5290 3 5290 3 5294 3 5728	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Place 80 Robert 80 Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Ruttina 3 PLA 80 Ruttina 3 PLA 80 Suttina 8 PLA	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femeranent) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Restoration) Maior Damace (Femeranent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emeranency Openina) Pavement Preservation (CAPM) Maior Damace (Emeranency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s)	133 133 31 55 51 13
3 5114 3 5131 3 5133 3 5134 3 5141 3 5142 3 5145 3 5149 3 5155 3 5155 3 5155 3 5155 3 5155 3 5165 3 5166 3	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 90 Debris and Tree Remayal Roseville MS Structure Replacements PLA 80 Structure Replacements PLA 80 Structure Replacements PLA 80 Ruttina 2 PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Sinkhole & Culvert PLAFED 89 Drainage Repairs Tahae City Housina Replacement SR 87 CAPM PLA 287 CAPM PLA 287 CAPM PLA 287 CACAPM PLA 288 Catific & Moleculman Seismic Retrofit Yol Curb Ramp Upgrades Installation of fiber optic cable	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Femanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Bridge Seisnic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Locatio	133 133 313 555 515 133 143 177
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5153 3 5154 3 5154 3 5163 3 5163 3 5163 3 5164 3 5164 3 5164 3 5164 3 5164 3 5164 3 5164 3 5164 3 5164 3 5166 3 5171 3 5289 3 5292 3 5228 3 5832 3 5832	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Isla CAPM Antelope to Siera College SAC 5 Slabs Winter 2021 Debris and Tree Removal Rosseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Ruttina 3 PLA 80 Sinkhole & Culvert PLA/ED 89 Drainage Repairs Tahoe Citly Housina Replacement SR 89 CAPM PLA 98 GAPM PLA 98 GACKfall PLA 267 CAPM Paintersville & Mokelumne Seismic Retrofit Yol Curb Ramp Upgrades	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femeranent) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Restoration) Maior Damace (Femeranent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emeranency Openina) Pavement Preservation (CAPM) Maior Damace (Emeranency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Loca	133 133 313 555 515 133 143 177
3 5114 3 5131 3 5133 3 5134 3 5142 3 5145 3 5149 3 5157 3 5157 3 5158 3 5157 3 5158 3 5165 3	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 90 Debris and Tree Remayal Roseville MS Structure Replacements PLA 80 Structure Replacements PLA 80 Structure Replacements PLA 80 Ruttina 2 PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Sinkhole & Culvert PLAFED 89 Drainage Repairs Tahae City Housina Replacement SR 87 CAPM PLA 287 CAPM PLA 287 CAPM PLA 287 CACAPM PLA 288 Catific & Moleculman Seismic Retrofit Yol Curb Ramp Upgrades Installation of fiber optic cable	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Femanent Restoration) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Locatio	13 13 31 55 55 51 12
3 5114 3 5131 3 5133 3 5133 3 5141 3 5142 3 5142 3 5149 3 5153 3 5153 3 5153 3 5154 3 5155 3 5154 3 5159 3 5159 3 5164 3 5166 3 5167 3 5167 3 5167 3 5289 3 5292 3 5294 3 5294 3 5846	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Roseville Mos Structure Replacements Placer 80 Roseville Mos Structure Replacements Placer 80 Rottlina 3 Placer 80 Ruttina 3 Placer 80 Ruttina 3 Placer 80 Ruttina 3 Placer 80 Rottlina 3 Placer 80	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emercency Openina) Tensportation (CAPM) Maior Damace (Emercency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment)	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Lone mile(s) Lone mile(s) Bridae(s) Curb ramp(s) Field element(s) Field element(s)	13 13 31 55 55 51 12
3 5114 3 5131 3 5133 3 5134 3 5142 3 5142 3 5145 3 5149 3 5155 3 5155 3 5155 3 5155 3 5155 3 5156 3 5156 3 5155 3 5165 3 5165 3 5165 3 5165 3 5165 3 5165 3 5165 3 5165 3 5166 3 5166	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencing Placer 80 Rehabilitation 180 CAPM Antelope to Sierra College SAC 5 Slabs Winter 2021 Debris and Tree Remayal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Suttina 3 PLA 80 Sinkhole & Culvert PLAFED 89 Drainage Repairs Tahoe City Housina Replacement SR 89 CAPM PLA 99 Posickfall PLA 267 CAPM PLA 99 Pointerage Repairs Toloc Urb Ramp Upgrades Installation of fiber optic cable Elkhorn SRRA Upgrades	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Fermanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Iransportation Management (TMC's & Field Equipment) Iransportation Management (TMC's & Field Equipment) Roadside Safety Improvements	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culver(s) (ea) Location(s) Field element(s) Field element(s) Field element(s)	133 133 31 5 555 51 13
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5153 3 5153 3 5153 3 5154 3 5163 3 5163 3 5163 3 5164 3 5164 3 5165 3 5163 3 5164 3 5165 3 5165 3 5166 3 5166	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmare Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation 180 CAPM Antelope to Sierra College SAC 5 Slabs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Sintina 2 PLA 80 Sinchole & Culvert PLA/ED 89 Drainage Repairs Talohoe City Housina Replacement SR 89 CAPM PLA 89 Rockfall PLA 267 CAPM Paintersville & Mokelumne Seismic Retrofit Yol Curb Ramp Uparades Installation of fiber optic cable Elkhorn SRRA Upgrades Uparade MBGR Sac 5-80-99 Var	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damace (Permanent Restoration) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Maior Damace (Emergency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femergency Assoration) Maior Damace (Emergency Openina) Maior Damace (Emergency Nopenina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced	13 13 31 55 51 1:
3 5114 3 5131 3 5133 3 5133 3 5141 3 5142 3 5142 3 5153 3 5153 3 5153 3 5154 3 5153 3 5153 3 5154 3 5153 3 5155 3 5164 3 5165 3 5166 3 5167 3 5167 3 5289 3 5289 3 5292 3 5294 3 5833 3 5846 3 5846 3 5846 3 5846	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Robert 80 Replacements Placer 80 Robert 80 Replacements Placer 80 Structure Replacements Placer 80 Structure Replacements Placer 80 Robert 80 Ro	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damace (Femeraency Openina) Maior Damace (Emeraency Openina) Maior Damace (Emeraency Openina) Maior Damace (Emeraency Openina) Maior Damace (Emeraency Restoration) Maior Damace (Emeraency Restoration) Maior Damace (Emeraency Restoration) Maior Damace (Emeraency Restoration) Maior Damace (Femeraency Openina) Maior Damace (Femeraency Openina) Maior Damace (Emeraency Openina) Pavement Preservation (CAPM) Maior Damace (Emeraency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements Safety Enhancements HOV/HOT lane-mile(s) constructed	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Field element(s) Field element(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	13 13 31 55 55 51 12
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5154 3 5153 3 5154 3 5153 3 5154 3 5153 3 5154 3 5163 3 5164 3 5164 3 5164 3 5164 3 5164 3 5164 3 5165 3 5171 3 5290 3 5292 3 5284 3 5846 3 5846 3 5846 3 5846 3 5846 3 5846 3 5848 3 5854A 3 5854A 3 5853 3 5154 3 5155 3 5164 3 5164 3 5164 3 5164 3 5164 3 5165 3 5166 3 51	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation 180 CAPM Antelope to Sierra College SAC 5 Slabs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Swittina 3 PLA 80 Sinkhole & Culvert PLA/ED 89 Drainage Repairs Talohe Citly Housina Replacement SR 89 CAPM PLA 98 CAPM PLA 98 CAPM Pointersville & Mokelumne Seismic Retrofit Yol Curb Ramp Upgrades Installation of fiber optic cable Elkhorn SRRA Upgrades Ubarade MBGR Sac 5-80-99 Var Sac 5 Corridor Enhancement Project	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damace (Permanent Restoration) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Maior Damace (Emergency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femergency Assoration) Maior Damace (Emergency Openina) Maior Damace (Emergency Nopenina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Curb ramp(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Milles Lane mile(s)	133 133 313 555 51 13
3 5114 3 5133 3 5133 3 5143 3 5142 3 5142 3 5145 5147 51	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Robert 80 Replacements Placer 80 Robert 80 Replacements Placer 80 Structure Replacements Placer 80 Structure Replacements Placer 80 Robert 80 Ro	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Femanent Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Iransportation Management (TMC's & Field Equipment) Iransportation Management (TMC's & Field Equipment) Roadside Safety Improvements Safety Enhancements HOV/HOI Tone-mile(s) constructed Roadway Rehabilitation (3R) Safety Improvements	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Curb ramp(s) Field element(s) Field element(s) Field element(s) Location(s)	13, 13, 13, 13, 13, 13, 13, 14, 15, 15, 15, 15, 15, 15, 15, 15, 15, 17, 17, 17, 17, 17, 17, 17, 17, 17, 18, 11, 11, 11, 11, 11, 11, 11, 11, 11
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5153 3 5153 3 5154 3 5159 3 5155 3 5164 3 5165 3 5166 3 5167 3 5289 3 5292 3 5292 3 5293 3 5833 3 5846 3 5848 3 5848 3 5854A 3 5854A 3 5854A 3 5854A 3 5854A 3 5133 3 5154 3 5165 3 5167 3 5289 3 5292 3 5292 3 5293 3 5833 3 5846 3 5848 3 5854A 3 5854A 3 5854A 3 5854A	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Rehabilit	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femeranent) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emeranency Openina) Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements Sofety Enhancements HOV/HOT Iane-mile(s) constructed Roadway Rehabilitation (SR)	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Lother mile(s) Bridae(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Miles Lane mile(s) Location(s) Location(13, 13, 13, 13, 13, 13, 13, 14, 15, 15, 15, 15, 15, 15, 15, 15, 15, 17, 17, 17, 17, 17, 17, 17, 17, 17, 18, 11, 11, 11, 11, 11, 11, 11, 11, 11
3 5114 3 5131 3 5133 3 5134 3 5141 3 5142 3 5149 3 5155 3 5155 3 5155 3 5155 3 5155 3 5164 3 5165 3 5166 3 5167 3 5166 3 5167 3 5289 3 5292 3 5294 3 5294 3 5846 3 5846 3 5846 3 5846 3 5854 3 5854	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebav Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Replacements Placer 80 Responsion Placer 80 Structure Replacements Placer 80 Structure Replacements Placer 80 Open-Graded Placer 80 Rottlina 1 Placer 80 Rottlina 1 Placer 80 Ruttlina 2 Placer 80 Ruttlina 3 P	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Maior Damace (Emergency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Pavement Preservation (CAPM) Maior Damace (Emergency Openina) Pavement (TMC's & Field Equipment) Roadside Safety Improvements Safety Enhancements HOV/HOT Iane-mile(s) constructed Roadway Rehabilitation (SR) Sofety Improvements Sound wall mile(s) constructed	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Lane mile(s) Field element(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Miles Mile(s) of cable	13, 13, 13, 13, 13, 13, 13, 13, 14, 15, 15, 15, 15, 15, 15, 15, 15, 15, 15
3 5114 3 5131 3 5133 3 5143 3 5144 3 5144 3 5144 3 5145 3 5149 3 5153 3 5153 3 5153 3 5155 3 5156 3 5163 3 5164 3 5164 3 5166 3	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation 180 CAPM Antelope to Sierra College SAC 5 Slabs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Storm Damage PLA 80 Open-Graded PLA 80 Ruttina 1 PLA 80 Ruttina 2 PLA 80 Ruttina 2 PLA 80 Ruttina 3 PLA 80 Suttina 3 PLA 80 Sinkhole & Culvert PLA/ED 89 Drainage Repairs Tanbee City Housina Replacement SR 89 CAPM PLA 98 Pockfall PLA 267 CAPM Paintersville & Mokelumne Seismic Retrofit Yol Curb Ramp Upgrades Installation of fiber optic cable Elkhorn SRRA Upgrades Uparade MBGR Sac 5-80-99 Var Sac 5 Corridor Enhancement Project	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emeraency Openina) Maior Damage (Emeraency Openina) Maior Damage (Emeraency Openina) Maior Damage (Emeraency Openina) Maior Damage (Emeraency Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Permanent Restoration) Maior Damage (Emeraency Restoration) Maior Damage (Emeraency Restoration) Maior Damage (Emeraency Restoration) Maior Damage (Emeraency Openina) Maior Damage (Emeraency Openina) Maior Damage (Emeraency Openina) Pavement Preservation (CAPM) Maior Damage (Emeraency Openina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements Sofety Enhancements HOV/HOT lane-mile(s) constructed Roadway Rehabilitation (SR) Safety Improvements Sound wall mile(s) constructed Transportation Management (Fiber Optic Cable) Pavement Preservation (CAPM)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Curb ramp(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Miles Lane mile(s) Mile(s) of cable Lane mile(s)	133 133 133 131 13 131 13 131 13 131 14 15 17 17 19 19 11 11 11 11 11 11 12 00 11
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5149 3 5153 3 5153 3 5153 3 5153 3 5154 3 5153 3 5153 3 5163 3 5164 3 5164 3 5167 3 5167 3 5188 3 5167 3 5188 3 5167 3 5289 3 5292 3 5292 3 5294 3 5893 3 5884 3 5846 3 5846 3 5846 3 5854A 3 5854A 3 5854A 3 58554 3 58554	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Placer 80 Rehabilit	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Femeranent) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Openina) Maior Damace (Emeranency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emeranency Openina) Pavement Preservation (CAPM) Maior Damace (Emeranency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements Softey Enhancements HOV/HOT Iane-mile(s) constructed Roadway Rehabilitation (SR) Safety Improvements Sound wall mile(s) constructed Transportation Management (Fiber Optic Cable)	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Cultison(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Miles Lane mile(s) Collision(s) reduced Miles Mile(s) of cable Lane mile(s) Bridae(s)	13, 13, 13, 13, 13, 13, 13, 13, 13, 13,
3 5114 3 5131 3 5133 3 5143 3 5144 3 5144 3 5145 3 5145 3 5153 3 5155 3 5156 3 5156 3 5156 3 5164 3 5164 3 5165 3 5165 3 5166 3	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencing Placer 80 Rehabilitation 180 CAPM Antelope to Sierra College SAC 5 Slabs Winter 2021 Debris and Tree Removal Roseville MS Structure Replacements PLA 80 Storm Damage PLA 80 Storm Damage PLA 80 Rottling 1 PLA 80 Rutting 2 PLA 80 Rutting 2 PLA 80 Rutting 2 PLA 80 Rutting 3 PLA 80 Sinkhole & Culvert PLAFED 89 Drainage Repairs Tahoe City Housing Replacement SR 89 CAPM PLA 98 PCAPM PLA 98 Poscifall PLA 267 CAPM PLA 98 Poscifall PLA 267 CAPM PLA 99 Drainage Repairs Installation of fiber optic cable Installation of fiber optic cable Installation of fiber optic cable Elkhorn SRRA Upgrades Upgrade MBGR Sac 5-80-99 Var Sac 5 Corridor Enhancement Project	Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Bridge Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment)	Culver(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Culvertex Field element(s) Field element(s) Field element(s) Collision(s) reduced Miles Location(s) Loc	13, 13, 13, 13, 13, 13, 13, 13, 13, 13,
3 5114 3 5131 3 5133 3 5134 3 5145 3 5145 3 5145 3 5145 3 5145 3 5145 3 5145 3 5145 3 5157 3 5158 3 5157 3 5158 3 5164 3 5165	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Mante Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Refention Fencina Placer 80 Rehabilitation Placer 80 Replacements Placer 80 Replacements Placer 80 Robert 80 Replacements Placer 80 Robert 80	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damace Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Permanent Restoration) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Maior Damace (Emercency Openina) Pavement Preservation (CAPM) Maior Damace (Emercency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment)	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Lane mile(s) Bridae(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Miles Mile(s) of cable Lane mile(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s)	13, 13, 13, 13, 13, 13, 13, 14, 15, 15, 15, 15, 15, 15, 15, 15, 17, 17, 17, 17, 17, 17, 17, 17, 17, 17
3 5114 3 5131 3 5133 3 5133 3 5140 3 5141 3 5142 3 5149 3 5153 3 5153 3 5154 3 5154 3 5154 3 5158 3 5154 3 5158 3 5164 3 5164 3 5166 3	Secret Town Culvert Rehabilitation Blue Canyon Pavement Rehabilitation Monte Vista Pavement Rehabilitation Monte Vista Pavement Rehabilitation Alta CAPM Whitmore Maintenance Station Rehab Drum Forebay Drainage Restoration PLA 80 Rock Retention Fencina Placer 80 Rehabilitation Resource 80 Removal Resource 80 Resource 90 Removal Resource 80 Resource 80 Removal Resource 80 Removal Resource 80 Removal Resource 80 Resource 80 Removal Resource 80 Removal Resource 80 Resource 80 Removal Resource 80 Resource 80 Removal Resource 80 Resource 80 Resource 80 Resource 90 R	Drainace System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maintenance Facilities Drainace System Restoration Maior Damaae (Permanent Restoration) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Maior Damaae (Emeraency Openina) Maior Damaae (Emeraency Openina) Maior Damaae (Emeraency Openina) Maior Damaae (Emeraency Openina) Maior Damaae (Emeraency Restoration) Maior Damaae (Permanent Restoration) Maior Damaae (Permanent Restoration) Maior Damaae (Permanent Restoration) Maior Damaae (Permanent Restoration) Maior Damaae (Emeraency Openina) Tonaparae (Emeraency Openina) Pavement Preservation (CAPM) Bridae Seismic Restoration ADA - New Curb Ramps Transportation Management (TMC's & Field Equipment) Transportation Management (TMC's & Field Equipment) Roadside Safety Improvements Safety Enhancements HOV/HOT Iane-mile(s) constructed Roadway Rehabilitation (SR) Safety Improvements Sound wall mile(s) constructed Transportation Management (Fiber Optic Cable)	Culvert(s) (ea) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Culvert(s) (ea) Location(s) Curb ramp(s) Field element(s) Field element(s) Field element(s) Collision(s) reduced Mile(s) Location(s) Collision(s) reduced Mile(s) Mile(s) Bridge(s) Bridge(s)	2: 13. 13. 13. 13. 13. 13. 13. 13. 13. 13.

2 5072	CAC C O COCIAL Daylor work	Literia Danner (Farance Consider)	1	0
3 5873 3 5874	SAC 5 & 50 Slab Replacement Three Mile Slough Emergency	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	
3 5875	Arena Blvd Grassland Fire	Major Damage (Emergency Opening)	Location(s)	i
3 5881	I-5 Grade Raise	SHOPP - Sustainability and Miscellaneous Safety Improvements	Centerline mile(s)	4.4
3 5884	SAC-5 Vision Zero Acceleration Lane	safety improvements	Annual fatal and serious injury collision(s)	0.2
3 5887 3 5888	SAC 5 Garden Hwy SAC 5 Garden Hwy	Major Damage (Emergency Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	3
3 5960	Rio Vista Bridge Rehab	Bridge Rehabilitation and Replacement	Bridge(s)	<u>5</u>
3 5961	Hwy 12/160 Intersection Improvements	Safety Improvements	Collision(s) reduced	26
3 5962	Rio Vista Drawbridge Emergency	Major Damage (Emergency Opening)	Location(s)	1
3 5963	SAC-12 Terminous Safety	Safety Improvements	Annual fatal and serious injury collision(s)	0.9
3 5964	Jackson Slough Road Intersection Improvement	Safety Improvements	Annual fatal and serious	0.5
			injury collision(s)	
3 5965	Rio Vista Bridge Op-Systems Upgrade	Major Damage (Permanent Restoration)	Location(s)	1
3 6003 3 6177	Eagles Nest Safety Project Sac 50 - Rehab Pavement	Safety Improvements Roadway Rehabilitation	Collision(s) reduced Lane mile(s)	53.6
3 6197	SAC 50 AUX LANES	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	143
0 (000		Improvements	Delay (DVHD)	100
3 6200	Sac 50, 65th to Howe Aux Lane	Non-Capacity Increasing Operational Improvements	Daily Vehicle Hour(s) of Delay (DVHD)	108
3 6239	Sac 50 Fiber Optics	Transportation Management (TMC's & Field	Field element(s)	8.6
2 (242	Harant Divin Off Dames Improvement	Equipment)	Daily Vahiala Hayrish of	2740
3 6242	Hornet Drive Off Ramp Improvement	Non-Capacity Increasing Operational Improvements	Daily Vehicle Hour(s) of Delay (DVHD)	2/40
3 6246	Sac Roadside Safety	Roadside Safety Improvements	Location(s)	76
3 6247	Sac 50 Paint	Capital Bridge Preventative Maintenance Program	Bridge(s)	11
3 6248	Sac/ED Fiber Optics	Transportation Management (Fiber Optic Cable)	Mile(s) of cable	3.5
3 6250 3 6254	US 50 ICM Infrastructure Sac 50 Design-Build	Transportation Management Systems HOV/HOT lane-mile(s) constructed	Field element(s) Miles	79 14
3 6254	Sac 50 Design-Build	Roadway Rehabilitation (3R)	Lane mile(s)	53.6
3 6254	Sac 50 Design-Build	Sound wall mile(s) constructed	Miles	2.4
3 6255 3 6256	TMC Rehab Emergency Pump Repair	Maintenance Facilities Major Damage (Emergency Opening)	Location(s) Location(s)	1
3 6257	Multi Location Bike Ped Improvements	Safety Improvements	Collision(s) reduced	0
3 6257A	Chico Green Bike Lane Loc 1	Safety Improvements	Collision(s) reduced	5
3 6257B 3 6257C	Tahoe City Rehab Loc 2 Bike & Ped Improvements	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	2
3 6258	Pioneer Bridge Damage	Major Damage (Emergency Opening)	Location(s)	7
3 6265	SAC Translab HVAC repair	Major Damage (Permanent Restoration)	Location(s)	1
3 6402 3 6402A	American River Bridge Rehabilitation SR-51 ARB Child Project (CP1)	Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s)	2
3 6402A 3 6402B	SR-51 ARB Child Project (CP1) SR-51 ARB Child Project (CP2)	Bridge Rehabilitation and Replacement	Bridge(s)	0
3 6402C	SR-51 ARB Child Project (CP3)	Bridge Rehabilitation and Replacement	Bridge(s)	0
3 6411	SAC Connector Ramp Meters	Transportation Management (TMC's & Field	Field element(s)	4
3 6412	SAC 51/80	Equipment) Bridge Rail Replacement/Upgrade	Linear feet	4413
3 6413	SAC 51 Roadside Safety	Roadside Safety Improvements	Location(s)	53
3 6414	Marconi Curve Barrier	Collision Severity Reduction	Collision(s) reduced	6
3 6416 3 6418	SAC 51 Fort Sutter SAC 51 Marconi Bridge Rail	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	1
3 6419	SAC-51 Outer Separation Barrier	Safety Improvements	Annual fatal and serious	0.16
			injury collision(s)	
3 6689X	I-80 Across the Top	Roadway Rehabilitation (3R)	Lane mile(s)	8
3 6701	Install Ramp Meters	Transportation Management (TMC's & Field	Field element(s)	4
0 (707	California Dados (H	Equipment)	Drieland (a)	0
3 6707 3 6711	Seismic Retrofit Rehabilitate Connection Ramp Pavement at var. locations	Bridge Seismic Restoration Pavement Rehabilitation	Bridge(s) Lane mile(s)	0.1
3 6712	ANTELOPE TRUCK SCALES	Weight Stations & Weight-In-Motion Facilities	Location(s)	2
3 6713	Sac/Placer 80 Fiber Optics	Transportation Management (Fiber Optic Cable)	Mile(s) of cable	18.4
3 6714	SAC 80 R&R RHMA	Pavement Rehabilitation	Lane mile(s)	31.4
3 6715	Maintenance safety improvement Watt to Placer Co. line	Roadside Safety Improvements	Location(s)	67
3 6716 3 6716A	Maintenance safety improvement Roseville rd U/C to 80/Bus 80 merge	Roadside Safety Improvements Roadside Safety Improvements	Location(s)	49 111
3 6716A	SAC 80 Roadside Safety Repair Loop Detectors	Transportation Management (TMC's & Field	Location(s) Field element(s)	300
		Equipment)	.,	
3 6717A	Repair Loop Detectors and Field Elements	Transportation Management (TMC's & Field	Field element(s)	338
3 6721	SAC 80 - Planting Rehab	Eauipmentl Roadside Rehabilitation	Acre(s)	10
3 6722	Var Loc OGAC HFST	Safety Improvements	Collision(s) reduced	262
3 6728 3 6912	Security Measures at Maintenance Station 1 Cosumnes Bridge Replc	Maintenance Facilities Bridge Rail Replacement/Upgrade	Location(s) Linear feet rail	5946
3 6912A	McConnel OH Fill	Bridge Rail Replacement/Upgrade	Linear feet	0
3 6912B	Temp River Bridge Foundations	Bridge Rail Replacement/Upgrade	Linear feet	0
3 6912C 3 6912D	McConnel OH Pre-cast Girders McConnell OH	Bridge Rail Replacement/Upgrade Bridge Rail Replacement/Upgrade	Linear feet rail Linear feet rail	0
3 6912E	Temp River Bridges	Bridge Rail Replacement/Upgrade	Linear feet	0
3 6912F	River Bridges	Bridge Rail Replacement/Upgrade	Linear feet rail	0
3 6916 3 6923	Lagoon Creek and American River Bridge Sawmill UC	Bridge Scour Bridge Rehabilitation	Bridge(s) Bridge(s)	1
3 6923B	21st Ave UC	Bridge Rehabilitation	Bridge(s)	1
3 6924	RHMA Overlay-ADA ramps/sw	Pavement Rehabilitation	Lane mile(s)	70.5
3 6925	Sac 99 Fiber Optics	Transportation Management (Fiber Optic Cable)	Mile(s) of cable	14
3 6930	SR 99 Aux Lanes Elk Grove Blvd to Calvine	Operational Improvements	Daily vehicle hour(s) of	298
2 (001	Sac 99 En litridge CADAA	Payament Process CARLS	delay (DVHD)	0.0
3 6931 3 6932	Sac 99 Fruitridge CAPM SAC 99/51 Pump Plant Project	Pavement Preservation (CAPM) Drainage System Restoration	Lane mile(s) Pump plant(s) (ea)	24.8
3 6933	2nd Ave UC Deck Repair	Major Damage (Emergency Opening)	Location(s)	1
3 6934	Bike ADA Safety Improvements	Safety Improvements	Collision(s) reduced	7
3 6936 3 6942	Willow Slough Replacement Bicyclist & Pedestrian Improvements	Bridge Rehabilitation and Replacement Safety Improvements	Bridge(s) Annual fatal and serious	0.19
3 0742	Sieyensi a i edesinari improventettis	Salary improvements	injury collision(s)	0.19
0 (CD 00 County Delice	CHOPP Code of The		-
3 6944 3 7295	SR-99 Grade Raise Safety Lighting - NB Off to Del Paso	SHOPP - Sustainability and Miscellaneous Safety Improvements	Centerline mile(s) Annual fatal and serious	2.3 0.09
3 / 273	caser, agrining The On To Bort 030	Salary improvements	injury collision(s)	0.09
3 7297 3 7298	SAC 160 Sinkhole Delta Bridges M/E upgrade 2	Major Damage (Emergency Opening) Major Damage (Permanent Restoration)	Location(s) Location(s)	
3 7778	Upgrade MBGR	Safety Enhancements	Collision(s) reduced	16
-			-	

2 7007	Makeroniala Curus	Cofeb Japanes Coments	Callisian (s) sadvand	10
3 7807 3 7809	Motorcycle Curve Yuba River Washouts	Safety Improvements Major Damage (Permanent Restoration)	Collision(s) reduced Location(s)	12
3 7812	SIE 49 Depot Hill Slipout	Major Damage (Emergency Opening)	Location(s)	
3 7813	SIE 49 Coyote Ravine Sinkhole	Major Damage (Emergency Opening)	Location(s)	1
3 7815 3 7816	SIE 49 Spring St Culvert SIE 49 Failed Retaining Wall	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	1
3 7926	Stateline 80 Rock Fall Protection	Roadway Protective Betterments	Bridge(s)	ì
3 7926A	Rock Fall Protection	Roadway Protective Betterments	Location(s)	2
3 8010 3 8028	SIE 89 Wildlife Xing Repair State Route 89 Henness Pass CAPM	Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Lane mile(s)	30.3
3 8132	Sutter Bypass Widening & Rehab	Roadway Rehabilitation	Lane mile(s)	13.5
3 8140	Feather River Scour	Bridge Scour	Bridge(s)	1
3 8145 3 8146	Scour Mitigation at various locations	Bridge Scour Safety Improvements	Bridge(s)	9
3 0146	Stafford Way Intersection Safety Improvement	salely improvements	Annual fatal and serious injury collision(s)	0.63
			ii ijo: y comsici i(s)	
3 8147	Humphrey Road Intersection Improvement	Safety Improvements	Annual fatal and serious	0.1
			injury collision(s)	
3 8153	SUT 99 2R	Roadway Rehabilitation (2R)	Lane mile(s)	19
3 8376A	Live Oak Streetscape, Rehab & Safety	Roadway Rehabilitation	Lane mile(s)	3.2
3 8376A 3 8378	Live Oak Streetscape, Rehab & Safety Live Oak Rehab	Safety Improvements Roadway Rehabilitation	Collision(s) reduced Lane mile(s)	51 3.2
3 8380	Habitiat Advanced Mitigation	Roadside Enhancement (Mitigation Site	Location(s)	9.2
		Relinauishments)		
3 8381	Live Oak Safety SR 99 Oswald Rd	Safety Improvements Safety Improvements	Collision(s) reduced	51 0.28
3 8383	Sk 99 Oswald kd	salely improvements	Annual fatal and serious injury collision(s)	0.26
			injury comsion(s)	
3 8385	SUT-99 Lomo Crossing	Safety Improvements	Collision(s) reduced	57
3 8386 3 8508	Queens PP Jennings/Knights Curve Improvement	Major Damage (Emergency Opening) Safety Improvements	Location(s) Annual fatal and serious	0.24
3 0300	Jennings/knights colve improvement	Screty improvements	injury collision(s)	0.24
3 8563 3 8571	I-5 Vertical Clearance (Yolo) AVC REPAIR & INSTALL	Trans Permit Requirements for Bridges Transportation Management (TMC's & Field	Bridge(s) Field element(s)	3 51
3 05/1	AYO NEI AIR & INSTALL	Eauioment)	riaid elemetri(s)	51
3 8572	I-5 Roadside Safety Improvements	Roadside Safety Improvements	Location(s)	32
3 8574	Elkhorn Bridge Debris Removal	Major Damage (Emergency Opening)	Location(s)	
3 8576 3 8578	Failed Culvert Yolo 5 Dunnigan 5 Rehab	Major Damage (Emergency Opening) Pavement Preservation (CAPM)	Lane mile(s)	24.7
3 8663	Esparto	Safety Enhancements	Collision(s) reduced	6
3 8663A	Capay	Safety Enhancements	Collision(s) reduced	2
3 8668 3 8669	Rumsey Slide Yolo 16/505 Debris Cleanup	Major Damage (Permanent Restoration) Major Damage (Emergency Opening)	Location(s) Location(s)	1
3 8671	Cache Creek Rehab	Roadway Rehabilitation (3R)	Lane mile(s)	10.8
3 8672	County Road 95 Intersection Improvement	Safety Improvements	Annual fatal and serious	0.05
			injury collision(s)	
3 8678	Woodland 16 Rehab	Roadway Rehabilitation (3R)	Lane mile(s)	5.6
3 8679	Yol-16 Vision Zero Shoulder Widening	Safety Improvements	Annual fatal and serious	0.23
			injury collision(s)	
3 8784	Yolo Pavement Rehab	Roadway Rehabilitation (3R)	Lane mile(s)	48.1
3 8788	YOL & SAC Trash BMP Project (IIJA)	Storm Water Mitigation	Acre(s)	200.6
			treated/pollutant	
3 8901 3 8920	Sac River BOH (Bryte Bend) Repair Field Elements	Bridge Rehabilitation Transportation Management (TMC's & Field	Bridge(s) Field element(s)	
0 0720	Repull Floid Elements	Equipment)	ricia dicinicin(s)	40
3 9058	YOL-84 Rehab Pavement	Major Damage (Permanent Restoration)	Location(s)	1
3 9307 3 9427	YOL 128 Slipouts Yol-275 Tower Br Fender Replc	Major Damage (Emergency Restoration) Bridge Rehabilitation	Location(s) Bridge(s)	2
3 9504	Putah Creek	Bridge Seismic Restoration	Bridge(s)	2
3 9579	Browns Valley Rehab	Roadway Rehabilitation (3R)	Lane mile(s)	9.9
3 9587	Loma Rica Rd./Spring Valley Road Widening & Rehab	Roadway Rehabilitation Safety Enhancements	Lane mile(s)	4.4
3 9590 3 9683	Timbuctoo Camptonville Slide Repair	Major Damage (Permanent Restoration)	Collision(s) reduced Location(s)	367
3 9684	YUB 49 Culvert Repair	Major Damage (Emergency Opening)	Location(s)	i
3 9732	Wheatland Donut Hole HMA and ADA	Pavement Preservation (CAPM)	Lane mile(s)	2.5
3 9733 3 9734	YUB 65 CAPM & Drainage McGowan Pump Plant	Pavement Preservation (CAPM) Major Damage (Emergency Opening)	Lane mile(s)	21.5
3 9812	Simmerly Slough (SHOPP)	Bridge Scour	Bridge(s)	i
3 9819	Yuba 70 Safety Segment 4 & 5 SHOPP	Safety Improvements	Collision(s) reduced	
3 9820 3 9820A	Marysville Railroad Bridge Rehab (SHOPP) CP1 Pump Plant	Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	2.3
3 9821	YUB 70 Median Barrier	Safety Enhancements	Collision(s) reduced	3
3 9822	YUB 70 Bridge Widening and Rail Replc	Bridge Rail Replacement/Upgrade	Linear feet rail	808
3 9827 3 9828	SR 70 Olivehurst Ave OC Bridge Hit Repairs YUB-SUT Campfire Debris Removal Pavement Damage Restoration	Major Damage (Emergency Opening) Major Damage (Permanent Restoration)	Location(s) Location(s)	
3 9830	Yuba 70 Laurellen to Butte County Line SHOPP & STIP Combine (SEG 4&5)	Passing lane mile(s) constructed	Miles	19.2
3 9830	Yuba 70 Laurellen to Butte County Line SHOPP & STIP Combine (SEG 4&5)	Safety Improvements	Collision(s) reduced	80
3 9833 3 9834	Security Measures at Maintenance Stations 2	Maintenance Facilities Maintenance Facilities	Location(s) Location(s)	4
3 9834 4 0012B	Marysville Hotel Fire FPI-Ramp Metering on 1880(Auto Mall-Mowry) & SR84(Thornton-Newark Blvd	Major Damage (Emergency Restoration) Transportation Management (TMC's & Field	Field element(s)	<u></u>
		Equipment)	7.7	
4 0044Q	Ala 880 Roadway Rehabilitation Project	Roadway Rehabilitation	Lane mile(s)	3.9
4 0050N 4 0064A	Lake Merritt Railroad Bridge Replacement Install 26 Miles of Fiber Optics Trunk Line, Hubs and TOS/TM\$ Elements	Bridge Rehabilitation and Replacement Transportation Management Systems	Bridge(s) Field element(s)	30
4 0076B	NILES CANYON SAFETY PROJECT (MEDIUM TERM IMPROVEMENTS)	Safety Improvements	Collision(s) reduced	90
4 0084B	NILES CANYON ALAMEDA CREEK BRIDGE REPLACEMENT PROJECT	Bridge Rehabilitation and Replacement	Bridge(s)	1
4 0086Q	CRANDALL CREEK SEISMIC RETROFIT BRIDGE #33-0273 Scofield Ave UC Seismic Retrofit CMGC	Bridge Seismic Restoration Bridge Seismic Restoration	Bridge(s) Bridge(s)	1
				0
4 0086R 4 0086S	Scofield Ave UC Seismic Retrofit CMGC	Bridge Seismic Restoration	Bridge(s)	
4 0086R		Bridge Seismic Restoration Capital Bridge Preventative Maintenance Program	Bridge(s)	1
4 0086R 4 0086S 4 0086U	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders.	Capital Bridge Preventative Maintenance Program	Bridge(s)	1
4 0086R 4 0086S	Scofield Ave UC Seismic Retrofit CMGC			30 15
4 0086R 4 0086S 4 0086U 4 0091P	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure	Bridge(s) Curb ramp(s)	
4 0086R 4 0086S 4 0086U 4 0091P 4 0124L 4 0124M	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY)	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s)	15 40
4 0086R 4 0086S 4 0086U 4 0091P 4 0124L 4 0124M	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY) UPGRADE CURB RAMPS/SIDEWALKS DOMINGO AVE TO MABEL ST	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s)	15 40 16
4 0086R 4 0086S 4 0086U 4 0091P 4 0124L 4 0124M	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY)	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s)	15 40
4 0086K 4 0086U 4 0086U 4 0091P 4 0124L 4 0124M 4 0135A 4 0144A 4 0222F	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY) UPGRADE CURB RAMPS/SIDEWALKS DOMINGO AVE TO MABEL ST Rte. 580 Rehab- Grind & Pave Roadway: Guard Rail; ADA Curbs @ Ramps UPGRADE CURB RAMPS/SIDEWALKS HILLER DR TO CLAREMONT AVE BRIDGE DECK PROGRAM	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Bridge Preventative Maintenance	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Bridge(s)	15 40 16 79.4 6
4 00868 4 00865 4 0086U 4 0091P 4 0124L 4 0124M 4 0124M 4 0135A 4 0144A 4 0222F 4 02269H	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE, TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY) UPGRADE CURB RAMPS/SIDEWALKS DOMINGO AVE TO MABEL ST Rte, 580 Rehab- Grind & Pave Roadway; Guard Rail; ADA Curbs @ Ramps UPGRADE CURB RAMPS/SIDEWALKS HILLER DR TO CLAREMONT AVE BRIDGE DECK PROGRAM CC 242 Pavement Rehab	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Bridge Preventative Maintenance Pavement Rehabilitation	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Bridge(s) Lone mile(s)	15 40 16
4 0086K 4 0086U 4 0086U 4 0091P 4 0124L 4 0124M 4 0135A 4 0144A 4 0222F	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY) UPGRADE CURB RAMPS/SIDEWALKS DOMINGO AVE TO MABEL ST Rte. 580 Rehab- Grind & Pave Roadway: Guard Rail; ADA Curbs @ Ramps UPGRADE CURB RAMPS/SIDEWALKS HILLER DR TO CLAREMONT AVE BRIDGE DECK PROGRAM	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Bridge Preventative Maintenance	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Bridge(s)	15 40 16 79.4 6
4 0086K 4 0086U 4 0086U 4 0091P 4 0124L 4 0124N 4 0135A 4 0144A 4 0222F 4 0269M 4 0273S 4 0278E	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps UPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY) UPGRADE CURB RAMPS/SIDEWALKS DOMINGO AVE TO MABEL ST Rte. 580 Rehob - Grind & Pave Roadway: Guard Rail: ADA Curbs @ Ramps UPGRADE CURB RAMPS/SIDEWALKS HILLER DR TO CLAREMONT AVE BRIDGE DECK PROGRAM CC 242 Povement Rehob SON 12 Bridge Scour Mitigation vvvvvvvvvvvvvvvvvvvvvvvvvvvvVMM315 Bridge Program 1-680/SR 4 Interchange - Widen Route 4 (Phase 3)	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Bridge Preventative Maintenance Pavement Rehabilitation Bridge Scour Bridge Preventative Maintenance HOV/HOT Iane-mile(s) constructed	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s)	15 40 16 79.4 6 6 5.1 2
4 00868 4 00865 4 0086U 4 0091P 4 0124L 4 0124M 4 0135A 4 0144A 4 0222F 4 0269H 4 0269H 4 0273S	Scofield Ave UC Seismic Retrofit CMGC SR 121 Repair Bridge Girders. ADA Curb Ramps LIPGRADE CURB RAMPS/SIDEWALKS SHATTUCK AVE. TO 7TH ST. ASHBY (17 LOC.) UPGRADE CURB RAMPS/SIDEWALKS CLAREMONT AVE. TO SHATTUCK AVE (ASHBY) UPGRADE CURB RAMPS/SIDEWALKS DOMINGO AVE TO MABEL ST Rte. 580 Rehab- Grind & Pave Roadway; Guard Rail; ADA Curbs @ Ramps UPGRADE CURB RAMPS/SIDEWALKS HILLER DR TO CLAREMONT AVE BRIDGE DECK PROGRAM CC 242 Povement Rehab SON 12 Bridge Scour Mitigation VVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVV	Capital Bridge Preventative Maintenance Program ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Bridge Preventative Maintenance Pavement Rehabilitation Bridge Scour Bridge Preventative Maintenance	Bridge(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Lane mile(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s)	15 40 16 79.4 6 6 5.1

4.000 Color Colo	4 0298E	L (OO/SD 4 Intershapers - Widon Doubs 4 /Dhave 2)	Nia beiden (a)	Freh	
Court Cour		I-680/SR 4 Interchange - Widen Route 4 (Phase 3) OLEMA CREEK	New bridge(s) Major Damage (Permanent Restoration)	Each Location(s)	1
ADDITION Company of the foliage for common to the foliage foliage for common to the foliage foli	4 0322B	Rehabilitate Culverts	Drainage System Restoration	Culvert(s) (ea)	21
Company					<u>1</u>
April	4 03343	kamp metering		neid elemeni(s)	- ' '
Color Color Process December Decembe					
April 1997 Apr			Major Damage (Emergency Opening) Bridge Pendshilitation and Pendscement		!
Gold Co. 61 pt Aut Mr. ADA	4 0417A				
APA DE CALL SERVICE		SCL 85 & ALA 80 ADA	ADA - New Curb Ramps	Curb ramp(s)	38
APA Mode Core Service APA Development					18
ASSEST PRODUCT PRESENTATION 2 RECORD LOCALISTICS 28 and 280 Capital stocks from present the present the present the present and the pres					C
GAMPA					3
GAMPA	101100	De de lei en 11 de de De conser (V. Wells Cofe la lacon conserta)	Cofety Folyman and the	Callistants) and so ad	15
4 AGRET Microsom Recorded Month Communication Month Communic					90
Sept Control Control Sept 2.1 A Sept	4 0472F	Nickname Required			- 2
ADMINISTRATION Biograph Prevention Administrations Biograph Prevention Administration and Management Biograph Prevention Administration and Management Biograph Biog					
Display Dec					0
GRADINICAL DEL INSTANCE					2
4,000 No. 1,000 No. 1,00					22
4 5897 10 72 73 73 73 74 74 74 74 74					1 79
Application Processing Pr					3
Application Processing Pr	4 0 4000	0.110.00		7. ()	—,
4,000000000000000000000000000000000000					4.3
4,000					1.5
Application Control	4 0480T	3E602 SF 101 Lombard St. CAPM		Lane mile(s)	8.4
49816 For Permitted Pringlich of Document of Section (1972) Application (197					3.6
4-98 Company Personnel Relationship to proper or proper to 100 App. 2-97 App. 2-97	4 0481B	SON-101 N OF PEPPER RD - REGRADE SLOPE			1
4 (April 1) 500-00 Green Portions Conceined	4 0481G	Environmental Mitigation for parent project 0J100	Major Damage (Permanent Restoration)	Location(s)	C
4 985 10 10 10 10 10 10 10 1					4259
4,0618 D. O. D. CHILDRON, CONTROL OF CONTROL					51 1
4 DBSIT SCL, 689- Goor Prevenent Rooding Sofeth Innocessment Rooding Sofeth Management (NCL's Red Re	4 0481P	REHABILITATE PAVEMENT	Roadway Rehabilitation (2R)	Lane mile(s)	29.4
Application Collision Severity Reduction Collision Sever					111
Appendent Appe					160
Application					4
4 DIRECT Social Pille Wolf Mocio Domogo (Permonet Reflocation) Location(s) 4 DIRECT SOCIAL PROPERTY Location(s) Location(s) 4 DIRECT SOCIAL PROPERTY Location(s) Location(s) 4 DIRECT SOCIAL PROPERTY Location(s) 5 DIRECT SOCIAL PROPERTY Location(s) 5 DIRECT S					
Joseph					2
Application Security Application Security Application Committed					107
A 0880		Suisun Crk Br Scour Mitigation			1
doss Development Programmer Programm					8.7
4 (0587) A Jennany Cricia ILC Deck Replocement Biscise Rehabilitation Bridge B					22.8
4 0987K SR 128 Conn Creek Bidde Replacement Plant Etablishment Biddes Scour Biddes	4 0587D	Alemany Circle UC Deck Replacement	Bridge Rehabilitation	Bridge(s)]
4					ļ
4 (0558) Min CAPM 4 (0559) Lis I Managed Lones Project - Northern Segment 4 (0559) Lis I Managed Lones Project - Northern Segment 4 (0558) Lis I Lis I Managed Lones Project - Northern Segment 4 (0558) Lis I					0
4 (07320) S. 2AD & Brillingscome ADA - Pedestrion Infortaturure ADA - Pedestrion Infortaturure ADA - Pedestrion Infortaturure ADA - Pedestrion Infortaturure Curb rompoli ADA - Pedestrion Infortaturure ADA - ADA - Pedestrion Infortaturure ADA - AD	4 0622B	SM-1 CAPM	Pavement Rehabilitation		21.2
407300 28 ADA Burlinacome					28.4
4 0732 SN-280 Culvert Rehab					120
4 OF48E Glesson Reciliamment Mocio Damose (Permonent Restorcition) Locotion(s)		SM 280 Culvert Rehab			99
40748K Glesson Blo Miligation Mojor Damage (Permonert Restoration) Location(s)					23
Algoritation Algo			Major Damage (Permanent Restoration)		1
A 0751E RSP and Drainace Maior Damace (Emeranery Openina) Location(s)					C
4 07753, SON-37 WIM. 4 07756, HILCHICA CREEK REMOVE CULVERTS AND WIDEN ROADWAY 5 Softe furnorements 6 OBJOINT ROADWAY 6 Softe furnorements 6 OBJOINT ROADWAY 6 Softe furnorements 6 OBJOINT ROADWAY 6 Softe furnorements 6 Collisionist reduced 6 WORLD ROADWAY 6 Softe furnorements 7 Collisionist reduced 6 WORLD ROADWAY 6 Softe furnorements 7 Collisionist reduced 6 WORLD ROADWAY 6 Softe furnorements 7 Collisionist reduced 6 WORLD ROADWAY 6 Softe furnorements 7 Collisionist reduced 6 WORLD ROADWAY 6 WORLD ROADWA	4 0751E	RSP and Drainage	Major Damage (Emergency Opening)	Location(s)	
4 (775G HIUCHICA CREEK REMOYE CULVERIS AND WIDEN ROADWAY Slotely Improvements Collisions reduced 4 (7878) # SRIGGE DECK PROGRAM Bidde Protect Sofety Improvements Collisions reduced 4 (8878 Uano Miscarlion Project Collisions of the Collisions of					2
4 (9878 SRIGGE DECK PROCRAM 4 (9878 Lono Mitigation Protect Sofety Improvements Collision(s) reduced 4 (9870 SON 1 C. Lrumble strip Sofety Improvements Collision(s) reduced 4 (9870 SON 1 C. Lrumble strip Sofety Improvements Collision(s) reduced 4 (9870 SON 1 C. Lrumble strip Sofety Improvements Collision(s) reduced 4 (9870 Son 1 C. Lrumble strip Sofety Improvements Collision(s) reduced 4 (9870 Son 1 C. Lrumble strip Sofety Improvement Bridges 4 (9870 Son 1 C. Lrumble strip Sofety Improvement Bridges 4 (9870 Son 1 C. Lrumble strip Sofety Improvement 4 (9880 Son 1 C. Lrumble strip Sofety Improvement Bridges 4 (9870 Son 1 Son 1 C. Lrumble strip Sofety Improvement 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (9880 Son 1 C. Lrumble strip Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (1988 Son 1 C. Lrumble strip Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (1988 Son 1 C. Lrumble strip Son 1 C. Lrumble strip Son 1 C. Lrumble strip 4 (1980 Son 1 C. Lrumble strip Son 1 C. Lrum					
4 (9830C Copell Cresk Bridge Replacement Bridge Replacition on Bridges 4 (9830C Copell Cresk Bridges Replacement Bridge Replacition on Bridges 4 (9830C North Replacement Bridges Replacition on Replacement 4 (9840 Nimer Stouch Stouch Bridge Replacition on Replacement 4 (9841 Nimer Stouch Stouch Bridge Replacition 4 (19842 ALAMEDA CREEK BRIDGE MITIGATION Bridge Remained Program 4 (19843 ALAMEDA CREEK BRIDGE MITIGATION Bridge Remained Replacement Bridges 4 (19844 ALAMEDA CREEK BRIDGE MITIGATION Bridge Remained Replacement Bridges 4 (19854 ALAMEDA CREEK BRIDGE MITIGATION Bridge Remained Replacement Bridges 4 (19854 ALAMEDA CREEK BRIDGE MITIGATION Bridge Remained Replacement Bridges 5 (Foll 1) S. Not Bridge Replacement Bridges Remained Replacement 5 (Foll 1) S. Not Boulster Replacement Bridges Remained Replacement 5 (Foll 1) S. Not Boulster Replacement Bridges Remained Replacement 5 (Foll 1) S. Not Boulster Replacement 6 (Foll 1) S. Not Bridges Replacement Bridges Remained Replacement 7 (Foll 1) S. Not Bridges Replacement 8 (Foll 1) S. Not Bridges Replacement Bridges Replacement 8 (Foll 1) S. Not Bridges Replacement 9 (Foll 1) S. Not Bridges Rep		BRIDGE DECK PROGRAM			- 5
40830E Capell Creek Bridge Replacement Bridge Rehabilitation Bridge Rehabilitation and Replacement Bridge St.	7 001710		Saicty improvements	Comportion	10
4 (0830C Capell Cr Milication & Plant Establishment Bidde Rehabilitation and Replacement Bidde(s)					196
4 1086	4 0830C	Capell Cr Mitigation & Plant Establishment	Bridge Rehabilitation and Replacement	Bridge(s)	(
Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended/Dollutant Intended Intende	4 0886	Miner Slough	Bridge Formula Program	Bridge(s)	
4 1084B ALAMEDA CREEK RRIDGE MITICATION Biridae Rehabilitation and Replacement Biridae(s)	4 1067C	U4-1A9U5_SF 1_SFPUC CONNECTION	Storm Water Mitigation		9.6
Al 1418C Alo 13/CC 24 Enhance Lighting Sofety Improvements Collision(s) reduced 1145/96 Sir-101 & SM-1 Baluster Rails Bridge Rail Replacement and Uparade Linear feet trail 2 2 4 145/96 Sir-101 & SM-1 Baluster Rails Bridge Rail Replacement and Uparade Linear feet trail 2 2 4 145/91 Sheet Pile Wall Major Damage (Permanent Restoration) Location(s) 4 145/91 Sheet Pile Wall Major Damage (Permanent Restoration) Location(s) 4 145/91 Sheet Pile Wall Major Damage (Permanent Restoration) Location(s) 4 145/91 Linear feet rail 1 1 1 1 1 1 1 1 1			Bridge Rehabilitation and Replacement	Bridge(s)	С
4 1450E SF-101 & SM-1 Balluster Rails Bridae Rail Replacement and Ubaraade Linear feet rail 2 1450J Sheet Pile Wall Major Damage (Permanent Restoration) Location(s) 14 1450J SOLDIER PILE WALL Major Damage (Permanent Restoration) Location(s) 14 1451A Replace Bridae Rails Bridae Rails (Permanent Restoration) Location(s) 14 1451A Replace Bridae Rails Bridae Rails (Permanent Restoration) Location(s) 14 1451A Replace Bridae Rails (Permanent Restoration) Location(s) 15 14 1451A Replace Bridae Rails (Permanent Rails (Permanent Restoration) Location(s) 16 17 17 17 17 17 17 17	4 1418C	Ala 13/CC 24 Enhance Lighting	Safety Improvements	Collision(s) reduced	65
4 1450H Sheet Pile Wall Major Damage (Permanent Restoration) Location(s)					2398
A 1450J SOLDIER PILE WALL Major Damage (Permanent Restoration) Location(s)	4 1450H	Sheet Pile Wall	Major Damage (Permanent Restoration)		1
A 1451C Hopper Slough Bridge Replac Bridge Rehabilitation and Replacement Bridge(s)	4 1450J	SOLDIER PILE WALL	Major Damage (Permanent Restoration)	Location(s)	
A 1452A SM-1 TOS Transportation Management Systems Field element(s)					1630
A 1452B MRN-37 11,2/11.46 CAPM					10
A 1452E SCI 152 - Construct MVPs & Vea Control Under MBGR Roadside Safety Improvements Location(s)	4 1452B	MRN-37 11.2/14.6 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	14
A 1452F Sol-80/29 Separation Trans Permit Requirements for Bridges Bridge(s)	4 1452D	SCL-152 CAPM			9.4
A 1452G Install RCP					56 1
A 1452H UniversityIncrease Vertical Clearance Trans Permit Requirements for Bridges Bridge(s)	4 1452G	Install RCP	Drainage System Restoration	Culvert(s) (ea)	- 3
A 1452K Roadside Safety Improvements Location(s)	4 1452H	UniversityIncrease Vertical Clearance	Trans Permit Requirements for Bridges	Bridge(s)	تِـــ
ALA-880 Roadside Pavina Roadside Safety Improvements Location(s)					5.6 28
A 1453A SCL 17 RUMBLE STRIPS, LIGHTING, BEACONS & STRIPING Safety Improvements Collision(s) reduced					16
A 1453C Rehabilitate Culvert Drainage System Restoration Culvert(s) (ea)	4 1453A	SCL 17 RUMBLE STRIPS, LIGHTING, BEACONS & STRIPING	Safety Improvements	Collision(s) reduced	264
1453D Water Board Compliance Units Storm Water Mitigation Acre(s) Storm Water Mitigation Acre(s) Storm Water Mitigation Acre(s)					18
teated/pollutant					52.1
4 1453H Replace Trees Roadside Rehabilitation Acre(s) 4 1453U Son Culverts Rehab Drainage System Restoration Culvert(s) (ea) 4 1453K SHEEHY CRK CULVERT REHAB Drainage System Restoration Culvert(s) (ea) 4 1454C CAPM ALA-84-6.9/10.8 Pavement Rehabilitation Lane mile(s) 4 1454F CC-04 SAFETY LIGHTING & HFST Safety Improvements Collision(s) reduced 4 1454B CAPM ALA-880-0.0/12.0 Pavement Preservation (CAPM) Lane mile(s) 4 1455B SM 84 Peek-A-Boo SPW Major Damage (Permanent Restoration) Location(s)				treated/pollutant	
1453J Son 1 Culverts Rehab Drainage System Restoration Culvert(s) (ea)				Location(s)	
A 1453K SHEEHY CRK CULVERT REHAB Drainage System Restoration Culvert(s) (eq)			Prainage System Restoration		8.2 23
4 1454C CAPM ALA-84-6,9/10.8 Pavement Rehabilitation Lane mile(s) 4 1454F CC-04 SAFETY LIGHTING & HFST Safety Improvements Collision(s) reduced 4 1454G CAPM ALA-880-0,0/12.0 Pavement Preservation (CAPM) Lane mile(s) 4 1455B SM 84 Peek-A-Boo SPW Major Damage (Permanent Restoration) Location(s)	4 1453K				4
4 1454G CAPM ALA-880-0.0/12.0 Pavement Preservation (CAPM) Lane mile(s) 9 4 1455B SM 84 Peek-A-Boo SPW Major Damage (Permanent Restoration) Location(s)	4 1454C	CAPM ALA-84-6.9/10.8	Pavement Rehabilitation	Lane mile(s)	12
4 1455B SM 84 Peek-A-Boo SPW Major Damage (Permanent Restoration) Location(s)					90.1
					7U.
		SM 84 Peek-A-Boo SPW	Major Damage (Permanent Restoration)	Location(s)	1

4 1457C	CCTV Technology Replacement	Transportation Management Systems	Field element(s)	13
4 1457L 4 1459C	DO/SB1/4Q420 SON-101 Culverts	Major Damage (Emergency Opening) Major Damage (Permanent Restoration)	Location(s) Location(s)	
4 1459D	Sol-80 Outer Separation	Safety Improvements	Collision(s) reduced	
4 1459E	04-3K420 SF-35 Signals at Skyline/Great HYW	Safety Improvements	Collision(s) reduced	
4 1460R	MacArthur Maze/Increase Vertical Clearance	Trans Permit Requirements for Bridges	Bridge(s)	
4 1461D	Storm Damage - Permanent restoration	Major Damage (Permanent Restoration)	Location(s)	
4 1461M 4 1462A	Nickname Required D4 HQ Elevators Repair	Major Damage (Permanent Restoration) Office Buildings	Location(s) Location(s)	
4 1462A 4 1462H	SCL/SM-Route 35 Horizontal Curve Safety Project	Safety Improvements	Collision(s) reduced	2
4 1462K	Bridge Rail Replacement	Bridge Rail Replacement/Upgrade	Linear feet	32
4 1462M	Son 1 Culverts Rehab	Drainage System Restoration	Culvert(s) (ea)	2
4 1462N	Son 1 Culverts Rehab	Drainage System Restoration	Culvert(s) (ea)	
4 1462P	SON101 Slide & Washout Repair	Major Damage (Permanent Restoration)	Location(s)	
4 1462R 4 1463A	CC-4 CAPM SM-35 Curve Safety	Pavement Preservation (CAPM) Safety Improvements	Lane mile(s) Collision(s) reduced	80.
4 1463A 4 1463D	Ala-680 Ramp Metering (Phase 2B)	Transportation Management (TMC's & Field	Field element(s)	4
11.005	The doc reality motoring (France 25)	Equipment)	riola ciorriolii(s)	
4 1464A	ALA Vehicle Speed Feedback Signs	Safety Improvements	Collision(s) reduced	1;
4 1464C	Sage Canyon Road slope stabilization/ Nap-128 Install RSP	Major Damage (Permanent Restoration)	Location(s)	
4 1464D 4 1464E	SCL-9 Install RSP and upgrade drainage SM 84 Injection Grouting	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
4 1464F	SON 116 Slide Repair	Major Damage (Permanent Restoration)	Location(s)	
4 1464H	Mitigation with Napa Flood Control	Roadside Enhancement (Mitigation Site	Location(s)	
	9	Relinauishments)	(.)	
4 1464J	SOL SR 37,80 & 780 RRFB	Collision Severity Reduction	Collision(s) reduced	-
4 1464K	TMDL Listed Pollutant Source Control	Storm Water Mitigation	Acre(s)	4:
4 1 4 / 41	THE Hand are Declarated	Towns and all and Administration of The Colon Street	treated/pollutant	
4 1464L	TMC Hardware Replacement	Transportation Management (TMC's & Field Equipment)	Field element(s)	
4 1464M	2018 SHOPP TMS Service Contract Project	Transportation Management (TMC's & Field	Field element(s)	80
	·	Equipment)		
4 1464M	2018 SHOPP TMS Service Contract Project	Transportation Management (TMC's & Field	Field element(s)	80
		Equipment)		
4 1464R	Nickname Required	Storm Water Mitigation	Acre(s)	2
4 1480A	MRN 1 CAPM	Pavement Preservation (CAPM)	treated/pollutant Lane mile(s)	27.8
4 1480B	SCL 17 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	27.i
4 1481B	INSTALL HIGH FRICTION SURFACE TREATMENT	Safety Enhancements	Collision(s) reduced	,
4 1482F	BIG PAVE SEGMENT 2	Roadway Rehabilitation (2R)	Lane mile(s)	43.
4 1482G	ALA-880 WIM	Weight Stations & Weight-In-Motion Facilities	Location(s)	
4 1482R	SCL, VAR, Sub-Structure Rehab.	Bridge Preventative Maintenance	Bridge(s)	
4 1482S	BRIDGE DECK PROGRAM	Capital Bridge Preventative Maintenance Program	Bridge(s)	•
4 1483B	Silverado Trail Five-Way Intersection Improvements	Interchange modification(s)	Each	
4 1483B	Silverado Trail Five-Way Intersection Improvements	Operational Improvements	Daily vehicle hour(s) of	40
			delay (DVHD)	
4 1483C	SM 101 Cordilleras Crk Br Replacement	Bridge Rehabilitation and Replacement	Bridge(s)	
4 1483D	East Crk Slough Scour Mitigation	Bridge Preventative Maintenance	Bridge(s)	
4 1483E 4 1483F	SR 29 One bridge, scour measures SCL 101 Rumble Strips.	Bridge Preventative Maintenance Safety Improvements	Bridge(s) Collision(s) reduced	8.
4 1483K	SCL, 280, Seismic Restoration, Arasteradero RD, UC and Bird Ave. OC	Bridge Seismic Restoration	Bridge(s)	0.
4 1483M	SM-1/84, Pillarcitos/S.Gregorio RSP	Bridge Preventative Maintenance	Bridge(s)	
4 1483N	PAVE AREAS FROM SHOULDER TO SOUNDWALL	Roadside Safety Improvements	Location(s)	5:
4 1483P	Construct Maintenance Worker Safety Improvements	Roadside Safety Improvements	Location(s)	3
4 1483\$	Bayshore Viaduct Structure Painting	Bridge Rehabilitation and Replacement	Bridge(s)	
4 1483T 4 1485E	Central Viaduct Structure Painting Rehabilitate Culvert	Bridge Rehabilitation and Replacement Drainage System Restoration	Bridge(s) Culvert(s) (ea)	
4 1485K	Bridge Rail Replacement	Bridge Rail Replacement and Upgrade	Linear feet rail	338
4 1486A	Clean up Roadside project	Collision Severity Reduction	Collision(s) reduced	000
4 1487A	TMS on ALA-580	Transportation Management (TMC's & Field	Field element(s)	7.
		Eauipment)		
4 1487D	San Antonio Creek	Bridge Preventative Maintenance	Bridge(s)	
4 1487E 4 1487F	CC-80 Roadway Rehab 2R Stormwater Mitigation	Roadway Rehabilitation (2R) Storm Water Mitigation	Lane mile(s)	12.
4 140/1	Sionnwaler Miligation	Storm water willigation	Acre(s) treated/pollutant	12.0
4 1487G	Various Locations Erosion Control Measures	Storm Water Mitigation	Acre(s)	7.8
		3	treated/pollutant	
4 1487J	SM101 CAPM Curb Ramps Upgrade	Pavement Preservation (CAPM)	Lane mile(s)	10.8
4 1487M	APS & Countdown Timers	Safety Enhancements	Collision(s) reduced	
4 1487N 4 1487P	APS & Countdown Timers	Collision Severity Reduction Safety Enhancements	Collision(s) reduced	2
4 1487P 4 1487Q	ALA Install 241 APSs Accessible Pedestrian Signal at various locations	Safety Enhancements Safety Enhancements	Collision(s) reduced Collision(s) reduced	18
4 1487S	SM101 Mainline Paving	Pavement Rehabilitation	Lane mile(s)	47.
4 1488N	SCL 280 Reconfigure NB Off-ramp to Foothill Exp.	Safety Improvements	Collision(s) reduced	2
4 1488P	Napa 29 NB First St. Roundabouts	Safety Improvements	Collision(s) reduced	4
4 1488S	Ala 80 Median Barrier & Lighting Detaction Restoration Social Contract	Safety Improvements Transportation Management (TMC's & Field	Collision(s) reduced	18:
4 1488T	Detection Restoration Service Contract	Transportation Management (TMC's & Field Equipment)	Field element(s)	24
4 1488V	Detection Restoration Service Contract	Transportation Management (TMC's & Field	Field element(s)	23.
		Equipment)		
4 1488W	Detection Restoration Service Contract	Transportation Management (TMC's & Field	Field element(s)	29
4 1 4007	Detection Posteration Control	Equipment)	Field element(:)	* *
4 1488X	Detection Restoration Service Contract	Transportation Management (TMC's & Field Equipment)	Field element(s)	14
4 1488Y	Detection Restoration Service Contract	Transportation Management (TMC's & Field	Field element(s)	39:
		Equipment)		37.
4 1488Z	Controller replacement	Transportation Management Systems	Field element(s)	44:
4 1489A	Outer Separation Concrete Barrier Installation	Safety Improvements	Collision(s) reduced	10
4 1489B	04-3J890 SF VAR ACCES. PED SIGNALS	Safety Enhancements	Collision(s) reduced	
4 1490A 4 1490D	04-3J300 SF 001 Lighting at MacArthur Tunnel SR 29 York to 128 Split CAPM	Signs and Lighting Rehabilitation Pavement Rehabilitation	Lighting fixture(s) Lane mile(s)	38i 15.:
4 1490D 4 1490F	04-4J390 SF 101-MITIGATE WET PAVEMENT	Safety Improvements	Collision(s) reduced	26
4 1490P	BARRIER SEPARATION	Safety Improvements	Collision(s) reduced	
4 1490Q	CAPM and ADA ramps	Pavement Rehabilitation	Lane mile(s)	3.
4 1491A	Mrn 131 ADA Infrastructure	ADA - New Curb Ramps	Curb ramp(s)	10
4 1491B	SON 116 Guerneville ADA	ADA - New Curb Ramps	Curb ramp(s)	18
4 1491C	Outer Separation Concrete Barrier Installation	Safety Improvements	Collision(s) reduced	7-
4 1491G 4 1491J	Reconstruct Ramps & Install Signal Install APS(Accessible Ped Signal)	Safety Improvements Collision Severity Reduction	Collision(s) reduced Collision(s) reduced	
4 14913 4 1492A	SCL 237 Aux-Lane-EB	Operational Improvements	Daily vehicle hour(s) of	52
			delay (DVHD)	
4 1492B	SCL 237 Aux-Lane-WB	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	33:
		Improvements	Delay (DVHD)	
		Roadway Rehabilitation (2R)	11 21 - 1-1	29.
4 1492C	PSSR - SCL-87 Pavement 2R		Lane mile(s)	27.0
4 1492D	PSR4 - SCL-280 Roadside paving	Roadside Safety Improvements	Location(s)	3'
4 1492D 4 1492E	PSR4 - SCL-280 Roadside paving SCL VAR Accessible Ped. Signal and Countdown Timer	Roadside Safety Improvements Collision Severity Reduction	Location(s) Collision(s) reduced	3:
4 1492D	PSR4 - SCL-280 Roadside paving	Roadside Safety Improvements	Location(s)	3'

4 1492H	CC-4 Install and extend MVP	Dendeide Cefek, Inneres energie	La action (a)	15
4 1492H	Mrn 101 Storm Damage Repair	Roadside Safety Improvements Major Damage (Permanent Restoration)	Location(s) Location(s)	2
4 1493A	Seismic Restoration	Bridge Seismic Restoration	Bridge(s)	1
4 1493C	Tulucay Creek Bridge Replacement	Bridge Rehabilitation and Replacement	Bridge(s)	1
4 1493E 4 1493F	Multi-asset Interchange Improvement Install Outer Separation Barriers	Bridge Seismic Restoration Safety Improvements	Bridge(s) Collision(s) reduced	23
4 1493G	04-4J970 SF 101-UPGRADE GATES AND FENCES	Roadside Safety Improvements	Location(s)	80
4 1493H	APS signal upgrade	Collision Severity Reduction	Collision(s) reduced	5
4 1493K	Irwn Cr Br Rehab Culvert	Capital Bridge Preventative Maintenance Program	Bridge(s)	1
4 1493M	SON 12 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	20.1
4 1493N	0K530 Install Ramp Metering	Transportation Management Systems	Field element(s)	41
4 1493P	BRIDGE DECK PROGRAM	Bridge Preventative Maintenance	Bridge(s)	15
4 1494C	ALA 185 CAPM Pave Gore & Narrow Areas	Pavement Preservation (CAPM)	Lane mile(s)	18.4
4 1494D 4 1494E	Bridge Rail Replacement	Roadside Safety Improvements Bridge Rail Replacement and Upgrade	Location(s) Linear feet rail	14 835
4 1494F	SOL 80 Roadway Rehab CAPM	Pavement Preservation (CAPM)	Lane mile(s)	C
4 1494G	SM-1 Pescadero Crk. Br. Rails	Bridge Rail Replacement and Upgrade	Linear feet rail	840
4 1494K 4 1495A	Bridge Rehab MBGR Replacement in Santa Clara County	Bridge Rehabilitation Collision Severity Reduction	Bridge(s) Collision(s) reduced	<u>1</u>
4 1495E	ALA & CC Concrete Barrier & MGS	Safety Enhancements	Collision(s) reduced	10
4 1495F	Install Power Supply	Safety Improvements	Collision(s) reduced	65
4 1495G	SCL 82 ADA	ADA - New Curb Ramps	Curb ramp(s)	2
4 1495K 4 1496A	MRN 101 ADA ALA CC Curve Warning Signs	ADA - New Curb Ramps Collision Severity Reduction	Curb ramp(s) Collision(s) reduced	10
4 1476A 4 1496E	SR 29 ADA Compliance	ADA - New Curb Ramps	Curb ramp(s)	19
4 1496J	SM 82 Roadway Rehab 3R	Roadway Rehabilitation (3R)	Lane mile(s)	15.2
4 1496K	HM315-Bridge Program	Bridge Preventative Maintenance	Bridge(s)	3
4 1497A	CAPM SR-84	Pavement Preservation (CAPM)	Lane mile(s)	16.5
4 1497F 4 1498A	MEDIAN BARRIER & SAFETY LIGHTING ALA DRAINAGE RESTORATION	Safety Improvements Drainage System Restoration	Collision(s) reduced Pump plant(s) (ea)	460
4 1498F	CAPM	Pavement Rehabilitation	Lane mile(s)	46.1
4 1498G	SM-280 Seismic at 5 Br.s	Bridge Seismic Restoration	Bridge(s)	5
4 1498M 4 1498N	PSR4 - SOL-680 storm damage restoration HM315	Major Damage (Permanent Restoration) Bridge Preventative Maintenance	Location(s) Bridge(s)	1
4 1498R	SM 280 MITIGATION AT LOS TRANCOS CREEK	Bridge Seismic Restoration	Bridge(s)	c
4 1499E	Rehabilitate Pump Elements and Controls	Drainage System Restoration	Pump plant(s) (ea)	2
4 1499H	Reconstruct Paved Ditch & Washout Slope w/ RSP	Major Damage (Permanent Restoration)	Location(s)	
4 1499J 4 1564R	ATMS and PCDC Upgrade Project Nickname Required	SHOPP - Misc Major Damage (Emergency Opening)	Location(s) Location(s)	l
4 1775H	Huichica Creek Bridge Mitigation	Safety Improvements	Collision(s) reduced	
4 2020B	BRIDGE SCOUR MITIGATION	Bridge Scour	Bridge(s)	1
4 2020C	BRIDGE REHABILITATION	Bridge Rehabilitation and Replacement	Bridge(s)	1
4 2020D	STORM WATER MITIGATION.	Storm Water Mitigation	Acre(s) treated/pollutant	23.2
4 2020E	STORM WATER MITIGATION	Storm Water Mitigation	Acre(s)	74.1
			treated/pollutant	
4 2020F	SCL-152 Drainage Improvement and MGS	Drainage System Restoration	Culvert(s) (ea)	1
4 2020G 4 2020H	RAMP METERING SYSTEMS ALAMEDA BMPs	Transportation Management Systems Storm Water Mitigation	Field element(s) Acre(s)	50 36.7
7 202011	ACTIVICED COVII S	Stoff Wald Wallgallon	treated/pollutant	00.7
4 2020J	SCL Recycled Water Facilities	Roadside Rehabilitation	Acre(s)	13
4 2020L	BRUNS DRIVE POC	Bridge Seismic Restoration	Bridge(s)	C
4 2020M 4 2020N	BRIDGE REHABILITATION Marin 1 Bridge Rail replacements	Bridge Seismic Restoration Bridge Rail Replacement and Upgrade	Bridge(s) Linear feet rail	504
4 2020P	SCL 680 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	76.2
4 2020Q	R-113 3R	Roadway Rehabilitation (3R)	Lane mile(s)	17.1
4 2020R	ALAMEDA BMPs	Storm Water Mitigation	Acre(s)	147.9
4 2020W	INSTALL TOS, RM & FIBER ON 580,680 & 780 In Ala, CC Cos -Child Pro-1	Transportation Management Systems	treated/pollutant Field element(s)	127
4 2020X	Upgrade Ramp Metering and Widen Ramps In CC County on Route 680	Transportation Management Systems	Field element(s)	6
4 2021A	SM-1 Safety Barrier	Safety Improvements	Collision(s) reduced	13
4 2021B 4 2021C	BRIDGE RAIL SCL 82 SAN MATEO BMPs	Bridge Rail Replacement and Upgrade Storm Water Mitigation	Linear feet rail Acre(s)	784 47.6
4 20210	SAN MATEO BIMES	Storm water Miligation	treated/pollutant	47.0
4 2021D	Storm Damage - Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	1
4 2021F	Storm Damage - Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	2
4 2021G 4 2021J	Storm Damage Permanent Restoration SM1 Br Seismic+Rail	Major Damage (Permanent Restoration) Bridge Seismic Restoration	Location(s) Bridge(s)	
4 2021K	BRIDGE REHABILITATION	Bridge Rehabilitation and Replacement	Bridge(s)	2
4 2021L	SCL-17-BRIDGE RAIL UPGRADE AND REPLACEMENT	Bridge Rail Replacement and Upgrade	Linear feet rail	1423
4 2022B 4 2022C	CAPM SF-280	Payement Preservation (CAPM)	Lane mile(s)	35
4 2022C 4 2022D	SM 1 Multi-asset Roadway Rehab Storm Damage - Permanent restoration	Roadway Rehabilitation (2R) Major Damage (Permanent Restoration)	Lane mile(s) Location(s)	16.7
4 2022E	Repair AC pavement and install new drainage system	Major Damage (Permanent Restoration)	Location(s)	2
4 2022F	Nap 121 Storm Damage Repair	Major Damage (Permanent Restoration)	Location(s)	1
4 2022H 4 2022J	STORM DAMAGE - PERMANENT RESTORATION Remove drought-stricken trees North Counties	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	1
4 2022J 4 2022K		Bridge Formula Program	Bridge(s)	2
41ZUZZN	I-80/APPIAN/CUMMINGS BRIDGE RAIL		Collision(s) reduced	19
4 2022N	RRFB	Collision Severity Reduction		
4 2022N 4 2022P	RRFB Jenner Replace Culvert	Drainage System Restoration	Culvert(s) (ea)	2
4 2022N	RRFB	Drainage System Restoration Non-Capacity Increasing Operational	Culvert(s) (ea) Daily Vehicle Hour(s) of	
4 2022N 4 2022P	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridge Rail Upgrade	Drainage System Restoration	Culvert(s) (ea)	577 398
4 2022N 4 2022P 4 2023H	RRFB Jenner Replace Culvert 37/121 Junction Roundabout	Drainage System Restoration Non-Capacity Increasing Operational Improvements	Culvert(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD)	2 577
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade	Culvert(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail	2 577 398 252
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM)	Culvert(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail	2 577 398 252 92.1
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade	Culvert(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s)	2 577 398 252
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024C 4 2024D	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade	Culvert(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s)	2 577 398 252 92.1
4 2022N 4 2022P 4 2033H 4 2023K 4 2024C 4 2024D 4 2024F	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-I CONNECTOR	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s)	2 577 398 252 92.1
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024H 4 2024H 4 2024H	RRFB Jenner Replace Culvert Jenner Replace Culvert Jordin Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB1/CC-24-PM R0.01	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s)	2 577 398 252 92.1
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024H 4 2024M 4 2024M 4 2024M 4 2024S	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Seament	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s)	2 577 398 252 92.1 0.01
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024H 4 2024M 4 2024M 4 2024M 4 2024M 4 2024M 4 2024S	RRFB Jenner Replace Culvert Jonction Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB 1 280 SB SR-1 CONNECTOR DO/SB 1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Segment 04-10820 SF 101-Roadway Rehab 3R	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Unear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Lane mile(s)	2 577 398 252 92.1 0.01
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024H 4 2024H 4 2024N 4 2024S 4 2025D 4 2025D	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB 1 280 SB SR-1 CONNECTOR DO/SB 1/CC-24-PM RQ.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Seament 04-1Q820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridae Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Povement Preservation (CAPM)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	2 577 398 252 92.1 0.01 1 3 0 59.4 14.2
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024H 4 2024M 4 2024M 4 2024M 4 2024M 4 2024M 4 2024S	RRFB Jenner Replace Culvert Jonction Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB 1 280 SB SR-1 CONNECTOR DO/SB 1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Segment 04-10820 SF 101-Roadway Rehab 3R	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridae Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Daily Vehicle Hour(s) of	2 577 398 252 92.1 0.01
4 2022P 4 2023P 4 2023P 4 2023S 4 2024C 4 2024D 4 2024F 4 2024H 4 2024M 4 2024M 4 2024M 4 2025D 4 2025S 4 2025P	RRFB Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM NOI South Seament 04-10820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridae Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Uparade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emeraency Restoration) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Calision(s) Calision	2 577 577 398 252 252 92.1 0.01 1 3 3 C C 59.4 14.2 866
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024H 4 2024H 4 2024M 4 2024M 4 2024M 4 2024S 4 2025D 4 2025D 4 2025P 4 2025T	RRFB Jenner Replace Culvert Jonction Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB 1 280 SB SR-1 CONNECTOR DO/SB 1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM- SM 101 South Segment 04-10820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Povement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Unear feet rail Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Cally Vehicle Hour(s) of Delay (DVHD) Collision(s)	2 577 398 252 92.1 0.01 1 3 0 59.4 14.2
4 2022N 4 2022P 4 2023H 4 2023H 4 2024C 4 2024D 4 2024H 4 2024M 4 2024M 4 2024M 4 2025D 4 2025D 4 2025P	RRFB Jenner Replace Culvert Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Seament 04-1Q820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties Remove dead and dying trees Santa Clara County	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridae Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Povement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridge(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Calision(s) of Delay (DVHD) Collision(s) reduced Location(s)	2 577 398 252 92.1 0.01 1 3 3 C 59.4 14.2 14.7 866
4 2022N 4 2022P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024H 4 2024M 4 2024M 4 2024M 4 2025M 4 2025S 4 2025P 4 2025S 4 2025S	REFB Jenner Replace Culvert Jenner Replace Culvert Jordina Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB I/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM NOI South Seament 04-1Q820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties Remove dead and dying trees Santa Clara County Nickname Required	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Povement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Location(s) Location(s)	2 577 398 252 92.1 0.01 1 3 3 C 59.4 14.2 14.7 866
4 2022N 4 2022P 4 2023H 4 2023H 4 2024C 4 2024D 4 2024H 4 2024H 4 2024M 4 2024M 4 2025D 4 2025D 4 2025P 4 2025T 4 2025U	RRFB Jenner Replace Culvert Jenner Replace Culvert 37/121 Junction Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Seament 04-1Q820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties Remove dead and dying trees Santa Clara County	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridae Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emeraency Restoration) Major Damage (Emeraency Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Povement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Collision(s) reduced Location(s)	2 577 398 252 92.1 0.01 1 3 3 C 59.4 14.2 14.7 866
4 2022P 4 2023P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024M 4 2024M 4 2024M 4 2024M 4 2025D 4 2025D 4 2025D 4 2025P 4 2025P 4 2025P 4 2025C 4 2026A 4 2026A 4 2026A	REFB Jenner Replace Culvert Jornicon Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB 1 280 SB SR-1 CONNECTOR DO/SB 1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Segment 04-10820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties Remove dead and dying trees Santa Clara County Nickname Required Route 101/680-Drainage Pump Plants STORM WAIER MITIGATION	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Drainage System Restoration Storm Water Mitigation	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Unear feet rail Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Culvert(s) (ea) Acre(s)	2 577 398 252 92.1 0.01 1 3 3 0 59.4 14.2 14.7 866 9 16 9
4 2022N 4 2022P 4 2023H 4 2023H 4 2024C 4 2024D 4 2024H 4 2024M 4 2024M 4 2024M 4 2025D 4 2025D 4 2025D 4 2025D 4 2025D 4 2025D 4 2025D 4 2025D 4 2026C 4 2026C 4 2026C	RRFB Jenner Replace Culvert Jonation Roundabout SCL-880 Park Ave Bridae Rail Uparade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB I 280 SB SR-1 CONNECTOR DO/SB I/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Seament 04-10820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties Remove dead and dying trees Santa Clara County Nickname Required Route 101/880-Drainage Pump Plants STORM WATER MITIGATION CAPM ON SR 82	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Bridge Rail Replacement and Uparade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Rail Replacement Restoration Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Fermanent Restoration) Major Damage System Restoration Storm Water Mitigation Pavement Preservation (CAPM)	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Lane mile(s) Location(s) Location(s	2 577 398 252 92.1 0.01 1 3 0 59.4 14.2 14.7 866 139 16 9 1 1 2 2 2 3 5 5 9 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0
4 2022P 4 2023P 4 2023H 4 2023K 4 2024C 4 2024D 4 2024F 4 2024M 4 2024M 4 2024M 4 2024M 4 2025D 4 2025D 4 2025D 4 2025P 4 2025P 4 2025P 4 2025C 4 2026A 4 2026A 4 2026A	REFB Jenner Replace Culvert Jornicon Roundabout SCL-880 Park Ave Bridge Rail Upgrade HILLSDALE BLVD OC BRIDGE (#35-0198) BALUSTER RAILS UPGRADE AND REPLACE CAPM MULTI ASSET PAVEMENT REHABILITATION Putah Creek, Bridge 23-0099 NB 1 280 SB SR-1 CONNECTOR DO/SB 1/CC-24-PM R0.01 Plant establishment follow-up to Director's Order CAPM - SM 101 South Segment 04-10820 SF 101-Roadway Rehab 3R Napa SR 121 CAPM Queue conflict reduction Improve Safety Remove drought-stricken trees East Counties Remove dead and dying trees Santa Clara County Nickname Required Route 101/680-Drainage Pump Plants STORM WAIER MITIGATION	Drainage System Restoration Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Pavement Preservation (CAPM) Bridge Rail Replacement and Upgrade Bridge Rail Replacement and Upgrade Bridge Seismic Restoration Major Damage (Emergency Restoration) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Roadway Rehabilitation Pavement Preservation (CAPM) Non-Capacity Increasing Operational Improvements Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Drainage System Restoration Storm Water Mitigation	Culver(s) (ea) Daily Vehicle Hour(s) of Delay (DVHD) Unear feet rail Linear feet rail Linear feet rail Lane mile(s) Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Culvert(s) (ea) Acre(s)	2 577 398 252 92.1 0.01 1 3 0 59.4 14.2 14.7 866 139 16

4 2026M	SR 12-Boas Dr Intersection Improvements	Safety Improvements	Collision(s) reduced	9
4 2027A	Sonoma SR 128 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	52.6
4 2027C 4 2027D	PAVEMENT PRESERVATION AND SAFETY IMPROVEMENTS	Pavement Preservation (CAPM)	Lane mile(s)	24. 12.
4 2027D 4 2027E	PAVEMENT REHABILITATION ROADWAY REHABILITATION	Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	15.
4 2027F	CAPITAL PREVENTATIVE MAINTENANCE	Pavement Preservation (CAPM)	Lane mile(s)	61.9
4 2027G	PAVEMENT PRESERVATION	Pavement Preservation (CAPM)	Lane mile(s)	18.4
4 2027J	INSTALL TOS/RM AND FIBERS	Transportation Management Systems	Field element(s)	84
4 2027P 4 2028B	Pavement Rehabilitation CCTV Technology Replacement	Pavement Preservation (CAPM) Transportation Management Systems	Lane mile(s) Field element(s)	25.3
4 2028C	04-2Q600 SF 101-HIGHWAY PLANTING	Roadside Rehabilitation	Acre(s)	18
4 2028G	ADA Pedestrian Infrastructure	ADA - New Curb Ramps	Curb ramp(s)	
4 2028H	Storm Damage Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	
4 2028K	Storm Damage - Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	
4 2028M 4 2028N	Storm Damage - Permanent Restoration Storm Damage - Permanent Restoration	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
4 2028P	SON 116 Bridge railing systems	Bridge Rail Replacement and Upgrade	Linear feet rail	430
4 2028Q	SON-121 Bridge railing upgrade	Bridge Rail Replacement and Upgrade	Linear feet rail	274
4 2028\$	Install Signals/Construct Roundabout	Safety Improvements	Annual fatal and serious injury collision(s)	0.02
4 00000	COM TO Printer with at four least to a	Distance De la Develor en estat en el Universita		00.4
4 2029C 4 2029D	SON-101 Bridge rails at four locations Nickname Required	Bridge Rail Replacement and Upgrade Major Damage (Emergency Opening)	Linear feet rail Location(s)	2345
4 2029G	Drainage System Restoration	Drainage System Restoration	Culvert(s) (ea)	29
4 2029H	Santa Rosa Maintenance Station	Maintenance Facilities	Location(s)	
4 2029L	GREEN VALLEY ROAD INTERSECTION CONTROL INSTALLATION	Safety Improvements	Annual fatal and serious injury collision(s)	0.2
4 2029N	SOLDIER PILE WALL	Major Damage (Emergency Opening)	Location(s)	
4 2030A 4 2030B	RPLC PVMT/Flood Wall Fifth Ave. DO Project	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 2030B 4 2030C	DO/SB1/REALIGNMENT/CIDH PILES	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	
4 2030D	STORM WATER MITIGATION	Storm Water Mitigation	Acre(s)	113.
			treated/pollutant	
4 2030E	Niles Canyon Flashing Beacons	Safety Improvements	Collision(s) reduced	13
4 2030F 4 2030G	Nickname Required DO/SB1/CSP CULVERT	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 2030G 4 2030H	RSP and REPLACE CULVERT	Major Damage (Emergency Opening)	Location(s)	
4 2030K	RSP and SLIPOUT	Major Damage (Emergency Opening)	Location(s)	
4 2030M	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
4 2030N	CONSTRUCT RSP/SLOPE	Major Damage (Emergency Opening)	Location(s)	
4 2030P 4 2030Q	DO/SB1/SOldier Pile DO/SB1/SOLDIER PILE/LAGGING WALL	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 2031A	SECENT PILE WALL	Major Damage (Emergency Opening)	Location(s)	
4 2031C	DO/SB1/REPLACE TIMBER SHEATHINGS	Major Damage (Emergency Opening)	Location(s)	
4 2031E	Safety Improvements-Signal Modification	Safety Improvements	Collision(s) reduced	21
4 2031F	DO/SB1/ALA 84 PM21.6 Slide	Major Damage (Emergency Opening)	Location(s)	- 1
4 2031H	SOLANO BMPS	Storm Water Mitigation	Acre(s) treated/pollutant	50.3
4 2031J	SON-116/121 INTERSECTION IMPROVEMENTS	Operational Improvements	Daily vehicle hour(s) of	300
	20 (20) (20) (20) (20) (20) (20) (20) (2		delay (DVHD)	
4 2031K 4 2031M	DO/SB1/SM 1 PM 39.0 Install Elec Generator	Major Damage (Emergency Opening)	Location(s)	
4 2031M	Storm Damage Restoration San Pablo CAPM in El Cerrito	Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Lane mile(s)	11.2
4 20318	Sheephouse Creek	Major Damage (Permanent Restoration)	Location(s)	11.2
4 2031T	ALA 92 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	26.2
4 2032A	STORM DAMAGE PERMANENT RESTORATION	Major Damage (Permanent Restoration)	Location(s)	
4 2032D	SM-35 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	29.
4 2032E 4 2032F	Follow-up mitigation to 2017 storm director's order project EA04-4K850 CAPM CC-242	Major Damage (Permanent Restoration) Pavement Preservation (CAPM)	Lane mile(s)	12.3
4 2032H	DO/SB1/ALA-880 PM28.6	Major Damage (Emergency Opening)	Location(s)	
4 2032M	Mrn101 Storm Damage Regrade Slope	Major Damage (Permanent Restoration)	Location(s)	
1 2002141				
4 2032N	MAJOR DAMAGE - PERMANENT RESTORATION	Major Damage (Permanent Restoration)	Location(s)	- 4
4 2032N 4 2032P	04-CC-680-PM RO,O/R7,7; CAPM I-680	Pavement Preservation (CAPM)	Lane mile(s)	60
4 2032N	04-CC-680-PM RO,O/R7,7; CAPM I-680 Mrn 1 10.7-11 Plant Establishment		Lane mile(s) Location(s)	60
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033D	04-CC-680-PM RO,O/R7,7; CAPM 1-680 Mm 1 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/FSPS ALA	Pavement Preservation (CAPM) Major Damage (Permanent Restoration)	Lane mile(s)	1
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033D 4 2033E	04-CC-680-PM RO,O/R7,7; CAPM 1-680 Mrn 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS MRN	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s)	1
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033D 4 2033E 4 2033H	04-CC-680-PM RO,O/R7,7; CAPM1-680 Mm I 10,7-11 Plant Establishment SON-1 CAPM DØ/SB1/PSPS ALA DØ/SB1/PSPS MRN DØ/SB1/FSPS MRN DØ/SB1/FSPG Generators	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s)	1
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033D 4 2033E	04-CC-680-PM RO,O/R7,7; CAPM1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/PSPS MRN DO/SB1/Femp Generators DO/SB1/Kincade Repair	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Lane mile(s) Location(s) Lone mile(s) Location(s) Location(s) Location(s) Location(s) Location(s)	12.6
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033D 4 2033E 4 2033H 4 2033J	04-CC-680-PM RO,O/R7,7; CAPM1-680 Mm I 10,7-11 Plant Establishment SON-1 CAPM DØ/SB1/PSPS ALA DØ/SB1/PSPS MRN DØ/SB1/FSPS MRN DØ/SB1/FSPG Generators	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina)	Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s)	12.6
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033D 4 2033H 4 2033H 4 2033J 4 2033M 4 2033N 4 2034D	04-CC-680-PM RO,O/R7,7; CAPM1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Fend Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Project	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Opening)	Lane mile(s) Location(s)	80 42.
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033E 4 2033H 4 2033H 4 2033M 4 2033M 4 2033M 4 2034D 4 2034D 4 2034D	04-CC-680-PM RO.O/R7.7; CAPM1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Ifemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froiect DO/SB1/Froiect	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Lane mile(s) Location(s)	12.c
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033J 4 2033M 4 2033N 4 2034D 4 2034D 4 2034E 4 2034H	04-CC-680-PM RO,O/R7,7; CAPM1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/FSPS MRN DO/SB1/Ifemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Project DO/SB1/Project DO/SB1/Project Install Electric System (Rashina Beacon with Type 9B sign W3-3)	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements	Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Lane mile(s) Location(s) Location(s) Collision(s) reduced	12.c
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033E 4 2033H 4 2033H 4 2033M 4 2033M 4 2033M 4 2034D 4 2034D 4 2034D	04-CC-680-PM RO.O/R7.7; CAPM1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Ifemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froiect DO/SB1/Froiect	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Lane mile(s) Location(s)	12.6 4 5 1 80 42.6
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033M 4 2033M 4 2034D 4 2034D 4 2034J 4 2034J	04-CC-680-PM.RO.O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Fiemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject Holdital Restoration Install Electric System (Rashina Beacon with Type 9B sign W3-3)	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration)	Lane mile(s) Location(s)	12.6 4 5 1 80 42.6
4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033M 4 2034D 4 2034D 4 2034C 4 2034L 4 2034L 4 2034L	04-CC-680-PM RO.O/R.7.; CAPM 1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Flemp Generators DO/SB1/Incade Repair Napa 29, 121 8. 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Project DO/SB1/Project DO/SB1/Project DO/SB1/Incap Backup Generators Install Electric System (Flashing Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction	Lane mile(s) Location(s)	12.6 2.6 3.8 88 42.4 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1
4 2032N 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033M 4 2033M 4 2034D 4 2034D 4 2034J 4 2034J	04-CC-680-PM.RO.O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Fiemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject Holdital Restoration Install Electric System (Rashina Beacon with Type 9B sign W3-3)	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious	12.6 2.6 3.8 88 42.4 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1
4 2032N 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034K 4 2034K	04-CC-680-PM RO,O/R7.7; CAPM 1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Ifemp Generators DO/SB1/Ifemp Bockup Generators Install Electric System (Flashina Beacon with Type 9B sian W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Safety Improvements Major Damage (Emergency Openinal) Safety Improvements Collision Severity Reduction	Lane mile(s) Location(s) Annual fatal and serious injury collision(s)	1 12.6
4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033M 4 2034D 4 2034D 4 2034C 4 2034L 4 2034L 4 2034L	04-CC-680-PM RO.O/R.7.; CAPM 1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Flemp Generators DO/SB1/Incade Repair Napa 29, 121 8. 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Project DO/SB1/Project DO/SB1/Project DO/SB1/Incap Backup Generators Install Electric System (Flashing Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious	1 12.6
4 2032N 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034K 4 2034K	04-CC-680-PM RO,O/R7.7; CAPM 1-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Ifemp Generators DO/SB1/Ifemp Bockup Generators Install Electric System (Flashina Beacon with Type 9B sian W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction Collision Severity Reduction	Lane mile(s) Location(s) Annual fatal and serious injury collision(s)	12. 12. 13. 14. 15. 16. 17. 18. 18. 18. 18. 18. 18. 18. 18
4 2032N 4 2032P 4 2032P 4 2032P 4 2033D 4 2033B 4 2033B 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034K 4 2035C	O4-CC-680-PM RO. O/R7.7; CAPM 1-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB 1/RSPS ALA DO/SB 1/RSPS MRN DO/SB 1/RSPS MRN DO/SB 1/RSPS MRN DO/SB 1/Rincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB 1/Project DO/SB 1/Temp Backup Generators Install Electric System (Flashina Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction Collision Severity Reduction	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Location(s) Annual fatal and serious injury collision(s)	12.c.
4 2032P 4 2032P 4 2032P 4 2032P 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034K 4 2034K 4 2034C 4 2034C 4 2035D 4 2035D 4 2035D	04-CC-680-PM RO O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS ARN DO/SB1/Fiemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject Sinstall Electric System (Flashina Beacon with Type 9B sian W3-3) Habitat Restration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Location(s)	12.c.
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2034D 4 2034H 4 2034H 4 2034H 4 2034H 4 2034C 4 2035C 4 2035C	04-CC-680-PM RO,O/R7.7; CAPM I-680 Mm 1 10,7-11 Plant Establishment SON-1 CAPM DO/SB1/FSPS ALA DO/SB1/FSPS ALA DO/SB1/FSPS MRN DO/SB1/FIGNED Generators DO/SB1/FIGNED Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject United Electric System (Flashing Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 IMS Equipment Rehab	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Major Damage (Emergency Openinal) Major Damage (Permanent Restoration) Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openinal) Collision Severity Reduction	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Location(s) Location(s) Lone mile(s) Location(s)	12.d.
4 2032P 4 2032P 4 2032P 4 2032P 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034K 4 2034K 4 2034C 4 2034C 4 2035D 4 2035D 4 2035D	04-CC-680-PM RO O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS ARN DO/SB1/Fiemp Generators DO/SB1/Kincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject Sinstall Electric System (Flashina Beacon with Type 9B sian W3-3) Habitat Restration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Location(s)	12.d.
4 2032N 4 2032P 4 2032P 4 2032P 4 2033P 4 2033B 4 2033B 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 4 2035D 4 2035D 4 2035D 4 2035D 4 2035D 4 2035D 4 2035D 4 2035D 4 2035D 4 2036A	Od-CC-680-PM RO. O/R7.7; CAPM 1-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/FSPS ALA DO/SB1/FSPS ALA DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/Fincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froiect DO/SB1/Froiect DO/SB1/Froiect DO/SB1/Froiect DO/SB1/Fore Backup Generators Install Electric System (Flashina Beacon with Type 9B sian W3-3) Habital Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SC135/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Collision Severity Reduction Collision Severity Reduction Callision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Iransportation Management Systems Collision Severity Reduction	Lone mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Location(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s)	12.4 88 42. 0. 0.18 54.2 299 0.29
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034C 4 2	04-CC-680-PM RO.O/R.7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Flemp Generators DO/SB1/Flemp Bockup Generators Install Electric System (Flashina Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Openina) Safety Improvements Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Transportation (CAPM) Major Damage (Emergency Openina) Transportation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s)	12 18.8.4 42 84 0 0 1 54 29 0
4 2032N 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034C 4 2034H 4 2034C 4 2035C 4 2035C 4 2035C 4 2035C 4 2035C 4 2035C 4 2045C 4 2046C 4 248C 4 24	O4-CC-680-PM.RO.O/R.7.; CAPM.1-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/Firenp Generators DO/SB1/Firenp Generators DO/SB1/Firenp Generators DO/SB1/Frop Generators DO/SB1/Frop Generators DO/SB1/Frop Generators Install Electric System (Flashina Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SC135/9.5 TIMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Iransportation (CAPM) Major Damage (Emergency Openina) Iransportation Management Systems Collision Severity Reduction Raadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina)	Lone mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Location(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s)	12 12 13 18.8.8.8. 18.8. 18.8. 18.8. 18.8. 18.8. 18
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034K 4 2034K 4 2034K 4 2034K 4 2034C 4 2035D 4 2035C	04-CC-680-PM RO O/R7.7; CAPM I-680 Mm I 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/Fiemp Generators DO/SB1/Rincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froiect DO/SB1/Froip Backup Generators Install Electric System (Flashina Beacon with Type 98 sian W3-3) Habitat Restration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC680 CAPM	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Sofety Improvements Occilision Severity Reduction Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Transportation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Pavement Preservation (CAPM)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Location(s	12.d.
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033D 4 2033B 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 4 2035C 4 2035C 4 2035D 4 2036D 4 2	Od-CC-680-PM RO. O/R7.7; CAPM 1-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/FSPS ALA DO/SB1/FSPS ALA DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/Fincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Iransportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s)	12
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034C 4 2	04-CC-680-PM RO.O/R.7.; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Flemp Generators DO/SB1/Indead Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Project DO/SB1/Project DO/SB1/Project DO/SB1/Project DO/SB1/Project Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Signs Upgrade in San Mateo and Santa Clara Counties CAPM DO/SB1/SCL35/9.5 TMS Equipment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements CAPM SE 29	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Ragor Damage (Emergency Openina) Iransportation (CAPM) Major Damage (Emergency Openina) Iransportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s)	12 88 42 80 0 0 0 54 43 43 11 29 10 11 29 11 12 13 14 15 16
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033D 4 2033B 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 4 2035C 4 2035C 4 2035D 4 2036D 4 2	Od-CC-680-PM RO. O/R7.7; CAPM 1-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/FSPS ALA DO/SB1/FSPS ALA DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/Fincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Iransportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s)	12 88 42 80 0 0 0 54 43 43 11 29 10 11 29 11 12 13 14 15 16
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034C 4 2	04-CC-680-PM RO.O/R.7.; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/Flemp Generators DO/SB1/Indead Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Project DO/SB1/Project DO/SB1/Project DO/SB1/Project DO/SB1/Project Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Signs Upgrade in San Mateo and Santa Clara Counties CAPM DO/SB1/SCL35/9.5 TMS Equipment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements CAPM SE 29	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Ragor Damage (Emergency Openina) Iransportation (CAPM) Major Damage (Emergency Openina) Iransportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Collision(s) reduced Location(s) Lane mile(s) Lane mile(s) Collision(s) reduced Location(s) Lane mile(s) Lane mile(s)	12
4 2032P 4 2032P 4 2032P 4 2032P 4 2033P 4 2033B 4 2033B 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034S 4 2034H 4 2035F 4 2035F 4 2035F 4 2036H 4 2	Od-CC-680-PM RO. O/R7.7; CAPM I-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/FSPS ALA DO/SB1/FSPS ALA DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FIND Generators DO/SB1/Fincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect DO/SB1/Froilect Sold Fince System (Flashina Beacon with Type 9B sian W3-3) Habital Electric System (Flashina Beacon with Type 9B sian W3-3) Habital Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements CAPM SR 29 SW Trash Capture SM - FCO SW Trash Capture MRN - FCO	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction Callision Severity Reduction Callision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Storm Water Mitigation	Lone mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Locatio	12.d.
4 2032P 4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034H 4 2034H 2 2034H 4 2035C	O4-CC-680-PM RO. O/R7.7; CAPM1-680 Mrn 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/FSPS MRN DO/SB1/Fincade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject DO/SB1/Froject Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SC135/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC-680 CAPM Qd-Alamada-61 Safety Improvements CAPM SR 29 SW Trash Capture SM - FCO	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Rayement Preservation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Raddway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Location(s)	12.c.
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H 4 2034H 4 2034K 4 2	Od-CC-680-PM RO. O/R7.7; CAPMI-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/RSPS MRN BORN BISTAIL Electric System (Flashina Beacon with Type 9B sian W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties CAPM DO/SB1/SCL35/9.5 TMS Equipment Warning Signs Blank Nickname Required DO CC680 CAPM Q4-Alameda-61 Safety Improvements CAPM SR 29 SW Trash Capture SM - FCO SW Trash Capture MRN - FCO	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Permanent Restoration) Collision Severity Reduction Callision Severity Reduction Callision Severity Reduction Pavement Preservation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Storm Water Mitigation	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lone mile(s) Location(s) Lane mile(s) Collision(s) reduced Location(s) Lane mile(s) Collision(s) reduced Location(s) Lane mile(s) Lane mile(s	12.c.
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H	04-CC-680-PM RO O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/FSPS MRN DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Bockup Generators Install Electric System (Flashina Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements CAPM SE 29 SW Trash Capture MRN - FCO SM BMPs Bridge Health - Broadway-Richmond Blvd UC DO/SB1/Deck and Girder Repair	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Collision Severity Reduction Roadway Rehabilitation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Storm Water Mitigation Storm Water Mitigation Bridge Rehabilitation and Replacement Major Damage (Emergency Opening)	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Liane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Collision(s) reduced Location(s) Lone mile(s) Collision(s) reduced Location(s) Lone mile(s) Location(s) Locat	12.c.
4 2032P 4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033H 4 2033H 4 2034H 4 2035D 4 2035D 4 2035D 4 2036H 4 2036H	OA-CC-680-PM RO. O/R7.7; CAPM 1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/FSPS MRN DO/SB1/Incade Repair Napa 29, 121 & 128 Rumble Strips CC-4 CAPM HILLCREST OC TO BYRON HWY DO/SB1/Froject DO/SB1/Froje	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Rapper (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Rapper (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Rapper (CAPM) Safety Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Storm Water Mitigation Storm Water Mitigation Bridge Rehabilitation and Replacement	Lone mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Lane mile(s) Location(s)	12 12 13 14 14 15 16 17 18 18 19 10 10 11 11 12 13 14 15 16 17
4 2032P 4 2032P 4 2032P 4 2032P 4 2033P 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2044H 4 2	04-CC-680-PM RO. O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS MRN DO/SB1/FSPS MRN DO/SB1/ISPS MRN BRN BRIGGE Health - Broadway-Richmond Blvd UC DO/SB1/IDPS AND MRN BRN BRIGGE Health - Broadway-Richmond Blvd UC DO/SB1/IDPS AND MRN BRN BRIGGE Health - Broadway-Richmond Blvd UC DO/SB1/IDPS AND MRN BRN BRN BRIGGE Health - Broadway-Richmond Blvd UC DO/SB1/IDPS AND MRN BRN BRN BRN BRN BRN BRN BRN BRN BRN B	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Callision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Collision Severity Reduction Radar Damage (Emergency Openina) Iransportation (CAPM) Major Damage (Emergency Openina) Iransportation (Management Systems Collision Severity Reduction Radaway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Storm Water Mitigation Storm Water Mitigation Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Storm Water Mitigation	Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Location(s) Lone mile(s) Collision(s) Lone mile(s) Collision(s) Lone mile(s) Location(s) Lone mile(s) Lone mile(s) Location(s) Lone mile(s) Location(s) Lone mile(s) Location(s) Loc	12.c.
4 2032P 4 2032P 4 2032P 4 2032Q 4 2033B 4 2033B 4 2033B 4 2033H 4 2033H 4 2033H 4 2033H 4 2034H 4 2034H	04-CC-680-PM RO O/R7.7; CAPM1-680 Mm 1 10.7-11 Plant Establishment SON-1 CAPM DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/PSPS ALA DO/SB1/FSPS MRN DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Generators DO/SB1/Fiemp Bockup Generators Install Electric System (Flashina Beacon with Type 9B sign W3-3) Habitat Restoration Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Upgrade in San Mateo and Santa Clara Counties SF Curve Warning Signs Horizontal Alignment Warning Signs CAPM DO/SB1/SCL35/9.5 TMS Equipment Rehab Horizontal Alignment Warning Signs Blank Nickname Required DO CC680 CAPM 04-Alameda-61 Safety Improvements CAPM SE 29 SW Trash Capture MRN - FCO SM BMPs Bridge Health - Broadway-Richmond Blvd UC DO/SB1/Deck and Girder Repair	Pavement Preservation (CAPM) Major Damage (Permanent Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Safety Improvements Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Collision Severity Reduction Roadway Rehabilitation (CAPM) Major Damage (Emergency Openina) Transportation Management Systems Collision Severity Reduction Roadway Rehabilitation (3R) Safety Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Storm Water Mitigation Storm Water Mitigation Bridge Rehabilitation and Replacement Major Damage (Emergency Opening)	Lone mile(s) Location(s) Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Lane mile(s) Location(s)	12. 8 42. 8 0. 0.1 54. 299 0.2 43. 1 29, 166 210.

4 2904D	Trash Capture FCO Pittsburg San Pablo	Storm Water Mitigation	Acre(s)	5.6
4 2904E	Trash Capture - FCO	Storm Water Mitigation	treated/pollutant Acre(s)	60
4 2904F	Trash Capture - FCO	Storm Water Mitigation	treated/pollutant Acre(s)	125
	·	_	treated/pollutant	
4 2904H 4 2904J	Pavement CAPM from Route 101/680 to Route 87 DO/SB1/Expansion Joint Repair SOL-37	Pavement Preservation (CAPM) Major Damage (Emergency Opening)	Lane mile(s) Location(s)	18.3
4 2904K	04-1Q820 SF 101-Roadway Rehab 3R	Roadway Rehabilitation (3R)	Lane mile(s)	15.4
4 2904N 4 2905A	MARIN SR 131, CAPM SON-12 CAPM	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	12.3
4 2905B	Rehab ALA 580	Pavement Preservation (CAPM)	Lane mile(s)	77.2
4 2905C	Landscape and Biological Mitigation	Bridge Scour	Bridge(s)	
4 2905D 4 2905E	DO/SB1/NAP-121 DO/SB1/SOL-80	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 2905H	i-680 Express Lanes/Rehab Project	Roadway Rehabilitation (2R)	Lane mile(s)	28.7
4 2905J 4 2906A	SB 680 REHAB - TO BE COMBINED WITH EL INSTALL TOS, RM & FIBER ON ROUTES 580, 680 & 780 IN ALA, CC & SOL	Pavement Preservation Transportation Management Systems	Lane mile(s) Field element(s)	28.7
4 2906B	DO/SB1/LNU/Myers Wildfire	Major Damage (Emergency Opening)	Location(s)	1
4 2906C	Minor Rehab - CAPM 001	Pavement Preservation (CAPM)	Lane mile(s)	18.8
4 2906D 4 2906E	DO/SB1/SCU Wildfire Damage DO/Sb1/SM-1-Wildfires Damage Repair	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 2906F	Corte Madera Bridge Maintenance	Bridge Rehabilitation and Replacement	Bridge(s)	1
4 2906G 4 2906H	Storm Damage Repair Retaining Wall on MRN 1	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	1
4 2906J	Construct Retaining Wall on MRN 131	Major Damage (Permanent Restoration)	Location(s)	i
4 2906K	DO/Sb1/Son-1/Drainage Repair	Major Damage (Emergency Opening)	Location(s)	1
4 2906M 4 2906N	DO/SB1/FENCING/ACCESS GATES DO	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 2907A	Son 1 Drainage System Restoration	Drainage System Restoration	Culvert(s) (ea)	23
4 2907B 4 2907C	DO/SB1/Repair Facilities Trash Capture install BMP	Major Damage (Emergency Opening) Storm Water Mitigation	Location(s) Acre(s)	1 70
		_	treated/pollutant	
4 2907D	DO/SB1/Construct Ret. Wall	Major Damage (Emergency Opening)	Location(s)	
4 2907E 4 2907H	D4 Cooling Tower Rehab DO	Office Buildings Major Damage (Emergency Opening)	Location(s) Location(s)	1
4 2907J	DO/SB1/EXPANSION JOINTS	Major Damage (Emergency Opening)	Location(s)	1
4 2907M 4 2908B	DO/SB1/SF/CONCRETEBARRIERREPAIR DO	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	1
4 2908D	DO/SB1/Repair at Junction Box	Major Damage (Emergency Opening)	Location(s)	i
4 2908E 4 2908F	DO/SB1/Slide Repair SF 101 13th Street FCO	Major Damage (Emergency Opening)	Location(s) Collision(s) reduced	3
4 2908G	DO DO	Collision Severity Reduction Major Damage (Emergency Restoration)	Location(s)	<u>3</u>
4 2908H	Replace failed erosion control mesh and regrade slope	Major Damage (Permanent Restoration)	Location(s)	1
4 2908K 4 2908N	DO DO	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	1
4 2909B	Posey-Webster Tubes Power Systems	Major Damage (Permanent Restoration)	Location(s)	2
4 2909C	DO	Major Damage (Emergency Opening)	Location(s)	
4 2909E 4 2909J	DO 04-1W710 ALA 680 DRAINAGE INLETS AND GUARDRAILS	Major Damage (Emergency Opening) Safety Improvements	Location(s) Annual fatal and serious	0.29
		, , ,	injury collision(s)	
4 2909N	SON 116 PM9.15 Storm Damage	Major Damage (Permanent Restoration)	Location(s)	
4 2909P	DO	Major Damage (Emergency Opening)	Location(s)	
4 2909P 4 2909Q			Annual fatal and serious	0.34
	DO	Major Damage (Emergency Opening)		0.34
4 2909Q 4 2909R	DO SR 152 Soft Median Barrier CC 24 Polyester Overlay	Major Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridge(s)	0.34
4 2909Q 4 2909R 4 2910A	DO SR 152 Soft Median Barrier CC 24 Polyester Overlay Scotts Corner Separation	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridge(s) Bridge(s)	0.34
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910D	DO SR 152 Soft Median Barrier CC 24 Polyester Overlay	Major Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s)	1 0.34 1 1 1 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910D 4 2910E	DO SR 152 Soft Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Bridae(s)	1 1 1 2 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910D 4 2910G 4 2910G	DO SR 152 Soft Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Bridae(s) Lone mile(s)	1 1 1 2 2 2 33.7
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910G 4 2910G 4 2910H 4 2910J	DO SR 152 Soft Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) TMS/CCTV Lifecycle Replacement	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lone mile(s) Field element(s)	1 1 1 2 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910G 4 2910G 4 2910H 4 2910J 4 2910J 4 2910J	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s)	1 1 2 2 2 33.7 25.5 383 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910G 4 2910G 4 2910G 4 2910J 4 2910J 4 2910M 4 2910M 4 2910M 4 2910M 4 2910M	DO SR 152 Soft Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) TMS/CCTV Lifecycle Replacement	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lone mile(s) Field element(s)	1 1 2 2 2 33.7 25.5
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910G 4 2910G 4 2910H 4 2910K 4 2910M 4 2910M 4 2910M 4 2910M 4 2910M 4 2910M 4 2911B	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO	Maior Damaae (Emergency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Restoration)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s) Culvert(s) (ea) Location(s)	1 1 2 2 2 33.7 25.5 383 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910G 4 2910G 4 2910G 4 2910J 4 2910J 4 2910M 4 2910M 4 2910M 4 2910M 4 2910M	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTIV_Lifecycle Replacement SM 101 Bridae Deck Overlay Marin Hwy 1 Combined Culvert replacement DO	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Fransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lane mile(s) Line mile(s) Field element(s) Bridae(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s)	1 1 2 2 2 33.7 25.5 383 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910B 4 2910H 4 2910J 4 2910M 4 2910M 4 2911B 4 2911E 4 2911F	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Povement Minor Rehab (CAPM) TMS/JCCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO DO	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s) Location(s) Location(1 1 2 2 2 33.7 25.5 383 2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910G 4 2910G 4 2910H 4 2910J 4 2910H 4 2910H 4 2910H 4 2911B 4 2911B 4 2911G 4 2911G	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Maior Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lone mile(s) Loue mile(s) Field element(s) Bridae(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Daily vehicle hour(s) of delay (DYHD)	1 1 2 2 33.7, 25.5 383 2 51 1 1 1 1 15 866
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2911F 4 2911F 4 2911C 4 2911M 4 2911N	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Povement Minor Rehab (CAPM) TMS/JCCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Eane mile(s) Bridae(s) Bridae(s) Culvert(s) (ea) Location(s) Bridae(s)	1 1 2 2 33.7 25.5 3833 2 51 1 1 1 15 866
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910C 4 2910G 4 2910G 4 2910H 4 2910M 4 2910M 4 2911B 4 2911B 4 2911F 4 2911F 4 2911F 4 2911F 4 2911F 4 2911P	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl.	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Povement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Fermanent Restoration)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Locotion(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Guivert(s) (ea) Locotion(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s)	1 1 2 2 33.7 25.5 3833 2 51 1 1 1 15 866
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H 4 2911F 4 2911F 4 2911H	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Povement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO DO DO MEPA Hooker & Sonoma Creek Bridges	Maior Damaae (Emergency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridae Scour Major Damage (Femergency Opening) Bridae Scour Major Damage (Femergency Opening)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s) Culvert(s) (ea) Location(s)	1 1 2 2 2 33.7, 25.5 383 2 51 1 1 1
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910M 4 2910M 4 2911B 4 2911B 4 2911F 4 2911K 4 2911M 4 2911M 4 2911M 4 2911M 4 2911P 4 2911Q	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Mojor Damage (Emergency Openina) Bridge Scour Major Damage (Permanent Restoration) Major Damage (Emergency Openina) Bridge Scour Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Field element(s) Bridae(s) Culvert(s) fea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Daily vehicle hour(s) of delay (DVHD) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Locatio	1 1 2 2 33.7 25.5 3833 2 51 1 1 1 15 866
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H 4 2911F 4 2911F 4 2911H 4 2912H	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalit Povement Minor Rehab (CAPM) TMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IIMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance	Maior Damaae (Emergency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridae Scour Major Damage (Emergency Openina) Bridae Scour Major Damage (Emergency Openina) Bridae Scour Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s) Bridae(s) Culvert(s) (ea) Location(s) Bridae(s) Location(s) Location(s) Location(s) Bridae(s) Location(s) Location(s	1 1 2 2 33.7 25.5 383 2 5 1 1 1 1 5 866 6 6 C C C C C C C C C C C C C C C C
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910B 4 2910B 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Asphalt Pavement Minor Rehab (CAPM) Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emergency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Mojor Damage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Opening) Bridae Scour Maior Damage (Fermanent Restoration) Moior Damage (Emergency Opening) Bridae Scour Maior Damage (Fermanent Restoration) Moior Damage (Fermanent Restoration)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s) Location(s) Bridae(s) Location(s) Location(s) Bridae(s) Location(s)	1 1 1 2 2 2 33.7 25.5 383 2 5 1 1 1 1 1 1 5 866 2 0 0 0 1
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910B 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910M 4 2910M 4 2911M 4 2911F 4 2911M 4 2911N 4 2911N 4 2911P 4 2911Q 4 2911R 4 2911C 4 2911C 4 2911C 4 2911C 4 2912C 4 2912C 4 2912C	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hww 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emeraency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Maior Damage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Femergency Openina) Bridae Scour Maior Damage (Femergency Openina) Maior Damage (Femergency Openina) Minintenance Facilities Pavement Preservation (CAPM) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Midor Damage (Femergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s) Culvert(s) (ea) Location(s) Bridae(s) Location(s)	1 1 2 2 33.7 25.5 383 2 5 1 1 1 1 5 866 6 6 C C C C C C C C C C C C C C C C
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H 4 291H 4 291	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Asphalt Pavement Minor Rehab (CAPM) Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s) Location(s) Bridae(s) Location(s) Location(s) Bridae(s) Location(s)	1 1 1 2 2 3 3 3
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2911B 4 2911B 4 2911B 4 2911B 4 2911B 4 2911C 4 2912C	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Asphalt Pavement Minor Rehab (CAPM) TMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Mointenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emeraency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Provement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridae Scour Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Location(s) Bridae(s) Location(s)	1 1 1 2 2 3 3 3 2 5 5 1 1 1 1 1 5 8 6 6 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910B 4 2910B 4 2910B 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912J 4 2912J 4 2912D 4 2912D 4 2912D 4 2912D 4 2912D	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DO DA PAVEMENT PROJECT DO Son 1 Culvert Rehab	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Openinge System Restoration	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Bridae(s) Ende element(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s)	1 1 1 2 2 3 3 3
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H 4 291H 4 2	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Map-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DAVEMENT PROJECT DO Son 1 Culvert Rehab DO HMA MEDIUM OVERLAY (CAPM)	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Daily vehicle hour(s) of delay (DVHD) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Location(s) Bridae(s) Location(s) Locati	1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H 4 2911E 4 2911F 4 2911H 4 291H	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Asponans R 114 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Miligation project for EA 0,1300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DO DO DO PAVEMENT PROJECT DO Son 1 Culvert Rehab DO Son 1 Culvert Rehab DO Son 1 Culvert Rehab	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Maior Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Drainage System Restoration) Major Damage (Emergency Opening) Drainage System Restoration)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Field element(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Locati	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911H 4 291H 4 2	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Map-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DAVEMENT PROJECT DO Son 1 Culvert Rehab DO HMA MEDIUM OVERLAY (CAPM)	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Annual fatal and serious injury collision(s) Bridae(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Daily vehicle hour(s) of delay (DVHD) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Location(s) Bridae(s) Location(s) Locati	1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910B 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2911F 4 2911F 4 2911F 4 2911H 4 291H 4 29	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Asponan SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) INS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Femergency Opening) Major Damage (Femergency Restoration) Pavement Preservation (CAPM) Major Damage (Femergency Opening) Major Damage (Femergency Restoration) Pavement Preservation (CAPM)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lane mile(s) Lane mile(s) Electric (s) Bridae(s) Electric (s) Bridae(s) Electric (s) Bridae(s) Electric (s) Eletric (s) Electric (s) Electric (s) Electric (s) Electric (s)	1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2912B 4 2913B 4 2913B 4 2913B 4 2913B	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DAVEMENT PROJECT DO Son 1 Culvert Rehab DO HMA MEDIUM OVERLAY (CAPM) INSTALL SHOULDER RUMBLE STRIPS	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Bridge Scour Major Damage (Emergency Openina) Major Damage (Emergency Opening) Drainage System Restoration Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s)	1 1 1 2 2 2 5 5 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2911F 4 2911F 4 2911F 4 2911R 4 2911R 4 2911R 4 2911R 4 2912B 4 2912E 4 2912E 4 2912E 4 2912E 4 2912F 4 2913B 4 2912F 4 2913B 4 2913B	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Asponan SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) INS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Femergency Opening) Major Damage (Femergency Restoration) Pavement Preservation (CAPM) Major Damage (Femergency Opening) Major Damage (Femergency Restoration) Pavement Preservation (CAPM)	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lane mile(s) Lane mile(s) Electric (s) Bridae(s) Electric (s) Bridae(s) Electric (s) Bridae(s) Electric (s) Eletric (s) Electric (s) Electric (s) Electric (s) Electric (s)	33.3 33.3 25.5 5 11.1 866 ((() 100.2 30.9 11.6 11.6 11.6 11.6 11.6 11.6
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910B 4 2910B 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2911B 4 2911K 4 2911K 4 2911K 4 2911N 4 2911N 4 2911N 4 2911N 4 2911N 4 2911N 4 2911P 4 2912D 4 2912B 4 2912C 4 2912B 4 2912C 4 2912B 4 2913B 4 2913B 4 2913B 4 2913B 4 2913B	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DO DO DO DO Son 1 Culvert Rehab DO Son 1 Culvert Rehab DO Major Damage Upgrade Median Concrete Barrier & Install Freeway Safety Lighting	Maior Damaae (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Transportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Openina) Bridge Scour Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Emergency Openina) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s) Eled element(s) Bridae(s) Bridae(s	33.3 33.3 25.5 5 5 11 11 18 866 30.6 100.2
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910H 4 2911B 4 2911E 4 2911F 4 2911H 4 291H 4 291	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) INS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Maior Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Maior Damage (Emergency Opening) Bridge Scour Major Damage (Fermanent Restoration) Molor Damage (Fermanent Replacement Pavement Preservation (CAPM) Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Mojor Damage (Emergency Opening) Mojor Damage (Fermanency Restoration) Pavement Preservation (CAPM) Major Damage (Fermanency Restoration) Pavement Preservation (CAPM) Mojor Damage (Fermanency Restoration) Pavement Preservation (CAPM) Mojor Damage (Fermanency Restoration) Pavement Preservation (CAPM) Safety Improvements Major Damage (Fermanency Restoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Eled element(s) Bridae(s) Location(s) Bridae(s) Location(s) Locat	33.3 38.3 38.3 38.3 5 5 11.3 86.4 100.2 30.4 30.4 30.1 30.1 31.5 31.5 31.5 31.5 31.5 31.5 31.5 31
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2913B	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Refrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DO Son 1 Culvert Rehab DO HM AMEDIUM OVERLAY (CAPM) INSTALL SHOULDER RUMBLE STRIPS DA ALA-238-CAPM MINOR PAVEMENT REHABILITATION (CAPM) SON-12 ADA Facilities Upgrade MINOR PAVEMENT REHABILITATION (CAPM) SON-12 ADA Facilities Upgrade	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Location(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s) Locat	33.3 38.3 38.3 38.3 5 5 11.3 86.4 100.2 30.4 30.4 30.1 30.1 31.5 31.5 31.5 31.5 31.5 31.5 31.5 31
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2911F 4 2911F 4 2911F 4 2911F 4 2911P 4 2912P 4 2912E 4 2912E 4 2912F 4 2912F 4 2912F 4 2913D 4 2913D 4 2913B 4 2913D 4 2913B 4 2913B 4 2913D 4 2913B 4 2913D 4 2913D 4 2913B 4 2913D 4 2913B 4 2913D 4 2913B 4 2913D 4 2913P 4 2913P 4 2913P 4 2914P	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DO DO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emergency Opening) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damaage (Emergency Opening) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Manaagement Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Maior Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) ADA- New Curt Ramps Bridae Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s) Colvert(s) (ea) Location(s) Bridae(s) Location(s) Location	33.33.33.33.33.33.33.33.33.33.33.33.33.
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910B 4 2910E 4 2910E 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2913B	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Refrofit Sonoma SR 116 CAPM Asphalt Pavement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DO Son 1 Culvert Rehab DO HM AMEDIUM OVERLAY (CAPM) INSTALL SHOULDER RUMBLE STRIPS DA ALA-238-CAPM MINOR PAVEMENT REHABILITATION (CAPM) SON-12 ADA Facilities Upgrade MINOR PAVEMENT REHABILITATION (CAPM) SON-12 ADA Facilities Upgrade	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Location(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Location(s) Locat	33.33.33.33.33.33.33.33.33.33.33.33.33.
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2913B 4 2914B 4 2914B 4 2914C 4 2914F 4 2914F	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Mointenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emeraency Openina) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damaage (Emergency Openina) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Povement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Major Damaae (Emergency Restoration) Pavement Preservation (CAPM) Major Damaae (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Sestoration) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Sestoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s)	33.3 33.3 33.3 33.3 33.3 33.3 33.6 66667 30.0 30.0 30.0 30.0 30.0 30.0 30.0 30.
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910E 4 2910H 4 2911B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2913B 4 2914B 4 2914G 4 2914G 4 2914G 4 2914G 4 2914G	DO SR 152 Soff Median Barrier CC 24 Polvester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Refrofit Sonoma SR 116 CAPM Asphalt Povement Minor Rehab (CAPM) IMS/CCTV Lifecycle Replacement SM 101 Bridae Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridaes Mitigation project for EA 0J300 for plant establishment/erosion ctrl. DO Maintenance Facility Rehabilitation CAPM Nap-Sol 12 Bridae Rehabilitation and Preventative Maintenance SCI-101-CAPM DO DO Son 1 Culvert Rehab DO HMA MEDIUM OVERLAY (CAPM) INSTALL SHOULDER RUMBLE STRIPS ALA-238-CAPM MINOR PAYEMENT REHABILITATION (CAPM) Son-12 CAPM Early CAPM INSTALL SHOULDER RUMBLE STRIPS ALA-238-CAPM MINOR PAYEMENT REHABILITATION (CAPM) SON-12 ADA Facilities Upgrade Bridae Rehabilitation, Seismic Retrofit End-of-life replacement of TMS field devices Waldo Turnel Lighting Rehabilitation Drainage Restoration - Fish Possage Waldo Turnel Lighting Rehabilitation Drainage Restoration - Fish Possage Waldo Turnel Lighting Rehabilitation Drainage Restoration - Fish Possage Waldo Turnel Lighting Rehabilitation Drainage Restoration - Fish Possage	Maior Damage (Emergency Opening) Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Bridge Seismic Restoration Bridge Seismic Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Iransportation Management Systems Bridge Rehabilitation and Replacement Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Pavement Preservation (CAPM) Operational Improvements Major Damage (Emergency Opening) Bridge Scour Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Pavement Preservation (CAPM) Ada Da Damage (Permanent Restoration) Collision Severity Reduction Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) ADA - New Curb Ramps Bridge Rehabilitation and Replacement Iransportation Management Systems Sians and Lighting Rehabilitation Signs and Lighting Rehabilitation	Annual fatal and serious injury collision(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s) Bridae(s) Lone mile(s) Lone mile(s) Location(s) Bridae(s) Location(s) Bridae(s) Bridae(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Locatio	33.33.33.33.33.33.33.33.33.33.33.33.33.
4 2909Q 4 2909R 4 2910A 4 2910B 4 2910B 4 2910E 4 2910G 4 2910H 4 2910H 4 2910H 4 2910H 4 2910H 4 2911B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2912B 4 2913B 4 2914B 4 2914B 4 2914C 4 2914F 4 2914F	DO SR 152 Soff Median Barrier CC 24 Polyester Overlay Scotts Corner Separation DO Foothill-Davenport Seismic Retrofit Ala 13 Seismic Retrofit Ala 13 Seismic Retrofit Sonoma SR 114 CAPM Asphalt Pavement Minor Rehab (CAPM) ITMS/CCTV Lifecycle Replacement SM 101 Bridge Deck Overlay Marin Hwy 1 Combined Culvert replacement DO DO CAPM-116 IMPROVE TRAFFIC OPERATIONS AT INTERSECTION DDO MEPA Hooker & Sonoma Creek Bridges Mitigation project for EA 0,1300 for plant establishment/erosion ctrl. DO Mointenance Facility Rehabilitation CAPM Nap-Sol 12 Bridge Rehabilitation and Preventative Maintenance SCI-101-CAPM DO	Maior Damaae (Emeraency Openina) Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Major Damaage (Emergency Openina) Bridae Seismic Restoration Bridae Seismic Restoration Pavement Preservation (CAPM) Povement Preservation (CAPM) Transportation Management Systems Bridae Rehabilitation and Replacement Drainage System Restoration Major Damaae (Emergency Openina) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Operational Improvements Major Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Bridae Scour Major Damaae (Emergency Openina) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Major Damaae (Emergency Restoration) Pavement Preservation (CAPM) Major Damaae (Emergency Restoration) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Openina) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Sestoration) Pavement Preservation (CAPM) Safety Improvements Major Damaae (Emergency Sestoration) Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Location(s)	1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3

4 2914\$	WRONG WAY PAVEMENT MARKERS	Safety Improvements	Annual fatal and serious injury collision(s)	0.27
4 2914V	Drainage Restoration - Fish Passage	Drainage System Restoration	Culvert(s) (ea)	
4 2914W	Saratoga Creek Bridge 2-yr PEP	Bridge Rehabilitation and Replacement	Bridge(s)	(
4 2914X	Saratoga Creek Bridge Plant Monitoring	Bridge Rehabilitation and Replacement	Bridge(s)	(
4 2914Y 4 2915B	MITIGATION AT SANBORN REGIONAL Napa City Pavement Preservation	Bridge Rehabilitation and Replacement Pavement Preservation (CAPM)	Bridge(s) Lane mile(s)	29
4 2915C	Safety Improvement Project	Safety Improvements	Annual fatal and serious injury collision(s)	0.09
4 2915D 4 2915E	SM-92-CAPM End-of-Life Traffic Signal Technology Replacement	Pavement Preservation (CAPM) Transportation Management Systems	Lane mile(s) Field element(s)	2º
4 2915F	TMS SIGNAL TECHNOLOGY REPLACEMENT	Transportation Management Systems	Field element(s)	14
4 2915G	SCL-101-Pavement Rehabilitation (2R)	Roadway Rehabilitation (2R)	Lane mile(s)	76.
4 2915H	SM-82-Pavement Preservation	Pavement Preservation (CAPM)	Lane mile(s)	20
4 2915J 4 2915L	SCI-880-CAPM Asphalt Pavement Roadway Rehabilitation	Pavement Preservation (CAPM) Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	81. 20.
4 2915L 4 2915M	Napa River Bridge Scour Mitigation	Bridge Scour	Bridge(s)	20.
4 2915N	DO DO	Major Damage (Emergency Opening)	Location(s)	
4 2916K	BRIDGE HEALTH PROJECT	Bridge Rehabilitation and Replacement	Bridge(s)	;
4 2916P	Bridge replacement for West Union Creek Br No 35 0044	Bridge Seismic Restoration	Bridge(s)	
4 2916Q 4 2916R	SM 1 - Road Realianment Trash Capture Devices	Major Damage (Permanent Restoration) Storm Water Mitigation	Location(s) Acre(s)	193.
4 2916\$	VMS, Queue Detection, and Lighting	Safety Improvements	treated/pollutant Annual fatal and serious injury collision(s)	0.0
4 2916T 4 2916V	Pavement Application Applicati	Pavement Preservation (CAPM)	Lane mile(s)	60.8
4 2916V 4 2916W	Mobility - ADA Follow up Mitigation Cordilleras Crk. (2J730)	ADA - New Curb Ramps Bridge Rehabilitation and Replacement	Curb ramp(s) Bridge(s)	2
4 2916X	Mitigation Plant establishment for EA 3J08A	Bridge Preventative Maintenance	Bridge(s)	(
4 2917A	Trash Capture Devices	Storm Water Mitigation	Acre(s) treated/pollutant	177.:
4 2917B	REHABILITATE PLUMP PLANT	Drainage System Restoration	Pump plant(s) (ea)	
4 2917C 4 2917D	Maior Storm Damage Marin City Second Culvert	Major Damage (Permanent Restoration) SHOPP - Sustainability and Miscellaneous	Location(s) Location(s)	
4 2917E	Marin City Second Curvert Plant Establishment and Environmental Mitigation	Bridge Rail Replacement and Upgrade	Annual fatal and serious injury collision(s)	(
4 2917G	RTE 123/ALA Pedestrian Crossing Improvements	SHOPP - Complete Streets	Bicycle and pedestrian infrastructure (linear feet)	750
4 2917L	DO DO WEST AND	Major Damage (Emergency Restoration)	Location(s)	
4 2917N 4 2917P	Devil's Slide Mitigation DO	Major Damage (Permanent Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2917Q	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2917R	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2917T	DO	Major Damage (Emergency Opening)	Location(s)	
4 2917V	DO Nichara Sanaira d	Major Damage (Emergency Opening)	Location(s)	
4 2917W	Nickname Required	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	(
4 2918A	DO	Major Damage (Emergency Restoration)	Location(s)	4
4 2918C	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2918F	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2918H 4 2918J	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2918K	DO	Major Damage (Emergency Opening)	Location(s)	
4 2918L	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2918M	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2918P 4 2918Q	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	3
4 2918T	DO	Major Damage (Emergency Opening)	Location(s)	
4 2918V	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2919A	DO	Major Damage (Emergency Restoration)	Location(s)	-
4 2919B 4 2919C	DO Posey Tube 33-0106R and Webster Tube 33-0106L - Ventilation Upgrade	Major Damage (Emergency Restoration) Bridge Rehabilitation and Replacement	Location(s) Bridge(s)	
4 2919D	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2919E	DO	Major Damage (Emergency Restoration)	Location(s)	5
4 2919F	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2919J 4 2919L	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	,
4 2919N	DO	Major Damage (Emergency Restoration)	Location(s)	42
4 2919P	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2919Q 4 2919R	DO	Major Damage (Emergency Opening)	Location(s)	
4 2919R 4 2919S	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
4 2919T	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2919V	CAPM	Pavement Preservation (CAPM)	Lane mile(s)	17
4 2919W 4 2919X	Nickname Required MEPA Gualala Kruse Ranch Rd to Vantage Rd	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	(
4 2919X 4 2920B	DO DO	Major Damage (Emergency Restoration)	Location(s)	296
4 2920C	DO	Major Damage (Emergency Opening)	Location(s)	29
4 2920E	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2920F 4 2920G	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
4 2920G 4 2920H	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2920J	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2920K	CAPM 152	Pavement Preservation (CAPM)	Lane mile(s)	52.
4 2920L 4 2920N	Future 680/237 Separation DO	Bridge Rehabilitation and Replacement Major Damage (Emergency Restoration)	Bridge(s) Location(s)	
4 2920P	DO	Major Damage (Emergency Restoration)	Location(s)	17
4 2920Q	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2920R 4 2920T	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Opening)	Location(s) Location(s)	
4 29201 4 2921A	DO	Major Damage (Emergency Opening) Major Damage (Emergency Restoration)	Location(s)	,
4 2921B	DO	Major Damage (Emergency Restoration)	Location(s)	3
4 2921C	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2921D	SR -12 / PAVEMENT PRESERVATION	Pavement Preservation (CAPM)	Lane mile(s)	16.
4 2921E 4 2921G	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2921H	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2921L	El Verano Safety Improvements	Collision Severity Reduction	Annual fatal and serious injury collision(s)	0.0
4 2921M	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2921N	Stormwater Trash Collection FCO	Storm Water Mitigation	Acre(s)	40
			treated/pollutant	

4 2921P	Stormwater Trash Collection FCO	Storm Water Mitigation	Acre(s) treated/pollutant	203.
4 2921R	Install/upgrade/enhance pavement markers and enhance stripes	Safety Improvements	Annual fatal and serious	0.2
			injury collision(s)	
4 29217	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2921V 4 2921W	DO Mitigation Plant Establishment	Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Lane mile(s)	
4 2922A	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2922C 4 2922G	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2922L	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2923C	DO	Major Damage (Permanent Restoration)	Location(s)	
4 2923D 4 2923E	DO DO	Major Damage (Emergency Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
4 2923H	DO	Major Damage (Permanent Restoration)	Location(s)	
4 2923S 4 2923W	DO Lincoln Ave Mitigation & Bio Monitoring	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
4 2924B	DO	Major Damage (Permanent Restoration)	Location(s)	
4 2924S	Town of Colma FCO	Storm Water Mitigation	Acre(s) treated/pollutant	16
4 2924T	City of Pacifica FCO	Storm Water Mitigation	Acre(s)	31.
4 000 07	O'h a f Cara La a FOO	Character Market Market	treated/pollutant	000
4 2924V	City of San Jose FCO	Storm Water Mitigation	Acre(s) treated/pollutant	203
4 2924W	Nickname Required	Bridge Preventative Maintenance	Bridge(s)	
4 2924Y 4 2925A	Nickname Required Port of Oakland FCO	Major Damage (Permanent Restoration) Storm Water Mitigation	Location(s) Acre(s)	1
4 2725A	1 off of odkidna reo	Stoff Water Willigation	treated/pollutant	
4 2925C	DO STATE OF THE SECOND STA	Major Damage (Emergency Restoration)	Location(s)	10
4 2925D	City of East Palo Alto FCO	Storm Water Mitigation	Acre(s) treated/pollutant	13
4 2925F	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2925K	DO	Major Damage (Permanent Restoration)	Location(s)	
4 2925M 4 2925T	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2925W	Flood Reduction Project (phase 1)	SHOPP - Sustainability and Miscellaneous	Centerline mile(s)	0
4 2925Y	Petaluma River Bridge Environmental Mitigation	Bridge Rehabilitation and Replacement	Bridge(s)	
4 2926A 4 2926B	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2926C	DO	Maintenance Facilities	Location(s)	
4 2926D 4 2926F	DO DO	Maintenance Facilities Major Damage (Permanent Restoration)	Location(s) Location(s)	
4 2926H	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2926J	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2926K 4 2926M	DO DO	Major Damage (Emergency Restoration) Maintenance Facilities	Location(s) Location(s)	
4 2926N	DO	Maintenance Facilities	Location(s)	
4 2926P	DO	Maintenance Facilities	Location(s)	
4 2926Q 4 2926R	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	3
4 2926S	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2926T	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2926V 4 2926W	DO Nickname Required	Major Damage (Emergency Restoration) Roadway Rehabilitation (2R)	Lane mile(s)	
4 2926X	82 CAPM & ADA	ADA - New Curb Ramps	Curb ramp(s)	
4 2926X	82 CAPM & ADA	Pavement Preservation (CAPM)	Lane mile(s)	46
4 2927A 4 2927D	DO DO	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2927E	DO	Major Damage (Emergency Restoration)	Location(s)	
4 2927E 4 2927F	DO DO	Major Damage (Emergency Restoration)	Location(s)	
4 2927E 4 2927F 4 2927M	DO D	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P	DO D	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s) Location(s) Location(s)	
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P 4 3033G	DO DO DO DO DO DO DO DO DO DO/SB1/SCL 880 PM 2.7	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Opening)	Location(s) Location(s) Location(s) Location(s) Location(s)	
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P	DO D	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s) Location(s) Location(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P 4 3033G 4 5200 4 8060B 4 8195B	DO DO DO DO DO DO DO DO DO SB1/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM	Major Damaae (Emeraency Restoration) Major Damaae (Emeraency Openina) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridae Preventative Maintenance	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P 4 3033G 4 5200 4 8060B 4 8195B 4 8315N	DO DO DO DO DO DO DOSBI /SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOM WISHOR Creek Br.	Major Damage (Emergency Restoration) Major Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Center(ine mile(s) Collision(s) reduced Bridae(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928E 4 3033G 4 5200 4 8060B 4 8195B 4 8315N 5 0040C	DO DO DO DO DO DO DO DO DO SB1/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM	Maior Damage (Emeraency Restoration) Maior Damage (Emeraency Openina) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Povement Preservation Roadway Rehabilitation (3R)	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P 4 3033G 4 5200 4 8060B 4 8195B 4 8315N 4 8315N 5 0040C 5 0072	DO DO DO DO DO DO DO SITISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOM WISON Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Planting Toro Creek Bridge replacement	Major Damage (Emergency Restoration) Major Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Center(ine mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P 4 3033G 4 5200 4 8060B 4 8195B 4 8315N 5 0040C 5 0072 5 0072A	DO DO DO DO DO DO DO DO/SB1/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM Dan Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitidadion Planting Toro Creek Bridge replacement Old Creek Bridge replacement	Maior Damaae (Emeraency Restoration) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridae Preventative Maintenance Bridae Rehabilitation Pavement Preservation Roadway Rehabilitation and Replacement Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928E 4 3033G 4 5200 4 8060B 4 8158B 4 8315N 5 0040C 5 0072A 5 0072A 5 0072C	DO D	Maior Damage (Emergency Restoration) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation on Replacement Bridge Rehabilitation on Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 2928P 4 3033G 4 5200 4 80608 4 81958 4 8315X 5 0040C 5 0072 5 0072A 5 0072B 5 0072C	DO DOSBI/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DON Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Trout Creek Bridge replacement Trout Creek Bridge replacement Toro Creek Biological Monitoring Old Creek Biological Monitoring	Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 2928P 4 3033G 4 5200 4 81958 4 8315N 4 8315N 5 0040C 5 0072 5 00728 5 00728 5 0072C	DO DO DO DO DO DO DO SIJSCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOM Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Toro L'Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Bidge Robing Robin	Maior Damage (Emergency Restoration) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation on Replacement Bridge Rehabilitation on Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Bridae(s)	2
4)2927E 4)2927F 4)2927F 4)2928E 4)2928E 4)3033G 4 \$1058 4 \$1558 6)0040C 5)0072 5)0072A 5)0072B 5)0072B 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C	DO DO DO DO DO DO DO DO SIDISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOM Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitiagation North Paso Robles Mitiagation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Trout Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Old Creek Biological Monitorina Irout Creek Biological Monitorina Arroyo Paredon Landscape Mitiagtion Plantina Arroyo Paredon Landscape Mitiagtion Plantina SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION	Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation and Replacement Bridge Scour	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 2928P 4 3033G 4 5200 4 80608 4 8158 5 0040C 5 0072A 5 0072A 5 0072B 5 0072C 5 0072B 5 0072C 5 0072C	DO DO DO DO DO DO DO SISTISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DON Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Torot Creek Biological Monitorina Torot Creek Biological Monitorina Torot Creek Biological Monitorina Arrovo Paredon Landscape Mitigation Plantina SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina	Maior Damage (Emergency Restoration) StHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventalive Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Bridae(s)	2
4)2927E 4)2927F 4)2927F 4)2928E 4)2928E 4)3033G 4 \$1058 4 \$1558 6)0040C 5)0072 5)0072A 5)0072B 5)0072B 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C 5)0072C	DO DO DO DO DO DO DO DO SIDISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOM Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitiagation North Paso Robles Mitiagation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Trout Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Old Creek Biological Monitorina Irout Creek Biological Monitorina Arroyo Paredon Landscape Mitiagtion Plantina Arroyo Paredon Landscape Mitiagtion Plantina SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION	Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation and Replacement Bridge Scour	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Lone mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 80608 4 81958 4 8315N 5 0040C 5 0072 5 0072A 5 0072C 5 0072B 5 0072C 5 10072C 5	DO DOSBI/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DORNISON Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Trout Creek Bridge replacement Trout Creek Bridge replacement Trout Creek Biological Monitoring Old Creek Biological Monitoring Old Creek Biological Monitoring Trout Creek Biological Monitoring Arrovo Paredon Landscape Mitigation Planting SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitoring Salsipuedes Biological Monitoring	Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Pavement Preservation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lone mile(s) Lone mile(s) Bridae(s) Cutvert(s) (ea) Cutvert(s) (ea) Cutvert(s) (ea) Cutvert(s)	2
4)2927E 4)2927F 4)2927M 4)2928E 4)2928E 4)3033G 4 5000B 4 8195B 5 0040C 5 0072A 5 0072A 5 0072B 5 0072C 5 0072B 5 0072C 5 007	DO DO DO DO DO DO DO DO SIJISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO OM Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Plantina Toro Creek Bridae replacement Old Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Toro Creek Biological Monitorina Old Creek Biological Monitorina Toro Creek Biological Monitorina Stals Puebes CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Dovenport Bio Hwy 17 Source Control Landscape Split	Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Bridge Scour Bridge System Restoration Drainage System Restoration Storm Water Mitigation	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 8060B 4 81958 4 8315N 5 0040C 5 0072C 5 0072A 5 0072C 5 0072D 5 0072C 5 10072D 5 10072D 5 10072D 5 10072C 5 10072D 5 10072C 5 10072D 5 10072C 5	DO D	Maior Damage (Emergency Restoration) Safety Improvements Bridge Rehabilitation Provement Preservation Roadway Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lone mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928E 4 2928P 4 3033G 4 5200 4 8050B 4 8158N 5 0040C 5 0072A 5 0072B 5 0072B 5 0072B 5 0072B 5 10572A 5 1072A 5 1072A 5 1072A 5 1072A 5 1072A 5 1072A 5 1072B 5 1072C 5 1	DO DO DO DO DO DO DO SISI /SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOM Wilson Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge replacement Torout Creek Bridge replacement Stave Wilson Wilson Wilson Wilson Salsipuedes Biological Monitorina Prove Paredon Landscape Mitigation Planting Arroyo Paredon Landscape Mitigation Planting SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Devenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKILN CREEK King City Trees planting mitigation	Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Preventative Maintenance Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Revenbilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 80608 4 81958 5 0040C 5 0072A 5 0072A 5 0072A 5 0072B 5 0072B 5 1501 5 11501 5 11967 5 11967X 5 1987Y 5 2336 5 2336 5 23386	DO D	Maior Damage (Emergency Restoration) Stofety Improvements Bridge Rehability and Miscellaneous Safety Improvements Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Callision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lone mile(s) Bridae(s) Culvert(s) (ea)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 2928P 4 3033G 4 5200 4 8060B 4 8158N 5 0040C 5 0072A 5 0072C 5 0072B 5 0072C 5 0072B 5 0072C 5 0072B 5 1501Y 5 1967X 5 1989Y 5 2336 5 2386X 5 238	DO DO DO DO DO DO SIB J SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOAN WISION Creek Br. Altamont Rehab Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge SCOUR MITIGATION SALSIPUEDES CREEK BRID	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Bridge Rehabilitation and Replacement Bridge Scour	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Contertine mile(s) Collision(s) reduced Bridae(s) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 80608 4 81958 4 8315X 5 0040C 5 0072C 5 0072A 5 0072A 5 0072B 5 0072C 5 10072C 5	DO D	Maior Damage (Emergency Restoration) StOPP - Sustainability and Miscellaneous Safety Improvements Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Seventry Reduction Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Bridae(s)	2
4 2927E 4 2927F 4 2927M 4 2928P 4 2928P 4 3033G 4 5200 4 8060B 4 8158N 5 0040C 5 0072A 5 0072C 5 0072B 5 0072C 5 0072B 5 0072C 5 0072B 5 1501Y 5 1967X 5 1989Y 5 2336 5 2386X 5 238	DO DO DO DO DO DO SIB J SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOAN WISION Creek Br. Altamont Rehab Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge SCOUR MITIGATION SALSIPUEDES CREEK BRID	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Bridge Rehabilitation and Replacement Bridge Scour	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Contertine mile(s) Collision(s) reduced Bridae(s) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Bridae(s)	
4)2927E 4)2927F 4)2927M 4)2928E 4)2928P 4)3033G 4 \$1508 4 \$1508 6 \$10072A 5 \$0072A 5 \$0072A 5 \$0072B 5 \$0072B 5 \$0072B 5 \$0072B 5 \$1501Y 5 \$1967X 5 \$1967X 5 \$1967X 5 \$1967X 5 \$2380 5 \$2386 5 \$2386 5 \$2381 5 \$2391 5 \$2392 5 \$2391 5 \$2391 5 \$2392 5 \$2391 5 \$2392 5 \$2392 5	DO DO DO DO DO DO DO DO SISI /SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO DO Wilson Creek Br. Altamont Rehab Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Dout Creek Biological Monitorina Trout Creek Biological Monitorina DAVENPORT CULVERT REPLACEMENT Dovenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKILIN CREEK Kina Cith Trees planting mitigation Hwy 217 San Jose Crk Bridge Replacement San Jose Creek 217 Biological Monitorina 217 San Jose Crk Bridge Mitigation Plantina & Monitorina Pismo Creek Scour Repair Project Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Biol Newley Biol Bridge Alamo Pintado Ped Bridge Biol Newley Biol Biol Biol Biol Biol Biol Biol Biol	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (187) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	11
4 2927E 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 81958 4 8315N 4 8315N 5 0040C 5 0072A 5 0072B 5 0072C 5 0072B 5 0072C 5 0072B 5 0072C 5 1072B 5 1501 5 1501 5 1967 5 1967 5 1989Y 5 2336 5 2386X 5 2386X 5 2391 5 2392 5 2426A	DO DO DO DO DO DO DO DO SISTISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOAN WIISON Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge SCOUR Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Arrovo Paredon Landscape Mitigation Plantina Arsup Paredon Landscape Mitigation Plantina SalsipueDES CREEK BRIDGE SCOUR MITIGATION SalsipueDES MITIGATION SalsipueDES CREEK BRIDGE SCOUR MITIGATION SalsipueDES Scour Report SalsipueDES Scour Report SalsipueDES Scour Report SalsipueDES Scour Report Project Alamo Pintado Pedestrion Project Alamo Pintado Pedestrion Bridge Bio Monitorina Cold Spring Bridge Mitigation SalsipueDES	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventality and Miscellaneous Safety Improvements Bridge Rehabilitation Roadway Rehabilitation (SR) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	111
4 2927E 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 8060B 4 81958 5 0040C 5 0072B 5 0072C 5 0072B 5 0072C 5 0072B 5 10072C 5 1072C 5 1072	DO DO DO DO DO DO DO DO SISI /SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO DO Wilson Creek Br. Altamont Rehab Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Dout Creek Biological Monitorina Trout Creek Biological Monitorina DAVENPORT CULVERT REPLACEMENT Dovenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKILIN CREEK Kina Cith Trees planting mitigation Hwy 217 San Jose Crk Bridge Replacement San Jose Creek 217 Biological Monitorina 217 San Jose Crk Bridge Mitigation Plantina & Monitorina Pismo Creek Scour Repair Project Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Biol Newley Biol Bridge Alamo Pintado Ped Bridge Biol Newley Biol Biol Biol Biol Biol Biol Biol Biol	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (187) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	111
4 2927F 4 2927F 4 2927F 4 2927F 4 2927F 4 2928P 4 3033G 4 5200 4 8060B 4 8195B 5 0040C 5 0072A 5 0072A 5 0072A 5 0072B 5 0072C 5 0072B 5 0072C 5 0072B 5 1501 7 1501 7 1501 7 1501 7 1501 7 1705 7 170	DO DO DO DO DO DO SISTISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOAN WISSON Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Plantina Toro Creek Ridge replacement Old Creek Ridge replacement Old Creek Ridge replacement Toro Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Arrovo Paredon Landscape Mitigation Plantina SALSIPUEDES CREEK RIDGE SCOUR MITIGATION Salispuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT REPLACEMENT NO SENDED SCOUR MITIGATION SALSIPUEDES COUR MITIGATION SALSIPUEDES SALSIPUEDES MITIGATION SALSIPUEDES SALSIPUEDES MITIGATION SALSIPUEDES MITIGAT	Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Darianae System Restoration Darianae System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation Safety Enhancements Roadway Rehabilitation Safety Enhancements Roadway Rehabilitation	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Bridae(s)	111
4 2927F 4 2927F 4 2928F 4 2928B 4 2928B 4 3033G 4 \$1508 4 \$1508 5 0004C 5 0072A 5 0072B 5 0	DO DO DO DO DO DO DO DO SISI /SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO DO MISION Creek Br. Altamont Rehab Mitigation Plantina Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Toro Creek Biological Monitorina Double Creek Biological Monitorina Toro Creek Biological Monitorina Arroyo Poredon Landscape Mitigation Plantina Salsi Pubers CREEK RENDES SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Dovenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKILIN CREEK Kina Citix Trees plantina mitigation Hwy 217 San Jose Crk Bridge Replacement San Jose Creek 217 Biological Monitorina 217 San Jose Crk Bridge Mitigation Plantina & Monitorina Pismo Creek Scour Repair Project Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Segment 4A Mitigation Monitorina Rehab Segment 4A Mitigation Monitorina Rehab Segment 4A Mitigation Monitorina Rehab Segment 4A Mitigation Monitorina	Maior Damage (Emergency Restoration) Safety Improvements Bridge Rehabilitation Provement Preservation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Bridge Scour Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	111
4 2927F 4 2927F 4 2927F 4 2927F 4 2927F 4 2928P 4 3033G 4 5200 4 8060B 4 8195B 5 0040C 5 0072A 5 0072A 5 0072A 5 0072B 5 0072C 5 0072B 5 0072C 5 0072B 5 1501 7 1501 7 1501 7 1501 7 1501 7 1705 7 170	DO DO DO DO DO DO SISTISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO DO MISION Creek Br. Altamont Rehab Mitigation North Paso Robles Mitigation Plantina Toro Creek Ridge replacement Old Creek Ridge replacement Old Creek Ridge replacement Toro Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Arrovo Paredon Landscape Mitigation Plantina SALSIPUEDES CREEK RIDGE SCOUR MITIGATION Salispuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT REPLACEMENT NOVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT REPLACEMENT DOVENPORT CULVERT NEAR LIMEKILIN CREEK Kina City Trees plantina mitigation Hww 217 San Jose Crk Bridge Replacement San Jose Creek Sour Repoir Project Alamo Pintado Pede Bridge Alamo Pintado Pedestrian Bridge Bio Monitorina Pismo Creek Scour Repoir Project Alamo Pintado Pedestrian Bridge Bio Monitorina DRID Rehab - Padarro (Segment 48) SB 101 Rehab - Padarro (Segment 46) Segment 40 - North EWP Segment 44 Mitigation Monitorina Rehab Segment 44 Mitigation Planting	Maior Damage (Emergency Restoration) Maior Damage (Emergency Openina) SHOPP - Sustainability and Miscellaneous Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Darianae System Restoration Darianae System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation Safety Enhancements Roadway Rehabilitation	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Bridae(s)	111
4 2927E 4 2927F 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 8050B 4 81958 4 8315N 5 0040C 5 0072B 5 0072C 5 0072B 5 0072C 5 10072C 5	DO DO DO DO DO DO DO SISI / SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO MISION Creek Br. Altamont Rehab Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina DIASIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Davenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKLIN CREEK Kina City Trees planting mitigation Hwy 217 San Jose Crk Bridge Mitigation Planting 217 San Jose Crk Bridge Mitigation Planting Pismo Creek 217 Biological Monitorina 217 San Jose Crk Bridge Mitigation Planting Pismo Creek Scour Repair Project Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge SB 101 Rehab - Padaro (Seament 48) Seament 4A Mitigation Monitoring Rehab Seament 4A Mitigation Planting Toro Creek Fish Passage Seament 4B Mitigation Monitoring Rehab Seament 4C Mitigation Monitoring	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Rehabilitation and Replacement Bridge Rehabilitation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Contertine mile(s) Collision(s) reduced Bridae(s) Br	111
4 2927E 4 2927F 4 2927M 4 2928P 4 2928P 4 3033G 4 5200 4 8060B 4 81958 5 0040C 5 0072A 5 0072C 5 0072B 5 0072C 5 0072B 5 10072C 5 10072B 5	DO DO DO DO SISTISCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOA WIlson Creek Br. Altamont Rehab Mitigation Plantina Toro Creek Ridge replacement Old Creek Ridge replacement Old Creek Ridge replacement Toro Creek Ridge Ridge SCOUR MITIGATION SALSIPUEDES CREEK RIDGE CREEK SA	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (SR) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation (3R)	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s)	111 66 ;
4 2927E 4 2927F 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 8050B 4 81958 4 8315N 5 0040C 5 0072B 5 0072C 5 0072B 5 0072C 5 10072C 5	DO DO DO DO DO DO DO SISI / SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO MISION Creek Br. Altamont Rehab Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina DIASIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Davenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKLIN CREEK Kina City Trees planting mitigation Hwy 217 San Jose Crk Bridge Mitigation Planting 217 San Jose Crk Bridge Mitigation Planting Pismo Creek 217 Biological Monitorina 217 San Jose Crk Bridge Mitigation Planting Pismo Creek Scour Repair Project Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge SB 101 Rehab - Padaro (Seament 48) Seament 4A Mitigation Monitoring Rehab Seament 4A Mitigation Planting Toro Creek Fish Passage Seament 4B Mitigation Monitoring Rehab Seament 4C Mitigation Monitoring	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Rehabilitation and Replacement Bridge Rehabilitation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Contertine mile(s) Collision(s) reduced Bridae(s) Br	111 66 2
4)2927E 4)2927F 4)2927F 4)2927F 4)2927F 4)2928F 2)	DO SISI/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOR MISION Creek Br. Altamont Rehab Mitigation North Paso Robles Mitiadiation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Arrovo Poredon Landscape Mitigation Plantina SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Davenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKILIN CREEK Kina City Trees plantina mitigation Hwy 217 Son Jose Crk Bridge Replacement San Jose Creek 217 Biological Monitorina Pismo Creek Scour Repoir Project Alamo Pintado Ped Bridge Monitorina Cold Sprina Bridge Maintenance Inspection Access SB 101 Rehab - Padaro (Segment 4B) SB 101 Rehab - Padaro (Segment 4B) SB 101 Rehab - Padaro (Segment 4B) Segment 4D - North EWP Segment 4A Mitigation Monitorina Rehab Segment 4A Mitigation Monitorina	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation (3R) Roadway Rehabilitation	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Louvert(s) (ea) Collision(s) reduced Bridae(s) Bri	111 66 :
4 2927E 4 2927F 4 2927F 4 2927M 4 2928P 4 3033G 4 5200 4 8050B 4 81598 6 8315N 6 8315N 6 8315N 6 8315N 6 8315N 7 80072B	DO DO DO DO DO DO DO DO SBI JSCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DO MISION Creek Br. Altamont Rehab Mitigation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina DIASIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Davenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKLIN CREEK Kina City Trees planting mitigation Hwy 217 San Jose Crk Bridge Mitigation Planting 217 San Jose Crk Bridge Mitigation Planting Pismo Creek 217 Biological Monitorina 217 San Jose Crk Bridge Mitigation Planting Pismo Creek Scour Repair Project Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge Alamo Pintado Ped Bridge SB 101 Rehab - Padaro (Seament 48) Seament 4A Mitigation Monitorina Rehab Seament 4A Mitigation Planting Toro Creek Fish Passage Seament 4B Mitigation Monitorina Rehab Seament 4C Mitigation Planting SB 101 AD North Landscape Mitigation	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Drainage System Restoration Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Collision Severity Reduction	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Contestine mile(s) Collision(s) reduced Bridae(s)	111 66 2
4)2927E 4)2927F 4)2927F 4)2927F 4)2927F 4)2928F 2)	DO SISI/SCL 880 PM 2.7 MRN 37 FLOOD REDUCTION PROJECT ENVIRONMENTAL MITIGATION BRIDGE DECK PROGRAM DOR MISION Creek Br. Altamont Rehab Mitigation North Paso Robles Mitiadiation Planting Toro Creek Bridge replacement Old Creek Bridge replacement Toro Creek Bridge replacement Toro Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Old Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Trout Creek Biological Monitorina Arrovo Poredon Landscape Mitigation Plantina SALSIPUEDES CREEK BRIDGE SCOUR MITIGATION Salsipuedes Biological Monitorina DAVENPORT CULVERT REPLACEMENT Davenport Bio Hwy 17 Source Control Landscape Split REPLACE CULVERT NEAR LIMEKILIN CREEK Kina City Trees plantina mitigation Hwy 217 Son Jose Crk Bridge Replacement San Jose Creek 217 Biological Monitorina Pismo Creek Scour Repoir Project Alamo Pintado Ped Bridge Monitorina Cold Sprina Bridge Maintenance Inspection Access SB 101 Rehab - Padaro (Segment 4B) SB 101 Rehab - Padaro (Segment 4B) SB 101 Rehab - Padaro (Segment 4B) Segment 4D - North EWP Segment 4A Mitigation Monitorina Rehab Segment 4A Mitigation Monitorina	Maior Damage (Emergency Restoration) Safety Improvements Bridge Preventative Maintenance Bridge Rehabilitation Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement Bridge Scour Bridge Scour Drainage System Restoration Drainage System Restoration Storm Water Mitigation Drainage System Restoration Collision Severity Reduction Bridge Rehabilitation and Replacement Bridge Rehabilitation Roadway Rehabilitation (3R) Roadway Rehabilitation	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Centerline mile(s) Collision(s) reduced Bridae(s) Louvert(s) (ea) Collision(s) reduced Bridae(s) Bri	111 66 :

5 0 4 40 1	D. f. of a APP of the District of	Distance Deliver Whether and Development	District)	
5 2448Y 5 2452	Refugio Mitigation Planting project Mon Scr Roadside Safety	Bridge Rehabilitation and Replacement Roadside Safety Improvements	Bridge(s) Location(s)	69
5 2460	North Santa Barbara County Roadside Safety	Roadside Safety Improvements	Location(s)	25
5 2462 5 2466	Gaviota Rest Area Water Systems Upgrade Guadalupe ADA	Roadside Safety Improvements ADA - New Curb Ramps	Location(s) Curb ramp(s)	
5 2468	Butterfly Lane PUC ADA	ADA - New Curb Ramps	Curb ramp(s)	20
5 2474	Salinas Rehab	Pavement Preservation	Lane mile(s)	17.7
5 2478 5 2518	Replace 7 Culverts on Mon-1 Route 101 and Route 41 Barrier Improvements	Drainage System Restoration Safety Enhancements	Culvert(s) (ea) Collision(s) reduced	38
5 2522	101/135 Bridge Replacement	Bridge Major Rehabilitation	Bridge(s)	JC.
5 2522Y	101/135 Landscape split	Bridge Rehabilitation and Replacement	Bridge(s)	C
5 2524	Limekiln Creek Bridge Replacement Corralitos Creek ADA	Bridge Rehabilitation and Replacement	Bridge(s) Curb ramp(s)	1
5 2530 5 2532	Route 41 Atascadero ADA Project	ADA - New Curb Ramps ADA - New Curb Ramps	Curb ramp(s)	36
5 2534	Big Sur CAPM	Pavement Rehabilitation	Lane mile(s)	69.9
5 2538	N Route 17 CAPM	Pavement Rehabilitation	Lane mile(s)	26.2
5 2540 5 2542	Salinas CAPM Las Cruces CAPM	Pavement Rehabilitation Pavement Rehabilitation	Lane mile(s) Lane mile(s)	54.6 42.6
5 2546	Paris Valley 2R Rehab	Pavement Preservation	Lane mile(s)	9.9
5 2561	Nojoqui Creek Bridge (51-0018) Railing Upgrade	Bridge Rail Replacement and Upgrade	Linear feet rail	844
5 2561A 5 2563	Nojoqui Bridge Rail - Bio Mitigation Monitoring Route 1/San Antonio Creek Bridge Scour Mitigation	Bridge Rail Replacement and Upgrade Bridge Scour	Linear feet rail Bridge(s)	
5 2565	San Antonio River bridge-seismic retrofit	Bridge Seismic Restoration	Bridge(s)	2
5 2565A	San Antonio river post-construction biological monitoring	Bridge Seismic Restoration	Bridge(s)	C
5 2567 5 2569	San Antonio Cr Seismic Retrofit SCr 9 South Drainage and Erosion Control Improvements	Bridge Seismic Restoration Storm Water Mitigation	Bridge(s)	6.3
3 2369	SCF 9 South Drainage and Erosion Control Improvements	Storm water Miligation	Acre(s) treated/pollutant	0.0
5 2571	Monterey-San Benito Co Roadside Safety Improvements	Roadside Safety Improvements	Location(s)	52
5 2585	Santa Cruz Bridge Rails	Bridge Rail Replacement/Upgrade	Linear feet	1525
5 2586 5 2587	Solomon Canyon CAPM Cayucos CAPM	Pavement Rehabilitation Pavement Rehabilitation	Lane mile(s) Lane mile(s)	18.5 25.6
5 2590	Santa Cruz County APS	ADA - New Curb Ramps	Curb ramp(s)	136
5 2593	Wildlife Habitat	Roadside Protection and Restoration	Location(s)	1
5 2594 5 2595	SB/SLO Horizontal Curve Signs Warning Sign Upgrades	Safety Enhancements Safety Enhancements	Collision(s) reduced Collision(s) reduced	20 18
5 2625	129/Lakeview Intersection Improvement	Safety Improvements	Collision(s) reduced	46
5 2627X	Santa Cruz 9 Drainage Bio Monitoring Child	Storm Water Mitigation	Acre(s)	C
5 2628	Pedestrian Signals #2	Safety Enhancements	treated/pollutant Collision(s) reduced	2
5 2629	Santa Maria CAPM	Pavement Rehabilitation	Lane mile(s)	24.5
5 2630	Pismo Beach CAPM	Pavement Preservation (CAPM)	Lane mile(s)	13.8
5 2633	Camp Roberts SRRA Infrastructure Upgrade	Roadside Safety Improvements	Location(s)	2
5 2634 5 2635	Box Beam Overhead Signs Market Street Northbound On-ramp Improvements	Signs and Lighting Rehabilitation Collision Severity Reduction	Lighting fixture(s) Collision(s) reduced	33
5 2636	Pasatiempo II	Safety Improvements	Collision(s) reduced	140
5 2647	Pacific Grove ADA Pathway	ADA - New Curb Ramps	Curb ramp(s)	8
5 2648 5 2649	Seaside ADA San Jose Creek Bridge replacement	ADA - New Curb Ramps Bridge Rehabilitation and Replacement	Curb ramp(s) Bridge(s)	13
5 2650	Santa Maria River Bridge Replacement	Bridge Rehabilitation and Replacement	Bridge(s)	1
5 2650X	Santa Maria Bridge - Bio Monitoring	Bridge Rehabilitation and Replacement	Bridge(s)	C
5 2650Y 5 2651	Santa Maria River Bridge - Landscape Mitigation	Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s)	
5 2655	Rehab Primavera & La Colina Bridges San Lorenzo River Bridge and Kings Creek Bridge Replacement	Bridge Rehabilitation and Replacement	Bridge(s)	2
5 2655Y	San Lorenzo River and Kings Creek Bridge Split Bio Mitigation	Bridge Rehabilitation and Replacement	Bridge(s)	C
5 2656	Castro Cyn Bridge Rail Upgrade	Bridge Rail Replacement and Upgrade	Annual fatal and serious injury collision(s)	0.01
5 2667	Solomon Canyon Rumble Strip/Shoulder Widening	Collision Severity Reduction	Annual fatal and serious injury collision(s)	0.38
5 2667X	Solomon Canyon Bio Monitoring	Collision Severity Reduction	Annual fatal and serious injury collision(s)	С
5 2674	154/Baseline-Edison Roundabout	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	10
5 2674Y 5 2678	SR154 Baseline/Edison Landscape Mitigation Castroville Improvement Project	Operational Improvements SHOPP - Sustainability and Miscellaneous	Daily vehicle hour(s) of delay (DVHD) Location(s)	C
5 2679	Prunedale CAPM	Pavement Preservation (CAPM)	Lane mile(s)	37
5 2696	Garrapata Creek Bridge Rail Replacement	Bridge Rail Replacement and Upgrade	Linear feet rail	650
5 2697Y	SB1-25 Curve Alignment Restoration SB1-25 Curve Planting Mitigation	Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s)	14 C
5 2699	Santa Maria Roadside Safety Improvements Project	Roadside Safety Improvements	Location(s)	66
5 2700	Gaviota-Nojogui CAPM	Pavement Preservation (CAPM)	Lane mile(s)	27.6
5 2701	Vineyard Roundabout	Safety Improvements	Collision(s) reduced	14
5 2703 5 2704	Route 135 Signal Modifications CTS Advance Mitigation	Safety Improvements Roadside Enhancement (Mitigation Site	Collision(s) reduced Location(s)	660
		Relinguishments)		
5 2705	ZEV project	SHOPP - Misc	Location(s)	3
5 2725 5 2726	Santa Cruz Route 1 CAPM North Buellton CAPM & Drainage	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	8.3 34.5
5 2735	TMS Detection Repair	Transportation Management (TMC's & Field	Field element(s)	100
		Equipment)		
5 2736 5 2736X	Soquel Creek Scour Protection Soquel Creek Biological Monitoring	Bridge Preventative Maintenance Bridge Preventative Maintenance	Bridge(s) Bridge(s)	1
5 2736Y	Soquel Creek Landscape Planting	Bridge Preventative Maintenance	Bridge(s)	C
5 2740	SB Marsh Street Improvements	Safety Improvements	Collision(s) reduced	20
5 2742 5 2745	Hwy 68 Curve Correction Bunny Avenue and North Broadway Ped Improvements	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	182
	SR 25/156 Roundabout	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	5 76
5 2746			Collision(s) reduced	C
5 2746Y	SR 25/156 Roundabout Landscape Split	Safety Improvements		
	SR 25/156 Roundabout Landscape Split NB SLO 101 Superelevation and OGFC Wellsona Safety Improvements	Safety Improvements Safety Improvements Safety Improvements	Collision(s) reduced Annual fatal and serious injury collision(s)	0.22
5 2746Y 5 2765	NB SLO 101 Superelevation and OGFC	Safety Improvements	Collision(s) reduced Annual fatal and serious	67 0.22
5 2746Y 5 2765 5 2766 5 2766Y	NB SLO 101 Superelevation and OGFC Wellsona Safety Improvements Wellsona Planting Mitigation Project	Safety Improvements Safety Improvements Safety Improvements	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s)	0.22 C
5 2746Y 5 2765 5 2766 5 2766Y 5 2775 5 2776	NB SLO 101 Superelevation and OGFC Wellsona Safety Improvements	Safety Improvements Safety Improvements	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious	0.22
5 2746Y 5 2765 5 2766 5 2766Y 5 2775 5 2776 5 2778	NB SLO 101 Superelevation and OGFC Wellsona Safety Improvements Wellsona Planting Mitigation Project 129 Pavina, Sian Panels, Liahtina, TMS Improvement SBT US101 Pavement Rehabilitation Project SLO County Asset Management Improvements	Safety Improvements Safety Improvements Safety Improvements Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s)	6.8 30.3 34.7
5 2746Y 5 2765 5 2766 5 2766Y 5 2775 5 2776 5 2778 5 2778X	NB SLO 101 Superelevation and OGFC Wellsona Safety Improvements Wellsona Planting Mitigation Project 129 Pavina, Sian Panels, Liahtina, TMS Improvement SBT US101 Pavement Rehabilitation Project SLO County Asset Managaement Improvements SLO County Asset Managaement Improvements SLO County Asset Managaement Improvements	Safety Improvements Safety Improvements Safety Improvements Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	0.22 0 6.8 30.3 34.7
5 2746Y 5 2766 5 2766Y 5 2775 5 2776 5 2778 5 2778 5 278X 5 2787	NB SLO 10.1 Superelevation and OGFC Wellsona Safety Improvements Wellsona Planting Mitigation Project 129 Pavina, Sian Panels, Lightina, TMS Improvement SBI US10.1 Pavement Rehabilitation Project SLO County Asset Management Improvements SLO County Asset Bio-Monitoring Project Route 68 Drainage Improvements SR-68 Culvetts Biological Monitoring Project	Safety Improvements Safety Improvements Safety Improvements Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Culvert(s) (ea) Culvert(s) (ea)	6.8 30.3 34.7
5 2746Y 5 2766 5 2766 5 2766 5 2776 5 2775 5 2776 5 2778 5 2778 5 2787 5 2787	NB SLO 101 Superelevation and OGFC Wellsona Safety Improvements Wellsona Planting Mitigation Project 129 Pavina, Sian Panels, Liahtina, TMS Improvement SBT US101 Pavement Rehabilitation Project SLO County Asset Management Improvements SR-68 Culverts Biological Monitorina Project Landscape restoration for 05-1J880 parent project	Safety Improvements Safety Improvements Safety Improvements Pavement Preservation (CAPM) Roadway Rehabilitation (2R) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Drainage System Restoration Drainage System Restoration Drainage System Restoration	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Cuvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea)	6.8 30.3 34.7 C
5 2746Y 5 2766 5 2766Y 5 2775 5 2776 5 2778 5 2778 5 278X 5 2787	NB SLO 10.1 Superelevation and OGFC Wellsona Safety Improvements Wellsona Planting Mitigation Project 129 Pavina, Sian Panels, Lightina, TMS Improvement SBI US10.1 Pavement Rehabilitation Project SLO County Asset Management Improvements SLO County Asset Bio-Monitoring Project Route 68 Drainage Improvements SR-68 Culvetts Biological Monitoring Project	Safety Improvements Safety Improvements Safety Improvements Pavement Preservation (CAPM) Roadway Rehabilitation (ZR) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Drainage System Restoration Drainage System Restoration	Collision(s) reduced Annual fatal and serious injury collision(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Culvert(s) (ea) Culvert(s) (ea)	0.22 C 6.8 30.3 34.7 C 34

5 2799 5 2799F	Could Count 101 Desirous	Davis and Carloss Barbara Para	0.1	20
	South Coast 101 Drainage Rincon Fish Passage	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	38
5 2804	Santa Cruz 1 CAPM and Bridge Rails	Bridge Rail Replacement/Upgrade	Linear feet	1525
5 2804	Santa Cruz 1 CAPM and Bridge Rails	Pavement Rehabilitation	Lane mile(s)	28.3
5 2843 5 2843A	SCR 1 Roadside Safety SCR 1 Roadside safety Freedom-State	Drainage System Restoration Collision Severity Reduction	Culvert(s) (ea) Collision(s) reduced	C
5 2843B	SCR1 Roadside Safety PM 10.6 to 26	Drainage System Restoration	Culvert(s) (ea)	29
5 2845	Santa Margarita 58 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	11.7
5 2845X 5 2845Y	Santa Margarita 58 Bio Monitoring Santa Margarita 58 Landscape	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	
5 2847	PM 10.8 Extend Side Hill Viaduct	Major Damage (Permanent Restoration)	Location(s)	1
5 2849	Little Sur Retaining Wall	Major Damage (Permanent Restoration)	Location(s)	1
5 2850	Mud Creek Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	
5 2853 5 2855	Big Creek Tieback Wall Pfeiffer Canyon Mitigation	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	1
5 2855X	Pfeiffer Mitigation Utility Relocation	Major Damage (Permanent Restoration)	Location(s)	
5 2870	Miller Street Signal Modification	Safety Improvements	Collision(s) reduced	25
5 2874	PM 1.0 and 4.0 Viaduct	Major Damage (Permanent Restoration)	Location(s)	2
5 2875 5 2876	Spring Cr. PM 15 Soldier Pile Wall PM 19.97 Hairpin Tieback	Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	
5 2879	South SCr 9 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	14.7
5 2880	Upper Hwy 9 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	14.2
5 2880F	Waterman Gap Fish Passage	SHOPP - Sustainability and Miscellaneous	Location(s)	1
5 2882 5 2883	Rumble Strip Project Mon Safety Rumble Strip Project	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	118 231
5 2889	Moss Landing CAP-M	Pavement Preservation (CAPM)	Lane mile(s)	22.4
5 2899	Salinas to Castroville CAPM	Pavement Preservation (CAPM)	Lane mile(s)	12.7
5 2900	King City CAPM	Pavement Preservation (CAPM)	Lane mile(s)	28
5 2900X 5 2900Y	King City CAPM Biological Monitoring King City CAPM Landscape Mitigation	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	(
5 2900Y 5 2902	North Nojoqui Grade CAPM & Drainage	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s)	14.4
5 2902X	North Nojoqui Grade Bio Monitoring	Pavement Preservation (CAPM)	Lane mile(s)	(
5 2902Y	North Nojoqui Grade Landscape Mitigation	Pavement Preservation (CAPM)	Lane mile(s)	(
5 2903 5 2904	Paso Robles 46 CAPM Bradley CAPM	Pavement Preservation (CAPM) Bridge Rehabilitation and Replacement	Lane mile(s)	8.2
5 2904	EFA - Contract #05A2162 - JPB Roadway Repair	Major Damage (Emergency Opening)	Bridge(s) Location(s)	1
5 2907	EFA - Contract #05A2173 - Mud Point Repair	Major Damage (Emergency Opening)	Location(s)	1
5 2908	EFA - Contract #05A2163 - Clear Arch Culvert	Major Damage (Emergency Opening)	Location(s)	
5 2909 5 2911	EFA - Contract #05A2172 - Drainage System Repair EFA - Contract #05A2179 - Clear Structures	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	1
5 2912	EFA - Contract #05A2179 - Clear Structures EFA - Contract #05A2180 - Repair Slip outs	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
5 2913	EFA - Contract #05A2181 - Repair at 3 locations	Major Damage (Emergency Opening)	Location(s)	3
5 2914	EFA - Contract #05A2183 - Repair Rockfall Barriers	Major Damage (Emergency Opening)	Location(s)	8
5 2916 5 2918X	Bradley - San Ardo CAPM Zaca Station to Orcutt Drainage Rehab Biological Monitering	Pavement Preservation (CAPM) Drainage System Restoration	Lane mile(s) Culvert(s) (ea)	44.1
5 2919	Hwy 154 Drainage Improvements	Drainage System Restoration	Culvert(s) (ea)	31
5 2919X	Highway 154 Bio Monitoring Project	Drainage System Restoration	Culvert(s) (ea)	Ċ
5 2919Y	Hwy 154 Landscape Mitigation	Drainage System Restoration	Culvert(s) (ea)	(
5 2920 5 2921	D5 Maintenance Station Relocation Hwy 17 Drainage Improvements	Maintenance Facilities Storm Water Mitigation	Location(s) Acre(s)	13.9
5 2921	nwy 17 Drainage improvements	Storm water Miligation	treated/pollutant	13.9
5 2927	Morro Rd Soldier Pile Wall	Major Damage (Permanent Restoration)	Location(s)	1
5 2927X	Morro Rd Soldier Wall- Bio Monitoring	Major Damage (Permanent Restoration)	Location(s)	C
5 2997	EFA - Contract #05A2189 - Polar Star	Major Damage (Emergency Opening)	Location(s)	
5 2998 5 3002	EFA Contract #05A2200 Repair Drainage Systems	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	I
5 3003	Glen Cyn Rd UC Median Barrier	Major Damage (Emergency Opening)	Location(s)	1
5 3004	PSPS High Priority Signals ? South ELB	Major Damage (Emergency Opening)	Location(s)	12
5 3006 5 3008	Guadalupe to Santa Maria SR 166 CAPM SCr Rts 1, 9, 17, 129 SBT 25, 156	Pavement Preservation (CAPM)	Lane mile(s)	22.6 753
5 3008	North San Ardo Rehab	Safety Improvements Roadway Rehabilitation (2R)	Collision(s) reduced Lane mile(s)	753
5 3010	Route 246 Cap-M and Robinson Bridge	Bridge Scour	Bridge(s)	1
5 3011	San Marcos Pass HFST	Safety Improvements	Collision(s) reduced	151
5 3012	Felton Pedestrian Safety Improvements	Safety Improvements	Annual fatal and serious	0.5
			injury collision(s)	
5 3013	Alamo Pintado Replacement Bridge	Bridge Scour	Bridge(s)	1
5 3014	San Lucas Rehab	Roadway Rehabilitation (2R)	Lane mile(s)	
5 3015	Gaviota Creek Improvements	Protective Betterments		24
5 3017 5 3018	Heartwood Hill Embankment Restoration		Location(s)	24 1
		Major Damage (Permanent Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s) Location(s)	24 1 1
5 3019	Santa Cruz Long-toed Salamander Connectivity & Drainage Project	Major Damage (Permanent Restoration) Drainage System Restoration	Location(s) Location(s) Culvert(s) (ea)	24 1 1 1 12
5 3019 5 3020	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration	Major Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening)	Location(s) Location(s) Culvert(s) (ea) Location(s)	1 1 1 12
5 3019 5 3020 5 3021	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB	Major Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s) Culvert(s) (ea) Location(s) Location(s)	1 1 12 12
5 3019 5 3020 5 3021 5 3022	Santa Cruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina)	Location(s) Location(s) Culvert(s) (ea) Location(s) Location(s	1 1 12 12
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals & North ELB Turnpike Sink Hole Atascodero Slab Replacements CZU August Lightning Complex Fire Restoration	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s) Culver(s) (ea) Location(s)	1 1 12 1 42 1 1
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025	Santa Cruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals & North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Openina) Safety Improvements	Location(s) Location(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Codisjon(s) Codisjon(s)	1 1 12 1 42 1 1
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025 5 3026	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole Atascadero Slab Realacements CZU August Lighthina Complex Fire Restoration Route 1 7 HFST SB/SLO Rumble Strip, Delineation, Sign Project	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Openina) Safety Improvements Safety Improvements	Location(s) Collision(s) reduced Collision(s) reduced	1 1 12 12 42 1 1 1 1 856
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025 5 3026 5 3027	Santa Cruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals & North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Openina) Safety Improvements	Location(s) Location(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Codisjon(s) Codisjon(s)	42 42 1 856
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025 5 3026 5 3027 5 3028 5 3029	Santa Gruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals & North ELB Turnpike Sink Hole Atascadero Slob Replacements CZU August Lightning Complex Fire Restoration Route 1 7 HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hozordous Tree Removal	Maior Domaae (Permanent Restoration) Drainage System Restoration Major Domage (Emergency Opening) Maior Domaae (Emergency Openina) Maior Domaae (Emergency Openina) Major Domaae (Emergency Openina) Major Domaae (Emergency Openina) Safety Improvements Safety Improvements Major Domaae (Emergency Openina)	Location(s) Location(s) Culver(s) (eq) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	42 42 1 856
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025 5 3026 5 3027 5 3028 5 3029 5 3030	Santa Cruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hiah Priority Signals & North ELB Turnpike Sink Hole Atascadero Slab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Roadway Protective Betterments	Location(s) Location(s) Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	42 42 1 856
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025 5 3026 5 3027 5 3028 5 3029 5 3030 5 3030 5 3030	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightnina Complex Fire Restoration Route 1 7 HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Major Damage (Emergency Opening) Safety Improvements Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Roadway Protective Betterments Major Damage (Emergency Opening)	Location(s) Location(s) Culver(s) (eq) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s)	12 42 43 85c 111
5 3019 5 3020 5 3021 5 3022 5 3023 5 3024 5 3025 5 3026 5 3027 5 3028 5 3029 5 3030 5 3030 5 3032	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals & North ELB Tumpike Sink Hole Alascoadero Slabo Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Morina to Castroville CAPM	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Roadway Protective Betterments Major Damage (Emergency Openina) Pavement Preservation (CAPM)	Location(s) Location(s) Culver(fs) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Lane mile(s)	12 42 43 85c 111
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3027 \$ 3028 \$ 3029 \$ 3033 \$ 3033 \$ 3033 \$ 3033 \$ 3033 \$ 3033	Santa Cruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hish Priority Sianals ? North ELB Turnpike Sink Hole Atlascadero Slab Replacements CZU Auaust Lightnina Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hozordous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Safety Improvements Safety Improvements Major Damage (Emergency Opening) Roadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements	Location(s) Location(s) Culver(s) (eq) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Collision(s) Collision(s) Collision(s) Collision(s)	42 42 43 45 45 47 47 47 47 47 47 47 47 47 47 47 47 47
\$ 3019 \$ 3020 \$ 3020 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3027 \$ 3026 \$ 3027 \$ 3028 \$ 3032 \$ 3032 \$ 3032 \$ 3033 \$ 3033 \$ 3033 \$ 3033 \$ 3033 \$ 3033 \$ 3039 \$ 3039	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hiah Priority Signals & North ELB Turnpike Sink Hole Alascadero Silab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest.	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Ragdway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Emergency Opening)	Location(s) Location(s) Colvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	42 42 43 45 45 47 47 47 47 47 47 47 47 47 47 47 47 47
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 30300 \$ 30300 \$ 30300 \$ 30300 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 303	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Turnpike Sink Hole Atascadero Slab Replacements CZU August Lightnina Complex Fire Restoration Route 1 7. HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM DS Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergancy	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Safety Improvements Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Fermanent Restoration)	Location(s) Location(s) Culver(s) (eq) Location(s)	42 42 43 45 45 47 47 47 47 47 47 47 47 47 47 47 47 47
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3028 \$ 3027 \$ 3028 \$ 3030 \$ 30300 \$ 30300 \$ 30300 \$ 30300 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 303	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hiah Priority Signals & North ELB Turnpike Sink Hole Alascadero Silab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest.	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Roadway Protective Betterments Major Damage (Emergency Openina) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Permanent Qpenina)	Location(s) Location(s) Couver(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s)	42 42 43 45 45 47 47 47 47 47 47 47 47 47 47 47 47 47
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3029 \$ 3030 \$ 30300 \$ 30300 \$ 30300 \$ 30300 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 303	Santa Cruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole Atlascadero Slab Replacements CZU August Lighthina Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sign Project Mon 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm, Rest. Rat Creek - Emergency Dolan Culvert Clearina Coastlonds Wall 2 Unsheltered Encampments North	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Raadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Major Damage (Ferencency Opening) Major Damage (Ferencency Opening) Major Damage (Ferencency Opening) Major Damage (Ferencency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s) Culvert(s) (eq) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Seridae(s) Location(s)	12 42 85 11 21 22 22.
\$ 3019 \$ 3020 \$ 3020 \$ 3022 \$ 3022 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3028 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 30300 \$ 30300 \$ 30300 \$ 30300 \$ 30300 \$ 3030 \$ 3030 \$ 3030 \$ 30	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals & North ELB Tumpike Sink Hole Atascoadero Slabo Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Morina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascoadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearina Coastlands Woll 2 Unsheltered Encampments North Unsheltered Encampments Central	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Roadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Emergency Opening)	Location(s) Location(s) Location(s) Culverf(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location	15 42 85, 11 21 22. 22. 166 8
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3022 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3027 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3041 \$ 3044 \$ 3044 \$ 3044 \$ 3045 \$ 3044	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Turnpike Sink Hole Atascadero Slab Replacements CZU August Lightning Complex Fire Restoration Route 17. HFST SSRSLO Rumble Strip, Delineation, Sign Project Man 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM DS Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergancy Dolan Culvert Clearing Coastlands Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jack's Peok CAPM	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Raadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s) Culverf(s) (eq) Location(s)	22.: 16: 18: 18: 18: 18: 11:
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 3040 \$ 3040 \$ 3040 \$ 3045 \$ 3045 \$ 3045 \$ 3055 \$ 3055 \$ 3065 \$ 3065	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hish Priority Sianals ? North ELB Turnpike Sink Hole Atascadero Slob Replacements CZU August Lightning Complex Fire Restoration Route 1 7 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hozardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Morina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slob Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearing Coastlands Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jacks Peak CAPM North of the Y on 41 CAPM	Maior Damage (Permanent Restoration) Drainage System Restoration Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Roadway Protective Betterments Major Damage (Emergency Openina) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Femanent Restoration) Maior Damage (Femergency Openina) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM)	Location(s) Location(s) Location(s) Culvert(s) (ea) Location(s) Lo	22.2 116 16 18 18 16 16 18 11.
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3041 \$ 3045 \$ 3052 \$ 3052 \$ 3052 \$ 3052 \$ 3052 \$ 3052 \$ 3052 \$ 3053	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hish Priority Sianals ? North ELB Tumpike Sink Hole Atlascadero Slab Replacements CZU August Lighthina Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearina Coasilonds Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jack's Peak CAPM North of the Y' on 41 CAPM Guadalupe CAPM Morro Bay CAPM	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Permanent Restoration) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Location(s) Location(s) Culver(s) (eq) Location(s) Lo	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3028 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3041 \$ 3045 \$ 3045 \$ 3055 \$ 3052	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hish Priority Sianals ? North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearing Coastlands Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jacks Peak CAPM Morro Bay CAPM	Maior Damage (Permanent Restoration) Drainage System Restoration Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Roadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Major Damage (Femergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Femergency Opening) Maior Damage (Femergency Opening) Maior Damage (Femergency Opening) Maior Damage (Femergency Restoration) Maior Damage (Femergency Restoration) Maior Damage (Femergency Restoration) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Location(s) Location(s) Location(s) Culver(s) (ea) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Locati	15. 42. 45. 45. 45. 45. 45. 45. 45. 45. 45. 45
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3022 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3031 \$ 3041 \$ 3045 \$ 3045 \$ 3055 \$ 3054 \$ 3055 \$ 3054 \$ 3055 \$ 3054	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Sianals ? North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightnina Complex Fire Restoration Route 17. HFST SSPSLO Rymble Strip, Delineation, Sian Project Man 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearina Coastlands Wall 2 Unshellered Encampments North Unshellered Encampments Central Jack's Peak CAPM North of the Y: on 41 CAPM Guadalpup CAPM Morro Bay CAPM Morro Bay CAPM Morro Bay CAPM Morro Bay CAPM Vandenberg Village Pavement Preservation Project Valencia Creek Improvement Project	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Roadway Protective Betterments Maior Damage (Emergency Openina) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Emergency Openina) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM)	Location(s) Location(s) Culverf(s) (eq) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Location(s) Location(22 16: 18: 18: 18: 18: 11: 11: 12: 4: 34: 22
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3041 \$ 3045 \$ 3045 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3056	Santa Gruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Turnpike Sink Hole Atascadero Slob Replacements CZU Auaust Lightnina Complex Fire Restoration Route 1 7 HFST SS/SLO Rumble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hazordous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearina Coastlands Wall 2 Unsheltered Encampments North Unsheltered Encampments North Unsheltered Encampments Central Jack's Peak CAPM North Of the Yon 41 CAPM Guadalupe CAPM Morro Bay CAPM Vandenberg Village Pavement Preservation Project Valencia Creek Improvement Project Valencia Creek Improvement Project	Maior Damage (Permanent Restoration) Drainage System Restoration Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Roadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Permanent Restoration) Maior Damage (Femergency Opening) Maior Damage (Femergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM)	Location(s) Location(s) Location(s) Culvert(s) (ea) Location(s) Bridge(s) Location(s) Loca	22 16: 18: 18: 18: 18: 11: 11: 12: 4: 34: 22
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3022 \$ 3024 \$ 3025 \$ 3026 \$ 3027 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3041 \$ 3041 \$ 3045 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3056 \$ 3064	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole Atlascadero Slab Replacements CZU August Lightnina Complex Fire Restoration Route 17 HFST SB/SLO Rumble Strip, Delineation, Sian Project Mon 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REAUGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergancy Dolan Culvert Clearing Coastiands Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jack's Peak CAPM North of the 'Y' on 41 CAPM Guadalupe CAPM Morro Bay CAPM Valencia Creek Improvement Project Unsheltered Encampments South Elephant Seals Culvert SLO 46 Sinkhole	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Fermanent Restoration) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM)	Location(s) Location(s) Location(s) Culvert(s) (ea) Location(s)	11. 42. 42. 42. 42. 42. 42. 42. 42. 42. 42
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3027 \$ 3028 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3040 \$ 3040 \$ 3040 \$ 3040 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3064 \$ 3065 \$ 3062	Santa Cruz Long-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hish Priority Sianals ? North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightning Complex Fire Restoration Route 17 HFST SSP/SIO Rymble Strip, Delineation, Sian Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hozardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Morina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearing Coastlands Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jacks Peak CAPM North of the Yon 41 CAPM Guadalupe CAPM Morro Bay CAPM Vandenberg Village Pavement Preservation Project Valencia Creek Improvement Project Unsheltered Encampments South Liephant Seals Culvert SLO 46 Sinkhole Alisal Fire Restoration	Maior Damage (Permanent Restoration) Drainage System Restoration Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Roadway Protective Betterments Major Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Major Damage (Permanent Restoration) Major Damage (Femergency Opening) Maior Damage (Femergency Opening) Maior Damage (Femergency Opening) Maior Damage (Femergency Restoration) Major Damage (Femergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Location(s) Location(s) Location(s) Culvert(s) (ea) Location(s)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3026 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3041 \$ 3042 \$ 3042 \$ 3045 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3065 \$ 3065	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightnina Complex Fire Restoration Route 17. HFST SSPSLOR Numble Strip, Delineation, Sign Project Man 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearing Cogstlands Wall 2 Unshellered Encampments North Unshellered Encampments Central Jack's Peak CAPM North of the Y on 41 CAPM Guadalupe CAPM Morro Bay CAPM Morro Bay CAPM Morro Bay CAPM Vandenberg Village Pavement Preservation Project Unshellered Encampments South Elephant Seals Culvert SLO 46 Sinkhole Alisal Fire Restoration Mon-1 December Storm Damage	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Ragdway Protective Betterments Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM) Drainage System Restoration Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening)	Location(s) Location(s) Culverf(s) (eq) Location(s)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3025 \$ 3026 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3040 \$ 3045 \$ 3040 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3056 \$ 3066 \$ 3066 \$ 3066 \$ 3066 \$ 3062	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS Hish Priority Sianals ? North ELB Turnpike Sink Hole Atascadero Slab Replacements CZU Auaust Lightnina Complex Fire Restoration Route 17 HFST SSPSIO Rymble Strip, Delineation, Sign Project Mon 101 Sinkhole Dolan Fire Restoration SCR 236 Hozordous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearina Coastiands Wall 2 Unsheltered Encampments North Unsheltered Encampments Central Jack's Peak CAPM North of the "Y on 41 CAPM Guadalupe CAPM Morro Bay CAPM Monro Bay CAPM Wandenberg Village Povement Preservation Project Valencia Creek Improvement Project Unsheltered Encampments South Elephant Seals Culvert SLO 46 Sinkhole Alisal Fire Restoration Mon-1 December Storm Damage	Maior Damage (Permanent Restoration) Drainage System Restoration Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Roadway Protective Betterments Major Damage (Emergency Openina) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Femanent Restoration) Maior Damage (Femanent Restoration) Maior Damage (Emergency Openina) Maior Damage (Emergency Apenina) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM) Pavement	Location(s) Location(s) Location(s) Culvert(s) (ea) Location(s) Lo	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
\$ 3019 \$ 3020 \$ 3021 \$ 3022 \$ 3023 \$ 3024 \$ 3025 \$ 3026 \$ 3026 \$ 3026 \$ 3029 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3030 \$ 3040 \$ 3041 \$ 3042 \$ 3042 \$ 3045 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3055 \$ 3065 \$ 3065	Santa Gruz Lona-toed Salamander Connectivity & Drainage Project Cave Fire Restoration PSPS High Priority Signals ? North ELB Tumpike Sink Hole Atascadero Slab Replacements CZU August Lightnina Complex Fire Restoration Route 17. HFST SSPSLOR Numble Strip, Delineation, Sign Project Man 101. Sinkhole Dolan Fire Restoration SCR 236 Hazardous Tree Removal REALIGNMENT AT MILL CREEK Sims Road Sinkhole Marina to Castroville CAPM D5 Maintenance Office SLO 101 Gore Safety Improvements Atascadero Slab Replacement Perm. Rest. Rat Creek - Emergency Dolan Culvert Clearing Cogstlands Wall 2 Unshellered Encampments North Unshellered Encampments Central Jack's Peak CAPM North of the Y on 41 CAPM Guadalupe CAPM Morro Bay CAPM Morro Bay CAPM Morro Bay CAPM Vandenberg Village Pavement Preservation Project Unshellered Encampments South Elephant Seals Culvert SLO 46 Sinkhole Alisal Fire Restoration Mon-1 December Storm Damage	Maior Damage (Permanent Restoration) Drainage System Restoration Major Damage (Emergency Opening) Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Maior Damage (Emergency Opening) Ragdway Protective Betterments Maior Damage (Emergency Opening) Pavement Preservation (CAPM) Maintenance Facilities Safety Improvements Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Pavement Preservation (CAPM) Drainage System Restoration Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening)	Location(s) Location(s) Culverf(s) (eq) Location(s)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

E 2071	CLO 1// CADM	Devicement Process (client (CARA))	Lanca maila (a)	14
5 3071 5 3072	SLO 166 CAPM Gaviota Wildlife Crossing	Pavement Preservation (CAPM) SHOPP - Sustainability and Miscellaneous	Lane mile(s) Location(s)	14.
5 3074	Inside Shoulder Widening	Safety Improvements	Collision(s) reduced	6
5 3075 5 3078	Coastlands II retaining wall Bridge Maintenance	Major Damage (Permanent Restoration) Bridge Preventative Maintenance	Location(s) Bridge(s)	
5 3078 5 3081	SLO 1 Storm Damage Repair	Major Damage (Emergency Opening)	Location(s)	
5 3082 5 3083	Colorado Fire Restoration Carpinteria Creek Culvert Fire	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
5 3084	Elkhorn Slough Bridge Scour	Major Damage (Emergency Opening)	Location(s)	
5 3085	Negranti Pond Embankment Repair	Major Damage (Emergency Restoration)	Location(s)	
5 3097 5 3098	SBt 101 Heave Mon-1 Sinkhole and Slide Clearing	Major Damage (Emergency Opening) Major Damage (Emergency Restoration)	Location(s)	
5 3099	Oceano OH UE Repairs	Major Damage (Emergency Restoration)	Location(s)	
5 3101	SLO-Var Sinkhole and Erosion Repairs	Major Damage (Emergency Restoration)	Location(s)	
5 3102 5 3104	Santa Cruz Various Storm Damage Bridge Rail Replacement at Rocky Creek Bridge	Major Damage (Emergency Restoration) Bridge Rail Replacement and Upgrade	Location(s) Annual fatal and serious	0.0
			injury collision(s)	
5 3105	Downtown Watsonville Safety Project	Safety Improvements	Annual fatal and serious	0.3
3 3 3 3	Bowinown Walsonville Salety Hojeet	salety improvements	injury collision(s)	0.0
5 3106	SR1/SR9 Junction Lighting Project	Safety Improvements	Annual fatal and serious	0.1
3 3106	SK1/SK7 JUTICITOTI EIGHTING PTOJECT	Safety improvements	injury collision(s)	0.1
5 0107				
5 3137 5 3138	Scotts Creek Coastal Resiliency Project SLO Various Storm Damage 1	Bridge Rehabilitation and Replacement Major Damage (Emergency Restoration)	Bridge(s) Location(s)	
5 3139	Gaviota Rockfall Protection Repair	Major Damage (Emergency Opening)	Location(s)	
5 3140	SB-101 Gaviota Flood and Storm Damage	Major Damage (Emergency Restoration)	Location(s)	1
5 3141 5 3142	SB 154, 246 Storm Damage SCR 35 Slip Out	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
5 3144	Big Sur South Storm Damage	Major Damage (Emergency Restoration)	Location(s)	3
5 3145 5 3146	Big Sur Central Storm Damage Big Sur North Storm Damage	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	2
5 3146	Mon, SBt Various Storm Damage	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	- 1
5 3148	SLO Various Storm Damage 1	Major Damage (Emergency Restoration)	Location(s)	1
5 3149 5 3150	SB 192, 150 Storm Damage District Office Flood Electrical Repairs	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	1
5 3151	District Office Flood - IT Restoration	Major Damage (Emergency Restoration)	Location(s)	
5 3152	District Office Flood Building Repairs	Major Damage (Emergency Restoration)	Location(s)	
5 3153 5 3154	SB Various Storm Damage 1 District Office Flood Haz Waste Removal	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
5 3155 5 3156	13th Street Pump Replacement	Major Damage (Emergency Restoration)	Location(s)	
5 3156 5 3157	Mon, SBt 101 Failed Drainage Repairs Salsipuedes Creek Slip Out	Major Damage (Emergency Opening)	Location(s) Location(s)	
5 3158	Remove Hazardous Tree - Snow	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	1
5 3159	SCR 1 PM 33 Embankment Washout	Major Damage (Emergency Restoration)	Location(s)	
5 3160 5 3161	129/152 Storm Damage Pajaro River Flood Response	Major Damage (Emergency Opening) Major Damage (Emergency Restoration)	Location(s)	
5 3162	SLO Slides and Scour	Major Damage (Emergency Restoration)	Location(s)	
5 3164	Rocky Creek bridge ECE	Bridge Formula Program	Bridge(s)	
5 3165 5 3167	Toro Creek southbound bridge replacement SB Various Storm Damage 2	Bridge Formula Program Major Damage (Emergency Restoration)	Bridge(s) Location(s)	1
5 3168	Slope Repairs and Sinkhole	Major Damage (Emergency Restoration)	Location(s)	
5 3169	Gaviota Creek Scour Emergency Project	Major Damage (Emergency Restoration)	Location(s)	
5 3170 5 3171	Roadway Settlement Clark OC Bridge Hit	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
5 3172	Ben Lomond Sinkholes	Major Damage (Emergency Restoration)	Location(s)	
5 3174 5 3176	Big Sur RSP Repair St. Francis Revetment Repair	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
5 3190	Limekiln T-wall Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	
5 3206	144, 192 slipout, sinkhole, and slides	Major Damage (Emergency Restoration)	Location(s)	1
5 3207 5 3208	Dolan Point Slide Regent's Slide Removal	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
5 3209	Slipouts, Landslides, and Rockfall Repairs	Major Damage (Emergency Restoration)	Location(s)	
5 3210	Hwy 246 Storm damage drainage repair	Major Damage (Emergency Restoration)	Location(s)	
5 3219 5 3220	US 101 Rocks Road Tree Removal Rockfall clearing and rockfall fence repairs	Major Damage (Permanent Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
5 3221	SB 192 PM 5.1 Soldier Pile Wall	Major Damage (Emergency Restoration)	Location(s)	
5 3222 5 3223	Rocky Creek Slip DO/EFA Santa Cruz 17 Culvert Replacement	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
5 3226	El Jaro Drapery System	Major Damage (Emergency Opening)	Location(s)	
5 3227	Anzar Road Sinkhole	Major Damage (Emergency Restoration)	Location(s)	
5 3229 5 3230	Rocky Creek Slip Out Permanent Structure D5 South Maintenance Station Security	Major Damage (Emergency Restoration) Maintenance Facilities	Location(s) Location(s)	
5 3231	D5 North Maintenance Station Security	Maintenance Facilities	Location(s)	
5 3237 5 3238	Waddell Bluffs 2024	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
5 3240	Hwy 166 Embankment Repairs SB Collapsed Culverts	Major Damage (Emergency Restoration) Major Damage (Emergency Opening)	Location(s) Location(s)	
5 3330	Gaviota Culvert Replacement	Drainage System Restoration	Culvert(s) (ea)	
5 3330X 5 3330Y	Gaviota Culvert Replacement Seed Collection Gaviota Culvert Replacement Landscape Mitigation	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	
5 4020	Mon 101 TMS	Transportation Management (TMC's & Field	Field element(s)	1
	SIO 101 NI Coh, TAKS	Equipment)		
5 4022	SLO 101 N Cnty TMS	Transportation Management (TMC's & Field Equipment)	Field element(s)	6
5 4928R	Piedras Offsite Mitigation-New Location	Protective Betterments	Location(s)	
5 4928X	Piedras Blancas Offsite Mitigation Plant Propagation	Roadway Protective Betterments Roadway Protective Betterments	Location(s)	
5 4928Y 5 7101L	Piedras Blancas Offsite Mitigation Project Carpinteria to Santa Barbara Widening – 4A Carpinteria Mitigation Pltg	Roadway Protective Betterments Roadway Rehabilitation (3R)	Location(s) Lane mile(s)	
5 7101P	Carpinteria to Santa Barbara Widening - Segment 4A Combined	HOV/HOT lane-mile(s) constructed	Miles	5.
5 7101P	Carpinteria to Santa Barbara Widening - Segment 4A Combined Carpinteria to Santa Barbara Widening - Segment 4A Combined	Modified/Improved interchange(s) Modified/Reconstructed bridge(s)	Each Each	
5 7101P 5 7101P	Carpinteria to Santa Barbara Widening - Segment 4A Combined	Roadway Rehabilitation	Lane mile(s)	7.
5 7101P	Carpinteria to Santa Barbara Widening - Segment 4A Combined	Sound wall mile(s) constructed	Miles	1.4
5 7101R 5 7101R	Padaro - (Segment 4B) Combined Padaro - (Segment 4B) Combined	HOV/HOT lane-mile(s) constructed Modified/Improved interchange(s)	Miles Each	5.
5 7101R	Padaro - (Segment 4B) Combined	Modified/Reconstructed bridge(s)	Each	
5 7101R	Padaro - (Segment 4B) Combined	Roadway Rehabilitation (3R)	Lane mile(s)	11.
5 7101R 5 7101S	Padaro - (Segment 4B) Combined Carpinteria to Santa Barbara Widening Project - Segment 4C Combined	Sound wall mile(s) constructed HOV/HOT lane-mile(s) constructed	Miles Miles	0.7 3.
5 71018	Carpinteria to Santa Barbara Widening Project - Segment 4C Combined	Modified/Improved interchange(s)	Each	
5 7101S 5 7101S	Carpinteria to Santa Barbara Widening Project - Segment 4C Combined Carpinteria to Santa Barbara Widening Project - Segment 4C Combined	Modified/Reconstructed bridge(s) Roadway Rehabilitation (3R)	Each Lane mile(s)	,
5 71015	Carpinteria to Santa Barbara Widening Project - Segment 4C Combined Carpinteria to Santa Barbara Widening Project - Segment 4C Combined	Sound wall mile(s) constructed	Miles	6 0
	SB 101 4D North San Ysidro to Olive Mill	Auxiliary lane constructed	Miles	0
5 7101T				
5 7101T 5 7101T	SB 101 4D North San Ysidro to Olive Mill	Auxiliary lane(s) Collision Severity Reduction	Miles Collision(s) reduced	0.
5 7101T		Auxiliary lane(s) Collision Severity Reduction HOV/HOT mainline constructed	Miles Collision(s) reduced Miles	1.

5 7101U	SB 101 4D South Three Creeks	Collision Severity Reduction	Annual fatal and serious injury collision(s)	0.1:
5 7101U 5 7101U	SB 101 4D South Three Creeks SB 101 4D South Three Creeks	Culvert(s) Curve and vertical alignment correction(s)	LF Each	233.6
5 7101U	SB 101 4D South Three Creeks	HOV/HOT mainline constructed	Miles	0.
5 7101U 5 7101U	SB 101 4D South Three Creeks SB 101 4D South Three Creeks	Mainline shoulder(s) constructed Mixed flow mainline constructed	Miles Miles	0.9
5 7101U	SB 101 4D South Three Creeks	New bridge(s)/tunnel(s)	SQFT	2060
5 7101U	SB 101 4D South Three Creeks	Ramp(s) and connector(s) constructed	Miles	0.
5 7101U 5 7101U	SB 101 4D South Three Creeks SB 101 4D South Three Creeks	Ramps modification(s) Shoulder widening	Each Each	-
5 7102L	SB 101 4B (Padaro) Landscape Planting Project	HOV/HOT lane-mile(s) constructed	Miles	(
5 7102L	SB 101 4B (Padaro) Landscape Planting Project	Modified/Improved interchange(s)	Each	
5 7102L 5 7102L	SB 101 4B (Padaro) Landscape Planting Project SB 101 4B (Padaro) Landscape Planting Project	Modified/Reconstructed bridge(s) Roadway Rehabilitation (3R)	Each Lane mile(s)	-
5 7102L	SB 101 4B (Padaro) Landscape Planting Project	Sound wall mile(s) constructed	Miles	(
5 7103L 5 7103L	Carpinteria to Santa Barbara Widening – 4C Summerland Mitigation Plant	HOV/HOT lane-mile(s) constructed Modified/Improved interchange(s)	Miles Each	
5 7103L	Carpinteria to Santa Barbara Widening – 4C Summerland Mitigation Plant Carpinteria to Santa Barbara Widening – 4C Summerland Mitigation Plant	Modified/Reconstructed bridge(s)	Each	
5 7103L	Carpinteria to Santa Barbara Widening – 4C Summerland Mitigation Plant	Roadway Rehabilitation (3R)	Lane mile(s)	I
5 7103L 6 3019	Carpinteria to Santa Barbara Widening – 4C Summerland Mitigation Plant KERN 223 REHAB	Sound wall mile(s) constructed Roadway Rehabilitation (2R)	Miles Lane mile(s)	1
6 3032A	Porterville Median Barrier Replacement Planting	Safety Improvements	Collision(s) reduced	
6 3386E	Route 46 Expressway Segment 4C	Intersection/Signal improvement(s)	Each	
6 3386E 6 3425	Route 46 Expressway Segment 4C SEMITROPIC CAPM	Roadway Iane mile(s) - new Pavement Preservation (CAPM)	Miles Lane mile(s)	6. 25.
6 3729	Kern 178 Maintenance Access	Roadside Safety Improvements	Location(s)	6
6 5335A	Madera 99 Widening	Roadway Rehabilitation	Lane mile(s)	23.
6 6286 6 6286	TULARE CULVERT REPLACEMENT TULARE CULVERT REPLACEMENT	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	
6 6521	Bridge Widening	Bridge Rail Replacement/Upgrade	Linear feet	114
6 6661	Bakersfield 99 Rehab I(North)	Roadway Rehabilitation	Lane mile(s)	34.
6 6661A 6 6673	Bakersfield 99 Rehab Replacement Planting Summit OH Bridge Rails	Roadway Rehabilitation (3R) Bridge Rail Replacement/Upgrade	Lane mile(s) Linear feet	113
6 6674	Cache Creek Bridge Replacement	Bridge Rehabilitation	Bridge(s)	
6 6678	Gap Closure Rehab	Roadway Rehabilitation	Lane mile(s)	10.
6 6679 6 6681	Tipton Bridge Deck Rehab Union Ave to White Lane 2R Rehab	Bridge Rehabilitation Roadway Rehabilitation (2R)	Bridge(s) Lane mile(s)	33.:
6 6696	Lovers Lane Rehab	Roadway Rehabilitation (3R)	Lane mile(s)	6.
6 6700	TULARE WORKER SAFETY IMPROVEMENTS	Roadside Safety Improvements	Location(s)	2
6 6708 6 6708A	Ranchos Rehab RANCHOS REHAB MITIGATION	Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	
6 6709	Derby Street Signalization	Safety Improvements	Collision(s) reduced	
6 6716	Oakhurst CAPM	Pavement Rehabilitation	Lane mile(s)	10
6 6725 6 6726	Tumey Gulch III Calif Aqueduct Bridge Rehab	Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s)	
6 6727	Kingsburg 99 Rehab	Roadway Rehabilitation (2R)	Lane mile(s)	16.
6 6729	Lost Hills Rubber Rehab	Pavement Preservation	Lane mile(s)	3
6 6731 6 6732	Kern 99 N/B 2R Chowchilla 2R Rehab	Pavement Preservation Pavement Preservation	Lane mile(s) Lane mile(s)	3:
6 6735	Bakersfield 99 Irrigation Upgrade	Highway Planting Restoration	Acre(s)	12.
6 6736	Coalinga SRRA Water & Wastewate Upgrade	Roadside Safety Improvements	Location(s)	
6 6737 6 6737A	Lemoore/Hanford Worker Safety Northbound 2R/Fast Freight Corridor	Roadside Safety Improvements Roadway Rehabilitation (2R)	Location(s) Lane mile(s)	3:
6 6737A	Northbound 2R/Fast Freight Corridor	Trans Permit Requirements for Bridges	Bridge(s)	
6 6747	Firebaugh ADA	ADA - New Curb Ramps	Curb ramp(s)	1
6 6749 6 6750	Grapevine Channel Repair CALIFORNIA TIGER SALAMANDER MITIGATION BANK	Drainage System Restoration Roadside Protection and Restoration	Culvert(s) (ea) Location(s)	2
6 6753	Derrick CAPM	Pavement Rehabilitation	Lane mile(s)	41
6 6754A	Shaver to Huntington CAPM & Culvert Rehab	Drainage System Restoration	Culvert(s) (ea)	5'
6 6754A 6 6755	Shaver to Huntington CAPM & Culvert Rehab Enos Lane CAPM & ADA Curb Ramps	Pavement Rehabilitation Pavement Rehabilitation	Lane mile(s) Lane mile(s)	40.:
6 6755	Enos Lane CAPM & ADA Curb Ramps	Pavement Rehabilitation	Lane mile(s)	
6 6756 6 6757	West Rosedale CAPM Ker 58 ADA	Pavement Rehabilitation	Lane mile(s) Curb ramp(s)	12.
6 6758	Arvin SR 223/184 Roundabout	ADA - New Curb Ramps Operational Improvements	Daily vehicle hour(s) of	122.
6 6766	Kings Canyon Bridge Rail	Bridge Rail Replacement/Upgrade	delav (DVHD) Linear feet	
6 6771	SOUTH FRESNO VIADUCT POLYESTER CONCRETE OVERLAY	Capital Bridge Preventative Maintenance Program		
6 6773			Bridge(s)	
	Firehaugh & Puttenvilley Pridge Pile Rengir	Pridge Proventative Maintenance		
6 6787	Firebaugh & Buttonwillow Bridge Pile Repair Woodloke Bridge Replacement	Bridge Preventative Maintenance Bridge Rehabilitation	Bridge(s) Bridge(s)	
6 6787 6 6788	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail	Bridge Rehabilitation Bridge Rail Replacement/Upgrade	Bridge(s) Bridge(s) Linear feet rail	149:
6 6787 6 6788 6 6789	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation	Bridge(s) Bridge(s) Linear feet rail Lane mile(s)	149:
6 6787 6 6788 6 6789 6 6791 6 6795	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Upgrades	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culver(s) (ea)	149: 119: 1:
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Upgrades Kem-Kings Pumpina Plant Upgrades	Bridge Rehabilitation Bridae Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culverf(s) (ea)	1493 11 11
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797	Woodlake Bridge Replacement Pikley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades ITULARE AND KINGS CO WIRE THEFT RESTORATION	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration)	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culverf(s) (ea) Culverf(s) (ea) Location(s)	149:
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6798 6 6799	Woodlake Bridge Replacement Pixtey-Earlimant Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Upgrades Kem-Kings Pumping Plant Upgrades TuLARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Honford Sk-198 Roadside Safety	Bridge Rehabilitation Bridae Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Cuiverf(s) (ea) Location(s) Lane mile(s) Location(s)	53. 149. 11. 11. 10. 29. 7.
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6797 6 6799 6 6800	Woodlake Bridge Replacement Pikley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Uparades Kern-Kings Pumpina Plant Uparades TULARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Payement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R)	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Lane mile(s)	149: 1: 1: 1: 29: 7.
6 6787 6 6788 6 6789 6 6791 6 6795 6 6797 6 6797 6 6799 6 6799 6 6800 6 6802	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Uparades Kem-Kinas Pumpina Plant Uparades ITULARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	149: 149: 11: 11: 10: 29: 7. 11: 33:
6 6787 6 6788 6 6789 6 6795 6 6795 6 6797 6 6797 6 6798 6 6800 6 6800 6 6803 6 6803	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Upgrades Kem-Kings Pumpina Plant Upgrades TulARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s)	149: 1: 1: 1: 29: 7. 1: 33:
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6798 6 6800 6 6800 6 6802 6 6805 6 6805	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Lul-Fre-Mad Pumping Plant Upgrades Kem-Kings Pumping Plant Upgrades Kem-Kings Pumping Plant Upgrades TULARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culverf(s) (ea) Location(s) Location(s) Lane mile(s)	149: 11 1. 11 1. 29: 7. 1. 33.
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6797 6 6798 6 6799 6 6800 6 6800 6 6805 6 6805 6 6805	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Upgrades Kem-Kings Pumpina Plant Upgrades TulARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s)	149: 1: 1. 1. 1. 29: 7. 1. 33.
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6797 6 6890 6 6800 6 6805 6 6805 6 6810 6 6810 6 6813	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM Was Roadside SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Roadside Safety Improvements Highway Planting Restoration	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Cuiverf(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s)	149: 11 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6798 6 6798 6 6798 6 6800 6 6800 6 6805 6 6805 6 6813 6 6813	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Upgrades Kem-Kinas Pumpina Plant Upgrades TulARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Morgan Canyon CAPM Morson Canyon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Inrigation Upgrades Lost Hills Rehab	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Restoration	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Lane mile(s)	149: 149: 11: 11: 12: 29: 7, 13: 33: 33: 34: 9: 17:
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6797 6 6890 6 6800 6 6805 6 6805 6 6810 6 6810 6 6813	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM Was Roadside SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Roadside Safety Improvements Highway Planting Restoration	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Cuiverf(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s)	149: 149: 11: 11: 12: 29: 7, 13: 33: 33: 34: 9: 17:
6 6787 6 6788 6 6789 6 6791 6 6795 6 6797 6 6797 6 6798 6 6802 6 6802 6 6802 6 6803 6 6810 6 6813 6 6813 6 6813 6 6857 6 6857 6 6857	Woodlake Bridge Replacement Pidey-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout IJU-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades ITULARE AND KINOS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Moraan Canvon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades Lost Hills Rehab Fre-168 Recycled Water Irrigation UpgradeFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rerbu Londscape Project	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Restoration Pavement Restoration Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Bridge(s) Bridge(s)	149: 149: 11 11 11 12 12 12 13 13 13 13 13 13 15 17 17 17 17 17 17 17 17 17 17 17 17 17
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6797 6 6800 6 6800 6 6802 6 6805 6 6805 6 6810 6 6810 6 6815 6 6815 6 6857 6 6857 6 6857	Woodlake Bridge Replacement Pixley-Earlimant Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Lui-Fre-Mad Pumpina Plant Uparades Kem-Kinas Pumpina Plant Uparades Kem-Kinas Pumpina Plant Uparades TULARE AND KINOS CO WIRE THEFT RESTORATION Mornina Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM SR 65 8. 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Itrijaation Uparades Lost Hills Rehab Fre-168 Recycled Water Irrigation UparadeFFICIENCY COTTONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills No Wasco Rouble Strip	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Preservation Pavement Preservation Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culverf(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Acre(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s)	149: 1 149: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6 6787 6 6788 6 6789 6 6791 6 6795 6 6796 6 6797 6 6798 6 6798 6 6799 6 6800 6 6802 6 6803 6 6803 6 6805 6 6805 6 6805 6 6813 6 6815 6 6857 6 6857 6 6857 6 6857	Woodlake Bridge Replacement Pidey-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout IJU-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades ITULARE AND KINOS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Moraan Canvon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades Lost Hills Rehab Fre-168 Recycled Water Irrigation UpgradeFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rerbu Londscape Project	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Restoration Pavement Restoration Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Bridge(s) Bridge(s)	149 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6797 6 6798 6 6798 6 6800 6 6800 6 6805 6 6805 6 6805 6 6805 6 6805 6 6810 6 6811 6 6851 6 6857 6 6857 6 6857 6 6866 6 6871	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Uparades Kern-Kinas Pumping Plant Uparades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive SR Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Henford SR-198 Roadside Safety Selma to Fowler Rehab Pre-188/Ker-119 Culverts Weedpatch Hwy SR Rehab Pumpkin Center 3R Rehab Pumpkin Center 3R Rehab Pumpkin Center 3R Rehab Moraan Canyon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Imigation Uparades Lost Hills Rehab Fre-168 Recycled Water Irrigation UparadeFFICIENCY COTTONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills Nasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker/204 ADA Ramp Repair	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Payement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Roadway Rehabilitation Payement Rehabilitation Roadside Safety Improvements Hidhway Planting Restoration Payement Preservation Hidhway Planting Restoration Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Cuivert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Bridge(s)	149 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6798 6 6798 6 6798 6 6800 6 6800 6 6803 6 6805 6 6810 6 6813 6 6813 6 6815 6 6857 6 6857 6 6857 6 6857 6 6857 6 6857 6 6857 6 6866 6 6865	Woodlake Bridge Replacement Pidey-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Henford SR-198 Roadside Safety Selma to Fowler Rehab Pre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades Lost Hills Rehab Fre-168 Recycled Water Irrigation UpgradeFFICIENCY COTTONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Ker204 ADA Ramp Repair Strafford Kinas River Bridge Replacement I-5 Fost Freight Corridor I-5/Rte 99 Separation	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Malor Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Rehabilitation Roadside Rehabilitation Roadside Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Reshabilitation Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements ADA - New Curb Ramps Bridge Rehabilitation and Replacement Irans Permit Requirements to Bridges	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Collision(s) Acre(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s)	149 1 1 1 299 7, 1 333, 21. 13, 3 9 9 17. 2 2 3 3
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6797 6 6798 6 6798 6 6800 6 6800 6 6805 6 6805 6 6805 6 6805 6 6805 6 6810 6 6811 6 6851 6 6857 6 6857 6 6857 6 6866 6 6871	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumping Plant Uparades Kern-Kinas Pumping Plant Uparades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive SR Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Henford SR-198 Roadside Safety Selma to Fowler Rehab Pre-188/Ker-119 Culverts Weedpatch Hwy SR Rehab Pumpkin Center 3R Rehab Pumpkin Center 3R Rehab Pumpkin Center 3R Rehab Moraan Canyon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Imigation Uparades Lost Hills Rehab Fre-168 Recycled Water Irrigation UparadeFFICIENCY COTTONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills Nasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker/204 ADA Ramp Repair	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Payement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Roadway Rehabilitation Payement Rehabilitation Roadside Safety Improvements Hidhway Planting Restoration Payement Preservation Hidhway Planting Restoration Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Cuivert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Bridge(s)	149 1 1 1 29 7, 1 33. 21. 13, 3. 3. 9 9 17,7 2 2 3 3
6 6787 6 6788 6 6789 6 6791 6 6795 6 6797 6 6797 6 6798 6 6802 6 6802 6 6802 6 6803 6 6805 6 6813 6 6813 6 6813 6 6813 6 6857 6 6857 6 6857 6 6857 6 6877 6 6877	Woodlake Bridge Replacement Pixiev-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout IU-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades IU-ARE AND KINOS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Henford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Moraan Canyon CAPM Wasco Route 46 CAPM SR 65 8. 1901/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades Lost Hills Rehab Fre-168 Recycled Water Irrigation UpgradeFFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No., 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker/204 ADA Ramp Repair Strafford Kinas River Bridge Replacement 1-5 Freight Corridor California Aqueduct Ashlan/Shaw Aux Lane	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Sofety Improvements Highway Planting Restoration Pavement Rehabilitation Roadside Rehabilitation Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements Safety Improvements ADA - New Curb Ramas Bridge Rehabilitation and Replacement Trans Permit Requirements for Bridges	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Callision(s) Acre(s) Bridge(s)	149 1 1 1 1 1 29 7. 1 3 33. 21. 13. 3 3 9 9 17. 2 2 3 3
6 6787 6 6788 6 6789 6 6791 6 6795 6 6797 6 6797 6 6797 6 6800 6 6800 6 6800 6 6800 6 6800 6 6810 6 6810 6 6811 6 6815 6 6857 6 6857 6 6857 6 6857 6 6857 6 6865 6 6865	Woodlake Bridge Replacement Pixley-Earlimant Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout Iu-Fre-Mad Pumpina Plant Uparades Kern-Kinas Pumpina Plant Uparades Kern-Kinas Pumpina Plant Uparades ITULARE AND KINOS CO WIRE HIEFT RESTORATION Mornina Drike 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM SR 65 & 1901/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Uparades Lost Hills Rehab Fre-168 Recycled Water Irrigation UparadeFFICIENCY COTTONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Strafford Kinas River Bridge Replacement L5- Freight Corridor L5/Rte 99 Separation L5- Freight Corridor Collifornia Aqueduct	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Payement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Maior Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Roadway Rehabilitation Roadway Plantina Restoration Payement Rehabilitation Payement Preservation Highway Plantina Restoration Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements Safety Improvements Safety Improvements Safety Improvements ADA - New Curb Romos Bridge Rehabilitation and Replacement Trans Permit Requirements for Bridges Trans Permit Requirements for Bridges Trans Permit Requirements for Bridges Operational Improvements	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Acre(s) Bridge(s)	149 1 1 1 1 1 29 7. 1 3 33. 21. 13. 3 3 9 9 17. 2 2 3 3
6 6787 6 6788 6 6789 6 6791 6 6795 6 6797 6 6797 6 6798 6 6802 6 6802 6 6802 6 6803 6 6805 6 6810 6 6813 6 6813 6 6815 6 6857 6 6857 6 6857 6 6877 6 6877 6 6877	Woodlake Bridge Replacement Pixiev-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout IU-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades IU-ARE AND KINOS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Henford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Moraan Canyon CAPM Wasco Route 46 CAPM SR 65 8. 1901/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades Lost Hills Rehab Fre-168 Recycled Water Irrigation UpgradeFFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No., 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker/204 ADA Ramp Repair Strafford Kinas River Bridge Replacement 1-5 Freight Corridor California Aqueduct Ashlan/Shaw Aux Lane	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Sofety Improvements Highway Planting Restoration Pavement Rehabilitation Roadside Rehabilitation Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements Safety Improvements ADA - New Curb Ramas Bridge Rehabilitation and Replacement Trans Permit Requirements for Bridges	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Callision(s) Acre(s) Bridge(s)	149 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6797 6 6798 6 6799 6 6800 6 6803 6 6803 6 6805 6 6805 6 6805 6 6805 6 6810 6 6813 6 6813 6 6857 6 6857 6 6857 6 6866 6 6877 6 6877 6 6877 6 6877	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Uparades Kern-Kinas Pumpina Plant Uparades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hantiord 198 Irrigation Uparades Lost Hills Rehab Fre-188 Recycled Water Irrigation UparadefFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker204 ADA Ramp Repair Stratford Kinas River Bridge Replacement L-5 Freight Corridor L-5/Rte 99 Separation IMS Repair Service Contract Fre-41:99:168 & 180 Fiber Optic	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainace System Restoration Drainace System Restoration Drainace System Restoration Major Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainace System Restoration Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Rehabilitation Highway Planting Restoration Highway Planting Restoration Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements ADA - New Curb Ramps Bridge Rehabilitation and Replacement Trans Permit Requirements for Bridges Trans Permit Requirements for Bridges Trans Permit Requirements for Bridges Trans Permit Requirements [TMC's & Field Equipment] Transportation Management (TMC's & Field Equipment) Transportation Management (Fiber Optic Cable)	Bridge(s) Bridge(s) Unear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Acre(s) Bridge(s)	149: 149: 149: 29: 7. 1. 13. 33. 34: 9: 17. 21. 18. 34: 35: 19. 11. 10. 11. 11. 12. 13. 14. 15. 16. 17. 18. 18. 18. 18. 18. 18. 18. 18
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6798 6 6798 6 6799 6 6800 6 6803 6 6803 6 6803 6 6805 6 6813 6 6813 6 6815 6 6857 6 6857 6 6857 6 6857 6 6857 6 6877 6 6879	Woodlake Bridge Replacement Pridey-Earlimart Bridge Rail Berenda CAPM Kem 184/Sunset Roundabout IJU-Fre-Mad Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades Kern-Kinas Pumping Plant Upgrades ITULARE AND KINOS CO WIRE HIEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Henford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Moraan Canvon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hanford 198 Irrigation Upgrades Lost Hills Rehab Fre-168 Recycled Water Irrigation UpgradeFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker204 ADA Ramp Repair Stratford Kinas River Bridge Replacement 1-5 Frei Freight Corridor 1-5/Rte 97 Separation 1-5 Freight Corridor 1-5/Rte 97 Separation I-S Freight Corridor 1-5/Rte 97 Separation I-S Freight Corridor 1-5/Rte 97 Separation I-S Freight Service Contract Fre-41;99;168 & 180 Fiber Optic Warlow SRRA Infrastructure Upgrades	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Malor Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Roadside Safety Improvements Highway Planting Restoration Pavement Rehabilitation Roadside Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements Safety Improvements ADA - New Curb Ramps Bridge Rehabilitation and Replacement Irans Permit Requirements for Bridges Trans Permit Requirements for Bridges Transportation Management (TMC's & Field Equipment)	Bridge(s) Bridge(s) Linear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Bridge(s)	149. 149. 110. 110. 110. 110. 110. 120. 130. 130. 130. 130. 140. 150. 160.
6 6787 6 6788 6 6789 6 6791 6 6795 6 6795 6 6797 6 6798 6 6798 6 6802 6 6803 6 6803 6 6803 6 6803 6 6813 6 6813 6 6813 6 6813 6 6813 6 6813 6 6857 6 6857 6 6857 6 6857 6 6857 6 6877 6 6877	Woodlake Bridge Replacement Pixley-Earlimart Bridge Rail Berenda CAPM Kern 184/Sunset Roundabout Tul-Fre-Mad Pumpina Plant Uparades Kern-Kinas Pumpina Plant Uparades Tul-ARE AND KINGS CO WIRE THEFT RESTORATION Morning Drive 3R Rehab Hanford SR-198 Roadside Safety Selma to Fowler Rehab Fre-198/Ker-119 Culverts Weedpatch Hwy 3R Rehab Pumpkin Center 3R Rehab Morgan Canyon CAPM Wasco Route 46 CAPM SR 65 & 190 I/C ROADSIDE SAFETY IMPROVEMENTS Hantiord 198 Irrigation Uparades Lost Hills Rehab Fre-188 Recycled Water Irrigation UparadefFICIENCY COTIONWOOD CREEK BRIDGE REPLACEMENT (Br. No. 41-0065 L/R&S) Cottonwood Creek Bridge Rehab Landscape Project Lost Hills to Wasco Rumble Strip Shepherd to Top o' the 4-Lane Rumble Strip Ker204 ADA Ramp Repair Stratford Kinas River Bridge Replacement L-5 Freight Corridor L-5/Rte 99 Separation IMS Repair Service Contract Fre-41:99:168 & 180 Fiber Optic	Bridge Rehabilitation Bridge Rail Replacement/Upgrade Pavement Rehabilitation Safety Improvements Drainage System Restoration Drainage System Restoration Malor Damage (Permanent Restoration) Roadway Rehabilitation (3R) Roadside Safety Improvements Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (2R) Drainage System Restoration Roadway Rehabilitation (3R) Roadway Rehabilitation (3R) Pavement Rehabilitation Pavement Rehabilitation Roadside Safety Improvements Highway Planting Restoration Pavement Rehabilitation Roadside Rehabilitation Bridge Rehabilitation Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Safety Improvements ADA - New Curb Ramps Bridge Rehabilitation and Replacement Trans Permit Requirements for Bridges Transportation Management (TMC's & Field Equiroment) Transportation Management (Fiber Optic Cable) Roadside Safety Improvements	Bridge(s) Bridge(s) Unear feet rail Lane mile(s) Collision(s) reduced Culvert(s) (ea) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Acre(s) Bridge(s)	149: 149: 11: 11: 11: 29: 7.

6 6885	Deina Dast Avan Infrastructura Un avandas	Decada de Carleta Januaro comente	
6 6886	Raine Rest Area Infrastructure Upgrades Highland Rumble Strip	Roadside Safety Improvements Location(s) Safety Improvements Collision(s) reduced	10
6 6887	SOUTH GATEWAY DRIVE OC DECK REHAB	Bridge Rehabilitation Bridge(s)	1
6 6888 6 6889	Fresno Irrigation Upgrades Golden Empire CAPM	Highway Planting Restoration Acre(s) Pavement Rehabilitation Lane mile(s)	214
6 6894	Ker 33 Culvert Rehab	Drainage System Restoration Culvert(s) (ea)	40
6 6895	Fort Tejon 2R Rehab	Roadway Rehabilitation (2R) Lane mile(s)	17.5
6 6896 6 6897	Maricopa Highway CAPM SR 63 & 137 Visalia & Exeter Rumble Strip	Pavement Preservation (CAPM) Lane mile(s) Safety Improvements Collision(s) reduced	17.9
6 6898	Porterville 65 & 190 Rumble Stips	Safety Improvements Collision(s) reduced	26
6 6921	Fresno 198 Culvert Rehab	Drainage System Restoration Culvert(s) (ea)	
6 6922	Fre-99 & 41 Recycled Water TMS Detection Repair	Roadside Rehabilitation Acre(s) Transportation Management (TMC's & Field Field element(s)	69
0 0723	INS Defection Repair	Eauioment)	0,
6 6924	Weedpatch to Lake Isabella Rumble Strips	Safety Improvements Collision(s) reduced	26
6 6925 6 6927	Kern Canyon Culvert Rehab Coalinga SR 33 2R Rehab	Drainage System Restoration Culvert(s) (ea) Roadway Rehabilitation (2R) Lane mile(s)	62
6 6928	Kettleman 2R Rehab	Roadway Rehabilitation (2R) Lane mile(s)	16.8
6 6934	McMullin Grade CAPM	Pavement Rehabilitation Lane mile(s)	12.3
6 6935 6 6944	Stratford-Lemoore CAPM Tulare City Rehab	Pavement Preservation (CAPM) Lane mile(s) Roadway Rehabilitation (2R) Lane mile(s)	23
6 6949	El Dorado to Clinton Rehab	Roadway Rehabilitation (3R) Lane mile(s)	18.9
6 6950	South Taff Rehab	Roadway Rehabilitation (3R) Lane mile(s)	9.5
6 6956 6 6957	Union Avenue High intensity Activated crossWalK Reward CAPM	Safety Improvements Collision(s) reduced Pavement Rehabilitation Lane mile(s)	18.8
6 6958	Bakersfield 99 Rehab II (South)	Roadway Rehabilitation (3R) Lane mile(s)	15.1
6 6959	Tul 245 Culvert Rehab	Drainage System Restoration Culvert(s) (ea)	155
6 6960 6 6962	Delano SR-155 Rehab (3R) Easton Rumble Strip	Roadway Rehabilitation (3R) Lane mile(s) Safety Improvements Collision(s) reduced	2.0
6 6963	Delano to Pixley Rehab	Roadway Rehabilitation (2R) Lane mile(s)	51.7
6 6964	LERDO CANAL MEDIAN GAP CLOSURE	Roadside Safety Improvements Location(s)	
6 6965 6 6970	Kings 43 CAPM Panoche CAPM	Pavement Rehabilitation Lane mile(s) Pavement Preservation (CAPM) Lane mile(s)	46.3
6 6971	Shields to Nees CAPM	Pavement Preservation (CAPM) Lane mile(s)	24.1
6 6972	Firebaugh 3R Rehab	Roadway Rehabilitation (3R) Lane mile(s)	6.0
6 6973 6 6974	West Ave. Maintenance Station Upgrade Cedar Grove Slope Repair	Maintenance Facilities Location(s) Major Damage (Emergency Opening) Location(s)	
6 6975	I-5 to Kerman Rumble Strip	Safety Improvements Collision(s) reduced	23
6 6976	Tejon SRRA Water & Wastewater Upgrades	Safety Roadside Rest Area Restoration Location(s)	2
6 6978 6 6979	Blackwell's Corner CAPM Camp Nelson Slide Repair	Pavement Preservation (CAPM) Lane mile(s) Major Damage (Emergency Opening) Location(s)	37.8
6 6980	Grapevine Rehab	Roadway Rehabilitation (2R) Lane mile(s)	23.2
6 6981	Edison 2R Rehab	Roadway Rehabilitation (2R) Lane mile(s)	5.8
6 6982 6 6984	Wasco SR43/46 Intersection Improvements Arvin CAPM	Safety Improvements Collision(s) reduced Pavement Preservation (CAPM) Lane mile(s)	20
6 6985	Wheeler Ridge CAPM	Pavement Preservation (CAPM) Lane mile(s)	42.7
6 6988 6 6992	Reef City CAPM	Pavement Preservation (CAPM) Lane mile(s)	31.2
6 6993	Fre 168 Culvert Rehab Goshen to Traver Emergency Pavement Replacement	Drainage System Restoration Culvert(s) (ea) Major Damage (Emergency Opening) Location(s)	136
6 6994	Taft Left Turn Channelization	Safety Improvements Collision(s) reduced	18
6 7005	Downtown Madera CAPM	Pavement Preservation (CAPM) Lane mile(s)	10.8
6 7006 6 7008	Sugar Pine Slipout Visalia Mall CAPM	Major Damage (Emergency Opening) Location(s) Pavement Preservation (CAPM) Lane mile(s)	18.5
6 7008	Visalia Mall CAPM	Pavement Preservation (CAPM) Lane mile(s)	
6 7009 6 7013	Dickenson Roundabout FRE 41 Roadside Safety Improvements	Safety Improvements Collision(s) reduced Roadside Safety Improvements Location(s)	20
6 7014	El Dorado 2R Rehab	Roadway Rehabilitation (2R) Lane mile(s)	43.9
6 7015	Tul 198 Culvert Rehab	Drainage System Restoration Culvert(s) (ea)	122
6 7031	Kettleman Roundabout 190/Rockford Road Roundabout	Safety Improvements Collision(s) reduced Safety Improvements Collision(s) reduced	43
6 7034	Shaver Marina Slipout	Major Damage (Emergency Opening) Location(s)	2
6 7037	Selma to Fowler Replacement Planting	Roadway Rehabilitation (2R) Lane mile(s)	(
6 7038 6 7040	Clovis Avenue to Temperance Median Barrier Mount Whitney Roundabout	Safety Improvements Collision(s) reduced Safety Improvements Collision(s) reduced	24
6 7042	Elkhorn Roundabout	Safety Improvements Collision(s) reduced	5,
6 7043		Salety improvements [Collision(s) reduced	54
6 7044	PSPS SIGNAL VISIBILITY IMPROVEMENTS	Major Damage (Emergency Opening) Location(s)	39
	Santa Fe Roundabout	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced	39 41 38
6 7047		Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior	39 41 38
6 7047	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s)	39 41 38
6 7047 6 7049	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs	Major Damage (Emergency Opening) Location(s)	39 41 38 0.08
6 7047	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s)	39 41 38
6 7047 6 7049 6 7052 6 7055 6 7056	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREK FIRE EMERGENCY WORK SQF Complex Emergency Work	Major Damage (Emergency Opening) Location(s)	39 41 38 0.08
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergancy Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips	Major Damage (Emergency Opening) Location(s)	39 41 38 0.08
6 7047 6 7049 6 7052 6 7055 6 7056	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shover Loke Viaduct FRESNO SR 41 REHAB	Major Damage (Emergency Opening) Location(s)	35 44 43 35 0.06
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7066	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier	Major Damage (Emergency Opening) Location(s)	35 41 35 55 0.08 22 1 1 1 12.5
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7061 6 7066 6 7070	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM	Major Damage (Emergency Opening) Location(s)	35 44 38 38 30 5 5 5 5 5 5 5 5 5
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7064 6 7064 6 7070 6 7071 6 7094	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER 15 CAPM Fresno County Culvert Improvements DELANO FACILITY	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Femergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restoration) Location(s) Pavement Preservation (CAPMI) Lane mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Drainage System Restoration Culvert(s) (eq) Maintenance Facilities Location(s)	35 34 35 36 37 37 37 37 37 37 37 37 37 37
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7070 6 7070 6 7074 6 7094	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIKE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM fresno County Culvert Improvements DELANO FACILITY Chowchillia CAPM	Major Damage (Emergency Opening) Location(s)	33 4 4 5 0.08 22 12.9 33 5.6 10
6 7047 6 7049 6 7059 6 7056 6 7056 6 7061 6 7064 6 7064 6 7070 6 7071 6 7095 6 7095	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsbura Rumble Strips Shaver Lake Viaduct FRESNOS R4 I REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project	Major Damage (Emergency Opening) Location(s)	33 4 4 33 5 0.04 2 2 12.1 33 56.1 10.0
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 70701 6 7071 6 7095 6 7096 6 7096 6 7097	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER 15 CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project	Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Major Damage (Emergency Opening) Safety Improvements Collision(s) reduced Major Damage (Permanent Restaration) Pavement Preservation (CAPM) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Drainage System Restaration Major Damage (Forenanent) Drainage System Restaration Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Restaration)	35 44 38 30 30 30 30 30 30 40 40 40 40 40 40 40 40 40 40 40 40 40
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7094 6 7097 6 7097 6 8000	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridae Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT KEM COUNTY SECURE BRIDGE EMERGENCY PROJECT	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restoration) Location(s) Pavement Preservation (CAPM) Lane mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Drainage System Restoration Culvert(s) (ea) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Mestoration) Location(s)	33 4 4 33(s) 0.04 2. 2. 112.12.33 5.6.10.00 6.13.33 3.33.33
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7060 6 7064 6 7064 6 7070 6 7071 6 7094 6 7095 6 7096 6 7098 6 8000	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergancy Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno Country Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern Country Country Country Country Country Secure Bridge Emergency Project MADERA 99 AND 152, BRIDGE DECK REHAB FRESNO S, BRIDGE DECK REHAB	Major Damage (Emergency Opening) Location(s)	33 4 4 5 0.08 22 12.1 33 5.5 5.6 10.0 4 6.1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7094 6 7097 6 7097 6 7097 6 8000 6 80001 6 80001	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno Country Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern Country Secure Bridge Emergency Project MADERA 97 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FUMP PLANT UPGRADES	Major Damage (Emergency Opening) Location(s)	33 4 4 34 35 0.00 22 12.2 33 5.6 10 4 6.3 3 3 3 3 3
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7064 6 7064 6 70704 6 7070 6 7071 6 7094 6 7095 6 7096 6 8000 6 8000 6 8000 6 80002 6 80002	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 99 AND I 52, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB South Madera Rehab PUMP PLANT UPGRADES EAST WASSOC CAPM	Major Damage (Emeraency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restaration) Location(s) Pavement Preservation (CAPM) Lane mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Drainage System Restaration Culvert(s) (ea) Major Lane Featilities Location(s) Pavement Preservation (CAPM) Lane mile(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Restraction) Locatio	33 4 4 34 35 0.00 22 12.2 33 5.6 10 4 6.3 3 3 3 3 3
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7094 6 7096 6 7097 6 7098 6 8000 6 8001 6 8002 6 8004 6 8005 6 8006	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER 15 CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridae Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridae Emergency Project MADERA 99 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5 BRIDG	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restoration) Location(s) Pavement Preservation (CAPM) Lone mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Drainage System Restoration Culvert(s) (ea) Maintenance Facilities Location(s) Pavement Preservation (CAPM) Lane mile(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Restoration) Location(s) Bridge Preventative Maintenance Bridge(s) Bridge Preventative Mointenance Bridge(s) Bridge System Restoration Pump plant(s) (ea) Drainage System Restoration Pump plant(s) (ea)	33 4 4 31 31 32 32 32 33 34 33 34 34 24 44
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7066 6 70701 6 7097 6 7098 6 8000 6 8000 6 8000 6 8007 6 8007	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 99 AND I 52, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHABILITATION South Madera Rehab PUMP PLANT UPGRADES EAST WASSO CAPM FRENCH FIRE EMERGENCY WORK Tulare SR 137 Rehab Bakersfield SR 58 & 204 ADA Improvements	Major Damage (Emergency Opening) Location(s)	33 4 4 33 50 0.00 2 2 12.1 33 56.1 10 6 33 3 3 3 3 3 1 24.1 12.1
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7094 6 7097 6 7098 6 8000 6 8001 6 8002 6 8004 6 8008 6 8011	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emercency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 97 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE	Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restoration) Location(s) Payement Preservation (CAPM) Lane mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Drainage System Restoration Culvert(s) (eq) Maintenance Facilities Location(s) Pavement Preservation (CAPM) Lane mile(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Restoration) Location(s) Bridge Preventative Maintenance Bridge(s) Bridge Preventative Maintenance Bridge(s) Bridge System Restoration Pump plant(s) (ed) Drainage System Restoration Pump plant(s) (ed)	33 4 4 33 35 0.00 22 112.2 33 56.6 100 63 3 3 3 3 24 12 12 9 8 6 6 6 8 9 9
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7064 6 7064 6 7070 6 7071 6 7094 6 7095 6 7095 6 8000 6 8000 6 8001 6 8002 6 8004 6 8005 6 8007 6 8008	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergancy Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno Country Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern Country Culvert Bridge Emergency Project MADERA 99 AND I 52, BRIDGE DECK REHAB FRESNO S, BRIDGE DECK REHABILITATION South Madera Rehab PUMP PLANT UPGRADES EAST WASCO CAPM FRENCH FIRE EMERGENCY WORK Tulore SR 137 Rehab Bakersfield SR 58 & 204 ADA Improvements Rehabilitate Pavement Ker SE CAPMWIMM update	Major Damage (Emeraency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emeraency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emeraency Opening) Location(s) Major Damage (Emeraency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restaration) Location(s) Pavement Preservation (CAPM) Lane mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Brain Reservation Culvert(s) (ea) Maintenance Facilities Location(s) Pavement Preservation (CAPM) Lane mile(s) Major Damage (Emeraency Opening) Location(s) Major Damage (Emeraency Restraction) Location(s) Bridge Preventative Maintenance Bridge(s) <td>33 4 4 33 35 0.00 2. 12, 33 56. 10 6. 4 33 3 3 3 3 3 3 4 24. 12, 12, 12, 12, 12, 13, 14, 15, 16, 16, 16, 16, 16, 16, 16, 16, 16, 16</td>	33 4 4 33 35 0.00 2. 12, 33 56. 10 6. 4 33 3 3 3 3 3 3 4 24. 12, 12, 12, 12, 12, 13, 14, 15, 16, 16, 16, 16, 16, 16, 16, 16, 16, 16
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7094 6 7097 6 7098 6 8000 6 8001 6 8002 6 8004 6 8008 6 8011	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emercency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 97 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE	Major Damage (Emergency Opening) Location(s)	33 4 4 33 5 0.00 2 2 12: 33 56: 10 6. 33 33 33 34 24: 24: 24: 24: 25: 26: 27: 28: 28: 28: 28: 28: 28: 28: 28: 28: 28
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7060 6 7061 6 7071 6 7094 6 7097 6 7097 6 7098 6 8000 6 8000 6 8001 6 8001 6 8011 6 8012 6 8014	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridae Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT KERN COUNTY SECURE BRIDGE DECK REHAB FRESNO 5. BRIDGE DECK FRESNO 5. BRIDGE FRESNO 5. BRIDGE FRESNO 5. BRIDGE FRESNO 5	Major Damage (Emeraency Opening) Location(s) Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serior injury collision(s) Major Damage (Emeraency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Safety Improvements Collision(s) reduced Major Damage (Permanent Restoration) Location(s) Pavement Preservation (CAPM) Lone mile(s) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Lane mile(s) Drainage System Restoration Culvert(s) (ea) Maintenance Facilities Location(s) Pavement Preservation (CAPM) Lane mile(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Restoration) Location(s) Major Damage (Emergency Restoration) Location(s) Bridge Preventative Mointenance Bridge(s) Bridge Preventative Mointenance Bridge(s) Bridge Preventative Mointenance Bridge(s)	3 4 4 3 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
6 7047 6 7049 6 7052 6 7055 6 7056 6 7060 6 7060 6 7064 6 7070 6 7071 6 7094 6 7095 6 7096 6 7097 6 7098 6 8000 6 8001 6 8001 6 8014 6 8016	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno Country Culvert Improvements DELANO FACILITY Chowchillo CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern Country Secure Bridge Emergency Project MADERA 97 AND 152, BRIDGE DECK REHAB FRESNO 5, BRID	Major Damage (Emergency Opening) Location(s)	3 4 4 3 3 5 0.0 0.0 15 12.1 3 5 5 6.1 10 10 10 10 10 10 10 10 10 10 10 10 10
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7095 6 7096 6 7097 6 7098 6 8000 6 8001 6 8001 6 8011 6 8014 6 8016	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emeraency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridae Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT KERN COUNTY SECURE BRIDGE DECK REHAB FRESNO 5. BRIDGE DECK SEND FRENCH FIRE EMERGENCY WORK Tulare SR 137 Rehab Bakersfield SR 58 8. 204 ADA Improvements Rehabilitate Pavement Ker 58 CAPM/WIM update Hanford 198 CAPM CURVE IMPROVEMENT ON ROAD 416	Major Damage (Emergency Opening) Location(s)	3 4 4 3 3 5 0.0 12. 3 5 6. 10 24. 12. 9, 8 8 6. 7 26. 15 0.5
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7064 6 7064 6 7070 6 7071 6 7095 6 7095 6 7095 6 8000 6 8001 6 8001 6 8002 6 8002 6 8004 6 8011 6 8014 6 8016	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergancy Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 99. AND I SZ, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHABILITATION South Madera Rehab PUMP PLANI UPGRADES EAST WASCO CAPM FRENCH HIRE EMERGENCY WORK Tulore SR 137 Rehab Bakersfield SR 58 & 204 ADA Improvements Rehabilitate Pavement Rehabilitate Pavement Rehabilitate Pavement Rehabilitate Pavement Rendo CURVE IMPROVEMENT ON ROAD 416 TUL 190 PRESERVATION	Major Damage (Emergency Opening) Location(s)	33 4 4 33 35 0.00 15 12.1 3.1 56 10 6.1 3.3 3.3 1.1 12.1 12.1 24.1 25 26.1 35 0.5
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7060 6 7061 6 7064 6 7070 6 7071 6 7095 6 7096 6 7097 6 7098 6 8000 6 8001 6 8001 6 8011 6 8014 6 8016	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergaency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emeraency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridae Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT KERN COUNTY SECURE BRIDGE DECK REHAB FRESNO 5. BRIDGE DECK SEND FRENCH FIRE EMERGENCY WORK Tulare SR 137 Rehab Bakersfield SR 58 8. 204 ADA Improvements Rehabilitate Pavement Ker 58 CAPM/WIM update Hanford 198 CAPM CURVE IMPROVEMENT ON ROAD 416	Major Damage (Emergency Opening) Location(s)	33 4 4 38 38 38 38 38 39 30 30 30 30 31 31 32 41 42 43 44 45 45 46 47 47 48 48 48 48 48 48 48 48 48 48
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7064 6 7064 6 7070 6 7071 6 7074 6 7075 6 7095 6 8000 6 8000 6 8001 6 8001 6 8002 6 8004 6 8011 6 8012 6 8014 6 8016	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergancy Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER 15 CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 99 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5 STORE STRIP STRIP STRIP STRIP MADERA 99 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO BARD STRIP STRIP STRIP LIVER STRIP STRIP STRIP LIVER STRIP STRIP STRIP LIVER STRIP STRIP STRIP LIVER STRIP STRIP LIVER STRIP STRIP BRESNO STRIP STRIP LIVER STRIP	Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Major Damage (Emergency Opening) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Safety Improvements Collision(s) reduced Major Damage (Permanent Restardion) Pavement Preservation (CAPM) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Drainage System Restardion Major Damage (Emergency Opening) Major Damage (Emergency Restardion) Bridge Preventative Maintenance Bridge Preventative Major (CAPM) Drainage System Restardion Pavement Preservation (CAPM) Drainage System Restardion Pavement Preservation (CAPM) Major Damage (Emergency Opening) Drainage System Restardion Pavement Preservation (CAPM) Drainage System Restardion Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) Annual fatal and serior injury collision(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s)	3 3 4 4 5 5 6 5 6 5 6 6 6 6 6 6 6 6 6 6 6 6
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7060 6 7061 6 7064 6 7066 6 7070 6 7071 6 7098 6 8000 6 8001 6 8001 6 8018 6 8016 6 8018 6 8019 6 8020	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergency Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emercency Work Kinasbura Rumble Strips Shaver Lake Viaduct FRESNO SR 41 REHAB Parkhust Median Barrier KER IS CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridae Emeraency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT KERN COUNTY SECURE BRIDGE DECK REHAB FRESNO 5. BRIDGE DECK SEND FRENCH FIRE EMERGENCY WORK Tulare SR 137 Rehab Bakersfield SR 58 & 204 ADA Improvements Rehabilitate Pavement Ker 58 CAPM/WIM update Hanford 198 CAPM CURVE IMPROVEMENT ON ROAD 416 TUL 190 PRESERVATION SR 43 (OROSI) TRAFFIC SAFETY IMPROVEMENT SR 180 Rumble Strip Project	Major Damage (Emergency Opening) Location(s)	3 3 4 4 3 3 3 3 5 0.00 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2
6 7047 6 7049 6 7052 6 7055 6 7056 6 7056 6 7064 6 7064 6 7070 6 7071 6 7074 6 7075 6 7095 6 8000 6 8000 6 8001 6 8001 6 8002 6 8004 6 8011 6 8012 6 8014 6 8016	Santa Fe Roundabout State Route 180 Two-way Left Turn Channelization Kern 5 Emergancy Pavement Repairs Buttonwillow Median Barrier CREEK FIRE EMERGENCY WORK SQF Complex Emergency Work Kingsburg Rumble Strips Shaver Lake Viaduat FRESNO SR 41 REHAB Parkhust Median Barrier KER 15 CAPM Fresno County Culvert Improvements DELANO FACILITY Chowchilla CAPM Fresno Secure Bridge Emergency Project TULARE COUNTY SECURE BRIDGE EMERGENCY PROJECT Kern County Secure Bridge Emergency Project MADERA 99 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO 5 STORE STRIP STRIP STRIP STRIP MADERA 99 AND 152, BRIDGE DECK REHAB FRESNO 5, BRIDGE DECK REHAB FRESNO BARD STRIP STRIP STRIP LIVER STRIP STRIP STRIP LIVER STRIP STRIP STRIP LIVER STRIP STRIP STRIP LIVER STRIP STRIP LIVER STRIP STRIP BRESNO STRIP STRIP LIVER STRIP	Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Major Damage (Emergency Opening) Safety Improvements Collision(s) reduced Major Damage (Emergency Opening) Safety Improvements Collision(s) reduced Major Damage (Permanent Restardion) Pavement Preservation (CAPM) Safety Improvements Collision(s) reduced Roadway Rehabilitation (3R) Drainage System Restardion Major Damage (Emergency Opening) Major Damage (Emergency Restardion) Bridge Preventative Maintenance Bridge Preventative Major (CAPM) Drainage System Restardion Pavement Preservation (CAPM) Drainage System Restardion Pavement Preservation (CAPM) Major Damage (Emergency Opening) Drainage System Restardion Pavement Preservation (CAPM) Drainage System Restardion Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) ADA - New Curb Rambs Curb ramp(s) Pavement Preservation (CAPM) Lane mile(s) Pavement Preservation (CAPM) Lane mile(s) Annual fatal and serior injury collision(s) Pavement Preservation (CAPM) Lane mile(s) Annual fatal and serior injury collision(s)	35 44 43 38 38 38 38 38 38 38 38 38 39 12 40 31 31 31 31 31 31 32 42 42 42 42 43 44 55 65 65 65 65 65 65 65 65 65 65 65 65

6 8048 6 8049				
6 8049	Maricopa Highway CAPM Environmental Mitigation	Pavement Preservation (CAPM)	Lane mile(s)	0
6 8052	FRE I-5 REHABILTATION SR 065 MODIFY TRAFFIC SIGNAL SYSTEM	Roadway Rehabilitation (2R)	Lane mile(s) Annual fatal and serious	39.6 0.09
6 6032	3K 063 MODIFT TRAFFIC SIGNAL STSTEM	Safety Improvements	injury collision(s)	0.07
			injury completing	
6 8053	Fre 180 Landscape Mitigation	Safety Improvements	Annual fatal and serious	0
			injury collision(s)	
6 8058	Remove and replace failed pavement for both NB and SB	Major Damage (Emergency Restoration)	Location(s)	253
6 8060	Tul 99 Emergency Debris Removal Fre 41 Santa Ana Pump Replace	Major Damage (Emergency Restoration)	Location(s)	3
6 8062 6 8063	Roadway / retaining wall / slope repairs	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
6 8064	TUL 063 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	15.5
6 8081	Fresno Materials Lab Replacement	Materials Laboratories	Location(s)	1
6 8088	KIN 41 DRAINAGE RESTORATION	Drainage System Restoration	Culvert(s) (ea)	86
6 8089	FRE 180 Emergency Slope Repairs	Major Damage (Emergency Restoration)	Location(s)	10
6 8092	STRATFORD-LEMOORE CAPM (ENVIRONMENTAL MITIGATION)	Pavement Preservation (CAPM)	Lane mile(s)	0
6 8095	KERN 204 BRIDGE RAIL UPGRADE	Bridge Rail Replacement and Upgrade	Annual fatal and serious	0.06
			injury collision(s)	
6 8096	Repair D06 Materials Lab	Major Damage (Permanent Restoration)	Location(s)	1
6 8096	Repair D06 Materials Lab	Major Damage (Permanent Restoration)	Location(s)	- '
6 8097	Blackwell's Corner Landscape Mitigation and Biological Monitoring	Pavement Preservation (CAPM)	Lane mile(s)	0
6 8098	Kern 5 SCALING/ROCK REMOVAL	Major Damage (Emergency Restoration)	Location(s)	1
6 8102	Maintenance Station Secure Fencing	Maintenance Facilities	Location(s)	2
6 8103	Maintenance Station Secure Fencing	Maintenance Facilities	Location(s)	2
6 8104 6 8105	Maintenance Station Secure Fencing	Maintenance Facilities	Location(s)	4
6 8105	Maintenance Station Secure Fencing Porterville Intersection Improvements I	Maintenance Facilities Operational Improvements	Location(s) Daily vehicle hour(s) of	441
00100	. S. S. Talo II no isocalo i i improvottionis i	ороганованнрюченнения	delay (DVHD)	441
6 8112	Delano to Pixley Mainline Improvement	Mixed flow lane-mile(s) constructed	Miles	25.2
6 8112	Delano to Pixley Mainline Improvement	Roadway Rehabilitation (2R)	Lane mile(s)	51.7
6 8115	DELANO TO PIXLEY REPLACEMENT PLANTING PROJECT	Roadway Rehabilitation (2R)	Lane mile(s)	0
6 8116	FRESNO 168 CULVERT REHAB CDFW COMPENSATORY MITIGATION	Drainage System Restoration	Culvert(s) (ea)	0
6 8121	KER 33 Environmental Mitigation UNION AVE & WASHINGTON ST PUMP HOUSE REPAIRS	Drainage System Restoration	Culvert(s) (ea)	0
6 8124 6 8125	Grapevine Rockfall Mitigation	Major Damage (Emergency Restoration) Major Damage (Permanent Restoration)	Location(s) Location(s)	2
6 8125	FRE 99 Repair Concrete Girders	Major Damage (Permanent Restoration) Major Damage (Emergency Restoration)	Location(s)	1
6 8127	FRE 99 Repair Concrete Girders	Major Damage (Emergency Restoration)	Location(s)	
6 8129	Repair Concrete Girders	Major Damage (Emergency Restoration)	Location(s)	1
7 2681	SOV_HOV	Operational Improvements	Daily vehicle hour(s) of	12.5
			delav (DVHD)	
7 3279	TMDL 18/19	Storm Water Mitigation	Acre(s)	25.7
7 3734	Clause Denie Dan eie	Drainage System Restoration	treated/pollutant	1
7 3884	Storm Drain Repair TMDL project	Storm Water Mitigation	Culvert(s) (ea) Acre(s)	33
7 3004	INDL project	Storm water Miligation	treated/pollutant	33
7 3923	TMDL- 19/20	Storm Water Mitigation	Acre(s)	92
			treated/pollutant	
7 4137	LA-710 Rehab Phase 1	Roadway Rehabilitation	Lane mile(s)	65
7 4174	TMDL- 18/19	Storm Water Mitigation	Acre(s)	17.2
7 4400			treated/pollutant	
7 4420	Storm Water Mitigation	Storm Water Mitigation	Acre(s)	23.2
7 4496	VEN-33, SA Crk, Br Rehab + Fish Psg	Bridge Scour	treated/pollutant Bridge(s)	1
7 4498	TRANCAS CREEK BRIDGE	Bridge Scool Bridge Rehabilitation and Replacement	Bridge(s)	i
7 4591	134 / 710 Seismic Retrofit	Bridge Seismic Restoration	Bridge(s)	2
7 4601	Bridge Rail	Bridge Rail Replacement/Upgrade	Linear feet rail	724
7 4617	29750 & 29530	Safety Enhancements	Collision(s) reduced	45
7 4632	Traffic Circle	Safety Enhancements	Collision(s) reduced	59
7 4652	27 1/Mulholland	Roadside Safety Improvements	Location(s) Lane mile(s)	12
7 4687 7 4688	Ven 101 Padre Juan Rehab VEN-23 REHAB	Roadway Rehabilitation (2R) Roadway Rehabilitation (2R)	Lane mile(s)	21.6 46.7
7 4696	SR 1 Cnty Ln Pavement Rehab	Pavement Rehabilitation	Lane mile(s)	14.1
7 4697	Cold Plane.	Pavement Rehabilitation	Lane mile(s)	24.6
7 4698	Pavement Rehab	Pavement Rehabilitation	Lane mile(s)	10.3
7 4699	SR-60 2R in Montebello	Roadway Rehabilitation (2R)	Lane mile(s)	78.7
7 4700	PCH CAPM	Pavement Preservation (CAPM)	Lane mile(s)	98.9
7 4702	Pavement Rehab	Pavement Preservation	Lane mile(s)	4
7 4704	91, 110, and 710 Seismic Retrofit	Bridge Formula Program	Bridge(s)	
7 4705	210 SW SOURCE CONTROL		Acro/c)	4
		Storm Water Mitigation	Acre(s)	13.3
7 4704	Rte 57 Roadside Safety		Acre(s) treated/pollutant Location(s)	
7 4706 7 4707	Rte 57 Roadside Safety Roadside Safety	Roadside Safety Improvements Roadside Safety Improvements	treated/pollutant	13.3 80 44
7 4707 7 4708	Roadside Safety Roadside Safety	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements	treated/pollutant Location(s) Location(s) Location(s)	80 44 47
7 4707 7 4708 7 4709	Roadside Safetv Roadside Safetv US101 Median Barrier	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction	treated/pollutant Location(s) Location(s) Location(s) Collision(s) reduced	80 44 47 248
7 4707 7 4708 7 4709 7 4713	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements	treated/pollutant Location(s) Location(s) Location(s) Collision(s) reduced Location(s)	80 44 47 248 60
7 4707 7 4708 7 4709 7 4713 7 4714	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements	treated/pollutant Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Location(s)	80 44 47 248 60 35
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715	Roadside Safety Roadside Safety US101 Medicin Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Réside Safety	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements	treated/pollutant Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Location(s) Location(s)	80 44 47 248 60 35 214
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rite 91 Roadside Safety Rite 10 Santa Monica Reside Safety LA-010-WORKER SAFETY 18/19	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements	treated/pollutant Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s)	80 44 47 248 60 35 214
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements	treated/pollutant Location(s)	80 44 47 248 60 35 214
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rite 91 Roadside Safety Rite 10 Santa Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R)	treated/pollutant Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Acre(s) treated/pollutant Lane mile(s)	80 44 47 248 60 35 214
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4718 7 4718	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Sanita Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s)	80 44 47 248 60 35 214 106 46.4
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rite 91 Roadside Safety Rite 10 Santa Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R)	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s)	80 44 47 248 60 35 214 106 46.4
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL-18/19	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s) treated/pollutant	80 44 47 248 60 35 214 106 46.4
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Santa Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weight Station	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s) treated/pollutant Location(s)	80 44 47 248 60 35 214 106 46.4
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL-18/19	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s) treated/pollutant Location(s)	80 44 47 248 60 35 214 106 46.4
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Santa Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weight Station	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) Bridae(s) Acre(s) Bridae(s)	80 44 47 248 60 35 214 106 46.4
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4729 7 4730	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL-18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Bridge(s) Bridge(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4730 7 4743	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Santa Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Stom Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) Bridae(s) Acre(s) Treated/pollutant Location(s) Acre(s) Treated/pollutant Location(s) Acre(s) Treated/pollutant Location(s) Bridge(s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1
7 4707 7 4708 7 4709 7 4719 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4722 7 4724 7 4729 7 4730	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western Ave ADA	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridae Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s) treated/pollutant Location(s) Deficient (s) The property of the	80 44 47 2488 60 35 214 106 46.4 44.5 1 9.1 1 1
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4729 7 4730 7 4743 7 4743 8 7 4743	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps ADA - New Curb Ramps ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) Curb ramp(s) Curb ramp(s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 1 1 2
7, 4707 7, 4708 7, 4709 7, 4713 7, 4714 7, 4715 7, 4716 7, 4717 7, 4718 7, 4721 7, 4722 7, 4724 7, 4729 7, 4730 7, 4743 7, 4743 7, 4744 7, 47458	Roadside Safety Roadside Safety Roadside Safety US101 Medicina Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Sanita Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western Ave ADA Western Ave ADA Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Deficient Bridge(s) Deficient Courb ramp(s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 1,9.1 2 1 1 1 1 1 1 2 1 35 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4729 7 4730 7 47438 7 47438 7 47444 7 47458	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s) Bridge(s) Bridge(s) Deficiently Bridge(s) Deficiently Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 1 1 2 130 61 42 5
7, 4707 7, 4708 7, 4709 7, 4713 7, 4714 7, 4715 7, 4716 7, 4717 7, 4718 7, 4721 7, 4722 7, 4724 7, 4729 7, 4730 7, 4743 7, 4743 7, 4744 7, 47458	Roadside Safety Roadside Safety Roadside Safety US101 Medicina Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Sanita Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western Ave ADA Western Ave ADA Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Deficient Bridge(s) Deficient Courb ramp(s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1 1 1 2 130 61 42 5 61 69
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4729 7 4730 7 4743 7 4743 7 4744 7 4745 7 4749 7 4749 7 4749	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL-18/19 405 SB Weight Station Bridge Paint Point LA River Bridge Western Ave ADA Western Aba R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps Hawthorne ADA W/o R/W Howthorne ADA W/ R/W Poyement Preservation and ADA Curb Ramps	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Bridge(s) Curb ramp(s) Location(s) Lane mile(s)	80 44 47 248 60 35 214 106 46.4 1,9.1 2 1 1 1 1 1 1 2 1 35 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4729 7 4730 7 4743 7 4743 7 4745 8 7 4745 8 7 4749 7 4749 7 4749 7 4749 7 4749 7 4749 7 4749 7 4749	Roadside Safety Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Sanita Monica Reside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL-18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps Hawthorne ADA W/R/W Hawthorne ADA W/R/W Hawthorne ADA W/R/W Pavement Preservation and ADA Curb Ramps Pavement Rehab and ADA curb ramps Pavement Rehab and ADA curb ramps Pavement Rehab and ADA curb ramps	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) Acre(s) Are(s) Are(s) Bridge(s) Acre(s) Acre(s) Acre(s) Acre(s) Acre(s) Bridge(s) Acre(s) Curb ramp(s) Lane mile(s) Lane mile(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1 1 1 2 130 61 42 5 61 69 69 69 69
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4724 7 4729 7 4730 7 4743 7 4743 7 4745 7 4749 7 4749 7 4749 7 4749 7 4769 7 4770 7 4778	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps Hawthorne ADA W/O R/W Hawthorne ADA W/O R/W Hawthorne ADA W/O R/W Pavement Preservation and ADA Curb Ramps Povement Rehab and ADA curb ramps Povement Rehab and ADA curb ramps Upgrade MBGR	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Driver promp(s) Curb ramp(s)	80 44 47 2488 60 35 214 106 46.4 44.5 1 1 9.1 1 1 2 2 130 61 42 5 6 61 69 69 69 69 69 69 69 69 69 69 69 69 69
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4722 7 4724 7 4729 7 4730 7 4743 7 4744 7 4745 8 7 4745 7 4749 7 4749	Roadside Safety Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL- 18/19 405 SB Weiaht Station Bridge Paint Paint LA River Bridge Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps Howthorne ADA W, R/W Howthorne ADA W, R/W Howthorne ADA W, R/W Pavement Preservation and ADA curb Ramps Pavement Rehab and ADA curb ramps Palesimic Retrofit	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1 2 130 61 42 5 61 69 69 16 41 13 13 13 14 15 16 16 16 16 16 16 16 16 16 16
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4722 7 4724 7 4729 7 4730 7 4743 7 4743 7 4745 7 4749 7 4749 7 4749 7 4749 7 4765 7 4785 7 4785 7 4788 7 4785 7 4788	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Hostin Mester Ave ADA Western Ave ADA Wester	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Deficient (s) Acre(s) treated/pollutant Location(s) Deficient (s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1 2 130 61 42 5 61 69 69 69 16 46.4 13 5 64.3
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4722 7 4724 7 4729 7 4730 7 4743 7 4744 7 4745 7 4745 7 4745 7 4749 7 4748 7 4748 7 4748 7 4748 7 4749 7 4749 7 4749 7 4749 7 4749 7 4749 7 4748 7 4748 7 4748 7 4748 7 4748 7 4748 7 4748 7 4748 7 4749 7 4748 7 4748 7 4748 7 4748 7 4748 7 4748 7 4749 7 4748 7	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS IMDL 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps Hawthorne ADA W/o R/W Howthorne ADA W/o R/W Howthorne ADA W/o R/W Pavement Rehab and ADA curb Ramps Pavement Rehab and ADA curb ramps Upgrade MBGR Seismic Retrofit LA-210 2R in Son Fernando RIMMA Overlay on NW LA-138	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridae Preventative Maintenance Storm Water Mitigation Weiaht Stations & Weiaht-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps ADA - New Cur	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridge(s) Bridge(s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 1 2 130 61 42 5 61 49 69 69 69 69 64 44 13 53 64 64 64 64 64 64 64 64 64 64
7 4707 7 4708 7 4709 7 4713 7 4714 7 4715 7 4716 7 4717 7 4718 7 4721 7 4722 7 4722 7 4724 7 4729 7 4730 7 4743 7 4743 7 4745 7 4749 7 4749 7 4749 7 4749 7 4765 7 4785 7 4785 7 4788 7 4785 7 4788	Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 10 Santa Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TIMDL 18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Hostin Mester Ave ADA Western Ave ADA Wester	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridge Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps ADA - New Curb Ra	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Deficient (s) Acre(s) treated/pollutant Location(s) Deficient (s) Curb ramp(s)	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1 2 130 61 42 5 61 69 69 69 16 46.4 13 5 64.3
7, 4707 7, 4708 7, 4709 7, 4713 7, 4714 7, 4715 7, 4716 7, 4717 7, 4718 7, 4721 7, 4722 7, 4724 7, 4729 7, 4730 7, 4743 7, 4743 7, 4744 7, 4745 7, 4745 7, 4747 7, 4749 7, 474	Roadside Safety Roadside Safety Roadside Safety US101 Median Barrier Landscape 18/19 Rte 91 Roadside Safety Rte 91 Roadside Safety Rte 10 Sanita Monica Rdside Safety LA-010-WORKER SAFETY 18/19 710 Source Control in Monterey Park 57 2R Lane Replacement REPLACE DRAINAGE INLETS TMDL-18/19 405 SB Weight Station Bridge Paint Paint LA River Bridge Western Ave ADA Western ADA R/W Upgrade Americans with Disabilities Act Ramps & Accessibility Foothill Curb Ramps - with R/W VEN-150 ADA Curb Ramps Hawthorne ADA W/R R/W Hawthorne ADA W/R R/W Pavement Preservation and ADA Curb Ramps Pavement Rehab and ADA curb ramps Upgrade MBGR Seismic Refrofit LA-210 2R in San Fernando RHMA Overlay on NW LA-138 Roadside Safety Improvement	Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Roadside Safety Improvements Collision Severity Reduction Roadside Safety Improvements Storm Water Mitigation Roadway Rehabilitation (2R) Bridae Preventative Maintenance Storm Water Mitigation Weight Stations & Weight-In-Motion Facilities Capital Bridge Preventative Maintenance Progran Capital Bridge Preventative Maintenance Progran ADA - New Curb Ramps ADA - New Cur	treated/pollutant Location(s) Acre(s) treated/pollutant Lane mile(s) Bridae(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Acre(s) treated/pollutant Location(s) Dridge(s) Curb ramp(s) Lourb	80 44 47 248 60 35 214 106 46.4 44.5 1 9.1 1 1 2 130 61 42 5 61 69 69 69 69 64 44 35 60 60 60 60 60 60 60 60 60 60

7 4813	Ven 101 Source Control in Ventura	Storm Water Mitigation	Acre(s) treated/pollutant	21.
7 4814	Rte 101 Stormwater Source Control	Storm Water Mitigation	Acre(s)	53.
7 4815	Stormwater Source Control	Storm Water Mitigation	treated/pollutant Acre(s)	7.
7 4816	Rte 134 Stormwater Source Control	9	treated/pollutant	12.
		Storm Water Mitigation	Acre(s) treated/pollutant	
7 4817 7 4818	LA-134 Pavement Preservation Pavement Rehab	Pavement Preservation (CAPM) Pavement Rehabilitation	Lane mile(s) Lane mile(s)	35.
7 4819	Upgrade TMS	Transportation Management (TMC's & Field	Field element(s)	11
7 4830	TMS Installations	Eauipment1 Transportation Management Systems	Field element(s)	15
7 4845	Drainage Improvement, Culvert Repair, Replacement	Drainage System Restoration	Culvert(s) (ea)	3
7 4846 7 4847	Solstice Creek Drainage Rehabilitation	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	1
7 4848 7 4849	Drainage Improvement	Drainage System Restoration	Culvert(s) (ea)	
7 4849	Drainage Improvement & Replace Culvert System Bridge Paint	Drainage System Restoration Capital Bridge Preventative Maintenance Program	Culvert(s) (ea) Bridge(s)	
7 4887	SR-14 2R in Palmdale	Roadway Rehabilitation (2R)	Lane mile(s)	79.
7 4894	Slope/Gore paving	Roadside Safety Improvements	Location(s)	11
7 4902 7 4903	El Monte Bus Sta Bridge Deck Replc Tunnel Lighting	Bridge Rehabilitation and Replacement Signs and Lighting Rehabilitation	Bridge(s) Lighting fixture(s)	25
7 4906	overhead sign panels	Signs and Lighting Rehabilitation	Lighting fixture(s)	52
7 4908	Source Control	Storm Water Mitigation	Acre(s) treated/pollutant	17.
7 4910	Upgrade Pumps	Drainage System Restoration	Culvert(s) (ea)	0
7 4913	Slope Paving, Drainage Corrections	Storm Water Mitigation	Acre(s) treated/pollutant	0.
7 4915	Encino POC Demo Permanent Slope Restoration	Bridge Rehabilitation and Replacement	Bridge(s)	
7 4930 7 4963	605/Live Oak Ramps	Major Damage (Permanent Restoration) Safety Improvements	Location(s) Collision(s) reduced	20
7 4966 7 4967	Strenathen Bridge Bridge Rehabilitation	Trans Permit Requirements for Bridges Trans Permit Requirements for Bridges	Bridge(s) Bridge(s)	
7 4968	LA-091 reduce severity collisions	Safety Enhancements	Collision(s) reduced	
7 4969 7 4971	Upgrade Curve Warning Signs TMDL- 20/21	Collision Severity Reduction Storm Water Mitigation	Collision(s) reduced Acre(s)	
		_	treated/pollutant	
7 4972 7 4973	Ventura OH Replacement Roadside Safety	Bridge Rehabilitation and Replacement Roadside Safety Improvements	Bridge(s) Location(s)	7
7 4975	Roadside safety improv	Roadside Safety Improvements	Location(s)	12
7 4976 7 4977	LA 14 Roadside Safety Improvements Storm Water Source Control	Roadside Safety Improvements Storm Water Mitigation	Location(s) Acre(s)	5 12.
	W 2 2 W 2 W 2 2 W 2 W 2 2 W		treated/pollutant	
7 4978	405 SW Source Control	Storm Water Mitigation	Acre(s) treated/pollutant	17.
7 4979 7 4980	Pavement Rehabilitation TMDL- 20/21	Pavement Rehabilitation Storm Water Mitigation	Lane mile(s) Acre(s)	95. 57.
			treated/pollutant	
7 4982 7 4983	SR-164 ADA SGR Bridge Rail Upgrade	ADA - New Curb Ramps Bridge Rehabilitation and Replacement	Curb ramp(s) Bridge(s)	9
7 4984	405/605 Bridge Scour (CMGC)	Bridge Scour	Bridge(s)	
7 4985 7 4997	LA-210, Upgrade ADA ramps (OS) TMDL- 21/22	ADA - New Curb Ramps Storm Water Mitigation	Curb ramp(s) Acre(s)	25 7
		<u> </u>	treated/pollutant	
7 4998 7 5000	PCH CAPM, OC to Torrance Reduce Frequency and Duration of HWY Workers Exposure	Pavement Preservation (CAPM) Roadside Safety Improvements	Lane mile(s) Location(s)	8 3
7 5001	TMDL - 21/22	Storm Water Mitigation	Acre(s)	39.
7 5002	Bridge Rail Upgrade (OS)	Bridge Rail Replacement and Upgrade	treated/pollutant Linear feet rail	156
7 5003 7 5004	Bridge Rail Upgrade Union Pacific OH Deck Rehabilitation	Bridge Rail Replacement and Upgrade Bridge Rehabilitation and Replacement	Linear feet rail Bridge(s)	332
7 5005	I-210 Glendora BMP	Storm Water Mitigation	Acre(s)	32.
7 5007	TCB CAPM	Pavement Preservation (CAPM)	treated/pollutant Lane mile(s)	60.
7 5008	Bridge Structure Painting	Capital Bridge Preventative Maintenance Program	Bridge(s)	00.
7 5009	Construct BMP for Storm Water Mitigation	Storm Water Mitigation	Acre(s)	4
	, and the second		treated/pollutant	
7 5010 7 5011	Upgrade ADA ramps and accessibility TMDL- 20/21	ADA - New Curb Ramps Storm Water Mitigation	Curb ramp(s) Acre(s)	34.
		<u> </u>	treated/pollutant	
7 5012	TMDL 21/22	Storm Water Mitigation	Acre(s) treated/pollutant	53.
7 5013 7 5014	I-5 Protective Betterments in Castaic VEN-150 CAPM	Protective Betterments Pavement Preservation (CAPM)	Location(s) Lane mile(s)	11.
7 5018	Ventura PCH CAPM	Pavement Preservation (CAPM)	Lane mile(s)	14.
7 5022 7 5023	Cold Plane and AC Overlay 57 Sunset Xina Worker Safety	Pavement Preservation (CAPM) Roadside Safety Improvements	Lane mile(s) Location(s)	7.
7 5024	Repair/upgrade pump stations	Drainage System Restoration	Pump plant(s) (ea)	
7 5025	TMDL- 20/21	Storm Water Mitigation	Acre(s) treated/pollutant	39.
7 5026	210 SGR Hinge and Diaphragm Repairs	Bridge Major Rehabilitation	Bridge(s)	
7 5027	TMDL- 20/21	Storm Water Mitigation	Acre(s) treated/pollutant	29.
7 5029 7 5030	Slab Replacement and Shoulder Resurfacing Roadside Safety Improvements	Pavement Rehabilitation Roadside Safety Improvements	Lane mile(s) Location(s)	39. 10
7 5030 7 5032	Tejon Pass OC Bridge; Seismic Retrofit	Bridge Seismic Restoration	Bridge(s)	
7 5034 7 5035	PCH CAPM, Torrance to Santa Monica SR- 39 Seismic Retrofit	Pavement Preservation (CAPM) Bridge Seismic Restoration	Lane mile(s) Bridge(s)	79.
7 5037	High Friction Surface Treatment	Safety Improvements	Collision(s) reduced	43
7 5040 7 5041	Upgrade Transportation Management System I-10 TMS Between SM and DTLA	Transportation Management Systems Transportation Management Systems	Field element(s) Field element(s)	6 12
7 5043	Heim Pump Station	Drainage System Restoration	Pump plant(s) (ea)	12
7 5046 7 5067	Upgrade MBGRs I-10 Closure Pour in El Monte	Collision Severity Reduction Bridge Preventative Maintenance	Collision(s) reduced Bridge(s)	
7 5068	Storm Water Mitigation	Storm Water Mitigation	Acre(s)	38.
7 5069	105-replace joint seals	Capital Bridge Preventative Maintenance Program	treated/pollutant Bridge(s)	
7 5070	Bridge Painting	Capital Bridge Preventative Maintenance Program	Bridge(s)	
7 5071	Castaic Weigh Station	Commercial Vehicle Enforcement Facilities & Weigh	-Location(s)	
7 5072	Hollywood Worker Safety	In-Motion Scales Roadside Safety Improvements	Location(s)	22
7 5073	N Hollywood Roadside safety I-110 Upgrade OHS	Roadside Safety Improvements Signs and Lighting Rehabilitation	Location(s) Sign(s)	8 50
7 5074		Laigus grig lighting Kengoliitation		

7 5070	Do adrido Cafak, Isaaya, asaast	Do adaida Cafaki Issaya a santa	Landian(s)	2/
7 5078 7 5080	Roadside Safety Improvement 210 Irrigation	Roadside Safety Improvements Roadside Rehabilitation	Location(s) Acre(s)	36 29.4
7 5081	Ven101 Rehab	Commercial Vehicle Enforcement Facilities & Weigh		27
		In-Motion Scales		
7 5082	Upgrade MBGR and End Treatments	Safety Enhancements	Collision(s) reduced	14
7 5083 7 5084	LA 110 Hard Running Shoulder HFST on 110 and 91 connector	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	50 ₄
7 5089	Stormwater Source Control	Storm Water Mitigation	Acre(s)	23.8
		3	treated/pollutant	
7 5091	Fwy 10/405 Erosion Control	Storm Water Mitigation	Acre(s)	38.5
7 5145	Death black have be	Callistan Councilla Bankarillan	treated/pollutant Annual fatal and serious	
/ 3143	Rock block barrier	Collision Severity Reduction	injury collision(s)	1
			ii ijoi y Collisioi i(s)	
7 5151	LA 2 MBGR	Collision Severity Reduction	Collision(s) reduced	24
7 5152	110/10 Reactive Safety	Safety Improvements	Collision(s) reduced	404
7 5153 7 5155	Safety Improvement 010 project	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	62
7 5155	Signal Modification Pilot Project #1	Roadside Safety Improvements	Location(s)	17 72.5
7 5157	SR-72 ADA & Relinquishment	Relinquishments	Centerline mile(s)	/2
7 5159	Pilot Project #2	SHOPP - Misc	Location(s)	i
7 5181	Big Sycamore Creek	Major Damage (Permanent Restoration)	Location(s)	1
7 5184	Route 2 Cold plane & Overlay	Pavement Preservation (CAPM)	Lane mile(s)	20.3
7 5185 7 5188	SR-138 ADA Palmdale Bluetooth Detection System	ADA - New Curb Ramps Transportation Management Systems	Curb ramp(s) Field element(s)	70
7 5193	Relinquishment	Relinquishments	Lane mile(s)	7 <i>6</i> 2. <i>6</i>
7 5196	Fair Oaks Avenue Improvements	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	64
		Improvements	Delay (DVHD)	
7 5201	Rte 10 Signs	Signs and Lighting Rehabilitation	Sign(s)	61
7 5204	Santa Clara River	Storm Water Mitigation	Acre(s)	38
7 5010	STORM WATER MITIGATION	Storm Water Mitigation	treated/pollutant	10.1
7 5212	STORINI VYATER MITIGATION	STOTE WATER MINIGRATION	Acre(s) treated/pollutant	13.1
7 5214	Workers Safety	Roadside Safety Improvements	Location(s)	29
7 5216	118 Sepulveda Roadside safety	Roadside Safety Improvements	Location(s)	32.7
7 5219	Rte 14 Drainage Culvert	Drainage System Restoration	Culvert(s) (ea)	17
7 5221	LA-101 Upgrade CCTV/CMS	Transportation Management Systems	Field element(s)	101
7 5222	LA-134 Upgrade TMS	Transportation Management Systems	Field element(s)	48
7 5223 7 5226	Culvert Repair Upgrade TMS	Drainage System Restoration Transportation Management Systems	Culvert(s) (ea) Field element(s)	1 75
7 5226	405 Roadside Safety 110-105	Roadside Safety Improvements	Location(s)	
7 5229	605 roadside safety	Roadside Safety Improvements	Location(s)	36
7 5231	Upgrade MBGR and End Treatment	Safety Enhancements	Collision(s) reduced	16
7 5233	ADA curb ramps upgrade	ADA - New Curb Ramps	Curb ramp(s)	23
7 5234	STORMWATER MITIGATION	Storm Water Mitigation	Acre(s)	54.5
7 5236	stormwater mitigation	Storm Water Mitigation	treated/pollutant Acre(s)	29
7 3230	Sioniwaler minganon	Sionn Water Miligation	treated/pollutant	27
7 5237	Protective Betterment	Protective Betterments	Location(s)	1
7 5239	LA-1, PCH/ Atlantic Safety Improv	Safety Improvements	Collision(s) reduced	32
7 5245	ITS Restoration Work in Hassan Manaa's area	Transportation Management (TMC's & Field	Field element(s)	170
7 5044	TTC Devices Proceeding China Process	Equipment)	Field described	20.4
7 5246	ITS Restoration work in Shimelis area	Transportation Management (TMC's & Field Eauioment)	Field element(s)	384
7 5247	ITS Restoration	Transportation Management (TMC's & Field	Field element(s)	602
		Equipment)	(-)	
7 5255	Ven 118 Weigh Station	Commercial Vehicle Enforcement Facilities & Weigh	Location(s)	2
		In-Motion Scales		
7 5257 7 5281	PCH @ Anaheim St. I-5 Freight Corridor	Safety Improvements Trans Permit Requirements for Bridges	Collision(s) reduced Bridge(s)	18 12
7 5287	District Building Roof Replacement	L&B Office Facilities	Location(s)	12
7 5291	Topanga Cyn Slide Repair	Major Damage (Permanent Restoration)	Location(s)	1
7 5292	CONSTRUCT RETAINING WALL	Major Damage (Permanent Restoration)	Location(s)	1
7 5293	Storm Damage	Major Damage (Permanent Restoration)	Location(s)	1
7 5294	Restore Slope Stability on 118	Major Damage (Permanent Restoration)	Location(s)	
7 5296 7 5297	maiSlope Stability Freight Corridor Improvements on LA-60	Major Damage (Permanent Restoration) Trans Permit Requirements for Bridges	Location(s) Bridge(s)	
7 5297	LA-39/ N. Fork San Gabriel Bridge Replacement	Bridge Scour	Bridge(s)	1
7 5321	I-5 TMDL in Burbank/Glendale	Storm Water Mitigation	Acre(s)	28
		<u> </u>	treated/pollutant	
7 5323	Crib-wall	Major Damage (Permanent Restoration)	Location(s)	1
7 5353	VEN-150 Pavement Rehab and Curb Ramps	Pavement Preservation (CAPM)	Lane mile(s)	6.3
7 5355 7 5357	Anaheim Street Overhead Bridge Rail Upgrade LA-710 TMS, POLB to I-405	Bridge Rail Replacement and Upgrade Transportation Management Systems	Linear feet rail Field element(s)	5150
7 5363	US-101 Workers Safety in the Valley	Roadside Safety Improvements	Annual fatal and serious	2.38
, 3363	35 TO INDIXOIS SQUOTY III THE FUILEY	negasiae salety improvements	injury collision(s)	2.30
7 5364	PCH @ LAR Bridge Seismic Retrofit	Bridge Seismic Restoration	Bridge(s)	2
7 5365	Mobility (TMS) on Ven 23	Transportation Management Systems	Field element(s)	44
7 5366 7 5370	LA-101 Pavement Rehab near Universal SR-91 ROADSIDE PRESERVATION	Pavement Preservation (CAPM) Signs and Lighting Rehabilitation	Lane mile(s) Sign(s)	37 12
7 5370	Western Ave CAPM & ADA Ramps	Pavement Preservation (CAPM)	Lane mile(s)	42.9
7 5372	LA-107 Torrance Maintenance Station	Maintenance Facilities	Location(s)	1
7 5373	Pavement Rehab on Ven 232	Pavement Preservation (CAPM)	Lane mile(s)	14.7
7 5374	LA-710, Drainage System Restoration	Drainage System Restoration	Pump plant(s) (ea)	4
7 5375	LA-134 Overhead Signs	Signs and Lighting Rehabilitation Storm Water Mitigation	Sign(s)	20
7 5377	FCO 22/23	STOTE WATER MINIGRATION	Acre(s) treated/pollutant	181
7 5378	LA10 Roadside Rehab	Roadside Rehabilitation	Acre(s)	22.5
7 5379	LA-D7 Office Building Boilers Replacement	L&B Office Facilities	Location(s)	1
7 5381	SR 39 Reopening	Protective Betterments	Location(s)	1
7 5382	405 2R, Westwood to Van Nuys	Roadway Rehabilitation (2R)	Lane mile(s)	91.6
7 5386 7 5391	210 Misc Stormwater Mitigation on Ven 23	Bridge Seismic Restoration	Bridge(s)	<u> </u>
/ 3371	Signification willigation on ven 25	Storm Water Mitigation	Acre(s) treated/pollutant	18.7
7 5392	LA2 ADA in LCF	ADA - New Curb Ramps	Curb ramp(s)	61
7 5393	I-210/SR-2 Upgrade Lighting Systems to LED	Signs and Lighting Rehabilitation	Lighting fixture(s)	1397
7 5395	District-wide CCTV	Transportation Management Systems	Field element(s)	65
7 5396	SR-39 Bridge rail upgrade	Bridge Rail Replacement and Upgrade	Linear feet rail	301
7 5397	Angeles Crest Hwy Drainage	Drainage System Restoration	Culvert(s) (ea)	11
7 5400	210 TMS Upgrade in San Dimas	Transportation Management Systems	Field element(s) Field element(s)	12
	170 TMS Upgrade + Safety			
7 5401	170 TMS Upgrade + Safety 710 Roadside Safety in LR	Transportation Management Systems Roadside Safety Improvements		0.74
	1170 TMS Uparade + Safety 710 Roadside Safety in LB	Roadside Safety Improvements	Annual fatal and serious	0.74
7 5401		Roadside Safety Improvements	Annual fatal and serious injury collision(s)	0.74
7 5401		Roadside Safety Improvements Commercial Vehicle Enforcement Facilities & Weigh	Annual fatal and serious injury collision(s)	0.74
7 5401 7 5404 7 5406	710 Roadside Safety in LB CVEF & WIM Near Somis	Roadside Safety Improvements Commercial Vehicle Enforcement Facilities & Weigh In-Motion Scales	Annual fatal and serious injury collision(s) -Location(s)	0.74
7 5401 7 5404	710 Roadside Safety in LB	Roadside Safety Improvements Commercial Vehicle Enforcement Facilities & Weigh	Annual fatal and serious injury collision(s)	0.74 1

	Comm. System Upgrade	Transportation Management Systems	Field element(s)	
5409	LA 2 Video Wall 405 ATM/ITS near LAX (CMGC)	Transportation Management Systems	Field element(s)	
5410 5412	CCTV Replacement D7 wide	Transportation Management Systems Transportation Management (TMC's & Field	Field element(s) Field element(s)	
0112	oer Replacement by mad	Equipment)	ricia cierricini(s)	
5412B	CCTV Camera Upgrades/Replacements	Transportation Management Systems	Field element(s)	
5412C	CCTV Camera Upgrades/Replacements	Transportation Management Systems	Field element(s)	
5413	7-LA/VEN-Various PMs Changeable Message Signs(CMS) Replacement Project	Transportation Management (TMC's & Field	Field element(s)	
5414	Seismic Retrofit of I-5/Route 2 Connector	Equipment Bridge Seismic Restoration	Bridge(s)	
5415	SR-110 Figueroa Improvements	Operational Improvements	Daily vehicle hour(s) of	
	, , , , , , , , , , , , , , , , , , ,	The state of the s	delay (DVHD)	
5429	LA-101, Bridge Rail Upgrade	Bridge Rail Replacement and Upgrade	Linear feet rail	
5432	Ven-118 CAPM in Moorpark	Pavement Preservation (CAPM)	Lane mile(s)	
5433 5434	I-5 Traffic Signal Upgrade @ Cesar Chavez Long Beach ADA	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	
5435	Left Turn/ADA	Safety Improvements	Collision(s) reduced	
5467	Nickname Required	Major Damage (Emergency Opening)		
5468	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5470	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5473	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5474 5475	Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	
5476	Nickname Required	Major Damage (Emergency Opening)	Location(s) Location(s)	
5477	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5478	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5480	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5481	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5482	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5484 5485	LA-405, Pavement Rehabilitation Upgrade 3rd St. Bridge Railing with Concrete Barriers	Pavement Preservation (CAPM) Major Damage (Permanent Pertoration)	Lane mile(s) Location(s)	
5485	I-5 Tunnel Lighting	Major Damage (Permanent Restoration) Signs and Lighting Rehabilitation	Lighting fixture(s)	
5490	LA-405 Bridge Seismic Restoration	Bridge Seismic Restoration	Bridge(s)	
5491	PCH CAPM, Malibu Lagoon to Ventura CL	Pavement Preservation (CAPM)	Lane mile(s)	
5499	Paint Hobart Yard OH Bridge	Bridge Rehabilitation and Replacement	Bridge(s)	
5500	Culver City New Crew Building	Maintenance Facilities	Location(s)	
5505	PCH and Las Flores 010 Safety	Safety Improvements	Collision(s) reduced	
5506	LA 118 Drainage System Restoration 105/405 Tunnels Lighting	Drainage System Restoration Sians and Liahtina Rehabilitation	Culvert(s) (ea)	
5507 5508	Stormwater Mitigation on Ven 33 (Seg #1)	Signs and Lighting Rehabilitation Storm Water Mitigation	Lighting fixture(s) Acre(s)	
5500	Sionnification willinguition veri 33 (3eg #1)	Sionn Harer Willigation	treated/pollutant	
5509	LA-2 Culvert	Drainage System Restoration	Culvert(s) (ea)	
5511	MTC Equip Trn Center Under 105	Maintenance Facilities	Location(s)	
5515	CAPM / ADA / Complete Streets	Pavement Preservation (CAPM)	Lane mile(s)	
5516	Replacing pump plant	Drainage System Restoration	Pump plant(s) (ea)	
5519	Stormwater Mitigation on Ven 126	Storm Water Mitigation	Acre(s)	
5521	I-605 Rehab, Telegraph to I-10	Roadway Rehabilitation (2R)	treated/pollutant Lane mile(s)	
5523	Stormwater Mitigation on Ven 33 (Seg #2)	Storm Water Mitigation	Acre(s)	
			treated/pollutant	
5534	Safety Upgrade 105/Crenshaw On/off ramps	Collision Severity Reduction	Collision(s) reduced	
5535	I-5 CAPM in Downey & Commerce	Pavement Preservation (CAPM)	Lane mile(s)	
5545	Pacific MTC Station	Maintenance Facilities	Location(s)	
5546 5548	Doran Maintenance Station Nickname Required	Maintenance Facilities Major Damage (Emergency Opening)	Location(s) Location(s)	
5548	Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	
5551	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5552	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5553	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5554	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5555 5557	Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	
5557	Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s)	
5560	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5562	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5565	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5568	BRIDGE RAIL UPGRADE	Bridge Preventative Maintenance	Bridge(s)	
5568	BRIDGE RAIL UPGRADE	Bridge Rail Replacement and Upgrade	Linear feet rail	
5572	170 HFST Installation	Safety Improvements	Collision(s) reduced Collision(s) reduced	
5573 5574	LA-138 Roundabout at 60th St W PCH at Los Alamitos Bay Br. Redux	Safety Improvements Bridge Seismic Restoration		
5575	PCH at Los Alamitos Bay Br., Redux Long Beach PCH - Upgrade curb ramps	ADA - New Curb Ramps	Bridge(s) Curb ramp(s)	
5589	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5593	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5594	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
5594 5597	Nickname Required	Major Damage (Emergency Opening)	Location(s) Location(s)	
5594 5597 5598	Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s) Location(s)	
5594 5597 5598 5599	Nickname Required Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s) Location(s) Location(s)	
5594 5597 5598 5599 5600 5602	Nickname Required Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s) Location(s)	
5594 5597 5598 5599 5600 5602 5603	Nickname Required	Major Damage (Emergency Openina)	Location(s)	
5594 5597 5598 5599 5600 5602 5603 5604	Nickname Required	Maior Damage (Emergency Opening)	Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606	Nickname Required	Major Damage (Emergency Openina)	Location(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607	Nickname Required	Major Damage (Emergency Openina)	Location(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608	Nickname Required	Maior Damage (Emergency Opening)	Location(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607	Nickname Required OO - Culvert failure	Major Damage (Emergency Openina)	Location(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611	Nickname Required Install Protected Left Turn Signal Install protected Left Turn Signal Install protected Left Turn Cannelization La-1, Signal Improvement	Major Damage (Emergency Openina) Safety Improvements Safety Improvements	Location(s) Codision(s) Collision(s) reduced Collision(s) reduced	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611 5612 5614	Nickname Required Installerotected Left Turn Signal Install Protected Left Turn Signal Install protected Left furn channelization LA-1, Signal Improvement	Major Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement	Location(s) Codision(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Bridae(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611 5612 5614	Nickname Required Install Protected Left Turn Signal Install protected Left Turn Signal Install protected Left flum Signal Install protected Left Signal Install Sycamore BIG SYCAMORE Arayle-Frankin (I/CI (53-0680) & Bia Tujunaa Wash (53-2249)	Maior Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Bridage Rehabilitation and Replacement	Location(s) Collision(s) Collision(s) reduced Collision(s) reduced Bridae(s) Bridae(s)	
5594 5597 5598 5598 5599 5600 5602 5603 5606 5606 5607 5608 5611 5612 5614 5616 5619	Nickname Required Install Protected Left Turn Signal Install Protected Left Turn Signal Install protected Left Turn Channelization La-I, Signal Improvement BIG SYCAMORE Arayle-Franklin (IUC) (53-0680) & Big Tujunga Wash (53-2249)	Major Damage (Emeraency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Pravement Preservation (CAPM)	Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Bridae(s) Bridae(s) Bridae(s) Lane mile(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611 5612 5614 5616 5619 5619	Nickname Required Nickname Req	Major Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Lane mile(s)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611 5612 5614 5616 5619 5620 5624	Nickname Required Nickname Req	Major Damage (Emeraency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Pravement Preservation (CAPM)	Location(s) Collision(s) Location(s) Collision(s) reduced Collision(s) reduced Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Pump plant(s) (ea)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5606 5607 5608 5611 5611 5612 5614 5616 5616 5619 5620 5620	Nickname Required Noc- culvert failure Install Protected Left Turn Signal Install protected Left Turn Signal Install protected Left Turn Signal Nickname Required Nickname Required Noc- culvert failure Install Protected Left Turn Signal Install Protected Left Turn Signal Nistall Protected Left Turn Signal N	Major Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Bridage Rehabilitation and Replacement Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM)	Location(s) Locati	
5594 5597 5598 5599 5600 5603 5604 5604 5607 5608 5611 5611 5612 5614 5616 5619 5620 5624 5624	Nickname Required Install Protected Left Turn Signal Install Protected Left Turn Signal Install protected Left Turn Channelization LI., Signal Improvement BIG SYCAMORE Arayle-Franklin (UC) (53-0680) & Big Tujunga Wash (53-2249) VEN-33 CAPM Ven-118 CAPM, ADA LA 105 - Droinage upgrade PCH CAPM, SM to Malibu Lagoon Ven-23 CAPM, JX LA-210 Droinage Nega Sunland Blvd	Major Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Pavement Preservation (CAPM)	Location(s) Locati	
5594 5597 5598 5599 5600 5600 5603 5604 5606 5607 5610 5611 5612 5614 5616 5619 5620 5620 5620 5622 5624 5626 5627	Nickname Required Nickname Req	Major Damage (Emeraency Openina) Safety (Improvements Safety (Improvements Safety (Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Pavement Preservation (CAPM) Drainage System Restoration Drainage System Restoration	Location(s) Bridace(s) Bridace(s) Bridace(s) Bridace(s) Lane mile(s) Culvert(s) (ea)	
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611 5612 5614 5616 5619 5620 5622 5623 5624 5625 5626 5628 5629 5631	Nickname Required Nickname Req	Major Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement Bridge Rehabilitation and Replacement Pavement Preservation (CAPM) Drainage System Restoration Drainage System Restoration Drainage System Restoration	Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Bridae(s) Lane mile(s) Lane mile(
5594 5597 5598 5599 5600 5602 5603 5604 5606 5607 5608 5610 5611 5611 5614 5614 5614 5614 5615 5614 5625 5625 5628 5629 5628 5629 5631	Nickname Required DO - Culvert Failure Install Protected Left Turn Signal Install protected Left Turn Signal Install protected Left Turn Channelization LA-I, Signal Improvement BIG SYCAMORE Arayle-Franklin (IUC) (33-0680) & Big Tujunga Wash (53-2249) Ven-118 CAPM. ADA LA 105 - Drainage upgrade PCH CAPM, SM to Malibu Laggon Ven-23 CAPM, JX LA-210 Drainage Near Sunland Blvd LA-210 Repair Drainage System 110 Culverts; San Pedra to 91 LA-5 Mobility - TMS	Major Damaga (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Prainage System Restoration Drainage System Restoration Drainage System Restoration	Location(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Culvert(s) (ea) Culvert(s) (ea) Culvert(s) (ea) Field element(s)	
5594 5597 5597 5598 5599 5600 5602 5603 5606 5606 5606 5607 5608 5611 5611 5612 5614 5616 5619 5620 5622 5623 5628 5629 5631	Nickname Required Noc- culvert failure Install protected Left Turn Signal Nickname Required Noc- Culvert Failure Install protected Left Turn Signal In	Major Damaga (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Bridage Rehabilitation and Replacement Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Drainage System Restoration Itansportation Management Systems Iransportation Management Systems	Location(s) Locati	
5594 5597 5598 5599 5600 5602 5603 5606 5607 5608 5610 5611 5611 5612 5614 5616 5619 5624 5628 5629 5631 5635 5631	Nickname Required Nickname Req	Major Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement Pravement Preservation and Replacement Pavement Preservation (CAPM) Drainage System Restoration Drainage System Restoration Drainage System Restoration Transportation Management Systems Transportation Management Systems	Location(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Culvert(s) Lane mile(s) Culvert(s) Lane mile(s) Culvert(s) Lane mile(s) Lane mi	
5594 5597 5597 5598 5599 5600 5602 5603 5606 5606 5606 5607 5608 5611 5611 5612 5614 5616 5619 5620 5622 5623 5628 5629 5631	Nickname Required Noc- culvert failure Install protected Left Turn Signal Nickname Required Noc- Culvert Failure Install protected Left Turn Signal In	Major Damaga (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Bridage Rehabilitation and Replacement Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Drainage System Restoration Itansportation Management Systems Iransportation Management Systems	Location(s) Locati	
5594 5597 5597 5598 5597 5598 5599 5600 5602 5603 5604 5606 5606 5606 5610 5611 5611 5612 5614 5616 5619 5620 5629 5623 5629 5631 5625 5624 5626 5628 5629 5631 5635 5636 5640 5640	Nickname Required DO - Culvert Failure Install Protected Left Tum Signal Install protected Left Tum Signal Install protected Left Tum Annelization LI. Signal Improvement BIG SYCAMORE Arayle-Frankin (UC) (53-0680) & Big Tujunga Wash (53-2249) VEN-33 CAPM Ven-118 CAPM, ADA LA 105 - Drainage Upgrade PCH CAPM, SM to Malibu Lagoon Ven-23 CAPM, JX LA-210 Drainage Near Sunland Blvd LA-210 Trainage Near Sunland Blvd LA-210 Repoir Drainage System 110 Culverts; San Pedro to 91 LA-5 Mobility - TMS LA-47 Upgrade TMS Upgrade TMS elements on LA-101 Mobility - TMS LA-40 Mobility - TMS LA-40 Mobility - TMS	Major Damaga (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Pavement P	Location(s) Peduced Collision(s) reduced Collision(s) reduced Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s	
5594 5597 5598 5597 5598 5599 5600 5602 5603 5606 5606 5606 5606 5610 5611 5611 5612 5614 5616 5619 5620 5622 5623 5624 5625 5628 5629 5631 5635 5640 5642 5643 5644 5643	Nickname Required Nochname Req	Major Damaga (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Bridage Rehabilitation and Replacement Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Drainage System Restoration Transportation Management Systems	Location(s) Iocation(s) Iocati	
5594 5597 5597 5598 5597 5598 5599 5600 5602 5603 5604 5606 5606 5606 5610 5611 5611 5612 5614 5616 5619 5620 5629 5623 5629 5631 5625 5624 5626 5628 5629 5631 5635 5636 5640 5640	Nickname Required DO - Culvert Failure Install Protected Left Tum Signal Install protected Left Tum Signal Install protected Left Tum Annelization LI. Signal Improvement BIG SYCAMORE Arayle-Frankin (UC) (53-0680) & Big Tujunga Wash (53-2249) VEN-33 CAPM Ven-118 CAPM, ADA LA 105 - Drainage Upgrade PCH CAPM, SM to Malibu Lagoon Ven-23 CAPM, JX LA-210 Drainage Near Sunland Blvd LA-210 Trainage Near Sunland Blvd LA-210 Repoir Drainage System 110 Culverts; San Pedro to 91 LA-5 Mobility - TMS LA-47 Upgrade TMS Upgrade TMS elements on LA-101 Mobility - TMS LA-40 Mobility - TMS LA-40 Mobility - TMS	Major Damaga (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Bridae Rehabilitation and Replacement Bridae Rehabilitation and Replacement Pavement Preservation (CAPM) Pavement P	Location(s) Peduced Collision(s) reduced Collision(s) reduced Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s	

7 5687	LA-1 TMDL, PE:KM-JX	Storm Water Mitigation Acre(s)	13.
/ 366/	LA-134 Storm Water	treated/pollutant	22.
	LA-134 SIOITI Water	Storm Water Mitigation Acre(s) treated/pollutant	22.
7 5690	VEN-101 Storm Water TMDL	Storm Water Mitigation Acre(s)	15.
7 5697	210/57 Safety Signs & Lighting Upgrades	treated/pollutant	6
7 5698	LA-57 Signs and Lighting	Signs and Lighting Rehabilitation Lighting fixture(s)	13
7 5701	LA-110 Bridge Replacement	Bridge Rail Replacement and Upgrade Annual fatal and serious injury collision(s)	0.0
7 5704 7 5705	SR-110,118 Sign rehab, PE:PN-KY Restore Slope Stability on 118	Signs and Lighting Rehabilitation Sign(s) Major Damage (Permanent Restoration) Location(s)	62
7 5710	Nickname Required	Major Damage (Emergency Opening) Location(s)	54
7 5711	Nickname Required	Major Damage (Emergency Opening) Location(s)	13
7 5712 7 5713	Nickname Required Nickname Required	Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	50 54
7 5714	Nickname Required	Major Damage (Emergency Opening) Location(s)	
7 5715 7 5718	Nickname Required Nickname Required	Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	
7 5723	Nickname Required	Major Damage (Emergency Opening) Location(s)	
7 5728 7 5730	LA-14, Bridge Replacement	Trans Permit Requirements for Bridges Bridge(s) Major Damage (Emergency Opening) Location(s)	
7 5731	Nickname Required Nickname Required	Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	
7 5732	LA 126 Reactive Safety 010	Safety Improvements Collision(s) reduced	
7 5733 7 5735	LA-5 Pavement Rehab in Burbank DO - UE	Roadway Rehabilitation (2R) Lane mile(s) Major Damage (Emergency Opening) Location(s)	3.7
7 5736	LA-10 Bridge Rail	Bridge Rail Replacement/Upgrade Linear feet rail	,
7 5736 7 5738	LA-10 Bridge Rail Buses and Infrastructure, 100 ZEBs, Project#2 (Tier II)	Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	
7 5738	Buses and Infrastructure, 100 ZEBs, Project#2 (Tier II)	Rail car(s) / transit vehicle(s) Each	100
7 5739	Alexandria Park LADWP FCO	Storm Water Mitigation Acre(s)	171.3
7 5740	LA-110 Upgrade Bridge Railing	Bridge Rail Replacement and Upgrade Annual fatal and serious	0.03
	1,0111110	injury collision(s)	3.00
7 5741	Strathern Park North LADWP FCO	Storm Water Mitigation Acre(s)	445
7 5743	Valley Plaza Park South LADWP FCO	treated/pollutant Storm Water Mitigation Acre(s)	138.4
	·	treated/pollutant	
7 5744 7 5746	LA-101/110 Four Level Interchange/Lighting Upgrades LA-10 ADA, PE:DA	Signs and Lighting Rehabilitation Lighting fixture(s)	30
7 5747	Nickname Required	ADA - New Curb Ramps Curb ramp(s) Major Damage (Emergency Opening) Location(s)	1
7 5749	Humphrey Maintenance Station L5816	Maintenance Facilities Location(s)	
7 5753 7 5780	DO - Wildfire LA-2 TMC Electrical	Major Damage (Emergency Opening) Location(s) TMC Facilities Location(s)	
7 5781	LA-2 TMC Mech	TMC Facilities Location(s)	
7 5786 7 5789	LA-710 Upgrade Pump Plant LA-57 OH Signs	Drainage System Restoration Pump plant(s) (ea) Signs and Lighting Rehabilitation Sign(s)	
7 5794	LA-014 Replace/Line Culverts	Drainage System Restoration Culvert(s) (ea)	18
7 5795	Arroyo Seco Pkwy Drainage	Drainage System Restoration Culvert(s) (ea)	16
7 5796 7 5799	LA-405 Drainage, PE:MN-KY VEN-1 Permanent Restoration/RSP	Drainage System Restoration Culvert(s) (ea)	52
7 5801	Ven-23 Drainage Near Bardsdale	Drainage System Restoration Culvert(s) (ea)	7
7 5802 7 5806	Replace Drainage for Segment 9 Valley Plaza Park North LADWP FCO	Drainage System Restoration Culvert(s) (ea)	523.2
7 3606	, and the second	treated/pollutant	323
7 5821	LA-101-PEH	Major Damage (Emergency Opening) Location(s)	58
7 5822 7 5826	Nickname Required DO - UE	Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	
7 5833	1XW004-LA 10 PM R8.94/R9.39	Major Damage (Permanent Restoration) Location(s)	8
7 5834 7 5836	07-1XW104-Ven 126, PM 20.30 Nickname Required	Major Damage (Permanent Restoration) Location(s) Major Damage (Emergency Opening) Location(s)	
7 5837	LA-405 PM 43.2 Unsheltered @ Raymer St OH	Major Damage (Emergency Restoration) Location(s)	
7 5838 7 5840	LA-105 Repair Damage Slope 1XW704-LA 1/103 PM 1.59/8.29	Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	
		Major Darriage (Erreigency Opening) [Location(s)	
7 5845	DO - UE	Major Damage (Emergency Restoration) Location(s)	
7 5845 7 5854	DO - UE LA-1 Lincoln/Fiji Safety	Safety Improvements Collision(s) reduced	55
7 5845	DO - UE	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious	8 58 0.18
7 5845 7 5854 7 5870	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious injury collision(s)	
7 5845 7 5854 7 5870 7 5872	DO - VE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s)	
7 5845 7 5854 7 5870 7 5872 7 5873 7 5875	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA 24-110 PM 6,6/7.45 - Washout	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s)	8 55 0.18
7 5845 7 5854 7 5870 7 5872 7 5873 7 5875 7 5883	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-110 PM 6.6/7.45 - Washout LA-103 PM 0.07, Repair Bridge Deck	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Openina) Location(s)	\$ 55 0.18
7 5845 7 5854 7 5870 7 5872 7 5873 7 5875	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA 24-110 PM 6,6/7.45 - Washout	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s)	8 58 0.18
7 5845 7 5854 7 5870 7 5872 7 5873 7 5875 7 5883 7 5885 7 5888 7 5888	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-110 PM 6.67.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56	Safety Improvements Collision(s) reduced Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Restoration) Location(s) Major Damage (Emergency Restoration) Location(s) Major Damage (Emergency Restoration) Location(s)	\$ 58 58 0.18
7 5845 7 5854 7 5870 7 5870 7 5872 7 5873 7 5875 7 5883 7 5885 7 5887 7 5888 7 5888	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA-210 - Washout LA-110 PM 6.6/7.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2X3304 - LA 10 - PM 18.33 ELA Hub 2XA504 , LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90	Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Location(s)	8 54 0.18
7 5845 7 5854 7 5870 7 5872 7 5873 7 5875 7 5883 7 5885 7 5888 7 5888	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-110 PM 6.67.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Location(s) Major Major Major (Acres)	8 54 0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5885 7, 5885 7, 5886 7, 5887 7, 5888 7, 5889 7, 5890 7, 5913	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM.6,77.45 - Washout LA-103 PM.0,07, Repoir Bridge Deck 2XA304 - LA 10 - PM.18.33 ELA Hub 2XA504, LA-91 PM.R1.35 Washout 07-2XA804-LA 710 PM.7.87/7.90 Front Street MS. Nickname Required	Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Safety Opening) Safety Opening S	0.18
7 5845 7 5854 7 5870 7 5872 7 5872 7 5873 7 5883 7 5883 7 5885 7 5887 7 5888 7 5888 7 5890 7 5913	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504 LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Location(s) Major Major Major (Acres)	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5875 7, 5883 7, 5885 7, 5880 7, 5890 7, 5914 7, 5916	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-110 PM 6.6/7.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504 LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Openinal Location(s) Major Damage (Emergency Openinal Location(s) Major Damage (Emergency Openinal Location(s) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Storm Water Mitigation Acre(s) Improved Major Damage (Storm Water Mitigation Acre(s) Improved Major Damage (Storm Water Mitigation Acre(s) Improved Major Ma	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5875 7, 5883 7, 5885 7, 5880 7, 5890 7, 5914 7, 5916	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-110 PM 6.6/7.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504 LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab	Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Major Damage	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5883 7, 5885 7, 5886 7, 5886 7, 5890 7, 5913 7, 5914 7, 5914	DO - UE LA-1 Lincoln/Fiii Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA-210 - Washout LA-110 PM 6.6/7.45 - Washout LA-110 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504 _ LA-91 PM R11.56 Washout 07-2XA804-LA-710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Storm Water Mitigation Acre(s) treated/pollutant Bridge Rehabilitation and Replacement Bridge(s) Bridge Rail Replacement and Upgrade Annual fatal and serious injury collision(s)	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5872 7, 5873 7, 5883 7, 5885 7, 5885 7, 5887 7, 5888 7, 5890 7, 5913 7, 5914 7, 5918 7, 5918	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-110 PM 6.6/7.45 - Washout LA-110 PM 0.07, Repair Bridge Deck 2X3304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Major Damage (Emergency Opening) Location(s) Storm Water Mitigation Acre(s) treated/pollutant Bridge Rehabilitation and Replacement Bridge(s) Bridge Rail Replacement and Upgrade Annual fatal and serious injury collision(s) Bridge Preventative Maintenance Capital Bridge Preventative Maintenance Program Bridge(s)	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5883 7, 5885 7, 5885 7, 5887 7, 5890 7, 5911 7, 5914 7, 5918 7, 5919 7, 5919 7, 5919 7, 5920 7, 5922	DO - UE LA-1 Lincoln/Fiii Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA-110 PM 6.6/7.45 - Washout LA-110 PM 6.07.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504 _ LA-91 PM R11.56 Washout 07-2XA804-LA-710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 14 & 126 Acc Br Deck - 2.5 & 110 Acc Br Deck - 2.10	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Maior Damage (Emergency Opening) Location(s) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) Maior Damage (Emergency	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5885 7, 5885 7, 5885 7, 5887 7, 5887 7, 5989 7, 5913 7, 5916 7, 5916 7, 5918	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 0.07, Repair Bridge Deck 2X3304 - LA 10 - PM 18.33 ELA Hub 2XA504 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polvester Acc Br Deck - 14 & 126 Acc Br Deck - 2.5 & 110 Acc Br Deck - 2.10 LA-002:005 Replace/Update Drainage Pumps	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Major Damage (Emergency Nestoration) Major Damage (Emergency Opening) Location(s) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergenc	0.18 56 0.23
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5883 7, 5885 7, 5885 7, 5887 7, 5890 7, 5911 7, 5914 7, 5918 7, 5919 7, 5919 7, 5919 7, 5920 7, 5922	DO - UE LA-1 Lincoln/Fiii Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA-110 PM 6.6/7.45 - Washout LA-110 PM 6.07.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504 _ LA-91 PM R11.56 Washout 07-2XA804-LA-710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 14 & 126 Acc Br Deck - 2.5 & 110 Acc Br Deck - 2.10	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Maior Damage (Emergency Opening) Location(s) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Opening) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Maior Damage (Emergency Opening) Maior Damage (Emergency	0.18
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5885 7, 5885 7, 5885 7, 5887 7, 5887 7, 5989 7, 5913 7, 5916 7, 5916 7, 5918	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 0.07, Repair Bridge Deck 2X3304 - LA 10 - PM 18.33 ELA Hub 2XA504 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polvester Acc Br Deck - 14 & 126 Acc Br Deck - 2.5 & 110 Acc Br Deck - 2.10 LA-002:005 Replace/Update Drainage Pumps	Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Major Damage (Eme	0.18 56 0.23
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5873 7, 5885 7, 5885 7, 5885 7, 5887 7, 5887 7, 5989 7, 5913 7, 5916 7, 5916 7, 5918	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 0.07, Repair Bridge Deck 2X3304 - LA 10 - PM 18.33 ELA Hub 2XA504 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polvester Acc Br Deck - 14 & 126 Acc Br Deck - 2.5 & 110 Acc Br Deck - 2.10 LA-002:005 Replace/Update Drainage Pumps	Safety Improvements Safety Improvements Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Opening) Location(s) Major Damage (Emergency Opening) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Opening) Ma	0.18 56 0.23
7, 5845 7, 5854 7, 5870 7, 5870 7, 5873 7, 5887 7, 5883 7, 5885 7, 5886 7, 5887 7, 5888 7, 5880 7, 5914 7, 5916 7, 5918 7, 5918 7, 5919 7, 5920 7, 5922 7, 5922 7, 5924 7, 5938 7, 5938 7, 5938	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 6,6/7.45 - Washout LA-103 PM 0,07, Repoir Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.55 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 14 & 126 Acc Br Deck - 2, 5 & 110 Acc Br Deck - 210 LA-002:005 Replace/Update Drainage Pumps 710 Florence Interchange Improvement (Long-term) LA-27 Maior Damage L-605 CAPM, Irwindale	Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Som Water Mitigation Acre(s) Som Water Mitigation Acre(s) Reded/Dollutant Bridge Rehabilitation and Replacement Bridge(s) Bridge Rail Replacement and Upgrade Annual fatal and serious injury collision(s) Bridge Preventative Maintenance Capital Bridge Preventative Maintenance Program Bridge(s) Bridge Preventative Maintenance Bridge(s) Bridge(s) Bridge Preventative Maintenance Bridge(s) Bridge(s) Bridge Preventative Maintenance Bridge(s)	0.18 56: 56: 0.29
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5887 7, 5883 7, 5885 7, 5887 7, 5888 7, 5890 7, 5913 7, 5914 7, 5916 7, 5918 7, 5920 7, 5921 7, 5922 7, 5924 7, 5939	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 0.07, Repair Bridge Deck 2X3304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 2, 5 & 110 Acc Br Deck - 2, 10 LA-022:005 Replace/Update Drainage Pumps 710 Florence Interchange Improvement (Long-term) LA-27 Major Damage	Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Openina) Major Openina Major Openin	0.18 56: 56: 0.29
7, 5845 7, 5854 7, 5870 7, 5870 7, 5873 7, 5887 7, 5883 7, 5885 7, 5886 7, 5887 7, 5888 7, 5880 7, 5914 7, 5916 7, 5918 7, 5918 7, 5919 7, 5920 7, 5922 7, 5922 7, 5924 7, 5938 7, 5938 7, 5938	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 6,6/7.45 - Washout LA-103 PM 0,07, Repoir Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.55 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 14 & 126 Acc Br Deck - 2, 5 & 110 Acc Br Deck - 210 LA-002:005 Replace/Update Drainage Pumps 710 Florence Interchange Improvement (Long-term) LA-27 Maior Damage L-605 CAPM, Irwindale	Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Damage (Perwentative Major Demage (Major Damage	0.18 56 0.29
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5887 7, 5883 7, 5885 7, 5885 7, 5887 7, 5887 7, 5918 7, 5914 7, 5916 7, 5918 7, 5918 7, 5918 7, 5918 7, 5918 7, 5922 7, 5922 7, 5924 7, 5939 7, 5939 7, 5946 7, 5946	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 6.6/7.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 2,5 & 110 Acc Br Deck - 210 LA-002-005 Replace/Ludate Drainage Pumps 710 Florence Interchange Improvement (Long-term) LA-27 Major Damage L-605 CAPM, Irwindale	Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Ma	0.18 56 0.23 3642 39 34
7, 5845 7, 5854 7, 5870 7, 5872 7, 5873 7, 5875 7, 5883 7, 5885 7, 5885 7, 5887 7, 5888 7, 5887 7, 5918 7, 5914 7, 5918 7, 5918 7, 5918 7, 5921 7, 5922 7, 5924 7, 5938 7, 5938 7, 5938 7, 5939 7, 5946 7, 5959 7, 5959	DO - UE LA-1 Lincoln/Fiii Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA-10 - Washout LA-110 PM 6.6/7.45 - Washout LA-103 PM 0.07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11,56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required S3 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polvester Acc Br Deck - 14 & 126 Acc Br Deck - 2, 5 & 110 Acc Br Deck - 210 LA-002:005 Replace/Update Drainage Pumps 710 Florence Interchange Improvement (Long-term) LA-27 Maior Damage L-605 CAPM, Irwindale L-605 CAPM, Irwindale LA-101 Western/Sunset/Fountain Bridge Rail/Fence	Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Damage (Perwentative Major Damage (Perwentative Major Damage (Perwentative Major Damage (Perwentative Major Damage (Permanent Restoration) Major Damage (Permanent	0.18 56 0.28 3 3 3 3 3 3 3 3
7	DO - UE LA-1 Lincoln/Fiji Safety LA-213 Traffic Signal, PE:LL DO - Rockslide LA 210 - Washout LA-103 PM 6,677.45 - Washout LA-103 PM 0,07, Repair Bridge Deck 2XA304 - LA 10 - PM 18.33 ELA Hub 2XA504, LA-91 PM R11.56 Washout 07-2XA804-LA 710 PM 7.87/7.90 Front Street MS Nickname Required 53 2419 LA River Deck Rehab Louise OC - Amestoy POC 91/710 Deck Polyester Acc Br Deck - 2.5 & 110 Acc Br Deck - 2.5 & 110 Acc Br Deck - 210 LA-002,005 Replace/Ludate Drainage Pumps 710 Florence Interchange Improvement (Long-term) LA-27 Maior Damage L-605 CAPM, Irwindale L-605 CAPM, Irwindale LA-101 Western/Sunset/Fountain Bridge Rail/Fence	Safety Improvements Annual fatal and serious injury collision(s) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Openina) Major Damage (Emergency Restoration) Major Damage (Emergency Openina) Major Ma	0.18 56: 56: 0.29 3364: 39.9 34.

7 5971	I-605 CAPM, OC to Telegraph	Storm Water Mitigation	Acre(s)	79
7 5972	CS near CSULB		treated/pollutant	
7 5972	C3 near C3ULB	SHOPP - Complete Streets	Bicycle and pedestrian infrastructure (linear feet)	314
7 5973	Storm Water Mitigation	Storm Water Mitigation	Acre(s)	90.
7 5975	VEN 150 December CADM	Development Drosen retire (CADA)	treated/pollutant	50.9
7 5976	VEN-150 Pavement CAPM LA-210 Drainage	Pavement Preservation (CAPM) Drainage System Restoration	Lane mile(s) Culvert(s) (ea)	20.5
7 5977	VEN-118 Arroyo Simi Safety Fence	Bridge Rehabilitation and Replacement	Bridge(s)	
7 5986 7 5991	VEN-33 Box Culvert LA-60 Safety 010 HFST	Drainage System Restoration Safety Improvements	Culvert(s) (ea) Annual fatal and serious	0.18
			injury collision(s)	
7 5993	LA-10 Bridge Rail	Bridge Rail Replacement and Upgrade	Annual fatal and serious injury collision(s)	0.23
7 5994	I-5 - Pavement Rehab in Castaic	Pavement Preservation (CAPM)	Lane mile(s)	112.5
7 5997 7 6000	DO - Wild Fire 2XC304-LA 23, PM 1.1/1.2	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
7 6001	Bridge Hit (Crib Wall)	Major Damage (Emergency Restoration)	Location(s)	
7 6003 7 6004	2XC604-LA 33, PM 12.9/19.0 2XC704 - Ven 126 PM 26.48 Hopper Creek	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6005	Landslide	Major Damage (Emergency Opening)	Location(s)	
7 6006 7 6007	Mudslide 2XE004 - LA 1 PM 40.07/40.55 Ratner Beach	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
7 6008	2XE104 - Ven 126 PM 9.77-24.61	Major Damage (Emergency Restoration)	Location(s)	7
7 6009 7 6011	Sinkhole 2XE404 - Ven 150 PM 0/20	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	15
7 6012	2XE504 - Ven 150 PM 20/32.2	Major Damage (Emergency Restoration)	Location(s)	15
7 6013	2XE604-LA PM 0 Ven 23 PM 3.3	Major Damage (Emergency Restoration)	Location(s)	10
7 6014 7 6018	2XE704 - Ven 23 PM 17.77/24.16 LA-110 Stormwater TMDL	Major Damage (Emergency Restoration) Storm Water Mitigation	Location(s) Acre(s)	29.6
			treated/pollutant	
7 6023 7 6024	Slauson Ave Deck Replacement Vincent Thomas Bridge Deck Replacement	Bridge Rehabilitation and Replacement Bridge Formula Program	Bridge(s) Bridge(s)	
7 6026	LA-010 Pavement 2R	Roadway Rehabilitation (2R)	Lane mile(s)	47.4
7 6027	LA-57 Stormwater TMDL	Storm Water Mitigation	Acre(s) treated/pollutant	76.3
7 6029	7-LA/VEN-Various PMs North - Changeable Message Signs(CMS) Replacement	Transportation Management Systems	Field element(s)	71
7 6030 7 6031	7-LA/VEN-Various PMs South - Changeable Message Signs(CMS) Replacement 7-LA/VEN-Various PMs East - Changeable Message Signs(CMS) Replacement	Transportation Management Systems	Field element(s) Field element(s)	84
7 6033	Z-L-V VEN-Valious Fins Edst - Characeable Message signisticms) Replacement SR-14 HOV Re-striping Project	Transportation Management Systems Collision Severity Reduction	Annual fatal and serious injury collision(s)	72 7.32
7 6034	Upgrade MBGR and End Treatments	Collision Severity Reduction	Collision(s) reduced	30
7 6034 7 6056	Upgrade MBGR and End Treatments 2XF004-LA 405, PM 16.56/19.74, Abutment	Roadside Safety Improvements Major Damage (Emergency Restoration)	Location(s) Location(s)	101
7 6060	Sinkhole	Major Damage (Emergency Restoration)	Location(s)	
7 6061 7 6062	2XF504 - Ven 33 PM 5.67/11.21 Clean-up 2XF604 - Ven 33 PM 23.75-27.50 Clean-up	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	12
7 6063	2XF704 - Ven 33 PM 27.50/57.2	Major Damage (Emergency Restoration)	Location(s)	35
7 6064	Landslide	Major Damage (Emergency Restoration)	Location(s) Location(s)	9
7 6066 7 6069	Washout 2XG304-LA 27, PM 0.18/10.62 Washout	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	10
7 6071	Landslide	Major Damage (Emergency Restoration)	Location(s)	
7 6072 7 6073	2XG604-LA 405, PM 36.35 Skirball 2XG704-Ven 118, PM 4.5/4.75 Washout	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6074	2XG804-LA 1, PM 35.23/44.12	Major Damage (Emergency Restoration)	Location(s)	12
7 6075 7 6077	2XG904-LA 1, PM 44.16/58.50 VEN-126 Pavement 2R	Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Lane mile(s)	54.2
7 6081	I-5 CAPM N/O DTLA	Pavement Preservation (CAPM)	Lane mile(s)	80.1
7 6082 7 6084	Landslide Wire Theft	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	3
7 6085	Unsheltered Encampment	Major Damage (Emergency Restoration)	Location(s)	
7 6086	2XH404-LA 1, PM 4.3 & 10.1, Sinkhole	Major Damage (Emergency Restoration)	Location(s)	2
7 6089 7 6090	2XH704-LA 105, PM R2.28/R2.28 - Tunnel Repair 2XH804-LA 10 PM R2.25-R5.20, Washout	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6092	2XJ004-LA 5, PM 16.05/17.30, Wire Theft	Major Damage (Emergency Restoration)	Location(s)	
7 6093 7 6094	2XJ104-LA 110, PM 21.45/25.72, Wire Theft 2XJ204-LA 101/110, PM 1.03/1.80 & 23.52/23.92, Wire Theft	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6095	2XJ304-LA 405/10, PM 1.05/1.80 & 23.32/23.72, Wire Theft	Major Damage (Emergency Restoration)	Location(s)	2
7 6096	2XJ404-Ven 34, PM 8.91/8.91	Major Damage (Emergency Restoration)	Location(s)]
7 6097 7 6099	07-2XJ504-LA 105, PM 2.001R/2.003R 2XJ704-LA 110, PM 2.70/3.21	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	2
7 6100	OH Sign Hit	Major Damage (Emergency Restoration)	Location(s)	
7 6103 7 6106	Rock Scaling + Slope Drapery Protection System Hawthorne Mobility Hub	Protective Betterments SHOPP - Complete Streets	Location(s) Bicycle and pedestrian infrastructure (linear feet)	460
7 6107	LA-5 (PM 17.2), Hollenbeck Park Lake BMPs construction - FCO	Storm Water Mitigation	Acre(s) treated/pollutant	101
7 6108	LA-405 (PM 23.5), Edward Vincent Jr. Park UIF installation - FCO	Storm Water Mitigation	Acre(s) treated/pollutant	90
7 6109	07-LA-10, (PM R9.13), Syd Kronenthal Park BMPs implementation for TMDL	Storm Water Mitigation	Acre(s) treated/pollutant	181
7 6117 7 6126	Signs and Lighting Rehabilitation LA-110 Reactive HFST & Polyester Concrete Overlay	Signs and Lighting Rehabilitation Safety Improvements	Sign(s) Annual fatal and serious	0.07
7 6127	010 HFST- SB 5 from I-210 to Roxford	Safety Improvements	injury collision(s) Annual fatal and serious injury collision(s)	1.2
7 6131	07-LA-10, (PM 33.45), Allan J. Martin Park UIG installation - FCO	Storm Water Mitigation	Acre(s)	88
7 6132	07-LA-10, (PM 32.5), Bassett High School regional Multi-Benefit stormw	Storm Water Mitigation	treated/pollutant Acre(s)	155
1	2XK004-LA/Ven 23, PM 0.0/3.3R Drainage Failure	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	treated/pollutant Location(s) Location(s)	10
7 6134 7 6135				
7 6135 7 6136	2XK204-Ven 101, PM 30.00/30.17	Major Damage (Emergency Restoration)	Location(s)	
7 6135 7 6136 7 6138	2XK204-Ven 101, PM 30.00/30.17 2XK404 LA - 2 Taylor Yard Overhead (DO)	Major Damage (Emergency Restoration)	Location(s)	
7 6135 7 6136 7 6138 7 6139	2KK204-Ven 101, PM 30.00/30,17 2XK404 LA - 2 Taylor Yard Overhead (DO) 2XK504-LA 101, PM 1.40/1.45	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	10
7 6135 7 6136 7 6138 7 6139 7 6141 7 6144	2XK204-Ven 101, PM 30.00/30.17 2XK404 LA - 2 Taylor Yard Overhead (DO) 2XK504-LA 101, PM 1.40/1.45 07-2XK704-LA 10, PM 15.6/17.6 2XL004-LA 10, PM 17/17.6	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s) Location(s) Location(s)	10
7 6135 7 6136 7 6138 7 6139 7 6141	2XK204-Ven 101, PM 30.00/30.17 2XK404 LA - 2 Taylor Yard Overhead (DO) 2XK504-LA 101, PM 1.40/1.45 07-2XK704-LA 10, PM 15.6/17.6	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s) Location(s)	10

7 6153 7 6195	2XL904-LA 103/1, PM 1.59/8.27 LA-138 Pavement CAPM	Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Location(s) Lane mile(s)	13.
7 6196	VEN-118 Stormwater TMDL	Storm Water Mitigation	Acre(s)	105.9
7 6217	VEN 1/34 Stormwater TMDL	Storm Water Mitigation	treated/pollutant Acre(s)	22.7
/ 621/	VEN 1/34 STORMWOTER TMDL	Storm water Miligation	treated/pollutant	22.
7 6249	0724000189, 2XM004, LA-210, Storm Damage (DO)	Major Damage (Emergency Restoration)	Location(s)	
7 6250 7 6251	2XM104,LA - 57, Human-made (DO) 2XM204-Ven 1, PM 1.4/7.3	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
7 6252	2XM304, LA - Var, Human Made (DO)	Maintenance Facilities	Location(s)	
7 6253	2XM404, LA - Var, Human Made (DO)	Maintenance Facilities	Location(s)	4
7 6254	07-2XM504-Ven Var, PM Var 07-2XM604-Ven 101, PM R40.0/T40.4	Maintenance Facilities Major Damage (Emergency Restoration)	Location(s)	
7 6255 7 6257	2XM804-LA 405, PM 36.3/37.1	Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6258	2XM904-LA 1, PM 50.44/50.77	Major Damage (Emergency Restoration)	Location(s)	
7 6259	2XN104-Ven 150, PM 20/32.2 2XN204-Ven 101, PM 32.4R/32.8R	Major Damage (Emergency Restoration)	Location(s)	12
7 6260 7 6261	2XN2U4-Ven 1U1, PM 32.4k/32.8k 2XN3U4-LA 10, PM S0.37/S0.55	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	
7 6264	2XN604-Ven 150, PM 6.1/6.3	Major Damage (Emergency Restoration)	Location(s)	
7 6265	2XN704-Ven 118, PM 22.3/32.51	Major Damage (Emergency Restoration)	Location(s)	
7 6266 7 6267	07-2XN804-Ven 150, PM 1.0/5.0 2XN904-LA 27, PM 0/5	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6272	Nickname Required	Bridge Rail Replacement and Upgrade	Annual fatal and serious	(
			injury collision(s)	
7 6273	Nickname Required	Collision Severity Reduction	Annual fatal and serious	(
		,	injury collision(s)	
7 6285 7 6291	07-2XP204-Ven 126 - Debris Removal 2XP804-LA 10, PM R7.8/R9.3	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
7 6356	LA-5 Pavement Preservation	Pavement Preservation (CAPM)	Lane mile(s)	93.9
7 6360	Wheeler Gorge 3 Tunnels	Bridge Formula Program	Bridge(s)	
8 0022K 8 0023C	RIV 60 REPLACE EXISTING GUIDE SIGNS (PHASE 1) RIV 62 MILL & OVERLAY	Signs and Lighting Rehabilitation Pavement Rehabilitation	Lighting fixture(s) Lane mile(s)	190 85.3
8 0023C 8 0033E	SBd 60 - REPLACE PIPELINE, MONTE VISTA AND BENSON BRIDGES	Bridge Rehabilitation	Bridge(s)	
8 0033N	Riv 60 Rehab Pavement near Beaumont	Pavement Rehabilitation	Lane mile(s)	17.
8 0043L	RIV 60 TRAFFIC OPERATIONS SYSTEM	Transportation Management Systems	Field element(s)	19
8 0045G 8 0046J	RIV 60 WB Shoulder Widening SR60 Truck Climbing/ Descending Lanes	Safety Improvements Pavement Preservation (CAPM)	Collision(s) reduced Lane mile(s)	382
8 0046J	SR60 Truck Climbing/ Descending Lanes	Truck climbing lane mile(s) constructed	Miles	4.5
8 0049T	RIV 10 UPGRADE CACTUS CITY SRRA	Safety Roadside Rest Area Restoration	Location(s)	
8 0050P 8 0066Q	Riv 74 Widen Lanes, Add Shoulders & Rumble Strips RIV-79 NEAR TEMECULA MILL & OVERLAY	Safety Improvements Pavement Rehabilitation	Collision(s) reduced Lane mile(s)	298 32.5
8 0127J	SBD 2 UPGRADE BR RAILING @ SHEEP CREEK	Bridge Rail Replacement/Upgrade	Linear feet rail	228
8 0133N	SBd 10 Santa Ana River Br Seismic Retrofit	Bridge Rehabilitation	Bridge(s)	
8 0163C 8 0178P	SBD 10 Redlands Rehab SBD 60 REPLACE EXISTING GUIDE SIGNS (PHASE 1	Pavement Preservation Signs and Lighting Rehabilitation	Lane mile(s) Lighting fixture(s)	9.0
8 0181J	SBD 18 CULVERTS	Drainage System Restoration	Culvert(s) (ea)	3
8 0184C	SBD 18 RELINE OR REPLACE CULVERTS	Drainage System Restoration	Culvert(s) (ea)	3
8 0205C	SBd 38 Replace Culverts	Drainage System Restoration	Culvert(s) (ea)	43
8 0206L 8 0224N	SBD 40 UPGRADE SRRA SBD 60 Replace Lanes and Slabs - (G-13)	Safety Roadside Rest Area Restoration Pavement Preservation	Location(s) Lane mile(s)	94.6
8 0241C	SBD 142 Chino Hills CAPM	Pavement Rehabilitation	Lane mile(s)	14
8 0256C	SBD 330 CITY CREEK REPLACE BRIDGE RAIL	Bridge Rail Replacement/Upgrade	Linear feet	1230
8 3001P 8 3001R	SBD L5726 UPGRADE FACILITY SBD 40 REGRADE MEDIAN CROSS SLOPE (NEAR ARIZONA)	L&B Maintenance Facilities Safety Enhancements	Location(s) Collision(s) reduced	28
8 30018	SBD 40 REPLACE OR REHABILITATE COLORADO RIVER BR	Bridge Rehabilitation and Replacement	Bridge(s)	
8 3001U	SBd 10 PLACE SLOPE PAVING	Roadside Safety Improvements	Location(s)	30
8 3001W	TRASH TREATMENT IN SIGNIFICANT TRASH GENERATING AREA (STGA)	Storm Water Mitigation	Acre(s) treated/pollutant	107
8 3001Y	RIV 74 SOURCE CONTROL IN LAKE ELSINORE	Storm Water Mitigation	Acre(s)	12
			treated/pollutant	
8 3002A	RIV 215 SEDIMENT STABILIZATION, EROSION CONTROL	Storm Water Mitigation	Acre(s) treated/pollutant	36
8 3002C	RIV 74/79/371 UPGRADE TO STANDARD BRIDGE RAIL	Bridge Rail Replacement and Upgrade	Linear feet rail	300
8 3002E	SBD 15 REGRADE CENTER MEDIAN	Collision Severity Reduction	Collision(s) reduced	20
8 3002F 8 3002G	RIV 10 REHAB SUBSTRUCTURE RIV 10 METHACRYLATE DECKS (VARIOUS ROUTES)	Bridge Rehabilitation	Bridge(s)	
8 3002G	RIV 10 METHACKITATE DECKS (VARIOUS ROUTES)	Capital Bridge Preventative Maintenance Progr	am Bridge(s)	
8 3002H	SBD 330 CONSTRUCT ROCKFALL BARRIER	Roadway Protective Betterments	Bridge(s)	,
8 3002J	RIV 74 SLOPE STABILIZATION	Roadway Protective Betterments	Bridge(s)	
8 3002L 8 3002Q	RIV 10 PALEN DITCH BRIDGE RAIL UPGRADE RIV 10 ADVANCE MITIGATION	Bridge Rail Replacement/Upgrade Roadside Protection and Restoration	Linear feet Location(s)	520 13
8 3002R	Riv 79 HEMET UPGRADE ADA	ADA - New Curb Ramps	Curb ramp(s)	24
8 3002S	SBD 215 MT VERNON/WASHINGTON ST OC	Bridge Rehabilitation and Replacement	Bridge(s)	,
8 3002T	Riv 10/60/86 Install Changeable Message Signs	Transportation Management (TMC's & Field Eauioment)	Field element(s)	
8 3002U	RIV 095 CONSTRUCT CONCRETE/RSP & REPLACE CULVERTS	Major Damage (Permanent Restoration)	Location(s)	20
			Lane mile(s)	47.8
8 3002V	SBD 95 Roadway Rehabilitation	Pavement Rehabilitation		
8 3002W	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E	Collision Severity Reduction	Collision(s) reduced	4
	SBD 95 Roadway Rehabilitation	Collision Severity Reduction Roadside Safety Improvements		323 193
8 3002W 8 3003F 8 3003J 8 3003K	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s)	323 193 13
8 3002W 8 3003F 8 3003J 8 3003K 8 3003L	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s)	323 192 12 54.6
8 3002W 8 3003F 8 3003J 8 3003K	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s)	323 193 13
8 3002W 8 3003F 8 3003J 8 3003K 8 3003L 8 3003M 8 3003M	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Powement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements	Collision(s) reduced Lacation(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Dally vehicle hour(s) of delay (DVHD)	32: 19: 12: 54.6 84.1 1823.1
8 3002W 8 3003F 8 3003J 8 3003K 8 3003K 8 3003M 8 3003N 8 3003P	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps	Callision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s)	32: 19: 1: 54. 84.: 1823.:
8 3002W 8 3003F 8 3003J 8 3003K 8 3003K 8 3003M 8 3003N 8 3003P 8 3003T	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 40 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Povement Preservation Pavement Rehabilitation Povement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s)	32: 19: 12: 54: 84.: 1823.: 70:
8 3002W 8 3003F 8 3003J 8 3003K 8 3003N 8 3003N 8 3003P 8 3003U 8 3003U 8 3003U	SBD 95 ROOCHWAY RENDDIFICTION SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - FROM THE SAFETY SBD 40 NEEDLES REGRADE MEDIAN TEMECULE LOINE REPLOCEMENT RIV 015 SLOB REPLOCEMENT RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation	Callision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	32: 19: 1: 54. 84.: 1823.:
8 3002W 8 3003F 8 3003J 8 3003K 8 3003M 8 3003M 8 3003N 8 3003N 8 3003P 8 3003T 8 3003U	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 SIAD Replacement RIV 015 SIAD Replacement SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation Transportation Management (TMC's & Field	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DYHD) Curb ramp(s) Lane mile(s) Lane mile(s)	32: 19: 12: 54. 84.: 1823.: 70: 11.: 59.
8 3002W 8 3003F 8 3003J 8 3003L 8 3003M 8 3003N 8 3003N 8 3003T 8 3003V 8 3003V 8 3003V	SBD 95 ROOCHWAY RENODIFICATION SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation Transportation Management (TMC's & Field Equipment)	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Field element(s)	32: 19: 12: 54.4 84. 1823. 77: 11.3 59.
8 3002W 8 3003F 8 3003J 8 3003K 8 3003N 8 3003N 8 3003P 8 3003U 8 3003U 8 3003U	SBD 95 ROOCHWAY RENDDIFICTION SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - FROM THE SAFETY SBD 40 NEEDLES REGRADE MEDIAN TEMECULE LOINE REPLOCEMENT RIV 015 SLOB REPLOCEMENT RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation Transportation Management (TMC's & Field	Callision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	32: 19: 12: 54. 84.: 1823.: 70: 11.: 59.
8 3002W 8 3003F 8 3003J 8 3003K 8 3003K 8 3003N 8 3003P 8 3003P 8 3003V 8 3003V 8 3003V 8 3004C	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABLITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 95 Roadway Rehabilitation SBD 62 Roadway Rehabilitation SBD 62 Roadway Rehabilitation	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation Transportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation	Callision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s)	32: 19: 19: 54.4 84.1 1823 7/ 113.3 59.9 64.1
8 3002W 8 3003F 8 3003J 8 3003L 8 3003M 8 3003M 8 3003N 8 3003T 8 3003V 8 3003V 8 3003X 8 3003X 8 3003X 8 3003X 8 3004A 8 3004C	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN IEMECULA Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB SBD 15 REHABLILTATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 95 Roadway Rehabilitation SBD 26 Roadway Rehabilitation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation Iransportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Preservation (CAPM) Roadside Protection and Restoration	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Location(s)	32: 19: 1: 54.4 84 1823 7: 11.3 59. 64 31.9 41.1 58
8 3002W 8 3003F 8 3003J 8 3003W 8 3003W 8 3003W 8 3003W 8 3003Y 8 3003V 8 3003X 8 3003X 8 3003X 8 3004A 8 3004C 8 3004C 8 3005A	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABLITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 95 Roadway Rehabilitation SBD 62 Roadway Rehabilitation SBD 62 Roadway Rehabilitation	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation Transportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation	Callision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s)	32: 19: 1: 54. 84. 1823. 70: 11.5 59. 64. 31.: 41. 58.
8 3002W 8 3003F 8 3003J 8 3003L 8 3003M 8 3003M 8 3003M 8 3003T 8 3003T 8 3003V 8 3003V 8 3003X 8 3004A 8 3004C 8 3004C 8 3005G	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN TEMECUIA Lane Replacement RIV 015 SIAD Replacement RIV 015 SIAD Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 40 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABILITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 95 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 71, 210, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBd 15 MIN POSS MICE 510 Emulsion tank	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Payement Preservation Payement Rehabilitation Payement Rehabilitation Operational Improvements ADA - New Curb Ramps Payement Preservation Roadway Rehabilitation (Roadway Rehabilitation Roadway Rehabilitation Iransportation Management (TMC's & Field Equipment) Payement Rehabilitation Payement Rehabilitation Payement Rehabilitation Payement Rehabilitation Sama and Restoration Roadside Protection and Restoration Sians and Lighting Rehabilitation L&B Maintenance Facilities	Collision(s) reduced Lacation(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Collision(s) reduced Lane mile(s) Location(s) Lighting fixture(s) Lighting fixture(s) Location(s)	32: 19: 54.4 84.1 1823.: 70: 11.3 59. 64.: 41.: 58.: 144: 75:
8 3002W 8 3003F 8 3003J 8 3003W 8 3003W 8 3003W 8 3003Y 8 3003Y 8 3003Y 8 3003Y 8 3004C 8 3004C 8 3004C 8 3005C 8 3005G 8 3005G	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABLIITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 220 INSTALL RAMP METERING SYSTEMS SBD 25 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 12 TNEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 71, 210, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 MIN POSS MICE STO EMUNION ENTRY IN TORTING TO SIGNS TORTING TO STORTING TO SIGNS (PHASE 2) SBD 15 MIN POSS MICE STO EMUNION ENTRY IN TORTING TO SIGNS (PHASE 2) SBD 15 MIN POSS MICE STO EMUNION ENTRY IN TORTING TO SIGNS (PHASE 2)	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation Transportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Preservation (CAPM) Roadside Protection and Restoration Sians and Lightting Rehabilitation Sians and Lightting Rehabilitation L&B Maintenance Facilities Safety Improvements	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Lane	32: 19: 54.4 84.1 1823.: 70: 11.3 59. 64.: 41.: 58.: 144: 75:
8 3002W 8 3003F 8 3003J 8 3003L 8 3003M 8 3003M 8 3003P 8 3003T 8 3003Y 8 3003V 8 3004C 8 3004C 8 3004C 8 3005C 8 3005C 8 3005C	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN I HEMECULA LORNE REPLACEMENT RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB SBD 15 REHABULTATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 25 Roadway Rehabilitation SBD 27 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitgation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitgation SBD 71, 210, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 Mth Pass Mtice Sta Emulsion tank Traffic Signal on 62, twentynine palms	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation Iransportation Management (TMC's & Field Equipment) Pavement Rehabilitation Iransportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Savement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Sians and Lightling Rehabilitation Sians and Lightling Rehabilitation Sians and Lightling Rehabilitation Sians and Lightling Rehabilitation Safety Improvements Major Damage (Permanent Restoration)	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Location(s) Location(s) Lightina fixture(s) Location(s) Collision(s) reduced Location(s)	32: 19: 1: 54.4 84.1 1823 7(11.3 59. 64.: 31.9 41.5 58 758
8 3002W 8 3003F 8 3003J 8 3003W 8 3003W 8 3003W 8 3003Y 8 3003Y 8 3003Y 8 3003Y 8 3004C 8 3004C 8 3004C 8 3005C 8 3005G 8 3005G	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABLIITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 220 INSTALL RAMP METERING SYSTEMS SBD 25 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 12 TNEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 71, 210, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 MIN POSS MICE STO EMUNION ENTRY IN TORTING TO SIGNS TORTING TO STORTING TO SIGNS (PHASE 2) SBD 15 MIN POSS MICE STO EMUNION ENTRY IN TORTING TO SIGNS (PHASE 2) SBD 15 MIN POSS MICE STO EMUNION ENTRY IN TORTING TO SIGNS (PHASE 2)	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation Transportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Preservation (CAPM) Roadside Protection and Restoration Sians and Lightting Rehabilitation Sians and Lightting Rehabilitation L&B Maintenance Facilities Safety Improvements	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Lane	32: 19: 54.4 84.1 1823.: 70: 11.3 59. 64.: 41.: 58.: 144: 75:
8 3002W 8 3003F 8 3003J 8 3003M 8 3003M 8 3003M 8 3003M 8 3003T 8 3003Y 8 3003Y 8 3004A 8 3004C 8 3004C 8 3005G 8 3005G 8 3005G 8 3005G 8 3005D 8 3005D 8 3005D	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN I TEMECULA LORE REPLACEMENT RIV 015 SIAB REPLACEMENT RIV 015 SIAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB SBD 15 REHABLILTATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 25 ROADWAY Rehabilitation SBD 27 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 17. 210, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 REPARE REATHER DIKE RIV 10 REPLACE PARE REATHER DIKE RIV 215 INSTALL AN OUTER SEPARATION BARRIER SBD 062 CONSTRUCT CONCRETERS PAPRONS	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation Iransportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Basia (CAPM) Roadside Protection and Restoration Sians and Lighting Rehabilitation L&B Maintenance Facilities Safety Improvements Maior Damage (Permanent Restoration) Safety Improvements Maior Damage (Permanent Restoration) Bridge Rehabilitation and Replacement	Collision(s) reduced Lacation(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Daliy vehicle hour(s) of delay (DVHD) Curb ramp(s) Lane mile(s) Location(s) Lightina fixture(s) Lightina fixture(s) Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Sidae(s)	32: 19: 15: 54.4 84.4 1823. 7(11.3 59. 64.7 31.5 141.7 12: 11: 12: 11: 11: 11: 11: 11: 11: 11
8 3002W 8 3003F 8 3003J 8 3003M 8 3003M 8 3003M 8 3003P 8 3003T 8 3003V 8 3003V 8 3004C 8 3004C 8 3004C 8 3005C 8 3005C 8 3005C 8 3005C 8 3005C 8 3005C 8 3005C	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABILITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 220 INSTALL RAMP METERING SYSTEMS SBD 25 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 17. 120, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 REPAIR EARTHEN DIKE RIV 215 INSTALL AN OUTER SEPARATION BARRIER SBD 062 CONSTRUCT CONCRETE/RSP APRONS RIV 74 REPLACE E SRIDGES	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation Iransportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Laument Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Signs and Lighting Rehabilitation Signs and Lighting Rehabilitation Signs and Lighting Rehabilitation Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Bridae Rehabilitation and Replacement Maintenance Facilities	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DYHD) Curb ramp(s) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Bridae(s) Location(s) Bridae(s) Location(s)	32: 19: 15: 54.4 84.4 1823 7/ 11.3 59 64.2 41 58 144 756
8 3002W 8 3003F 8 3003J 8 3003M 8 3003M 8 3003M 8 3003M 8 3003T 8 3003Y 8 3003Y 8 3004A 8 3004C 8 3004C 8 3005G 8 3005G 8 3005G 8 3005G 8 3005D 8 3005D 8 3005D	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN I TEMECULA LORE REPLACEMENT RIV 015 SIAB REPLACEMENT RIV 015 SIAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHAB SBD 15 REHAB SBD 15 REHABLILTATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 25 ROADWAY Rehabilitation SBD 27 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 17. 210, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 MIT POSS MITCE STATEMENT SIGNS (PHASE 2) SBD 15 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 REPARE REATHER DIKE RIV 10 REPLACE PARE REATHER DIKE RIV 215 INSTALL AN OUTER SEPARATION BARRIER SBD 062 CONSTRUCT CONCRETERS PAPRONS	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Rehabilitation (2R) Pavement Rehabilitation (17) Transportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Lawment Preservation (CAPM) Roadside Protection and Restoration Sians and Lightting Rehabilitation L&B Maintenance Facilities Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Bridae Rehabilitation Bridae Rehabilitation	Collision(s) reduced Lacation(s) Collision(s) reduced Lane mile(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Bridae(s) Location(s) Doily Vehicle Hour(s) of	32: 19: 15: 54.4 84.4 1823 7/ 11.3 59 64.2 41 58 144 756
8 3002W 8 3003F 8 3003J 8 3003M 8 3003M 8 3003M 8 3003P 8 3003T 8 3003V 8 3003V 8 3004C 8 3004C 8 3004C 8 3005C 8 3005C 8 3005C 8 3005C 8 3005C 8 3005C 8 3005C	SBD 95 Roadway Rehabilitation SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN - MULTIPHASE A&E SBD 10 WORKER SAFETY SBD 40 NEEDLES REGRADE MEDIAN Temecula Lane Replacement RIV 015 Slab Replacement RIV 015 Slab Replacement RIV 015 CAPM & SLAB REPLACEMENT SBD 60 ADD WB AUX LANE, ADD EB DECEL LANE RIV 74 HEMET UPGRADE ADA SBD 15 REHAB SBD 15 REHABILITATE EXISTING MAINLINE AND RAMP PAVEMENT SBD 210 INSTALL RAMP METERING SYSTEMS SBD 220 INSTALL RAMP METERING SYSTEMS SBD 25 Roadway Rehabilitation SBD 42 Roadway Rehabilitation SBD 127 NEAR BAKER PAVEMENT REHAB RIV CO Advanced Mitigation SBD 17. 120, 215, 259, REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) RIV 10 REPLACE EXISTING GUIDE SIGNS (PHASE 2) SBD 15 REPAIR EARTHEN DIKE RIV 215 INSTALL AN OUTER SEPARATION BARRIER SBD 062 CONSTRUCT CONCRETE/RSP APRONS RIV 74 REPLACE E SRIDGES	Collision Severity Reduction Roadside Safety Improvements Safety Enhancements Pavement Preservation Pavement Rehabilitation Pavement Rehabilitation Operational Improvements ADA - New Curb Ramps Pavement Preservation Roadway Rehabilitation (2R) Pavement Preservation Roadway Rehabilitation Iransportation Management (TMC's & Field Equipment) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Laument Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation Signs and Lighting Rehabilitation Signs and Lighting Rehabilitation Signs and Lighting Rehabilitation Safety Improvements Major Damage (Permanent Restoration) Safety Improvements Major Damage (Permanent Restoration) Bridae Rehabilitation and Replacement Maintenance Facilities	Collision(s) reduced Location(s) Collision(s) reduced Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Daily vehicle hour(s) of delay (DYHD) Curb ramp(s) Lane mile(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Bridae(s) Location(s) Bridae(s) Location(s)	32: 19: 15: 54: 84: 1823: 7(11: 55: 64: 41: 58: 41: 184: 75:

SOCIAL DESTRUCTION FOR CASE STREET CONTROL OF STREET CONTROL	0 20075	EDD 10 CONSTRUCT BARS ASSOCIATION	Cotabalana	Callida a (1) and a card	00
Section Description Desc					29 108
A DOOR	8 3006H	SBD 95 SHOULDER RUMBLE STRIPS	Safety Improvements	Collision(s) reduced	67
ACCOUNTS ACCOUNTS Proceedings ACCOUNTS ACCOUN					1
					65
Description					1
SYMER SYMERITE CONTRIBUTION			In-Motion Scales		
BODD					1
8 8000 - 100	8 3006W	RIV/SBD REPAIR DETECTION SITES		Field element(s)	86
BODIEST SECRETARY PROFESS AND CONTROLS A	8 3006X	RIV 60 CONSTRUCT TRAFFIC SIGNAL		Collision(s) reduced	14
BOX. DESCRIPTION DESCRIP					4
SOUTH 150 SERVICION PROPERTY 150 SERVICION Property Represent Property P					253
SOURCE Comment Comme					490
SOURCE Source Comment Proposed Face Comment Face Comment C					37.8
8.00000 2011 PALA PROPERTY PROVIDED Inconferent PALA PROPERTY Provided Section Provided Pala Pala Pala Pala Pala Pala Pala Pal					11.6
SOURCE Company Control Contr	8 3007Q	RIV 15 IMP SAFETY FOR MTCE	Roadside Safety Improvements	Location(s)	32
5000000000000000000000000000000000000	8 3007\$	SBD 215/259 INSTALL TMS FIELD ELEMENTS		Field element(s)	32
SOURCE SOURCE ACCORDING PAYOR REAR PARTON	9 200711	DIV/111 BALAA CDIAICC ADA (DHACE 2)	Equipment)	Structure (c)	128
SECURITY					13.9
8. 3000 APP OF CONTROL APPORT SERIES SECURITY DESIGNATION OF CONTROL APPORT SERIES SECURITY DESIGNATION CONTROL APPORT SERVICE SERVICE SECURITY DESIGNATION CONTROL APPORT SERVICE SER					18
# SOUTH 10 1 1 1 1 1 1 1 1				Collision(s) reduced	41
8 SORD Ref 15 Sectiones 10 Social Section Social Control Section Secti					49.5
SOCIAL PLANS DEFINICION DE PROPERTIES AND PRODUCCIÓN DE PROPERTIES AND					27.1 47.5
SIZE STATE 11 FAILA SPRINCE CEPM Content CapPM Content CapPM Content CapPM Content CapPM	0 3000E	KIV 13 Sediment Stabilization, Erosion Control	Sionni water Miligation		47.3
8.3956 NO. 20 BRODE SCHOLD MITCALCH Proceeding of Section Proceeding Proceding Proceding Proceding Proceding Proceeding Proceding Proceding Proceeding Proceding Proceding Proceding Proceding Proceeding Proceding	8 3008G		Pavement Preservation (CAPM)		34.9
## STORY ADVIS DEPLACE DESIDES (EXC.) SOFT PROCESSORY PROCESSORY ADVIS DEPLACE DESIDES (EXC.) SOFT PROCESSORY ADVIS DEPLACE DESIDES (EXC.) SOFT PROCESSORY ADVIS DEPLACE DESIDES (EXC.) SOFT PROCESSORY ADVIS DEPLACED	8 3008K	SBD 40 BRIDGE SCOUR MITIGATION	Bridge Rehabilitation and Replacement	Bridge(s)	2
8 50008. JPM 10 REPLACE DESIDES (EDICAL SUPE PROTECTION). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPE PROTECTION). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES (EDICAL SUPERACE). Inches Republished. 8 0006. TWO SUPERACE DESIDES. Inches Republished. 9 0006. TWO SUPERACE DESIDES. INCHES TWO SUPERACE DESIDES. INCH					42.7
A 2006 Dev. DREPT ACE, DREPT RECOCK SHOPE PROJECTION Development between the third between the project of the project					16
8 3006 AV 10 ENERGINE PROPERTY SERVICE MARKET STATE AND					18
BIOMES NO 15 NO PROCESSOR ASSECTATION WATER Industry Processor In					15
8 30000. BP 10 PAYEMBRI REPLACEMENT. South Payer State Country Countr	8 3008S	RIV 15 NORCO/CORONA RECYCLED WATER	Highway Planting Restoration	Acre(s)	75 106
8 SSWW 85D 38 IMPLEMENT SCHWING CONTROLS (porting) Prices 2 SSWW 85D 38 IMPLEMENT SCHWING CONTROLS (porting) Prices 2 SSWR 85D 10 STRICT LANG ELECTRIC SCHWING			Roadside Safety Improvements		106
SOUTH STATE CONTRIVENCE PROJECT Section Proj					64
BODDER SPUIL DISPATE CHRIST PLANTMENT EFFARE ANAMENIES, SHOULDESS, RAWES CL-13 Southern Shedulination (28)	0 3008W	1999 90 IIVII LEMENT SEDIMENT CONTROLS (pidniing) pridse 2	Sionii Waler Miligalion		27
SUPPLE S	8 3008Y	RIV 10 DESERT CENTER PAVEMENT REHAB: MAINLINE, SHOULDERS, RAMPS G-13	Roadway Rehabilitation (2R)		114
A SUDPER SED 210 CAP CICOSER PROJECT Austract view miletils controlled Miles		SBD 10 INSTALL TMS ELEMENTS		Field element(s)	26
BISSOPE SIZE 2016 CAP CLOSURE PROJECT ITS element S					
9 STOPP SIRE 201 COAP CLOSURE PROJECT Mode of tow Incremited protection of the Committee of]
S. 2009F SSD 210 CAP CLOSURE PROJECT Modified/Reconstructed biodeles Earch					11
8 S009F S80 210 CAP CLOSURE PROJECT South Project Secretary Sound volumbals controlled Meter meth 2 S009F S80 210 CAP CLOSURE PROJECT SOUTH SECRETARY SOUND SECRETARY SOUND SECRETARY SOUND SECRETARY SOURCE SOUTH SECRETARY SOUND SECRETARY SECRETARY SOUND SECRETARY SOUND SECRETARY SOUND SECRETARY SOUND SECRETARY SECRETARY SECRETARY SOUND SECRETARY S					9
83.099H 380.936.MIL 0.20* AND OVERAY 0.20* SUBBEREIZED ASHINAT WITH DIGGUIS Provement Preservation In CAPM Icone miletal 6 8.2007 800.7 801.7	8 3009E	SBD 210 GAP CLOSURE PROJECT	Roadway Rehabilitation (2R)	Lane mile(s)	28.3
83.099H 380.936.MIL 0.20* AND OVERAY 0.20* SUBBEREIZED ASHINAT WITH DIGGUIS Provement Preservation In CAPM Icone miletal 6 8.2007 800.7 801.7					2.1
B STOPK Rs 10 Birthe Powement Rehots (markine, shoulder, comps Powement Preservation Long-miles) B STOPK SD 71 BISTALL CEVIL, CKS, VS & REBORD (FUTIC COMA) YS				Lane mile(s)	28.3
\$ 300PN 380 71 INSTALL CCTV. CMS. VDS & REBER OFFICE COMM 575 Transportation Management (IMC's & Reid Field element(s) \$ 300PN 380 71 INSTALL CCTV. CMS. VDS & REBER OFFICE COMM 575 Enablasment of Management (IMC's & Reid Field element(s) \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles 4 \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles 4 \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles 4 \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles 4 \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles 4 \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles 4 \$ 300PR 380 74 SEARCHARD CC. HCV/HOI Inter-relief contributed Miles Miles					60.7 88.2
Supple 10 Express Lones-Son Antonio Ave to Route 15 (Contract 11) HOV/910 lane-milest constructed Meles 4					37
8 20078 SS 20 S RAMONA OC SISSON STATES SCORE AND SOURCESS SIGHT Improvements for Bridges Significant Produced Significant States States Significant States States Significant States Significant States States Significant States St			Equipment)		
8 S1016 SBD 138 WIDN MEDDAM AND SHOULDERS 8 S1076 WIT A REFLACE CLUVER AND BESTORE AND ROADWAY. 8 S1016 SBD 138 WIDN MEDDAM AND SHOULDERS 8 S1076 MIN AND SHOULDERS 8 S1077 MIN AND SHOULDER WIDSHING 8 S1077 MIN AND SHOULDER WIDSHING 9 POWERING PRESENCE OF AND SHOULDER WIDSHING 9 S1077 MIN AND SHOULDERS 9 S1					41.4
SOIGH SID 158 WIDEN MEDIAN AND SHOULDERS Sofe AND ROADWAY. Moior Domose Permanent Restoration Location(s)					123
8 SIGN SIV 74 REFE LACE CULVERT AND PESTORE SLOPE AND ROADWAY. Major Damage (Permanent Restoration) Location(s)					55
8 S100H RV 0214 FEMET HORIZONTAL DRAINS Mojor Damoge (Permonent Restoration) Location S 8 J010L S8 J1 S18 LS SAFETY IMPROVEMENTS Safety Improvements Collision Saf					5
8 S010L SBD 15 INSTALL MEDIAN ARRIPER Softety Improvements Collision for reduced 8 S100W SBD 128 INSTALL TRAFFIC SIGNALS - TIGER Softety Improvements Collision for reduced Coll			Major Damage (Permanent Restoration)		1
8 SOIDQ RIV GWIDEN SHOULDERS Solder Improvements Collisions (reduced 8 SOIDX RIV 27 INSTALL MIDWEST GUARDEAU STEER AND STEER Sofety Improvements Collisions (reduced 1 8 SOIDX RIV 27 INSTALL MIDWEST GUARDEAU STEER AND STEER SOLD RIVER AND ST					44
8 SOIOW SID 138 INSTALL TRAFFIC SIGNALS - TICER - Collision Start Reduction Start Reduction Reduction Reduction Start Reduction Reduction Start Reduction Reduction Re		ISBD 15 INSTALL MEDIAN BARRIER			14
8 3010X RIV ZP INSTALL MIDWEST GUARDRAIL SYSTEM (MGS) Softey Encomens's Collision Severity Reduction Collision (Severity Reduction PROSPORT) ROBIT OF CONTROL OF CONT					10
8 5010Y HORIZONTAL CURVE WARNING SIGNS 5010F NIV 60 INSTALL NEW PARAPM METERING SYSTEMS Florisportation Management Systems 6 2011 C 81V 58D VAR INSTALL TEV CHARGING SYSTEMS Florisportation Management Systems 8 2011 C 81V 58D VAR INSTALL TEV CHARGING SYSTEMS 8 2011 C 81V 58D VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL TEV CHARGING SYSTEMS 8 2011 F SED VAR INSTALL THE CITY OF CHARGING 8 2012 F SED VAR INSTALL THE CITY OF CHARGING 8 2012 F SED VAR INSTALL THE CITY OF CHARGING 8 2012 F SED VAR INSTALL THE CITY OF CH					14.2
8 3011C RIVSBD VAR INSTALL ZEV CHARGING STATIONS 8 3011E SDD 247 PAVEMENT AND SHOULDER WIDENING Provement Preservation ICAPM Lane milest 4 8 3011C SDD 247 PAVEMENT AND SHOULDER WIDENING 8 3011H RIV 215 CAPM IN PERRIS 8 3011H RIV 215 CAPM Lane milest 8 3011H RIV 215 CAPM Lane milest 8 3011H RIV 215 CAPM LANE ELSINORE FACILITY RIV CAPM LANE ELSINORE FACILITY RIV CAPM LANE ELSINORE FACILITY Mointenance Facilities 8 3011L RIV CAPM LANE ELSINORE FACILITY Mointenance Facilities 8 3011D SRD 165 FACILITY Mointenance Facilities 8 3011C SDD 165 FACILITY MOINTENANCE FACIL					C
8 3011E RV 215 CAPM Lone milefs1 2 2 8 3011F SR 24 PAVEMENT AND SHOULDER WIDENING Provement Preservation (CAPM) Lone milefs1 4 8 3011G SR 83 RELINQUISHMENT TO THE CITY OF ONTARIO Relinquishments Centerine milefs1 3 3 8 3011 SR 83 RELINQUISHMENT TO THE CITY OF ONTARIO Relinquishments Centerine milefs1 3 3 8 3011 SR 80 18 CAPM MILL AND OVERLAY Provement Preservation (CAPM) Lone milefs1 2 2 8 3011M SRD 18 CAPM MILL AND OVERLAY Provement Preservation (CAPM) Lone milefs1 2 2 8 3011M SRD 18 CAPM MILL AND OVERLAY Provement Preservation (CAPM) Lone milefs1 2 2 8 3011M SRD 15 Voiley Wells SRRA SIGHEN FACILITY Monitorence Focilities Location(s) 1 8 3011M SRD 15 Voiley Wells SRRA SIGHEN FACILITY MONITOR MILL AND OVERLAY PAYEMENT PRESERVATION (CAPM) Lone milefs1 2 8 3011M SRD 15 Voiley Wells SRRA SIGHEN FACILITY PROVENTIAL PREVENTIVE MAINTENANCE (CAPM) Ridder Formula Preservation (CAPM) Lone milefs1 2 8 3011M SRD 15 VOILE PREVENTIVE MAINTENANCE (CAPM) Provement Preservation (CAPM) Lone milefs1 2 8 3011M SRD 15 VOILE PREVENTIVE MAINTENANCE (CAPM) Provement Preservation (CAPM) Lone milefs1 2 8 3011M SRD 15 SRD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT CASIS) SIGHEN ROADSIDE REST AREAS (DESERT CASI					34
8 3011 F SBD 247 PAVEMENT AND SHOULDER WIDENING Povement Preservation (CAPM) Lone milets 4 8 3011 F SB 28 REINQUISIMENT TO THE CITY OF ONTARIO Reliquisiments Centerline milets 3 8 3011 F SB 28 REINQUISIMENT TO THE CITY OF ONTARIO Reliquisiments Centerline milets 3 3 3 3 3 3 3 3 3					24.6
8 3011 Nr 215 CAPM IN PERRIS Povement Preservation (CAPM) Lane mile(s) 3 8 3011 Nr V71 LAKE EISINORE FACILITY Maintenance Facilities Location(s) 8 3011 Nr V71 LAKE EISINORE FACILITY Maintenance Facilities Location(s) Nr V71 LAKE EISINORE FACILITY Nr V71 LAKE EISINORE FACILIT					47.5
8 3011				Centerline mile(s)	7.1
8 3011L SID 15 VOIR EASE ELSINORE FACILITY 8 3011G SID 15 VOIR Wells STRA 8 3011G SID 15 VOIR SID 15					32.9
8 3011W SBD 15 Vallev Wells SRRA 8 3011Q BRIDGE SCOUR Bridge Scour Bridge(s) 8 3011R SBD 15 RRIDGE RAIL UPGRADE 8 3011R SBD 15 RRIDGE RAIL UPGRADE 8 3011R SBD 15 RRIDGE RAIL UPGRADE 8 3011W SBD 15 RRIDGE RAIL UPGRADE 8 3011W CAPITAL RECYENTIVE MAINTENANCE (CAPM) 1 CAPITAL RECYENT MAINTENANCE (CAPM) 1 CAPITAL RECYENTIVE MAINTENANCE (CAPM) 1 CAPITAL RECYENTIVE MAINTENANCE (CAPM) 1 CAPITAL RECYENTIVE MAINT					22.4
8 301 IQ SRIPGE SCOUR BROOKER STATE					1 2
Biddle Formula Program					4
8 SOILU CAPTIAL PREVENTIVE MAINTENANCE (CAPM) Provement Preservation (CAPM) Lone milets 2 8 SOILW RIV 10 PAVEMENT REHAB ROADWAY Rehabilitation (2R) Lone milets 2 8 SOILW RIV 10 PAVEMENT REHAB ROADWAY Rehabilitation (2R) Lone milets 2 8 SOILW RIV 10 PAVEMENT REHAB ROADWAY Rehabilitation (2R) Lone milets 2 8 SOILW RIV 10 PAVEMENT REHAB ROADWAY REHABILITATION (2R) Lone milets 2 8 SOILW RIV 10 PAVEMENT REHAB ROADWAY REHABILITATION (2R) Lone milets 2 8 SOILW RIV 10 PAVEMENT REHAB ROADWAY REHABILITATION (2R) Lone milets 3 2 REPARLS SLOPE/EMBANKMENT REHABILITATION (2R) Lone milets 3 2 REPARLS SLOPE/EMBANKMENT REHABILITATION (2R) Lone milets 3 2 REPARLS SLOPE/EMBANKMENT REHABILITATION (2R) LONE REMAPLS AND COTHER PARLS FOR AND A PARLS RESTAURED (2R) REMAPLS REMAPLS AND COTHER PARLS FOR AND A PARLS RESTAURED (2R) REMAPLS REMAPL	8 3011R	SBD 15 BRIDGE RAIL UPGRADE	Bridge Formula Program	Bridge(s)	1
8 3011V RIV 10 PAYMENT REHAB 8 3011X SRD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT OASIS) 8 3011X SRD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT OASIS) 8 3011X SRD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT OASIS) 8 3011Y RIV 15 CAPM Pavement Preservation (CAPM) Lane milets) 8 3012A REPAIR SLOPE/FLMBANKMENT Major Damage (Permanent Restoration) 8 3012C RIV 15 UPGRADE CURB RAMPS AND OTHER ADA RELATED ITEMS 8 3012C RIV 15 UPGRADE CURB RAMPS AND OTHER ADA RELATED ITEMS 8 3012E UPGRADE ADA CURB RAMPS ADA - New Curb Ramps Curb ramp(s) 8 3012H RIV 10 REPLACE EXISTING WIM SYSTEM Commercial Vehicle Enforcement Facilities & Weigh-Location(s) 8 3012E RIV 10 REPLACE EXISTING WIM SYSTEM Commercial Vehicle Enforcement Facilities & Weigh-Location(s) 8 3012R RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION 8 3012R RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION 8 3012R RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION 8 3012R SRD VAR Install Changeable Message Signs (CMS) 8 3012R SRD PARLAC CONS VAR ROUTES 7 Transportation Management Systems 8 3012R SRD REPLACE CAS VAR ROUTES 7 Transportation Management Systems 8 3012R RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION 8 3012R SRD REPLACE CAS VAR ROUTES 7 Transportation Management Systems 8 3012R RIV 10 REPLACE CONS VAR ROUTES 8 3012R SRD REPLACE CONS VAR ROUTES 8 3012R SRD REPLACE CONS VAR ROUTES 9 Transportation Management Systems 9 Field element(s) 9 SRD REPLACE CONS VAR ROUTES 9 Transportation Management Systems 9 Field element(s) 9 SRD REPLACE CONS VAR ROUTES 9 SRD REPLACE CO					26.6
8 3011W RIV 10 PAVEMENT REHAB 8 3011X SBD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT OASIS) 8 3011Y RIV 215 CAPM 10 PAVEMENT REHABNITY ROADSIDE REST AREAS (DESERT OASIS) 8 3011Y RIV 215 CAPM 11 STORM PROVEMENT PRESENTATION (CAPM) (CONTROLL) 8 3011Y RIV 215 CAPM 12 STORM PROVEMENT PRESENTATION (CAPM) (CONTROLL) 8 3011Y RIV 215 CAPM 13 STORM PROVEMENT REHABNITY (CAPM) (CAPM) (CAPM) (CAPM) (CAPM) (CAPM) 8 3011Y RIV 215 CAPM 14 STORM PROVEMENT REHABNITY (CAPM)					18 24.1
8 3011X SBD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT OASIS) 8 3011Y RIV 215 CAPM 1 RIV 215 CAPM 1 RIV 215 CAPM 1 RIV 215 CAPM 1 RIV 215 CAPM 2 REPAIR SLOPFE/EMBANKMENT 1 Midlor Damage (Permanent Restoration) 1 Location(s) 8 3012C UPGRADE CURB RAMPS AND OTHER ADA RELATED ITEMS 2 ADA - New Curb Ramps 3 Curb ramp(s) 8 3012E UPGRADE ADA CURB RAMPS 3 ADA - New Curb Ramps 4 ADA - New Curb Ramps 5 Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS 4 ADA - New Curb Ramps 5 Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS 4 ADA - New Curb Ramps 5 Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS 4 ADA - New Curb Ramps 5 Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS 5 Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS 6 Cammercial Vehicle Enforcement Facilities & Weigh-Location(s) 8 3012F UPGRADE ADA CURB RAMPS 6 Cammercial Vehicle Enforcement Facilities & Weigh-Location(s) 8 3012J RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION 8 3012K PAVEMENT REHABILITATION (CAPM) 8 3012K PAVEMENT REHABILITATION (CAPM) 9 Pavement Preservation (CAPM) 1 Lane mile(s) 8 3012Y SBD INSTALL CMS VAR ROUTES 7 Transportation Management Systems 7 Field element(s) 8 3012Q RIV VAR ROUTES AWAS 8 3012Q RIV VAR ROUTES AWAS 8 Transportation Management Systems 8 3012Q RIV VAR ROUTES Transportation Management Systems 8 5012B REPLACE CMS VAR ROUTES 9 SBD REPLACE COMS VAR ROUTES 9 Transportation Management Systems 9 Field element(s) 9 SB REPLACE COMS VAR ROUTES 9 ROUTE AWAS 9 Transportation Management Systems 9 Field element(s) 9 SB REPLACE COMS VAR ROUTES 9 ROUTE AWAS 9 SB REPLACE COMS VAR ROUTES 9 ROUTE AWAS 9 Transportation Management Systems 9 Field element(s) 9 SB REPLACE COMS VAR ROUTES 9 ROAD MAIN ROAD REPLACE COMS VAR ROUTES 9 SB REPLACE COMS VAR ROUTES 9 ROAD MAIN ROAD REPLACE COMS VAR ROUTES 9 ROAD ROAD REPLACE COMS VAR ROUTES 9 SB REPLACE COMS VAR					24.1
8 30112 RIV 215 CAPM Pavement Preservation (CAPM) Lane mile(s) 2 8 3012A REPAIR SLOPE/EMBANK/MENT Major Damage (Permanent Restoration) Location(s) 8 3012C RIV 15 UPGRADE CURB RAMPS AND OTHER ADA RELATED ITEMS ADA - New Curb Ramps Curb ramp(s) 8 3012E UPGRADE ADA CURB RAMPS 8 3012F UPGRADE ADA CURB RAMPS ADA - New Curb Ramps Curb ramp(s) 8 3012F RIV 10 REPLACE EXISTING WIM SYSTEM Commencial Vehicle Enforcement Facilities & Weigh-Location(s) 8 3012J RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION Bridge Scour B	8 3011X	SBD 40 UPGRADE SAFETY ROADSIDE REST AREAS (DESERT OASIS)	Safety Roadside Rest Area Restoration	Location(s)	2
8 3012C RIV 15 UPGRADE CURB RAMPS AND OTHER ADA RELATED ITEMS ADA - New Curb Ramps Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS ADA - New Curb Ramps Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS ADA - New Curb Ramps Curb ramp(s) 8 3012F UPGRADE ADA CURB RAMPS ADA - New Curb Ramps Curb ramp(s) 8 3012H RIV 10 REPLACE EXISTING WIM SYSTEM Commercial Vehicle Enforcement Facilities & Weigh-In-Motion Scales 8 3012L RIV 10 REPLACE EXISTING ROCK SLOPE PROTECTION Bridge Scour Bridg	8 3011Y	RIV 215 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	21.3
8 3012F UPGRADE ADA CURB RAMPS ADA - New Curb Ramps Curb ramp(s) ADA - New Curb Ramps ADA - New Curb Ramps Curb ramp(s) ADA - New Curb Ramps And ramps ADA - New Curb ramps ADA - New Curb ramps ADA - New Curb ramps And ramps ADA - New Curb ramps And ramps And ramps And ram					_1
B 3012F UPGRADE ADA CURB RAMPS ADA - New Curb Romps Curb ramp(s)					26
8 3012H RIV 10 REPLACE EXISTING WIM SYSTEM Robin Scales Robin					15
In-Motion Scales In-Motion In-Motion Scales In-Motion In-					1
8 3012K PAYEMENT REHABILITATION (CAPM) Pavement Preservation (CAPM) Lone mile(s) 6 8 3012M SBD VAR Install Chanacable Message Signs (CMS) Transportation Management Systems Field element(s) 8 3012P SBD INSTALL CMS VAR ROUTES Transportation Management Systems Field element(s) 8 3012P SBD REPLACE CMS VAR ROUTES Transportation Management Systems Field element(s) 8 3012Q RIV VAR ROUTES AVMS Transportation Management Systems Field element(s) 8 3012R SBD 215 REPLACE JOINT ARMORS DO Major Damage (Emergency Opening) Location(s) 8 3012T SBD 38 DO Major Damage (Emergency Opening) Location(s) 8 3012T RIV 74 (RANSTON FIRE DO PH 1 Major Damage (Emergency Opening) Location(s) 8 3012U RIV 10 DESERT CENTER MICE STA DO WELL DRILLING Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA, REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013C RIV 10 REPAIR STORM DAMAGE DO Major Damage (Emergency Opening) Location(s) 8 3013C RIV 10 REPAIR STORM DAMAGE DO Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA, REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA REPLACE DAMAGED ASPHAL			In-Motion Scales	``'	
8 3012M SBD VAR Install Chanaeoble Message Signs (CMS) Transportation Management Systems Field element(s) 8 3012P SBD REPLACE CMS VAR ROUTES Transportation Management Systems Field element(s) 8 3012P SBD REPLACE CMS VAR ROUTES Transportation Management Systems Field element(s) 8 3012P SBD SEPLACE CMS VAR ROUTES Transportation Management Systems Field element(s) 8 3012P SBD SEPLACE JOINT ARMORS DO Major Damage (Emergency Opening) Location(s) 8 3012S SBD 21S REPLACE JOINT ARMORS DO Major Damage (Emergency Opening) Location(s) 8 3012V SBD 21S REPLACE JOINT ARMORS DO Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 CRANSTON FIRE DO PH Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RO REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RO REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013Y RIV STANSTON FIRE DO PH 2 Major Damage (E					2
B 3012N SBD INSTALL CMS VAR ROUTES Transportation Management Systems Field element(s)					60.8
8 3012P SBD REPLACE CMS VAR ROUTES Transportation Management Systems Field element(s) 8 3012Q RIV VAR ROUTES AVMS Transportation Management Systems Field element(s) 8 3012R SBD 215 REPLACE CIONT ARMORS DO Major Damage (Emergency Opening) 8 3012T RIV 74 CRANSTON FIRE DO PH 1 8 3012U RIV 74 CRANSTON FIRE DO PH 1 8 3012U RIV 10 DESERT CENTER MICE STA DO WELL DRILLING Major Damage (Emergency Openina) Location(s) 8 3012V RIV 74 WARREN RO REPLACE CULVERT DO Major Damage (Emergency Openina) Location(s) 8 3012V RIV 74 WARREN RO REPLACE CULVERT DO Major Damage (Emergency Openina) Location(s) 8 3012V RIV 74 WARREN RO REPLACE CULVERT DO Major Damage (Emergency Openina) Location(s) 8 3012V RIV 74 WARREN RO REPLACE CULVERT DO Major Damage (Emergency Openina) Location(s) 8 3012Y RIV 74 WARREN RO REPLACE DAMAGED ASPHALT Major Damage (Emergency Openina) Location(s) 8 3013Y RIV 74 SERPAL REPLACE DAMAGED ASPHALT Major Damage (Emergency Openina) Location(s) 8 3013Y RIV 74 WARREN MASHED OUT AREA REPLACE DAMAGED ASPHALT Major Damage (Emergency Openina) Location(s) 8 3013Z RIV 10 REPAIR STORM DAMAGE DO Major Damage (Emergency Openina) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of 33 delay (DYHD) 8 3013K JOHN WILKIE SRRA REHAB					26
8 3012Q RIV VAR ROUTES AVMS FrankORS DO Major Damage (Emergency Opening) Location(s) 8 3012S SBD 215 REPLACE JOINT ARMORS DO Major Damage (Emergency Opening) Location(s) 8 3012T SBD 38 DO Mojor Damage (Emergency Opening) Location(s) 8 3012T RIV 74 CRANSTON FIRE DO PH 1 Mojor Damage (Emergency Opening) Location(s) 8 3012U RIV 10 DESERT CENTER MICE STA DO WELL DRILLING Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 243 LAKE FULMER BR DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 243 LAKE FULMER BR DO Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED QUT AREA, REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013E RIV 10 REPLAR STORM DAMAGE DO Mojor Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DYHD) 8 3013K JOHN WILKIE SRRA REHAB	8 3012P	SBD REPLACE CMS VAR ROUTES	Transportation Management Systems	Field element(s)	42
8 3012X SBD 38 DO Maior Damage (Emergency Opening) Location(s) 8 3012T RIV 74 CRANSTON FIRE DO PH 1 Maior Damage (Emergency Opening) Location(s) 8 3012V RIV 10 DESERT CENTER MICE STA DO WELL DRILLING Maior Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Maior Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Maior Damage (Emergency Opening) Location(s) 8 3012Y RIV 74 CRANSTON FIRE DO PH 2 Maior Damage (Emergency Opening) Location(s) 8 3012Y RIV 243 LAKE FULMER BR DO Maior Damage (Emergency Opening) Location(s) 8 3013Y RIV 243 LAKE FULMER BR DO Maior Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED QUT AREA, REPLACE DAMAGED ASPHALT Maior Damage (Emergency Opening) Location(s) 8 3013E RIV 10 REPAIR STORM DAMAGE DO Maior Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DYHD) 8 3013K JOHN WILKIE SRRA REHAB		RIV VAR ROUTES AVMS			20
8 3012T RIV 74 CRANSTON FIRE DO PH 1 Major Damage (Emergency Openina) Location(s) 8 3012V RIV 10 DESERT CENTER MICE STA DO WELL DRILLING Major Damage (Emergency Openina) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Openina) Location(s) 8 3012W RIV-74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Openina) Location(s) 8 3012Y RIV 243 LAKE FULMER BR DO Major Damage (Emergency Openina) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA, REPLACE DAMAGED ASPHALT Major Damage (Emergency Openina) Location(s) 8 3013E RIV 10 REPAIR STORM DAMAGE DO Major Damage (Emergency Openina) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DVHD) 8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restaration Location(s)					1
8 3012V RIV 10 DESERT CENTER MICE STA DO WELL DRILLING Maior Damage (Emergency Opening) Location(s) 8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Major Damage (Emergency Opening) Location(s) 8 3012W RIV-74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012W RIV-74 STAND FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3013C RIV 243 LAKE FULMER BR DO Major Damage (Emergency Opening) Location(s) 8 3013C RIV 249 LAKE FULMER BR DO Major Damage (Emergency Opening) Location(s) 8 3013C RIV 10 REPAIR STORM DAMAGE DO Major Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DVHD) 8 3013K JOHN WILKIE SRRA REHAB					7
8 3012V RIV 74 WARREN RD REPLACE CULVERT DO Maior Damage (Emergency Opening) Location(s) 8 3012V RIV 74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV 243 LAKE FULMER BR DO Major Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED QUT AREA, REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013E RIV 10 REPLAR STORM DAMAGE DO Major Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DYHD) 8 3013K JOHN WILKIE SRRA REHAB					1
8 3012W RIV-74 CRANSTON FIRE DO PH 2 Major Damage (Emergency Opening) Location(s) 8 3012Y RIV-24 LAKE FULMER BR DO Moior Damage (Emergency Opening) Location(s) 8 3013C SBD 62 REPAIR WASHED OUT AREA, REPLACE DAMAGED ASPHALT Major Damage (Emergency Opening) Location(s) 8 3013E RIV 10 REPAIR STORM DAMAGE DO Moior Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DVHD) 8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restaration Location(s)	8 3012V	RIV 74 WARREN RD REPLACE CULVERT DO	Major Damage (Emergency Opening)		i
8 3013C SBD 62 REPAIR WASHED OUT AREA, REPLACE DAMAGED ASPHALT Maior Damage (Emergency Opening) Location(s) 8 3013E RIV 10 REPAIR STORM DAMAGE DO Major Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DYHD) 8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restoration Location(s)	8 3012W	RIV-74 CRANSTON FIRE DO PH 2	Major Damage (Emergency Opening)	Location(s)	
8 3013E RIV 10 REPAIR STORM DAMAGE DO Maior Damage (Emergency Opening) Location(s) 8 3013F Temecula Auxiliary Lanes Operational Improvements Daily vehicle hour(s) of delay (DVHD) 8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restoration Location(s)			Major Damage (Emergency Opening)	Location(s)	1
8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restoration Location(s)					1
8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restoration Location(s)					23 3556
8 3013K JOHN WILKIE SRRA REHAB Safety Roadside Rest Area Restoration Location(s)	5,55161				5550
8 3013N RIV 243/74 ROAD WASHOUT REPAIR Major Damage (Emergency Opening) Location(s)				Location(s)	
	8 3013N	RIV 243/74 ROAD WASHOUT REPAIR	Major Damage (Emergency Opening)	Location(s)	11

8 3013P	DIV 111 VO DO AD WASHOUT DEDAID	Marian Daniera (Farancia de Caracia de)	1	0
8 3013Q	RIV 111/60 ROAD WASHOUT REPAIR SSBD 18 ROAD WASHOUT REPAIR	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	9
8 3013R	Nickname Required	Major Damage (Emergency Opening)	Location(s)	1
8 3013U 8 3013W	SBD 62/95 ROADWAY REHABILITATION RIV 215 S/B & N/B AUX LANE-TIGER	Pavement Rehabilitation Safety Improvements	Lane mile(s) Collision(s) reduced	89 221
8 3014A	RIV 74 ROCK SLOPE STABILIZATION	Major Damage (Emergency Opening)	Location(s)	4
8 3014F	SBD COUNTY CENSUS STATIONS UPGRADE	Transportation Management Systems	Field element(s)	40
8 3014G 8 3014N	SBD 38 PAVEMENT REHAB SBD 38 PAVEMENT REHAB (+IIJA CS, FIBER)	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	5.6 3.8
8 3014Q	RIV 10 DESERT HILLS WB CVEF UPGRADE	Commercial Vehicle Enforcement Facilities & Weigh		3.0
		In-Motion Scales		
8 3014U 8 3014V	RIV 10 INDIO MAINT FACILITY UPGRADE (+IIJA FC) COMBINED EA (1M400 AND 1L070)	Maintenance Facilities	Location(s) Culvert(s) (ea)	1
8 3015A	SBD 247 PAVEMENT REHAB (+IIJA CS)	Drainage System Restoration Pavement Preservation (CAPM)	Lane mile(s)	22 12.3
8 3015C	SBD 83 RELINQUISHMENT TO CITY OF CHINO	Relinquishments	Centerline mile(s)	6.3
8 3015E	SBD-18 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	27.8 23.1
8 3015G 8 3015H	RIV-91 CAPM SBD 18 LUCERNE VALLEY PAVEMENT REHAB	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	23.1
8 3015J	SBD 15 PAVEMENT REHAB	Pavement Preservation (CAPM)	Lane mile(s)	50.6
8 3015L	RIV 215 PAVEMENT REHAB	Pavement Preservation (CAPM)	Lane mile(s)	65.7
8 3015M 8 3015N	RIV 91 RIVERSIDE PAVEMENT REHAB RIV 79 BARRIER NEAR SAN JACINTO	Pavement Preservation (CAPM) Safety Improvements	Lane mile(s) Collision(s) reduced	19.6 15
8 3015T	SBD 95 PAVEMENT REHAB	Pavement Preservation (CAPM)	Lane mile(s)	14.1
8 3015U	RIV 15 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	95.9
8 3015V 8 3015X	SBD 178 REPAIR ROADWAY DAMAGE Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	5
8 3015Y	RIV 91 HIGHWAY PLANTING	Roadside Rehabilitation	Acre(s)	13
8 3016A	SBD 83 SAFETY ENHANCEMENTS	Safety Improvements	Collision(s) reduced	20
8 3016C 8 3016E	SR-259 Concrete Barrier SBD 10 & 71 PAVEMENT DELINEATION	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	1
8 3016F	SR-18 CAPM, CULVERT REPAIR, GUARDRAIL UPGRADE	Pavement Preservation (CAPM)	Lane mile(s)	17.8
8 3016G	RIV-10 PAVEMENT MARKINGS AND STRIPING	Safety Improvements	Collision(s) reduced	4
8 3016H	SBD 62 ROAD REPAIR	Major Damage (Emergency Opening)	Location(s)	
8 3016J 8 3016K	SBD-18 ROCK FENCE DO DO SBD-10 AT RTE 38 & SIXTH ST	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	2
8 3016L	SR-210U FRONTAGE RD LYTLE CREEK BRIDGE SEISMIC RETROFIT	Bridge Seismic Restoration	Bridge(s)	1
8 3016M	SBD-15 BRIDGE REPAIR	Bridge Preventative Maintenance	Bridge(s)	2
8 3016N 8 3016Q	SBD-15 - REPLACE RSP FOR 6 BRIDGES (+IIJA SAFETY) 15/395 Connector	Bridge Scour Major Damage (Emergency Opening)	Bridge(s) Location(s)	6
8 3016R	RIV 74 LAKE ELSINORE MEDIAN BUFFER & WIDEN SHLDRS	Safety Improvements	Collision(s) reduced	21
8 3016T	Restriping	Safety Improvements	Collision(s) reduced	119
8 3016U 8 3016Y	PSPS DO Nickname Required	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	96
8 3017A	RTE 40/95 SEP DO	Major Damage (Emergency Opening)	Location(s)	i
8 3017F	Nickname Required	Major Damage (Emergency Opening)	Location(s)	
8 3017G 8 3017J	MOJAVE RIVER BRIDGE DECK OVERLAY CULVERT REPAIR/REPLACEMENT (+IIJA SM)	Bridge Rehabilitation and Replacement Drainage System Restoration	Bridge(s) Culvert(s) (ea)	1
8 3017K	SBd Rte 40 RSP Replacement	Bridge Formula Program	Bridge(s)	
8 3017L	RTE 15 UPGRADE MGS VAR LOCATIONS (+IIJA SM & FIBER)	Collision Severity Reduction	Annual fatal and serious	0.26
8 3017R	SBD-395 MEDIAN BUFFER	Safety Improvements	injury collision(s) Annual fatal and serious	0.18
			injury collision(s)	
8 3017S	ROUTE 38 FIRE DAMAGE	Major Damage (Emergency Opening)	Location(s)	1
0 20171	DOUTE 30 WATERCHED ANTICATION			
8 3017T 8 3017U	ROUTE 38 WATERSHED MITIGATION RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS	Major Damage (Emergency Restoration) Safety Improvements	Location(s) Collision(s) reduced	1 4
8 3017U 8 3017X	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION	Safety Improvements Roadside Rehabilitation	Collision(s) reduced Acre(s)	1 4 36.9
8 3017U 8 3017X 8 3017Y	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s)	29.9
8 3017U 8 3017X	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION	Safety Improvements Roadside Rehabilitation	Collision(s) reduced Acre(s)	1 4 36.9 29.9 39 24
8 3017U 8 3017X 8 3017Y 8 3018A	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea)	29.9 39
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018F	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s)	29.9 39 24
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018F	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s)	29.9 39 24 0.36
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018F 8 3018H 8 3018L 8 3018M	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-138 CULVERTS REPAIR PROJECT SB-42 CAPM SR-38 CULVERTS REPAIR PROJECT SR-64 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	29.9 39 24 0.36 1 27.9 41.2
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018F	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s)	29.9 39 24 0.36
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018F 8 3018H 8 3018M 8 3018N 8 3018N 8 3018N 8 3018Q	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM STORM DRAINAGE & ADA STORM WITH ORDER OF THE STATION UPGRADE SR-079 CAPM DRAINAGE & ADA STORM WITH ORDER OF THE STATION UPGRADE STORM WITH ORDER OF THE STATION UPGR	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Storm Water Mitigation Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) tane mile(s) treated/oollutant Lane mile(s)	29,9 39 24 0.36 1 27,9 41,2 93,7 162,5
8 3017U 8 3017X 8 3017X 8 3018A 8 3018E 8 3018F 8 3018H 8 3018M 8 3018M 8 3018N 8 3018Q	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-32 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM Water Mitigation 1-40 CAPM SR-18 CAPM SR-18 CAPM	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Storm Water Mitigation Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s)	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018H 8 3018H 8 3018M 8 3018M 8 3018M 8 3018M 8 3018M 8 3018M	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM Worlder Mitigation 1-40 CAPM. SBD-40 Bridge Scour	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s)	29.9 39 24 0.36 1 27.9 41.2 33.7 162.5 54.9
8 3017U 8 3017X 8 3017X 8 3018A 8 3018E 8 3018F 8 3018H 8 3018M 8 3018M 8 3018M 8 3018Q 8 3018R 8 3018B 8 3018B 8 3018B 8 3018B 8 3018B 8 3018B 8 3018B	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-82 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA Storm Water Mitigation 1-40 CAPM SSR-18 CAPM SSR-18 CAPM SSR-40 Bridge Scour SR-18 CAPM COMBINED EA (1M520 & 1C073)	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Storm Water Mitigation Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Itreated/pollutant Lane mile(s)	29,9 39 24 0.36 1 27,9 41,2 93,7 162,5
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018B 8 3018B 8 3018M 8 3018M 8 3018N 8 3018N 8 3018Q 8 3018V 8 3018U 8 3018U	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM STORM DRAINAGE & ADA STORM Wider Miligation 1-40 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (1M520 & 1C073) RIV 10 WRITE WATER SRRA (WATER/WASTEWATER)	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Pavement Preservation (CAPM) Storm Water Mitigation Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s)	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018E 8 3018H 8 3018H 8 3018N 8 3018N 8 3018N 8 3018N 8 3018N 8 3018X 8 3018X 8 3018X 8 3018X 8 3019A	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-35, 242 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STOCKAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (11M520 & 1C073) RIV 10 WHITE WAITER SRRA [WAITER/WASTEWATER) Truck fire on SBD 40	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Major Damage (Emergency Opening)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Freated/foollutant Lane mile(s) Location(s)	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3017X 8 3018A 8 3018E 8 3018B 8 3018B 8 3018M 8 3018M 8 3018M 8 3018M 8 3018W 8 3018W 8 3018Z 8 3	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-32 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STOOTM Woter Mitigation 1-40 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (INS20 & 1CO73) RIV 10 WITHE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKName Required RIV 10 WITHE WATER SRRA (WATER/WASTEWATER)	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridge Scour Pavement Preservation (CAPM) Bridge Scour Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Roadside Rest Area Restoration	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Lane mi	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3017X 8 3018A 8 3018E 8 3018H 8 3018H 8 3018N 8 3018N 8 3018N 8 3018N 8 3018N 8 3018X 8 3018Y 8 3018X 8 3019C 8 3019C	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-32 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA Storm Water Mitigation 1-40 CAPM SR-18 CAPM SBD-40 Bridge Scour SR-18 CAPM COMBINED EA (1M520 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 Nickname Required RIV 10 WILEYS WELLS SRRA (WATER/WASTEWATER) RIV 10 WILEYS WELLS SRRA (WATER/WASTEWATER)	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Maior Damaae (Emergency Openina) Maior Damaae (Emergency Openina) Safety Roadside Rest Area Restoration Maior Damaae (Emergency Openina) Safety Roadside Rest Area Restoration Safety Roadside Rest Area Restoration	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Rcre(s) freated/acollutant Lane mile(s) Lane mile(s) Line m	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3017X 8 3018A 8 3018E 8 3018B 8 3018B 8 3018M 8 3018N 8 3018N 8 3018N 8 3018V 8 3018V 8 3018V 8 3018Y 8 3019C 8 3019C 8 3019C 8 3019C	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM SIV 10 CAPM, DRAINAGE & ADA STORM Wider Miligation 1-40 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (1M520 & 1C073) RIV 10 WILLEY WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKHOME REQUIRED RIV 10 WILLEYS WELLS SRRA (WATER/WASTEWATER) RIV 10 JS, 74 PC OVERLAY	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Storm Water Mitigation Pavement Preservation (CAPM) Maidae Scour Pavement Preservation (CAPM) Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Maior Damace (Emeraency Openina) Maior Damace (Emeraency Openina) Safety Roadside Rest Area Restoration Bridae Preventative Maintenance	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Lane mi	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3018A 8 3018E 8 3018B 8 3018B 8 3018B 8 3018U 8 3018N 8 3018N 8 3018N 8 3018Q 8 3018V 8 3018V 8 3018V 8 3018V 8 3018V 8 3018V 8 3018V 8 3018V 8 3019C 8 3019C 8 3019C 8 3019K	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM WITH THE WATER STATION UPGRADE SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (11\u00e4520 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 USTERS WELLS SRRA (WATER/WASTEWATER) RIV 10 UTS WELLS SRRA (WATER/WASTEWATER) RIV 10 USTERS WELLS RAD (WATER/WASTEWATER) RIV 10 USTERS WELLS RAD (WATER/WASTEWATER) RIV 10 USTERS WELLS RAD (WATER/WASTEWATER)	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridge Scour Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Major Damage (Emergency Openina) Major Damage (Emergency Openina) Safety Roadside Rest Area Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ed) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Lane mi	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3018A 8 3018E 8 3018B 8 3018B 8 3018B 8 3018M 8 3018M 8 3018W 8 3019W 8 3	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-32 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L15 CAPM RIV 10 CAPM, DRAINAGE & ADA STOOTH Woter Mitigation 1-40 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (INS20 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 NITE'S WELLS SRRA (WATER/WASTEWATER) RIV 10 WHITE'S WELLS SRRA (WATER/WASTEWATER) RIV 10 NICKNAME POLYSTER CONCRETE OVERLAY NICKNAME REQUIRED HORIZONTAL CURVE WARNING SIGNS	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridge Scour Bridge Preventative Area Restoration Major Damage (Emergency Openina) Safety Roadside Rest Area Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Major Damage (Emergency Openina) Collision Severity Reduction	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fotal and serious injury collision(s) Location(s) Lane mile(s) Location(s) Locat	29.9 399 24 0.36 1 27.9 41.2 33.7 162.5 54.9 39.7 2 2 1.1 1 1 1 5 3 3 2 2 7 3 3 3 7 3 7 2 3 3 3 7 2 3 3 3 7 3 3 7 3 7
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018M 8 3018M 8 3018Q 8 3018Q 8 3018Q 8 3018Q 8 3018Q 8 3018V 8 3018Y 8 3019C 8 3019C 8 3019G 8 3019G 8 3019G	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-35 APM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA Storm Water Mitigation 1-40 CAPM. SR-18 CAPM SBD-40 Bridge Scour SR-18 CAPM COMBINED EA (1M520 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKName Required RIV 10 NILEY'S WELLS SRRA (WATER/WASTEWATER) RIV 10, 15, 74 PC OVERLAY SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKName Required HORIZONIAL CURVE WARNING SIGNS	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Storm Water Mitigation Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Maior Damage (Emergency Openina) Maior Damage (Emergency Openina) Safety Roadside Rest Area Restoration Bridae Preventative Maintenance Bridae Preventative Maintenance Maior Damage (Emergency Openina) Collision Severity Reduction	Collision(s) reduced Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Itreated/pollutant Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s) Collision(s) Collision(s) Location(s)	29.9 399 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2
8 3017U 8 3017X 8 3018A 8 3018E 8 3018B 8 3018B 8 3018B 8 3018M 8 3018M 8 3018W 8 3019W 8 3	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-32 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L15 CAPM RIV 10 CAPM, DRAINAGE & ADA STOOTH Woter Mitigation 1-40 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (INS20 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 NITE'S WELLS SRRA (WATER/WASTEWATER) RIV 10 WHITE'S WELLS SRRA (WATER/WASTEWATER) RIV 10 NICKNAME POLYSTER CONCRETE OVERLAY NICKNAME REQUIRED HORIZONTAL CURVE WARNING SIGNS	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridge Scour Bridge Preventative Area Restoration Major Damage (Emergency Openina) Safety Roadside Rest Area Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Major Damage (Emergency Openina) Collision Severity Reduction	Collision(s) reduced Acre(s) Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Acre(s) Ireated/collutant Lane mile(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Annual fatal and serious	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 2 2 1.1 1 1 5 3 3 2 7 7
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018C 8 3019C	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM WITH OF CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (IN520 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKNOME REQUIRED RIV 10 WHITE SWELLS SRRA (WATER/WASTEWATER) RIV 10 MILTSY WELLS SRRA (WATER/WASTEWATER) RIV 10 MILTSY WELLS SRRA (WATER/WASTEWATER) RIV 10 MICHAIL CURVE WARNING SIGNS SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKNOME REQUIRED HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC NICKNOME REQUIRED	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Rayement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Brayement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Bridae Scour Brayement Preservation (CAPM) Brayement Preservation (CAPM) Brayement Preservation (CAPM) Brayement Preservation (CAPM) Brayement Breservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Location(s)	29.9 399 24 0.36 1 27.9 41.2. 93.7 162.5 54.9 99.9 2 1 1 1 1 5 3 3 3 7 3 7 2 1 8 3 9 3 7 2 1 8 3 9 3 7 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018N 8 3018V 8 3018V 8 3019C	RIV 8. SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-35, 262 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-386 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM Witer Mitigation 1-40 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (1M520 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKName Required RIV 10, 15, 74 PC OVERLAY SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKNAME REQUIRED HORIZONTAL CURVE WARNING SIGNS HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC NICKNAME REQUIRED RIV-10 (1C083+1N060 COMBINE) SBD 138 CURVE REVISION E/O 1-15 (+IIJA CR) NICKNAME REQUIRED	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Major Damage (Emergency Openina) Safety Roadside Rest Area Restoration Bridae Preventative Maintenance Brid	Collision(s) reduced Acre(s) Acre(s) Lane mile(s) Culver(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Acre(s) freated/collutant Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Line mile(s) Annual fatal and serious injury collision(s) Line mile(s) Line mi	29.9 399 24 0.36 1 27.9 41.2. 93.7 162.5 54.9 99.9 2 1 1 1 1 5 3 3 3 7 3 7 2 1 8 3 9 3 7 2 1 8 3 9 3 7 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018C 8 3019C	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM WITH OF CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM SR-18 CAPM COMBINED EA (IN520 & 1C073) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKNOME REQUIRED RIV 10 WHITE SWELLS SRRA (WATER/WASTEWATER) RIV 10 MILTSY WELLS SRRA (WATER/WASTEWATER) RIV 10 MILTSY WELLS SRRA (WATER/WASTEWATER) RIV 10 MICHAIL CURVE WARNING SIGNS SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKNOME REQUIRED HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC NICKNOME REQUIRED	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Rayement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Brayement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Bridae Scour Brayement Preservation (CAPM) Brayement Preservation (CAPM) Brayement Preservation (CAPM) Brayement Preservation (CAPM) Brayement Breservation (CAPM)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Location(s)	29.9 399 244 0.36 1 27.9 41.2.7 33.7 162.5 54.9 39.7 2 2.1.8 99.9 2 1 1 1 1 5 5 3 3 3 3 3 3 3 3 3 3 3 3 3 3
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018C 8 3019C	RIV 8 SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM WITH OF CAPM, SR-18 CAPM OMBINED EA (INS20 & 1CO73) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 WILTYS WELLS SRRA (WATER/WASTEWATER) RIV 10 MILTYS WELLS SRRA (WATER/WASTEWATER) RIV 10 MILTYS WELLS SRRA (WATER/WASTEWATER) RIV 10, 15, 74 PC OVERLAY SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKNAME REQUIRED HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC NICKNAME REQUIRED	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Rater Pre	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Location(s)	29.9 39 24 0.36 1 22.9 41.2 33.7 162.5 54.9 39.7 2 11 1 1 5 3 2 2 7 3 0.08
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018C 8 3019C	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM Worder Miligation 1-40 CAPM SR-18 CAPM SBD-40 Bridge Scour SR-18 CAPM COMBINED EA (INSZ0 & 1 CO73) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKName Required RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) RIV 10 JS, 74 PC OVERLAY SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKName Required HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC RIV-10 (11C083+1N060 COMBINE) SBD 138 CURVE REVISION E/O I-15 (+IIJA CR) NICKName Required	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Cafety Roadside Rest Area Restoration Maior Damaae (Emeraency Openina) Maior Damaae (Emeraency Openina) Collision Severity Reduction Safety Improvements Roadway Rehabilitation (2R) Safety Improvements Maior Damaae (Emeraency Openina)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Iteated/collutant Lane mile(s) Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Collision(s) reduced Location(s) L	29.9 39 24 0.36 1 27.9 41.2 33.7 162.5 54.9 39.7 2 2 11.3 1 5 3 0.08 88.2 0.52
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018C 8 3019C	RIV 8 SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM WITH OF CAPM, SR-18 CAPM OMBINED EA (INS20 & 1CO73) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 WILTYS WELLS SRRA (WATER/WASTEWATER) RIV 10 MILTYS WELLS SRRA (WATER/WASTEWATER) RIV 10 MILTYS WELLS SRRA (WATER/WASTEWATER) RIV 10, 15, 74 PC OVERLAY SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKNAME REQUIRED HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC NICKNAME REQUIRED	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Rater Pre	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Location(s)	29.9 399 24 0.36 1 27.9 41.2 33.7 162.5 54.9 39.7 2 1.1 1 1 5 3 2 2 7 3 0.08 88.2 0.52
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018M 8 3019M 8 3020M	RIV 8. SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM SR-18 CAPM COMBINED EA (IM520 & 1CO73) RIV 10 WILLEY WATEN SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKHOME REQUIRED RIV 10 WILLEYS WELLS SRRA (WATER/WASTEWATER) RIV 10 WILLEYS WELLS SRRA (WATER/WASTEWATER) NICKHOME REQUIRED HORIZONTAL CURVE WARNING SIGNS NICKHOME REQUIRED NICKHOME REQUIRED SBD 138 CURVE REVISION E/O I-15 (HIJA CR) NICKHOME REQUIRED NICKHOME	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Maior Damace (Emergency Openina) Maior Damace (Emergency Openina) Safety Roadside Rest Area Restoration Bridae Preventative Maintenance Maior Damace (Emergency Openina) Collision Severity Reduction Collision Severity Reduction Safety Improvements Roadway Rehabilitation (2R) Safety Improvements Maior Damace (Emergency Openina) Major Damace (Emergency Openina) Major Damace (Emergency Openina) Major Damace (Emergency Openina) Safety Improvements Operational Improvements	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s) Location(29.9 399 24 0.36 1 27.9 41.2 33.7 162.5 54.9 39.7 2 1.1 1 1 5 3 2 2 7 3 0.08 88.2 0.52
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018W 8 3018W 8 3018W 8 3018W 8 3018V 8 3018V 8 3018V 8 3018V 8 3019C 8 3019C 8 3019C 8 3019C 8 3019C 8 3019W 8 3019V	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM Worder Miligation 1-40 CAPM SR-18 CAPM SBD-40 Bridge Scour SR-18 CAPM COMBINED EA (INSZ0 & 1 CO73) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKNAME REQUIRED RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) RIV 10 JS, 74 PC OVERLAY SBD-15, 40 POLYESTER CONCRETE OVERLAY NICKNAME REQUIRED HORIZONTAL CURVE WARNING SIGNS HORIZONTAL CURVE WARNING SIGNS SBD 210 WIDEN E/B OFF RAMP @ WATERMAN AVE OC RIV-10 (11C083+1N060 COMBINE) SBD 138 CURVE REVISION E/O I-15 (+IIJA CR) NICKNAME REQUIRED SBD 040 COLD PLANE AND OVERLAY SBD-164 SEQUIRED SBD 040 COLD PLANE AND OVERLAY	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Cafety Roadside Rest Area Restoration Maior Damaae (Emeraency Openina) Safety Roadside Rest Area Restoration Bridae Preventative Maintenance Maior Damaae (Emeraency Openina) Collision Severity Reduction Safety Improvements Maior Damaae (Emeraency Openina) Major Damaae (Emeraency Openina) Safety Improvements	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Location(s) Loc	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2 21.8 99.9 2 1 1 1 5 3 3 3 3 4 4 4 4 4 4 4 4 4 4 4 4 4
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018C 8 3019C	RIV & SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-32 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM OF MITTING OF THE MARKET MARK	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Major Damage (Emergency Openina) Safety Roadside Rest Area Restoration Bridae Preventative Maintenance Bridae Bridae Bridae Bridae Bridae Bridae Bridae Bridae Bridae Brida	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ed) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Location(s) Annual fatal and serious injury collision(s) Daily vehicle hour(s) of delay (DVHD) Location(s) Annual fatal and serious injury collision(s)	29.9 39 24 0.36 1 27.9 41.2 33.7 162.5 54.9 39.7 2 2 1.8 97.9 2 2 1 1 1 1 5 3 3 2 2 7 3 0.08 88.2 0.52
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018M 8 3019M 8 3020M 8 3020M	RIV 8 SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM SR-18 CAPM COMBINED EA (IM520 & 1 CO73) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 WILET'S WELLS SRRA (WATER/WASTEWATER) RIV 10 WILET'S WELLS SRRA (WATER/WASTEWATER) HORIZONTAL CURVE WARNING SIGNS SBD 138 CURVE REVISION E/O I-15 (+IIJA CR) NICKname Required NICKname Required NICKname Required SBD 040 COLD PLANE AND OVERLAY SBD-14 SPC-18 SP	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridge Scour Pavement Preservation (CAPM) Pavement Preservation (CAPM) Raid Reservation (CAPM) Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Maior Damaae (Emergency Opening) Safety Roadside Rest Area Restoration Bridge Preventative Maintenance Maior Damaae (Emergency Opening) Collision Severity Reduction Safety Improvements Maior Damaae (Emergency Opening)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Lanual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lanual fatal and serious injury collision(s) Lane mile(s) Annual fatal and serious injury collision(s) Lacation(s) Lacat	29.9 39 24 0.36 1 27.9 41.2 33.7 162.5 54.9 39.7 2 2 1.8 97.9 2 2 1 1 1 1 5 3 3 2 2 7 3 0.08 88.2 0.52
8 3017U 8 3017X 8 3017X 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018C 8 3019C 8 302C 8 30	RIV 8 SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-13B CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT L-15 CAPM RIV 10 CAPM, DRAINAGE & ADA STORM HORE MITTER AND STATE STA	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridae Scour Pavement Preservation (CAPM) Rater	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Lane mile(s) Location(s)	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2 21.8 99.9 2 2 1 1 1 5 3 3 3 2 4 4 2 1 1 1 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3
8 3017U 8 3017X 8 3017Y 8 3018A 8 3018B 8 3018B 8 3018B 8 3018B 8 3018M 8 3019M 8 3020M 8 3020M	RIV 8 SBD REPLACE PAVEMENT MARKINGS AT VARIOUS LOCATIONS SBD 215, 210, 10 & RIV 10 ROADSIDE REHABILITATION SR-62 CAPM SR-138 CULVERTS REPAIR PROJECT SB-62 CAPM SR-86 AND 81ST AVE SIGNAL VICTORVILLE MAINTENANCE STATION UPGRADE SR-079 CAPM DRAINAGE AND BRIDGE RAIL PROJECT I-15 CAPM SR-18 CAPM COMBINED EA (IM520 & 1 CO73) RIV 10 WHITE WATER SRRA (WATER/WASTEWATER) Truck fire on SBD 40 NICKname Required RIV 10 WILET'S WELLS SRRA (WATER/WASTEWATER) RIV 10 WILET'S WELLS SRRA (WATER/WASTEWATER) HORIZONTAL CURVE WARNING SIGNS SBD 138 CURVE REVISION E/O I-15 (+IIJA CR) NICKname Required NICKname Required NICKname Required SBD 040 COLD PLANE AND OVERLAY SBD-14 SPC-18 SP	Safety Improvements Roadside Rehabilitation Pavement Preservation (CAPM) Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Maintenance Facilities Pavement Preservation (CAPM) Bridge Scour Pavement Preservation (CAPM) Pavement Preservation (CAPM) Raid Reservation (CAPM) Pavement Preservation (CAPM) Safety Roadside Rest Area Restoration Maior Damaae (Emergency Opening) Safety Roadside Rest Area Restoration Bridge Preventative Maintenance Maior Damaae (Emergency Opening) Collision Severity Reduction Safety Improvements Maior Damaae (Emergency Opening)	Collision(s) reduced Acre(s) Lane mile(s) Culvert(s) (ea) Lane mile(s) Annual fatal and serious injury collision(s) Location(s) Lane mile(s) Lanual fatal and serious injury collision(s) Lane mile(s) Lane mile(s) Lane mile(s) Lanual fatal and serious injury collision(s) Lane mile(s) Annual fatal and serious injury collision(s) Lacation(s) Lacat	29.9 39 24 0.36 1 27.9 41.2 93.7 162.5 54.9 39.7 2 21.8 99.9 2 2 1 1 1 5 3 3 3 2 4 4 2 1 1 1 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3

8 3021C	Nickname Required	Major Damage (Emergency Restoration)	Location(s)	
8 3021F 8 3021J	Nickname Required RIV 371 INSTALL LEFT TURN LN (BIM4I)	Major Damage (Emergency Restoration) Safety Improvements	Location(s) Annual fatal and serious	0.0
			injury collision(s)	
8 3021K	I-15 MOJAVE WILDLIFE CROSSINGS	SHOPP - Sustainability and Miscellaneous	Location(s)	
8 3021L	I-15 CORONA DECELERATON LANE	Safety Improvements	Annual fatal and serious injury collision(s)	0.3
0.200114	ROUTE 62 COLLISION REDUCTION SAFETY PROJECT	Cofebularous console		0.7
8 3021M	ROUTE 62 COLLISION REDUCTION SAFETT PROJECT	Safety Improvements	Annual fatal and serious injury collision(s)	0.6
8 30215	Nickname Required	Major Damage (Emergency Restoration)	Location(s)	
8 3022L	2023 HURRICANE HILLARY TROPICAL STORM DAMAGE	Major Damage (Emergency Restoration)	Location(s)	
8 3022M 8 3022X	2023 HURRICANE HILLARY TROPICAL STORM DAMAGE HURRICANE HILARY STORM DAMAGE	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	2
8 3022Y	HURRICANE HILARY STORM DAMAGE	Major Damage (Emergency Restoration)	Location(s)	
8 3023A 8 3023C	2023 HURRICANE HILARY TROPICAL STORM DAMAGE 2023 HURRICANE HILARY TROPICAL STORM DAMAGE	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
8 3023E	Install Signals at SB-18 & Pawnee Rd	Safety Improvements	Annual fatal and serious	0.1
			injury collision(s)	
8 3023F 8 3023J	SUMMER STORM DAMAGE RIV 010 INSTALL HTCB AND MGS	Major Damage (Emergency Restoration)	Location(s)	0.7
6 30233	RIV UTUTINSTALL FILES AND MIGS	Safety Improvements	Annual fatal and serious injury collision(s)	0.7
8 3023K	RIV-10 INSTALL BARRIER TO COVER EMBANKMENT ON WB	Safety Improvements	Annual fatal and serious	0.1
0 3023K	RIV-10 INSTALL BARRIER TO COVER EMBAIRMENT ON WE	salely improvements	injury collision(s)	0.1
8 3023L	Nickname Required	Major Damage (Emergency Restoration)	Location(s)	
8 3023M	Riv 015 Auxiliary Lane NB15 at Magnolia	Safety Improvements	Annual fatal and serious	0.
			injury collision(s)	
8 3023N	RIV-74 CAPM + MMBN (CONST ONLY)	Pavement Preservation (CAPM)	Lane mile(s)	27.
8 3023R 8 3023S	DO IIJA FENCING AT MTCE STATIONS Nickname Required	Maintenance Facilities Major Damage (Emergency Restoration)	Location(s)	
8 3023U	Nickname Required	Major Damage (Emergency Restoration)	Location(s)	
8 3024E	I-10 EB BARRIER INSTALL	Safety Improvements	Annual fatal and serious injury collision(s)	0.
8 3024R	TRAFFIC CALMING FOR SBD COUNTY	Safety Improvements	Annual fatal and serious injury collision(s)	2.7
0 00000				
8 3032P 8 3032Q	DO IIJA FENCING AT MTCE STATIONS DO IIJA FENCING AT MTCE STATIONS	Maintenance Facilities Maintenance Facilities	Location(s) Location(s)	
9 0653	Shoshone Drainage	Drainage System Restoration	Culvert(s) (ea)	11
9 0657 9 0658	South Lone Pine CAPM Conway Guardrail	Pavement Rehabilitation Safety Enhancements	Lane mile(s) Collision(s) reduced	11.
9 0661	Mt Cartago Mitigation Bank	Roadside Enhancement (Mitigation Site	Location(s)	1
9 0662	North Sherwin Shoulders	Relinauishments1 Safety Enhancements	Collision(s) reduced	2
9 2460	SONORA JCT SHOULDERS	Collision Severity Reduction	Collision(s) reduced	1
9 2600 9 2616	Aspen Fales Shoulders Mono Chain Up Area	Safety Enhancements Roadside Safety Improvements	Collision(s) reduced Location(s)	5
9 2617	168 Safety Improvements	Safety Enhancements	Collision(s) reduced	1
9 2620 9 2621	Cummings Valley Rd Int Mono Mitigation Bank	Safety Enhancements Roadside Enhancement (Mitigation Site	Collision(s) reduced Location(s)	1
		Relinauishments)		
9 2624 9 2631	CONWAY RANCH SHOULDERS D9 End Treatments	Collision Severity Reduction Safety Enhancements	Collision(s) reduced Collision(s) reduced	
9 2633	Rosamond-Mojave Rehab	Pavement Preservation	Lane mile(s)	31.
9 2634 9 2639	TEHACHAPI MAINTENANCE STATION RELOCATION Virginia Creek Shoulders	Maintenance Facilities Safety Enhancements	Location(s) Collision(s) reduced	5
9 2641	MEADOW FARMS ADA	ADA - New Curb Ramps	Curb ramp(s)	Ĭ.
9 2643 9 2645	DISTRICT 9 ZEV LEE VINING REHAB	SHOPP - Misc ADA - New Curb Ramps	Location(s) Curb ramp(s)	2
9 2647	LONE PINE SIDEWALK	ADA - New Curb Ramps	Curb ramp(s)	1
9 2648 9 2649	BRIDGEPORT REHAB D9 LAB	Roadway Rehabilitation (3R) Materials Laboratories	Lane mile(s) Location(s)	9.
9 2653	BISHOP PAVEMENT	Roadway Rehabilitation (2R)	Lane mile(s)	13.
9 2654 9 2661	MOJAVE PAVEMENT ASPEN WALKER	Roadway Rehabilitation (3R) Safety Enhancements	Lane mile(s) Collision(s) reduced	7
9 2662	INDEPENDENCE EQUIP CANOPY	Maintenance Facilities	Location(s)	
9 2667 9 2668	FISH SPRINGS PAVEMENT KEENE PAVEMENT	Roadway Rehabilitation (3R) Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	37. 44.
9 2669	ROCK CREEK PAVEMENT	Roadway Rehabilitation (3R)	Lane mile(s)	11.
9 2670 9 2671	127 PAVEMENT MANZANAR PAVEMENT	Pavement Rehabilitation Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	4
9 2672	FREEMAN 3 CAPM	Pavement Rehabilitation	Lane mile(s)	15.
9 2679 9 2685	NORTH LONE PINE PAVEMENT RIDGECREST/INYOKERN PAVEMENT	Pavement Preservation (CAPM) Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	4. 23.
9 2688	MANOR MARKET COMPLETE STREETS	SHOPP - Complete Streets	Bicycle and pedestrian	365
			infrastructure (linear feet)	
0.0700	TOWNE DASS FLOOD	Mela Dana and Francisco	·	
9 2703 9 2705	TOWNE PASS FLOOD FREEMAN GULCH SAFETY IMPROVEMENTS	Major Damage (Emergency Opening) Collision Severity Reduction	Location(s) Annual fatal and serious	3
		,	injury collision(s)	
9 2709	TOPAZ SLIPOUT	Major Damage (Emergency Restoration)	Location(s)	
9 2710 9 2711	OLANCHA 4-LANE FLOOD DAMAGE ROSAMOND REHAB	Major Damage (Emergency Restoration) Roadway Rehabilitation (2R)	Lane mile(s)	18.
9 2712	203 PAVEMENT	Roadway Rehabilitation (2R)	Lane mile(s)	26.
9 2713 9 2717	MONO COUNTY PAVEMENT DAMAGE CACHE CREEK PAVEMENT	Major Damage (Emergency Restoration) Pavement Preservation (CAPM)	Lane mile(s)	30.
9 2719	KEOUGH CAPM	Pavement Preservation (CAPM)	Lane mile(s)	48.
9 2720 9 2733	BENTON PAVEMENT CENTENNIAL FLOOD DAMAGE DO	Pavement Preservation (CAPM) Major Damage (Emergency Restoration)	Lane mile(s) Location(s)	19.
9 2734	DEATH VALLEY FLOOD DAMAGE DO	Major Damage (Emergency Restoration)	Location(s)	
9 2735 9 3715	BISHOP PAVEMENT MITIGATION AND MONITORING SHOULDERS MITIGATION AND MONITORING	Roadway Rehabilitation (2R) Collision Severity Reduction	Lane mile(s) Annual fatal and serious	
. 15, .5		2235.135.131.1 103051011	injury collision(s)	
			1	
9 4205	178 INYOKERN PAVEMENT	Pavement Preservation (CAPM)	Lane mile(s)	3
9 4205 9 5063	178 INYOKERN PAVEMENT 158 JUNE LAKE SLOPE FAILURE DDO	Pavement Preservation (CAPM) Major Damage (Emergency Restoration)	Lane mile(s) Location(s)	
	178 INYOKERN PAVEMENT 158 JUNE LAKE SLOPE FAILURE DDO SECURITY MEASURES AT MAINTENANCE STATIONS. ROCK CREK LONG TERM MIT MON			3

10 0126	WEST LONG BARN CAPM	Pavement Rehabilitation	Lane mile(s)	
10 0128	Long Barn CAPM	Pavement Rehabilitation	Lane mile(s)	41.8
10 0165	CLEMENTS CAPM	Pavement Rehabilitation	Lane mile(s)	20 19.7
10 0167 10 0280	AMADOR SR 88 ROADWAY IMPROVEMENTS Alternative Delivery Method (CMGC) Ferguson Rock Shed	Pavement Preservation (CAPM) Major Damage (Permanent Restoration)	Location(s)	19./
10 0280B	Alternative Delivery Method (CMGC) Ferguson Slide Talus Removal	Major Damage (Permanent Restoration)	Location(s)	C
10 0321 10 0335	RIPON BRIDGE REHAB CAPM East of Buck Meadows	Bridge Rehabilitation Pavement Rehabilitation	Bridge(s) Lane mile(s)	41.1
10 0338	DWR BRIDGE SEISMIC RETROFIT	Bridge Seismic Restoration	Bridge(s)	6
10 1044 10 22370	SR4 Pavement Anchor Project	Pavement Preservation (CAPM)	Lane mile(s)	63.4 25
10 2680	East Sonora 108 CAPM PEDDLER HILL PAVEMENT ANCHOR	Pavement Preservation (CAPM) Drainage System Restoration	Lane mile(s) Culvert(s) (ea)	13
10 3009	WESTLEY REST AREA REHAB	Roadside Safety Improvements	Location(s)	1
10 3018 10 3067A	MER 140 GUARDRAIL UPGRADE Wagon Trail Construction Capital Funding	Safety Enhancements Roadway Rehabilitation (3R)	Collision(s) reduced Lane mile(s)	2.6
10 3074	MER 140 SAFETY DEVICES	Collision Severity Reduction	Collision(s) reduced	2.0
10 3088	SR99 STANISLAUS CAPM RAMPS	Pavement Rehabilitation	Lane mile(s)	20
10 3089 10 3102	SR99 MERCED REHAB D10 BRIDGE SUBSTRUCTURE REPAIRS	Roadway Rehabilitation (2R) Capital Bridge Preventative Maintenance Program	Lane mile(s) Bridge(s)	<u>19.6</u>
10 3102	DTO BRIDGE SOBSTRUCTURE RELAIRS	Capital Blage Heverhalive Maintenance Hogiani	blidge(s)	10
10 3110	SR4 MVP & ROADSIDE PAVING	Roadside Safety Improvements	Location(s)	38
10 3111 10 3112	SR205 MVP & ROADSIDE PAVING SJ I-5 MVP & ROADSIDE PAVING	Roadside Safety Improvements Roadside Safety Improvements	Location(s) Location(s)	41
10 3113	SJ BRIDGE MAINTENANCE	Bridge Preventative Maintenance	Bridge(s)	ī
10 3118 10 3119	SJ I-5 BRIDGE REHAB	Bridge Seismic Restoration	Bridge(s)	3
10 3119	TUOLUMNE DRAINAGE RESTORATION SR120 MVP & ROADSIDE PAVING	Drainage System Restoration Roadside Safety Improvements	Culvert(s) (ea) Location(s)	35 65
10 3122	MERCED SEISMIC RESTORATION	Bridge Seismic Restoration	Bridge(s)	7
10 3125 10 3126A	Modesto Soil Stockpile Encapsulation SR99/120 Interchange	Hazardous Waste Mitigation Operational Improvements	Location(s) Daily vehicle hour(s) of	2385
10/3126A		орегалона птрючениенз	delay (DVHD)	
10 3129	STA/SJ SIGNS REHAB	Signs and Lighting Rehabilitation	Lighting fixture(s)	23
10 3131 10 3133	MARIPOSA CROSSWALKS STOCKTON CHANNEL VIADUCT BRIDGE REHAB	Safety Enhancements Bridge Rehabilitation	Collision(s) reduced Bridge(s)	13
10 3133A	10-0X461 Stockton Channel Viaduct Bridge Replacement /Southbound	Bridge Rehabilitation and Replacement	Bridge(s)	1
10 3133B	10-0X462 Stockton Channel Viaduct Bridge Replacement /Northbound	Bridge Rehabilitation and Replacement	Bridge(s)	2
10 3134 10 3134A	MOUNTAIN COUNTIES BRIDGE RAILS Riparian Habitat Mitigation	Bridge Rail Replacement and Upgrade Bridge Rail Replacement/Upgrade	Linear feet rail Linear feet rail	893
10 3136	SR120 SLOPE MODIFICATION	Roadway Protective Betterments	Bridge(s)	1
10 3137 10 3138	SR108 TUOLUMNE WIRE MESH ALP/AMA/TUO CULVERT REHAB	Roadway Protective Betterments	Bridge(s)	49
10 3138A	Alpine 4 Biological Monitoring	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	49
10 3139	DRAINAGE RESTORATION	Drainage System Restoration	Culvert(s) (ea)	19
10 3140 10 3141	SJ CULVERTS SJ/ALP 88 DRAINAGE SYSTEM	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	10 39
10 3141	ALPINE CULVERT REHAB	Drainage System Restoration	Culvert(s) (ea)	38
10 3142A	Alpine 4 Biological Monitoring	Drainage System Restoration	Culvert(s) (ea)	C
10 3143 10 3144	STA 99 MVP/EXTENDED GORES/SLOPE PAVING WESTLEY REST AREA	Roadside Safety Improvements Safety Roadside Rest Area Restoration	Location(s) Location(s)	40
10 3145	VICTOR ONRAMP	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	158
		Improvements	Delay (DVHD)	
10 3146 10 3147	SR205 SMART CORRIDOR - PHASE 2 AMA/MER/SJ/MPA/SCL/SBT TMS ELEMENT UPGRADES	Transportation Management Systems Transportation Management (TMC's & Field	Field element(s) Field element(s)	21 26
		Equipment)	(0)	
10 3148	SJ 4/99 BRIDGE REHAB	Trans Permit Requirements for Bridges	Bridge(s)	1
10 3149 10 3151	MER-152,165 Upgrade ADA facilities SR140 Curb Ramps and Sidewalk Installation	ADA - New Curb Ramps ADA - New Curb Ramps	Curb ramp(s) Curb ramp(s)	40
10 3156	SJ 99 ADA Improvements	ADA - New Curb Ramps	Curb ramp(s)	40
10 3158 10 3165	Culvert Rehabilitation near Fish Camp in Mariposa County SJ SR 4 Pavement Resurfacing and Restoration	Drainage System Restoration Roadway Rehabilitation (2R)	Culvert(s) (ea) Lane mile(s)	19 4.7
10 3167	MPA Route 140 Pavement Preservation	Pavement Preservation (CAPM)	Lane mile(s)	54.8
10 3169	SJ Route 26 Increase Bridge Vertical Clearance	Trans Permit Requirements for Bridges	Bridge(s)	1
10 3177 10 3189	SJ Middle River Bridge Roadway Realignment STA SR 99 Maintenance Worker Safety Improvements	Safety Improvements Roadside Safety Improvements	Collision(s) reduced Location(s)	62 39
10 3190	Install Midwest Guardrail System	Safety Enhancements	Collision(s) reduced	3
10 3192	STA SR 99 Replace Bridge Deck AC Overlay	Capital Bridge Preventative Maintenance Program	Bridge(s)	6
10 3193	SJ SR 5 Bridge Deck Rehabilitation	Bridge Rehabilitation	Bridge(s)	2
10 3194	SR140 SLOPE REPAIR	Roadway Protective Betterments	Location(s)	1
10 3198	SJ SR 4 Reconstruction of Hinge 32	Capital Bridge Preventative Maintenance Program	Bridge(s)	1
10 3199	SR 88 Guardrail Upgrade	Safety Enhancements	Collision(s) reduced	5
10 3206	SJ Route 99 Bridge Girder Replacement	Capital Bridge Preventative Maintenance Program	Bridge(s)	1
10 3207	Liberty Safety Improvement	Safety Improvements	Collision(s) reduced	36
10 3209A	ERRECA AND LODI ZEV	SHOPP - Misc	Location(s)	3
10 3215 10 3219	MER John Erreca Roadside Rest Area Mokelumne River Bridge Upgrade	Safety Roadside Rest Area Restoration Bridge Rail Replacement and Upgrade	Location(s) Linear feet rail	810 810
10 3219	SR 4 and SR 26 in Calaveras, Amador, and Alpine Co.	Safety Improvements	Collision(s) reduced	24
10 3226	D 10 TMS REPAIR	Transportation Management (TMC's & Field	Field element(s)	20
1	D TO THIS REL AIR			
10 3227		Eauipment)	Field element(s)	<i>A</i> 1
10 3227	D 10 MVDS replacement and upgrade	Eauioment) Transportation Management (TMC's & Field Eauipment)	Field element(s)	41
10 3229	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE	Eauiomentl Transportation Management (TMC's & Field Eauioment) Drainage System Restoration	Pump plant(s) (ea)	5
	D 10 MVDS replacement and upgrade	Eauioment) Transportation Management (TMC's & Field Eauipment)		41 5 8.9
10 3229 10 3230 10 3231	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction	Equipment Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements	Pump plant(s) (ea) Mile(s) of cable Collision(s) reduced	5 8.9 264
10 3229 10 3230 10 3231 10 3233	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Moriposa SR 49 CAPM	Equipment Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation	Pump plant(s) (ea) Mile(s) of cable Collision(s) reduced Lane mile(s)	
10 3229 10 3230 10 3231 10 3233 10 3235 10 3235B	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Mathews Road UC DEUEL OVERHEAD UC	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rein Replacement/Upgrade	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridge(s) Linear feet rail	5 8.9 264 34.6
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Mathews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements	Equipment Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridge(s) Linear feet rail Location(s)	5 8,9 264 34.6 964
10 3229 10 3230 10 3231 10 3233 10 3235 10 3235 10 3237 10 3237	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Mathews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements	Equiomentl Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps	Pump plant(s) (ea) Mile(s) of cable Collision(s) reduced Lane mile(s) Bridge(s) Linear feet rail Location(s) Curb ramp(s)	5 8.9 264 34.6 964 26 29
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3245	D 10 MVDS replacement and upgrade S.J DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Mathews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left turn lane	Equipment Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements	Pump plant(s) (ea) Mile(s) of cable Collision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD)	5 8.9 264 34.6 964 26 29 41.4
10 3229 10 3230 10 3231 10 3233 10 3235 10 3235 10 3235 10 3237 10 3241 10 3245	D 10 MVDS replacement and upgrade S.J. DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Moriposa SR 49 CAPM Mothews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left turn lane Uparade bridae rails of two bridaes in CAL Co	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridge(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail	264 34.6 964 22 25 41.2
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3247 10 3250	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Matthews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left turn lane Ubarade bridae rails of two bridges in CAL Co SJ Changeable Message Signs	Equipment Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Upgrade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Upgrade Transportation Management Systems	Pump plant(s) (ea) Mile(s) of cable Collision(s) reduced Lane mile(s) Bridge(s) Linear (set rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s)	264 34.6 964 22 25 41.2
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3247 10 3250 10 3251 10 3251	D 10 MVDS replacement and upgrade S.J DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposo SR 49 CAPM Matthews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements SR 132 ADA Improvements Uparade bridae rails of two bridaes in CAL Co S.J Changeable Message Signs Replace Drainage Pumps SR140 MARIPOSA CAPM	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Iransportation Management Systems Drainage System Restoration Pavement Preservation (CAPM)	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s)	\$.5 8.5 264 34.6 964 22 25; 41.4 806 28 6
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3245 10 3250 10 3251 10 3250 10 3251	D 10 MVDS replacement and upgrade S.J DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Mathews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left turn lane Uparade bridae rails of two bridaes in CAL Co S.J Changeable Message Signs Replace Drainage Pumps SR 140 MARIPOSA CAPM S.J 12 ADA S.J 2 ADA	Eauiomentl Transportation Management (TMC's & Field Eauioment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Transportation Management Systems Drainage System Restoration Pavement Preservation (CAPM) ADA - New Curb Ramps	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridae(s) Linear (set rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s) Curb ramp(s)	\$.5 8.5 264 34.6 964 22 25; 41.4 806 28 6
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3245 10 3247 10 3250 10 3252 10 3252 10 3252	D 10 MVDS replacement and upgrade S.J DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposo SR 49 CAPM Matthews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements SR 132 ADA Improvements Uparade bridae rails of two bridaes in CAL Co S.J Changeable Message Signs Replace Drainage Pumps SR140 MARIPOSA CAPM	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Iransportation Management Systems Drainage System Restoration Pavement Preservation (CAPM)	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s)	\$5 8.5 264 34.6 964 22 25 41.6 806 26 4 2.3.6 10
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3245 10 3250 10 3251 10 3250 10 3251	D 10 MVDS replacement and upgrade S.J DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Moriposa SR 49 CAPM Mothews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left furn lane Uparade bridge rails of two bridges in CAL Co S.J Changeable Message Signs Replace Drainage Pumps SR140 MARIPOSA CAPM S.J 12 ADA Bridge Replacement	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Roll Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Roll Replacement and Uparade Transportation Management Systems Drainage System Restoration Pavement Preservation (CAPM) ADA - New Curb Ramps Bridge Rehabilitation and Replacement	Pump plant(s) (ea) Nile(s) of cable Calision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s) Curb ramp(s) Bridae(s)	\$5 8.5 264 34.6 964 22 25 41.6 806 26 4 2.3.6 10
10 3229 10 3230 10 3231 10 3233 10 3235 10 32258 10 3237 10 3241 10 3245 10 3251 10 3252 10 3252 10 3253 10 3253 10 3253 10 3253 10 3253 10 3253 10 3253	D 10 MVDS replacement and upgrade S.J DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposo SR 49 CAPM Matthews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements SR 132 ADA Improvements CAL SR 4 two way left furn lane Upgrade bridge rails of two bridges in CAL Co S.J Changeable Message Signs Replace Drainage Pumps SR140 MARIPOSA CAPM S.J 12 ADA Bridge Replacement S.J 12 ADA Bridge Replacement S.J 12 ADA UPGRADE Potato Slough Bridge Bearing Pads	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Iransportation Management Systems Drainage System Restoration Pavement Preservation (CAPM) ADA - New Curb Ramps Bridge Rehabilitation and Replacement ADA - New Curb Ramps Capital Bridge Preventative Maintenance Program	Pump plant(s) (ea) Nile(s) of cable Collision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramo(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s) Curb ramo(s) Bridae(s) Curb ramo(s) Bridge(s)	\$ 5 8.9 264 34.6 964 26 29 41.4 808 28 6 23.6 10 1
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3241 10 3247 10 3255 10 3255 10 3255 10 3255 10 3255 10 3255 10 3255	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Mariposa SR 49 CAPM Matthews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left turn lane Uparade bridge rails of two bridges in CAL Co SJ Changeable Message Signs Replace Drainage Pumps SR140 MARIPOSA CAPM SJ 12 ADA Bridge Replacement SJ 12 ADA UPGRADE	Equipment Iransportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rein Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Transportation Management Systems Drainage System Restoration Pavement Preservation (CAPM) ADA - New Curb Ramps Bridge Rehabilitation and Replacement ADA - New Curb Ramps Capital Bridge Preventative Maintenance Program Transportation Management Systems	Pump plant(s) (ea) Mile(s) of cable Calision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s) Curb ramp(s) Bridae(s) Curb ramp(s) Bridge(s) Field element(s)	5 8.9 264 34.6 964 26 29 41.4 808 28 6 23.6 10
10 3229 10 3230 10 3231 10 3233 10 3235 10 32358 10 3237 10 3247 10 3247 10 3250 10 3252 10 3254 10 3254 10 3254 10 3254 10 3254 10 3254	D 10 MVDS replacement and upgrade SJ DRAINAGE PUMP PLANT UPGRADE SR 120 TMC UPGRADE Wet Collisions Reduction Moriposa SR 49 CAPM Matthews Road UC DEUEL OVERHEAD UC Roadside Safety Improvements SR 132 ADA Improvements CAL SR 4 two way left turn lane Uparade bridae rails of two bridaes in CAL Co SJ Changeable Messaae Sians Replace Drainage Pumps SR140 MARIPOSA CAPM SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement SJ 12 ADA Bridae Replacement	Equipment Transportation Management (TMC's & Field Equipment) Drainage System Restoration Transportation Management (Fiber Optic Cable) Safety Improvements Pavement Rehabilitation Bridge Rehabilitation Bridge Rehabilitation Bridge Rail Replacement/Uparade Roadside Safety Improvements ADA - New Curb Ramps Non-Capacity Increasing Operational Improvements Bridge Rail Replacement and Uparade Transportation Management Systems Drainage System Restoration Pavement Preservation (CAPM) ADA - New Curb Ramps Bridge Rehabilitation and Replacement ADA - New Curb Ramps Capital Bridge Preventative Maintenance Program Transportation Management Systems	Pump plant(s) (ea) Mile(s) of cable Collision(s) reduced Lane mile(s) Bridae(s) Linear feet rail Location(s) Curb ramp(s) Daily Vehicle Hour(s) of Delay (DVHD) Linear feet rail Field element(s) Pump plant(s) (ea) Lane mile(s) Curb ramp(s) Bridae(s) Curb ramp(s) Bridge(s) Field element(s)	5 8.9 2644 34.6 964 22 29 41.4 808 28 6 23.6 10 1 1

10 3286	TTI SYSTEM UPGRADE	Transportation Management (TMC's & Field Equipment)	Field element(s)	5
10 3288	CAL County Bridges Rehab	Bridge Rehabilitation and Replacement	Bridge(s)	1
10 3296	MODESTO COLLISION SEVERITY REDUCTION	Collision Severity Reduction	Annual fatal and serious injury collision(s)	0.14
10 3298 10 3299	SR 99 ROADSIDE SAFETY IMPROVEMENTS SR 140 BRIDGE RAIL UPGRADE	Roadside Safety Improvements Bridge Rehabilitation and Replacement	Location(s) Bridge(s)	13
10 3401	SAN JOAQUIN RIVER (GARWOOD) BRIDGE	Bridge Rehabilitation and Replacement	Bridge(s)	1
10 3407	SJ 99 ROADSIDE IMPROVEMENTS	Roadside Safety Improvements	Location(s)	17
10 3409 10 3411	CAL 4 Culvert Replacement SR 120 TUO Drainage System	Drainage System Restoration Drainage System Restoration	Culvert(s) (ea) Culvert(s) (ea)	22 39
10 3417	152 Intersection Control	Safety Improvements	Collision(s) reduced	10
10 3418 10 3420	Intersection Control Improvement STA 5 BRIDGE REHAB	Safety Improvements Bridge Rehabilitation and Replacement	Collision(s) reduced Bridge(s)	34 20
10 3422	SR-4 ITS UPDATE	Transportation Management Systems	Field element(s)	40
10 3425 10 3427	Los Banos SR 152 Pavement Anchor I-5 PAVEMENT ANCHOR PROJECT	Pavement Preservation (CAPM) Roadway Rehabilitation (3R)	Lane mile(s) Lane mile(s)	18 83.4
10 3427	LODI ROADSIDE REHAB	Roadside Rehabilitation	Acre(s)	14
10 3429	SR 49 Angels Camp Complete Streets	ADA - New Curb Ramps	Curb ramp(s)	26
10 3430 10 3431	Blank Merced County SR 99	Major Damage (Emergency Restoration) Major Damage (Emergency Opening)	Location(s) Location(s)	!
10 3432	Fire Erosion Control Measures on Mariposa SR 140	Major Damage (Emergency Opening)	Location(s)	15
10 3433 10 3434	CAPLES LAKE REHABILITATION CAL 49 Mobility Improvement	Maintenance Facilities Operational Improvements	Location(s) Daily vehicle hour(s) of	1 204
10 3434	CAL 47 Mobility Improvement	Operational improvements	delay (DVHD)	204
10 3435	SR 49 San Andreas Complete Streets	ADA - New Curb Ramps	Curb ramp(s)	49
10 3436 10 3438	Carson TMS MER 140/165 Mobility Improvements	Transportation Management Systems Operational Improvements	Field element(s) Daily vehicle hour(s) of	21 53.2
			delay (DVHD)	
10 3439 10 3441	Merced Pavement Anchor Project Mer 33 Curb Ramps	Pavement Preservation (CAPM) ADA - New Curb Ramps	Lane mile(s) Curb ramp(s)	24 67
10 3442	MERCED 99 GUARDRAIL	Collision Severity Reduction	Collision(s) reduced	5
10 3443	SJ & STA TMS	Transportation Management Systems	Field element(s)	69
10 3447	MER 5 OPERATIONAL IMPROVEMENTS	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	144.6
10 3449	Calaveras County Storm Damage	Major Damage (Emergency Opening)	Location(s)	1
10 3450	Mariposa County Storm Damage	Major Damage (Emergency Opening)	Location(s)	1
10 3457 10 3459	Amador County Roadway Slip Out Tuolumne County Slip Out	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	
10 3466	SR 59 Intersection Control	Safety Improvements	Collision(s) reduced	22
10 3474	SR 205 Guardrail Upgrade	Collision Severity Reduction	Collision(s) reduced	7
10 3475	TUOLUMNE RIVER TRASH CONTROL	Storm Water Mitigation	Acre(s) treated/pollutant	19
10 3476	VALLEY OAKS INTERSECTION	Safety Improvements	Collision(s) reduced	18
10 3477	French Camp RD Intersection Control	Safety Improvements	Collision(s) reduced	25
10 3478 10 3479	SJ SR 12 Mokelumne Bridge Repair Mariposa SR 140 Briceburg Fire	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)]
10 3477	99 & 205 Surface treatment	Safety Improvements	Collision(s) reduced	121
10 3481	Amador County SR 16	Major Damage (Emergency Restoration)	Location(s)	48
10 3483	Alpine County SR 88 Culverts	Major Damage (Emergency Opening)	Location(s)	1
10 3486 10 3488	Merced SR 99 Overlay SR4 CULVERT REPLACEMENT	Major Damage (Emergency Restoration) Drainage System Restoration	Location(s) Culvert(s) (ea)	31
10 3490	Claus Road Intersection Control	Safety Improvements	Collision(s) reduced	11
10 3491	SJ County Fencing	Major Damage (Emergency Opening)	Location(s)	1
10 3492 10 3493	SJ SR4 Left-turn Channelization Chowchilla River CVEF	Safety Improvements Commercial Vehicle Enforcement Facilities & Weight	Collision(s) reduced	18
		In-Motion Scales		
10 3494	HWY 26/49 Intersection Control Improvement	Safety Improvements	Collision(s) reduced	22
10 3495 10 3496	CAL SR4 CAPM SR 59 Pavement Anchor Project	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	20.5
10 3498	MER 165 Intersection Control	Safety Improvements	Collision(s) reduced	9
10 3501	I-5 WIM Station	Commercial Vehicle Enforcement Facilities & Weigh	- Location(s)	1
10 3504	Blank	In-Motion Scales Major Damage (Emergency Restoration)	Location(s)	1
10 3505	SR 152 Median Barrier	Safety Improvements	Collision(s) reduced	58
10 3506	MER 140 Planada Intersection	Safety Improvements	Collision(s) reduced	17
10 3506	MER 140 Planada Intersection	Safety Improvements	Annual fatal and serious injury collision(s)	
			injury comsion(s)	
10 3508	Blank	Major Damage (Emergency Restoration)	Location(s)	1
10 3509	SJ 120 Median Barrier	Safety Improvements	Annual fatal and serious injury collision(s)	0.23
			7.,	
10 3510	Mer-99 Install Median Barrier	Safety Improvements	Collision(s) reduced	124
10 3511 10 3515	Drainage System Restoration Repair/replace old TMS	Drainage System Restoration Transportation Management Systems	Culvert(s) (ea) Field element(s)	34
10 3516	HAR Signal Upgrade	Transportation Management Systems	Field element(s)	24
10 3517	SJ 4 CAPM	Pavement Preservation (CAPM)	Lane mile(s)	17.4
10 3518 10 3523	SR 099 at PM 20.12 Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	<u>]</u>
10 3526	Hoods Creek Bridge Replacement	Bridge Scour	Bridge(s)	1
10 3527		Maintenance Facilities	Location(s) Bridge(s)	1
	MODESTO MTN.STN. REHABILITATION SP. 205 Bridge Atten Rengir			
10 3528	MODESTO MTN.STN. REHABILITATION SR 205 Bridge Mtce Repair	Capital Bridge Preventative Maintenance Program	blidge(3)	2
		Capital Bridge Preventative Maintenance Program Capital Bridge Preventative Maintenance Program	Bridge(s)	
10 3528 10 3529	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance	Capital Bridge Preventative Maintenance Program	Bridge(s)	6
10 3528	SR 205 Bridge Mtce Repair			6
10 3528 10 3529 10 3531 10 3533 10 3534	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridae Repair 1 580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R)	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance	Bridge(s) Bridge(s) Bridge(s) Bridge(s)	6
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridge Repair I 580 Separation Bridge MTCE Mer-97 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB1282 Merced L5 Pavement Anchor Project.	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s)	1 1 4 128.1
10 3528 10 3529 10 3531 10 3533 10 3534	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridae Repair 1 580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R)	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance	Bridge(s) Bridge(s) Bridge(s) Bridge(s)	1 1 2 128,1
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3536	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slough BOH, Bridge Repair 1.580 Separation Bridge MTCE Mer-99 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced I-5 Pavement Anchor Project. Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Major Damage (Emergency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s) Location(s) Annual fatal and serious	128. 118.
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3536 10 3537	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridae Repair I 580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R) ABI 282 Merced I-5 Pavement Anchor Project. Blank Blank	Capital Bridge Preventative Maintenance Program Bridae Preventative Maintenance Bridae Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s) Location(s)	128. 118.
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3536 10 3537	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridae Repair I 580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R) ABI 282 Merced I-5 Pavement Anchor Project. Blank Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Safety Improvements	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s) Location(s) Annual fatal and serious	128. 118.
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3537 10 3540 10 3541	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slough BOH, Bridge Repair 1580 Separation Bridge MTCE Mer-99 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced I-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Safety Improvements Major Damage (Emergency Restoration) Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s) Location(s) Annual fatal and serious injury collision(s) Location(s) Location(s)	128. 128.
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3536 10 3537 10 3540 10 3541 10 3542 10 3543	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridge Repair I 580 Separation Bridge MTCE INSTITUTE MET SP Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced L-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank Blank Blank Blank Blank Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Maior Damage (Emeraency Restoration) Maior Damage (Emeraency Restoration) Safety Improvements Maior Damage (Emeraency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Location(s)	128. 128.
10 3528 10 3529 10 3531 10 3533 10 3533 10 3536 10 3536 10 3540 10 3541 10 3542 10 3543 10 3543	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Marmon Slough BOH, Bridge Repair 1 580 Separation Bridge MICE Mer-99 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced I-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank Blank Blank Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Safety Improvements Maior Damage (Emergency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mille(s) Location(s)	128. 118.
10 3528 10 3529 10 3531 10 3533 10 3533 10 3535 10 3535 10 3536 10 3540 10 3541 10 3542 10 3543 10 3544 10 3545	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH. Bridae Repair 1580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R) AB 1282 Merced 1-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank Blank Blank Blank Blank Blank Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Maior Damage (Emercency Restoration) Major Damage (Emercency Restoration) Safety Improvements Major Damage (Emercency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s)	128. 118.
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3537 10 3540 10 3541 10 3542 10 3544 10 3545 10 3555	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Marmon Slouah BOH, Bridae Repair 1 580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R) AB1282 Merced I-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Maior Damage (Emergency Restoration) Maior Damage (Emergency Restoration) Safety Improvements Maior Damage (Emergency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s) Location(s) Annual fatal and serious injuy collision(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	128. 118.
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3536 10 3537 10 3540 10 3541 10 3542 10 3543 10 3544 10 3545 10 3545 10 3545 10 3545 10 3555 10 3555	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH. Bridae Repair 1580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridaes (39-0126L/0126R/0128L/0128R) AB 1282 Merced 1-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank Blank Blank Blank Blank Blank Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Maior Damage (Emercency Restoration) Major Damage (Emercency Restoration) Safety Improvements Major Damage (Emercency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s)	1 1 4 128.1 11 8
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3537 10 3540 10 3541 10 3542 10 3543 10 3544 10 3545 10 3554 10 3555 10 3556 10 3555	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridge Repair 1 580 Separation Bridge MTCE Mer-97 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced L-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank Blank	Capital Bridge Preventative Maintenance Program Bridae Preventative Maintenance Bridae Preventative Maintenance Bridae Preventative Maintenance Bridae Preventative Maintenance Pavement Preservation (CAPM) Maior Damaae (Emeraence Restoration) Safety Improvements Maior Damaae (Emeraency Restoration) Bridae Rehabilitation and Replacement Major Damage (Emeraency Restoration) Bridae Rehabilitation and Replacement Major Damage (Emeraency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Location(s)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
10 3528 10 3529 10 3531 10 3533 10 3533 10 3535 10 3535 10 3537 10 3540 10 3541 10 3542 10 3543 10 3544 10 3545 10 3555 10 3555	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridae Repair I 580 Separation Bridae MTCE Mer-99 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced I-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank	Capital Bridge Preventative Maintenance Program Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation (CAPM) Maior Damage (Emeraency Restoration) Maior Damage (Emeraency Restoration) Safety Improvements Major Damage (Emeraency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Lane mile(s) Location(s) Annual fatal and serious	1 1 4 128.1 11 8
10 3528 10 3529 10 3531 10 3533 10 3534 10 3535 10 3537 10 3540 10 3541 10 3542 10 3543 10 3544 10 3545 10 3554 10 3555 10 3556 10 3555	SR 205 Bridge Mtce Repair MER SR 152 Bridge Maintenance Mormon Slouah BOH, Bridge Repair 1 580 Separation Bridge MTCE Mer-97 Rehabilitate Four Bridges (39-0126L/0126R/0128L/0128R) AB 1282 Merced L-5 Pavement Anchor Project. Blank Blank Wamble Road Left-Turn Channelization Merced County SR 99 NB Blank Blank	Capital Bridge Preventative Maintenance Program Bridae Preventative Maintenance Bridae Preventative Maintenance Bridae Preventative Maintenance Bridae Preventative Maintenance Pavement Preservation (CAPM) Maior Damaae (Emeraence Restoration) Safety Improvements Maior Damaae (Emeraency Restoration) Bridae Rehabilitation and Replacement Major Damage (Emeraency Restoration) Bridae Rehabilitation and Replacement Major Damage (Emeraency Restoration)	Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Bridge(s) Location(s)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

10 3561	Hilmar Complete Street	SHOPP - Complete Streets	Bicycle and pedestrian infrastructure (linear feet)	31110
10 3562	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3563 10 3573	MER STA, & TUO TMS Replacement Blank	Transportation Management Systems Major Damage (Emergency Restoration)	Field element(s) Location(s)	2
10 3574	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3575	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3576 10 3577	Blank Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
10 3578	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3580	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3581 10 3582	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3583	Blank Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	1
10 3584	Blank	Major Damage (Emergency Restoration)	Location(s)	6.
10 3585	Blank	Major Damage (Emergency Restoration)	Location(s)	3
10 3586 10 3588	Blank Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	23
10 3589	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3590	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3591 10 3592	Blank Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
10 3594	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3595	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3597	Levee Restoration at Smith Canal Bridges	Bridge Rehabilitation and Replacement	Bridge(s)	1.13
10 3598	SR 152 Intersection Control Improvement	Safety Improvements	Annual fatal and serious injury collision(s)	1.1:
10 3599	Stanislaus ADA Curb Ramp Project	ADA - New Curb Ramps	Curb ramp(s)	6
10 3600 10 3605	Blank Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	
10 3606	Blank	Major Damage (Emergency Restoration)	Location(s)	5:
10 3608	Replace/install new TMS in VAR counties and VAR State Routes	Transportation Management Systems	Field element(s)	15
10 3618 10 3619	Mariposa 49 Pavement Anchor Project Blank	Pavement Preservation (CAPM) Major Damage (Emergency Restoration)	Lane mile(s) Location(s)	42.
10 3620	SR 120 Intersection Control Improvement.	Safety Improvements	Annual fatal and serious injury collision(s)	0.1:
10 3622	Midwest Guardrail System Installation	Collision Severity Reduction	Annual fatal and serious injury collision(s)	0.13
10 3623	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3625	Merced 165 Pavement Anchor Project	Pavement Preservation (CAPM)	Lane mile(s)	10.:
10 3626 10 3627	Tuolumne 49 Pavement Anchor Project Blank	Pavement Preservation (CAPM) Major Damage (Emergency Restoration)	Lane mile(s) Location(s)	117
10 3629	Crosswalks and Flashing Beacons in Merced, San Joaquin, Stanislaus, an	SHOPP - Complete Streets	Bicycle and pedestrian infrastructure (linear feet)	38
10 3631	SJ 5, 99, &120 TMS Repair	Transportation Management Systems	Field element(s)	2
10 3634	Blank	Major Damage (Emergency Restoration)	Location(s)	;
10 3636 10 3642	Alternative Delivery Method (CMGC) Ferauson Rock Avalanche Shed MER County SR 165 Intersection Control Improvement	Major Damage (Permanent Restoration) Safety Improvements	Location(s) Annual fatal and serious injury collision(s)	0.3
10 3649	Blank	Major Damage (Emergency Restoration)	Location(s)	
10 3658 10 3659	Automated Gates & Fence Installation - DO Maintenance Station Security Measures DO	Maintenance Facilities Maintenance Facilities	Location(s) Location(s)	
10 3660	McHenry Ave & Cordivood Road Intersection Control Improvement	Safety Improvements	Annual fatal and serious injury collision(s)	0.0
10 3664 10 3740 10 4736	Blank SR 152 Metal Beam Upgrade Midpines CAPM	Major Damage (Emergency Restoration) Safety Enhancements Pavement Rehabilitation	Location(s) Collision(s) reduced Lane mile(s)	6
10 5411	RIVERBANK SLOPE PROTECTION	Roadway Protective Betterments	Bridge(s)	0.
10 5431	MER-99 PAVEMENT REHABILITATION	Roadway Rehabilitation (2R)	Lane mile(s)	16.
10 5431Y 10 7546	MER 99 Highway planting and irrigation SR88 Pavement Anchor Project	Roadway Rehabilitation (2R) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	22.
11 0602	CULVERT REPLACEMENT	Drainage System Restoration	Culvert(s) (ea)	22,
11 0615F	I-5 North Coast Corridor HOV Extension - Phase 1 - Encinitas HOV	Auxiliary lane mile(s) constructed	Miles	
11 0615F 11 0615F	I-5 North Coast Corridor HOV Extension - Phase 1 - Encinitas HOV I-5 North Coast Corridor HOV Extension - Phase 1 - Encinitas HOV	HOV/HOT lane-mile(s) constructed	Miles	17.
11 0615F	I-5 North Coast Corridor HOV Extension - Phase 1 - Encinitas HOV I-5 North Coast Corridor HOV Extension - Phase 1 - Encinitas HOV	Operational improvement(s) Pedestrian/Bicycle facilities mile(s) constructed	Each Miles	8.5
11 0615J	I-5 NCC CARLSBAD HOV	Auxiliary Iane mile(s) constructed	Miles	
11 0615J	I-5 NCC CARLSBAD HOV	HOV/HOT lane-mile(s) constructed	Miles Each	8.
11 0615J 11 0615J	I-5 NCC CARLSBAD HOV I-5 NCC CARLSBAD HOV	Operational improvement(s) Operational improvements	Daily vehicle hour(s) of delay (DVHD)	7
11 0615J	I-5 NCC CARLSBAD HOV	Pedestrian/Bicycle facilities mile(s) constructed	Miles	0.4
11 0615K	I-5 NCC FINAL CMGC PACKAGE	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	26
11 0615K	I-5 NCC FINAL CMGC PACKAGE	Pedestrian/Bicycle facilities mile(s) constructed	Miles	0.8
11 1065	SR-75 CORONADO BRIDGE-PIERS	Bridge Rehabilitation and Replacement	Bridge(s)	
11 1085 11 1125	BUCKMAN SPRINGS SRRA WATER SYSTEMS ROUTE 78 SLOPE AND EROSION REPAIR	Roadside Safety Improvements Storm Water Mitigation	Location(s) Acre(s) treated/pollutant	4.3
11 1127	CONSTRUCT CURB RAMPS	ADA - New Curb Ramps	Curb ramp(s)	6
11 1134	CULVERT REHABILITATION RUMBLE STRIPS, UPGRADE END TREATMENTS	Drainage System Restoration Safety Enhancements	Culvert(s) (ea) Collision(s) reduced	3
11 1136	CMGC-SB AUX LANE	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	127
		Improvements	Delay (DVHD)	
11 1141 11 1142	ROADSIDE SAFETY IMPROVEMENT ROADSIDE SAFETY	Roadside Safety Improvements Roadside Safety Improvements	Location(s) Location(s)	10'
11 1142	PAVE MAINTENANCE VEHICLE PULLOUTS BEYOND GORE AREAS	Roadside Safety Improvements	Location(s)	9
11 1162	SR-78 PAVEMENT REHABILITATION	Pavement Rehabilitation	Lane mile(s)	13.
11 1164	I-5 DETENTION BASINS	Storm Water Mitigation	Acre(s)	7:
11 1165	11-SD-8 & 805 ROADSIDE SAFETY IMPROVEMENTS	Roadside Safety Improvements	treated/pollutant Location(s)	4
11 1166	11-SD-8 & 15 ROADSIDE SAFETY IMPROVEMENTS	Roadside Safety Improvements	Location(s)	2-
11 1167	11-SD-8 ROADSIDE SAFETY IMPROVEMENTS	Roadside Safety Improvements	Location(s)	3'
11 1168 11 1171	11-SD-8 & 125 ROADSIDE SAFETY IMPROVEMENTS TMS ELEMENT IN-HOUSE FIBER OPTIC	Roadside Safety Improvements Transportation Management (TMC's & Field Equipment)	Location(s) Field element(s)	1:
11 1174	DVMS PANELS	Transportation Management (TMC's & Field	Field element(s)	2.
11 1175	805 - PAVEMENT REHAB	Eauipmentl Pavement Rehabilitation	Lane mile(s)	14.

11 1177	SR-94 PAVEMENT REHAB	Pavement Rehabilitation	Lane mile(s)	18.
11 1188	SR 54 PAVEMENT PRESERVATION	Pavement Preservation (CAPM)	Lane mile(s)	36.
11 1189	GRADING IMPROVEMENTS, UPGRADING GUARDRAIL AND END TREATMENTS	Safety Enhancements	Collision(s) reduced	
11 1190	SD - UPGRADE END TREATMENTS & INSTALL SHOULDER RUMBLE STRIPS	Safety Improvements	Collision(s) reduced	6
11 1191 11 1194	INSTALL ADA RAMPS I-8 CULVERT REPLACEMENT	ADA - New Curb Ramps Drainage System Restoration	Curb ramp(s) Culvert(s) (ea)	2
11 1200	UPGRADE/INSTALL CURVE WARNING SIGNS AT HORIZONTAL CURVES	Safety Enhancements	Collision(s) reduced	
11 1201	UPGRADE/INSTALL CURVE WARNING SIGNS	Safety Enhancements	Collision(s) reduced	
11 1203	I-5 SLOPE STABILIZATION	Storm Water Mitigation	Acre(s)	1
11 1204	SR 75 MOBILITY PROJECT	Relinquishments	treated/pollutant Lane mile(s)	1.
11 1218	I-5 REPAIR - Bike Path	SHOPP - Sustainability and Miscellaneous	Location(s)	
11 1219	SR-52 ROADSIDE SAFETY IMPROVEMENT	Roadside Safety Improvements	Location(s)	5
11 1221	BRIDGE PRESERVATION RT 5/54/94/125/163	Capital Bridge Preventative Maintenance Program	Bridge(s)	3
11 1227 11 1237	I-8 ADA RAMPS REPLACE SIGNS WITH TYPE XI SHEETING	ADA - New Curb Ramps	Curb ramp(s)	1 377
11 1240	RTE 98 ADA	Signs and Lighting Rehabilitation ADA - New Curb Ramps	Lighting fixture(s) Curb ramp(s)	2
11 1241	Intelligent Transportation System Technology (Advanced Technology Corridors at	ITS element(s)	Each	16
	Border Ports of Entry)			
11 1241	Intelligent Transportation System Technology (Advanced Technology Corridors at	Transportation Management (Fiber Optic Cable)	Mile(s) of cable	13
11 1040	Border Ports of Entry)	De addide Debat 29 at a	A = = = (-)	
11 1243 11 1244	RECYCLED WATER PROJECT / SD I-805 RECYCLED WATER PROJECT/SD I-805/I-905	Roadside Rehabilitation Roadside Rehabilitation	Acre(s) Acre(s)	11
11 1245	I-5 ROADSIDE REHAB	Roadside Rehabilitation	Acre(s)	136
11 1246	SD-008-L0.7/R23.0 - DRAINAGE SYSTEM RESTORATION	Drainage System Restoration	Culvert(s) (ea)	9
11 1247	CULVERT REPLACEMENT	Drainage System Restoration	Culvert(s) (ea)	8
11 1248	ADA RAMPS AND SIDEWALKS /I-805	ADA - New Curb Ramps	Curb ramp(s)	
11 1250 11 1251	RTE 8, SD NEAR EL CAJON ROADSIDE SAFETY RTE 56 - ROADSIDE WORKER SAFEY	Roadside Safety Improvements	Location(s) Annual fatal and serious	1.8
11 1231	RIE 00 RONDOIDE WORKER SALET	Roadside Safety Improvements	injury collision(s)	1.0
11 1252	IMP, NEAR/IN EL CENTRO, ROADSIDE SAFETY	Roadside Safety Improvements	Location(s)	3
11 1253	11-SD-94-PM:4.4/7.3 - ROADSIDE WORKER SAFETY	Roadside Safety Improvements	Location(s)	2
11 1255 11 1256	I8 - PAVEMENT REHAB	Roadway Rehabilitation (2R) Bridge Rail Replacement/Upgrade	Lane mile(s)	22
11 1256 11 1257	E8-S163 CONNECTOR OC SR-125 PAVEMENT REHAB	Pavement Preservation (CAPM)	Linear feet rail Lane mile(s)	31 49
11 1258	Route 98 Widening	Intersection(s) modified	Each	47.
11 1258	Route 98 Widening	Operational improvement(s)	Each	
11 1258	Route 98 Widening	Pedestrian/Bicycle facilities mile(s) constructed	Miles	0.
11 1262	REPAIR EXISTING LOOP DETECTORS INSTALL RADAR DETECTION SYSTEMS	Transportation Management Systems	Field element(s)	17
11 1263	INSTALL RADAR DETECTION SYSTEMS	Transportation Management (TMC's & Field Eauinment)	Field element(s)	4
11 1264	SR-75 CITY OF SD RELINQUISHMENT	Relinquishments	Lane mile(s)	4.
11 1265	I-5 INSTALL HIGH TENSION CABLE BARRIER (HTCB)	Collision Severity Reduction	Collision(s) reduced	
11 1276	SR163 BRIDGE RAIL UPGRADE (LONG LEAD SHOPP)	Bridge Rail Replacement/Upgrade	Linear feet rail	195
11 1279	I-5 CANNON RD SB AUXILIARY LANE	Non-Capacity Increasing Operational	Daily Vehicle Hour(s) of	7
11 1280	I-805 SWEETWATER RIVER BRIDGE UPGRADE	Improvements Bridge Rail Replacement/Upgrade	Delay (DVHD) Linear feet rail	192
11 1281	I-5NCC ITS ELEMENTS	Transportation Management (TMC's & Field	Field element(s)	10
	TOTAGO NO ELEMENTO	Equipment)	ricia dicinicini(s)	
11 1285	I-805 North Operational Improvements	# Sign(s), light(s), greenway, or other safety /	Each	1
		beautification		
11 1285	I-805 North Operational Improvements	Auxiliary lane constructed	Miles	1.2
11 1285 11 1285	I-805 North Operational Improvements I-805 North Operational Improvements	Auxiliary Iane mile(s) constructed Bicycle Iane mile(s)	Miles Miles	0.3
11 1285	I-805 North Operational Improvements	Close circuit television camera(s)	Each	0.0
11 1285	I-805 North Operational Improvements	Communications (fiber optics)	Miles	0.
11 1285	I-805 North Operational Improvements	Culvert(s)	LF	61
11 1285	I-805 North Operational Improvements	Freeway ramp meter(s)	Each	
11 1285 11 1285	I-805 North Operational Improvements I-805 North Operational Improvements	Mainline shoulder(s) constructed New bridge(s)/tunnel(s)	Miles SQFT	1. 0.
11 1285	I-805 North Operational Improvements	Operational Improvements	Daily vehicle hour(s) of	88
	1 des richin operational improvements	operational improvements	delay (DVHD)	00
11 1285	I-805 North Operational Improvements	Ramp(s) and connector(s) constructed	Miles	1.
11 1301	I-5 PAVEMENT REHAB	Pavement Rehabilitation	Lane mile(s)	
11 1302	SR-52 DIPS PAVEMENT REHAB	Roadway Rehabilitation (3R)	Lane mile(s)	7.
11 1303	SD-94 CULVERT REHAB SR 75/282- CORONADO RELINQUISHMENT	Drainage System Restoration	Culvert(s) (ea)	3
11 1304	SR94 CULVERT REHAB & SR188 CAPM	Relinquishments Drainage System Restoration	Lane mile(s) Culvert(s) (ea)	9. 5
11 1307	SD-76 CULVERT REHAB	Drainage System Restoration	Culvert(s) (ea)	8
11 1308	I805 NORTH MAINT & REHAB	Drainage System Restoration	Culvert(s) (ea)	1
11 1309	I805 MIDDLE MAINT & REHAB	Transportation Management Systems	Field element(s)	7
11 1310 11 1311	SD-125 (SD-54 TO SD-94)	Roadway Rehabilitation (2R) Roadway Rehabilitation (2R)	Lane mile(s) Lane mile(s)	11.
11 1311	I-805 S. MAINT AND REHAB PROJECT SR-79 NORTH - CULVERT ASSET MANAGEMENT	Drainage System Restoration	Culvert(s) (ea)	137. 3
11 1314	SR-67 DRAINAGE RESTORATION	Drainage System Restoration	Culvert(s) (ea)	3
11 1315	I-15 \$ - CULVERT/TUNNEL LIGHTING/ADA	Drainage System Restoration	Culvert(s) (ea)	
11 1318	SR-111 & I-8 - COLLISION REDUCTION	Collision Severity Reduction	Collision(s) reduced	20.
		Pavement Rehabilitation	Lane mile(s) Daily Vehicle Hour(s) of	
11 1319	SD-78 CORRIDOR REHABILITATION			
		Non-Capacity Increasing Operational		55
11 1319	SD-78 CORRIDOR REHABILITATION		Delay (DVHD) Miles	
11 1319 11 1320 11 1325 11 1325	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s)	Delav (DVHD) Miles Each	55
11 1319 11 1320 11 1325 11 1325 11 1325	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchange(s)	Delay (DVHD) Miles Each Each	
11 1319 11 1320 11 1325 11 1325	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s)	Delav (DVHD) Miles Each	
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY	Non-Capacity Increasing Operational Improvements Mixed flow lane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr	
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridge Rehabilitation and Replacement	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridge(s)	80
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1327 11 1332 11 1332	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-006-R25.1/R40,1 - REHABILITATION	Non-Capacity Increasing Operational Improvements Mixed flow lane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s)	80
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1329 11 1332 11 1334 11 1339	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40,1 - REHABILITATE CULVERTS, 11-1MP-008-BRIDGE REHABILITATION 1-8 EL CAJON BRIDGE REHAB	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridae Rehabilitation and Replacement Drainaae System Restoration Bridae Preventative Maintenance Bridae Preventative Maintenance	Delay (DVHD) Miles Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Bridae(s)	80
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1332 11 1332 11 1334 11 1339 11 1342	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25,1/R40,1 - REHABILITATE CULVERTS, 11-IMP-008-BRIDGE REHABILITATION 1-B EL CAJON BRIDGE REHAB 11-IMP-98 COLD-IN-PLACE RECYCLE	Non-Capacity Increasing Operational Improvements Mixed flow lane-mile(s) constructed New bridge(s) New Interchanae(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s)	80
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1329 11 1330 11 1330 11 1334 11 1334 11 1343	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40,1 - REHABILITATE CULVERTS. 11-IMP-008-RIDGE REHABILITATION I-8 EL CAJON BRIDGE REHAB 11-IMP-98 COLD-IN-PLACE RECYCLE I-8 DIRECTOR'S ORDER (WEST FIRE)	Non-Capacity Increasing Operational Improvements Mixed flow Igne-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation Maior Damage (Emergency Openina)	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Location(s)	80
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1332 11 1332 11 1334 11 1339 11 1342	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25,1/R40,1 - REHABILITATE CULVERTS, 11-IMP-008-BRIDGE REHABILITATION 1-B EL CAJON BRIDGE REHAB 11-IMP-98 COLD-IN-PLACE RECYCLE	Non-Capacity Increasing Operational Improvements Mixed flow lane-mile(s) constructed New bridge(s) New Interchanae(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s)	80
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1336 11 1336 11 1339 11 1343 11 1343 11 1344 11 1347	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40.1 - REHABILITATE CULVERTS. 11-IMP-008-BRIDGE REHABILITATION I-8 EL CAJON BRIDGE REHABILITATION I-8 EL CAJON BRIDGE REHAB 11-IMP-98 COLD-IN-PLACE RECYCLE I-8 DIRECTOR'S ORDER (WEST FIRE) 11-SD-47 RHMA OVERLAY W/ SAMI DO SAN PASQUAL WILDFIRE I-15 CONCRETE LANE REPLACEMENT	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchange(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation Maior Damage (Emergency Opening) Roadway Rehabilitation (3R) Major Damage (Emergency Opening) Roadway Rehabilitation (3R)	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Location(s)	11 49
11 319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1332 11 1336 11 1342 11 1344 11 1347 11 1350 11 1350	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40.1 - SEHABILITATE CULVERTS. 11-IMP-008-BRIDGE REHABILITATION 1-8 EL CAJON BRIDGE REHABILITATION 1-8 EL CAJON BRIDGE REHAB 11-1MP-98 COLD-IN-PLACE RECYCLE 1-8 DIRECTOR'S ORDER (WEST FIRE) 11-SD-67 FAHMA OVERLAY W / SAMI DO SAN PASQUAL WILDFIRE 1-15 CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation Maior Damage (Emeraency Opening) Roadway Rehabilitation (3R) Major Damage (Emergency Opening) Roadway Rehabilitation (3R) Bridge Rehabilitation and Replacement	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Gulverf(s) (ea) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s)	111
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1324 11 1334 11 1343 11 1347 11 1350 11 1350 11 1355	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40.1 - REHABILITATE CULVERTS. 11-IMP-908-BRIDGE REHABILITATION 1-8 EL CAJON BRIDGE REHABILITATION 1-8 EL CAJON BRIDGE REHABILITATION 1-1-IMP-908-COLO-IN-PLACE RECYCLE 1-8 DIRECTOR'S ORDER (WEST FIRE) 11-SD-67 RHMA OVERLAY W/SAMI DO SAN PASQUAL WILDFIRE 1-15 CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER SR163 MOBILITY	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridae Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation Maior Damaae (Emercency Openina) Roadway Rehabilitation (3R) Maior Damage (Emergency Openina) Roadway Rehabilitation (3R) Bridge Rehabilitation (3R) Bridge Rehabilitation (3R) Bridge Rehabilitation (3R)	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Frield element(s)	111
11 1319 11 1320 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1334 11 1343 11 1344 11 1347 11 1350 11 1355 11 1355	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40,1 - REHABILITATE CULVERTS. 11-IMP-008-BRIDGE REHABILITATION I-BEL CAJON BRIDGE REHABILITATION I-BEL CAJON BRIDGE REHABILITATION I-BEL CAJON BRIDGE REHABILITATION I-BEL CAJON BRIDGE REHABILITATION I-BEL CAJOR STRUCTURE RECYCLE I-B DIRECTOR'S ORDER (WEST RIKE) 11-IMP-98 COLD-IN-PLACE RECYCLE I-B DIRECTOR'S ORDER (WEST RIKE) I-IS-CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER SR163 MOBILITY DO REPARE SINKHOLE ON RTE 805	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridae Rehabilitation and Replacement Drainaae System Restoration Bridae Preventative Maintenance Bridae Preventative Maintenance Pavement Preservation Maior Damaae (Emeraency Openina) Roadway Rehabilitation (3R) Major Damage (Emergency Openina) Roadway Rehabilitation (3R) Bridae Rehabilitation and Replacement Transportation Management Systems Major Damage (Emergency Openina)	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Lane mile(s) Lane mile(s) Location(s) Lane mile(s) Lone mile(s) Bridae(s)	11 49
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1336 11 1336 11 1342 11 1343 11 1344 11 1345 11 1355 11 1355 11 1355 11 1355 11 1355 11 1358	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25 I/K4Q.1 - REHABILITATE CULVERTS. 11-IMP-908-BRIDGE REHABILITATION 18-B EL CAJON BRIDGE REHABILITATION 18-B EL CAJON BRIDGE REHABILITATION 11-SD-67 RHMA OVERLAY W/ SAMI DO SAN PASQUAL WILDFIRE 11-SD-67 RHMA OVERLAY W/ SAMI DO SAN PASQUAL WILDFIRE SR-135 MOBILITY DO REPAIR SINKHOLE ON RITE 805 SR163 MOBILITY DO REPAIR SINKHOLE ON RITE 805	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridae Rehabilitation and Replacement Drainage System Restoration Bridae Preventative Maintenance Bridae Preventative Maintenance Provement Preservation Maior Damage (Emeraency Openina) Roadway Rehabilitation (3R) Major Damage (Emergency Openina) Roadway Rehabilitation (3R) Bridae Rehabilitation (3R) Bridae Rehabilitation (3R) Bridae Rehabilitation (3R) Bridae Rehabilitation Management Systems Major Damage (Emergency Openina) Safety Improvements Safety Improvements	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Codision(s) Collision(s)	11 49
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1330 11 1330 11 1343 11 1343 11 1347 11 1350 11 1355 11 1355 11 1356 11 1358	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-006-R25.1/R40,1 - REHABILITATE CULVERTS. 11-IMP-008-BRIDGE REHABILITATE CULVERTS. 11-IMP-98 COLD-IN-PLACE RECYCLE 18-DIRECTOR'S ORDER (WEST FIRE) 11-SD-67 RHMA OVERLAY W/SAMI DO SAN PASQUAL WILDFIRE L-15 CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER SR163 MOBILITY DO REPAIR SINKHOLE ON RTE 805 1805/18 - INSTALL HIGH FRICTION SURFACE TREATMENT DO STORM EVENT REPAIRS	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchange(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation Major Damage (Emergency Opening) Roadway Rehabilitation (3R) Major Damage (Emergency Opening) Roadway Rehabilitation and Replacement Transportation Management Systems Major Damage (Emergency Opening) Safety Improvements Major Damage (Emergency Opening) Safety Improvements Major Damage (Emergency Opening)	Delay (DVHD) Miles Each Each Fach In,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lone mile(s) Bridae(s) Bridae(s) Location(s)	11 49
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1336 11 1336 11 1342 11 1342 11 1343 11 1343 11 1345 11 1355 11 1355 11 1358 11 1358 11 1364 11 1364 11 1364 11 1368	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40.1 - REHABILITATE CULVERTS. 11-IMP-908-BRIDGE REHABILITATION 18-B L CAJON BRIDGE REHABILITATION 18-B L CAJON BRIDGE REHABILITATION 11-IMP-908-BRIDGE SUIDE REHABILITATION 11-IMP-908-BRIDGE SUIDE BRIDGE SUICIDE BARRIER SP-075-CORONADO BRIDGE SUICIDE BARRIER SR163 MOBILITY DO REPAIR SINKHOLE ON RTE 805 1805/183 - INSTALL HIGH FRICTION SURFACE TREATMENT DO STORM EVENT REPAIRS DO CLEAN CULVERTS & RESTORE STREAM BANK ON RTE 79 DO - MUD POT SR111	Non-Capacity Increasing Operational Improvements Mixed flow Innermile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Department of the Innermile of th	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Bridae(s) Bridae(s) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Lane mile(s) Location(s) Location(s) Location(s) Location(s) Codision(s) Collision(s)	11 49
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1336 11 1336 11 1343 11 1343 11 1343 11 1343 11 1355 11 1355 11 1356 11 1356 11 1364 11 1365 11 1365	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40.1 - REHABILITATE CULVERTS. 11-IMP-908-BRIDGE REHABILITATION I-8 EL CAJON BRIDGE REHABILITATION I-8 EL CAJON BRIDGE REHABILITATION I-18 EL CAJON BRIDGE REHABILITATION I-18 EL CAJON BRIDGE REHABILITATION I-19 EL CAJON BRIDGE REHABILITATION I-10 ENCRETO STRUCTURE RECYCLE I-8 DIRECTORS ORDER (WEST RIKE) 11-15 CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER SR163 MOBILITY DO REPAR SINKHOLE ON RTE 805 I805/I8- INSTALL HIGH FRICTION SURFACE TREATMENT DO STORM EVENT REPARS DO CLEAN CULVERTS & RESTORE STREAM BANK ON RTE 79 DO -MUD POT SR111	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchange(s) Operational Improvements Operational Improvements Operational Improvements Operational Improvements Operational Improvements Operational Improvements Operational Op	Delay (DVHD) Miles Each Each Fach Jo00 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Lane mile(s) Location(s)	111 49 12
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1332 11 1336 11 1342 11 1344 11 1347 11 1350 11 1355 11 1356 11 1356 11 1368 11 1368	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25 1/R40,1 - REHABILITATE CULVERTS. 11-IMP-008-BRIDGE REHABILITATION 18-B EL CAJON BRIDGE REHABILITATION 18-B EL CAJON BRIDGE REHAB 11-IMP-98 COLD-IN-PLACE RECYCLE 18- DIRECTOR'S ORDER (WEST FREE) 11-SD-47 RHMA OVERLAY W / SAMI DO SAN PASQUAL WILDFIRE 1-15 CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER SR 163 MOBILITY DO REPAIR SINKHOLE ON RTE 805 1805/8- INSTALL HIGH FRICTION SURFACE TREATMENT DO STORM EVENT REPAIRS DO CLEAN CULVERTS & RESTORE STREAM BANK ON RTE 79 DO - MUD POT SR 111 CLAREMONT BRIDGE REHAB	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridae Rehabilitation and Replacement Drainaes System Restoration Bridae Preventative Maintenance Bridae Preventative Maintenance Provement Preservation Maior Damage (Emeraency Openina) Roadway Rehabilitation (3R) Major Damage (Emergency Openina) Roadway Rehabilitation (3R) Bridae Rehabilitation (3R) Stride Rehabilitation (3R) Stride Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM)	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Location(s) Bridae(s) Location(s) Loca	111 49 12
11 319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1336 11 1336 11 1343 11 1343 11 1343 11 1345 11 1350 11 1355 11 1358 11 1364 11 1368 11 1388 11 1388 11 1388 11 1388 11 1383	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25.1/R40.1 - REHABILITATE CULVERTS. 11-IMP-908-BRIDGE REHABILITATE CULVERTS. 11-IMP-908-BRIDGE REHABILITATION 1	Non-Capacity Increasing Operational Improvements Mixed flow Inne-mile(s) constructed New bridge(s) New interchange(s) New interchange(s) Operational Improvements Bridge Rehabilitation and Replacement Drainage System Restoration Bridge Preventative Maintenance Bridge Preventative Maintenance Bridge Preventative Maintenance Pavement Preservation Maior Damage (Emergency Opening) Roadway Rehabilitation (3R) Major Damage (Emergency Opening) Roadway Rehabilitation and Replacement Transportation Management Systems Major Damage (Emergency Opening) Safety Improvements Major Damage (Emergency Openina) Bridge Rehabilitation and Replacement Pavement Preservation (CAPMI)	Delay (DVHD) Miles Each Each Fach 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Bridae(s) Lane mile(s) Location(s) Lane mile(s) Location(s)	80 2 111 49 12 10
11 1319 11 1320 11 1325 11 1325 11 1325 11 1325 11 1325 11 1325 11 1336 11 1339 11 1342 11 1343 11 1344 11 1347 11 1350 11 1355 11 1356 11 1358 11 1368 11 1368 11 1368 11 1368	SD-78 CORRIDOR REHABILITATION 1-5 MOBILITY PROJECT SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY SR-125 SB CONNECTORS TO SR-11/905 & SR-11 4-LANE FREEWAY IMP BRIDGE STRUCTURE REHAB SD-008-R25 1/R40,1 - REHABILITATE CULVERTS. 11-IMP-008-BRIDGE REHABILITATION 18-B EL CAJON BRIDGE REHABILITATION 18-B EL CAJON BRIDGE REHAB 11-IMP-98 COLD-IN-PLACE RECYCLE 18- DIRECTOR'S ORDER (WEST FREE) 11-SD-47 RHMA OVERLAY W / SAMI DO SAN PASQUAL WILDFIRE 1-15 CONCRETE LANE REPLACEMENT SD-075-CORONADO BRIDGE SUICIDE BARRIER SR 163 MOBILITY DO REPAIR SINKHOLE ON RTE 805 1805/8- INSTALL HIGH FRICTION SURFACE TREATMENT DO STORM EVENT REPAIRS DO CLEAN CULVERTS & RESTORE STREAM BANK ON RTE 79 DO - MUD POT SR 111 CLAREMONT BRIDGE REHAB	Non-Capacity Increasing Operational Improvements Mixed flow Iane-mile(s) constructed New bridge(s) New interchanae(s) Operational Improvements Bridae Rehabilitation and Replacement Drainaes System Restoration Bridae Preventative Maintenance Bridae Preventative Maintenance Provement Preservation Maior Damage (Emeraency Openina) Roadway Rehabilitation (3R) Major Damage (Emergency Openina) Roadway Rehabilitation (3R) Bridae Rehabilitation (3R) Stride Rehabilitation (3R) Stride Rehabilitation (3R) Safety Improvements Major Damage (Emergency Openina) Safety Improvements Major Damage (Emergency Openina) Bridae Rehabilitation and Replacement Pavement Preservation (CAPM)	Delay (DVHD) Miles Each Each 1,000 vehicle hour(s)/yr Bridae(s) Culvert(s) (ea) Bridae(s) Lane mile(s) Location(s) Location(s) Bridae(s) Bridae(s) Location(s)	\$55 800 2 11. 49. 12. 10 9. 45. 46.

11	1007	AD A CURR DAVID IN DROVENTS ITS	ADA No. Code Donor	Contraction (a)	00
	1386 1387	ADA CURB RAMP IMPROVEMENTS BRIDGE PRESERVATION - 43090K	ADA - New Curb Ramps Bridge Rehabilitation and Replacement	Curb ramp(s) Bridge(s)	28 4
11	1390	SR 76 - PAVEMENT REHABILITATION	Pavement Preservation (CAPM)	Lane mile(s)	33
	1397	VEHICLE DETECTION, WORKER SAFETY, COMPLETE STREETS	Transportation Management Systems	Field element(s)	47
	1398	IMPROVE MTCE FACILITY	Maintenance Facilities	Location(s)	1 20
	1399	11-43097X - ADA & TMS SR 56, 0.0/2.93 PAVEMENT REHABILITATION	ADA - New Curb Ramps Pavement Preservation (CAPM)	Curb ramp(s) Lane mile(s)	13
	1407	Blank	Major Damage (Emergency Restoration)	Location(s)	1
	1412	DO REPAIR EROSION DAMAGE	Major Damage (Emergency Opening)	Location(s)	1
	1413	DO- REPLACE CULVERT FAILURE & REPAIR SINKHOLE ROSE CANYON BR	Major Damage (Emergency Opening)	Location(s)	1
	1414	DO - REPLACE FAILED CULVERT AT CARMEL MOUNTAIN RD ON I-5 DO - 52 SUB-SURFACE GROUND STABILIZATION	Major Damage (Emergency Opening) Major Damage (Emergency Opening)	Location(s) Location(s)	1
		DO - REPLACE BACKPLATES, INSTALL BACKUP GENERATORS AND SIGNS	Major Damage (Emergency Restoration)	Location(s)	91
11	1421	DO I-8 SINK HOLE FLINN SPRINGS	Major Damage (Emergency Opening)	Location(s)	1
	1423	DO - REPLACE FAILED CULVERTS	Major Damage (Emergency Opening)	Location(s)	1
11	1431	LOS PENASQUITOS LAGOON RESTORATION FCO	Storm Water Mitigation	Acre(s)	46
11	1433	OTAY MESA CVEF SCALE	Commercial Vehicle Enforcement Facilities & Weight	treated/pollutant Location(s)	1
			In-Motion Scales	(,,	
	1434	I-5 ASSET MGMT SPLIT	Pavement Preservation (CAPM)	Lane mile(s)	55.8
11	1439	SR-76 SHOULDER WIDENING	Safety Improvements	Annual fatal and serious	0.06
				injury collision(s)	
11	1445	DO-REPLACE BRIDGE DECK 57-0365	Major Damage (Emergency Opening)	Location(s)	1
	1446	DO- BRIDGES ENCAMPMENTS	Major Damage (Emergency Restoration)	Location(s)	62 30
		SR-15 ADA CURB RAMPS SD-79 JAPATUL VALLEY ROAD PAVEMENT	ADA - New Curb Ramps	Curb ramp(s)	30 27.7
	1455 1456	IMP-98 PAVEMENT REHAB	Pavement Preservation (CAPM) Pavement Preservation (CAPM)	Lane mile(s) Lane mile(s)	27.7
	1458	I-8 PAVE REHAB FROM LAKE JENNINGS UC TO WILLOWS RD OC	Pavement Preservation (CAPM)	Lane mile(s)	16.8
	1459	DO - SD 5 SLOPE REPAIR	Major Damage (Emergency Restoration)	Location(s)	26
	1460	SD-78 DO SLOPE REPAIR	Major Damage (Emergency Restoration)	Location(s)	6
	1465 1467	LANDSCAPE MITIGATION FOR 42210 REPAIR BRIDGE DECK	Drainage System Restoration Bridge Preventative Maintenance	Culvert(s) (ea) Bridge(s)	0
11	1468	SR125 AND SR52 BRIDGE PRESERVATION	Bridge Preventative Maintenance	Bridge(s)	2
11	1469	DO - REPLACE FAILED CULVERTS	Major Damage (Emergency Restoration)	Location(s)	1
	1470	DO - REPAIR DAMAGE DUE TO WATERLINE BREAK	Major Damage (Emergency Restoration)	Location(s)	1
	1471 1472	DO - STABILIZE RETAINING WALL COMPLETE STREETS FOR IMP 86, 111 AND 115	Major Damage (Emergency Restoration) SHOPP - Complete Streets	Location(s) Bicycle and pedestrian	47238
''	14/2	COMIT LETE STREETS FOR HAIR GO, FFF AND FFS	STOLL - COMPLETE SHEETS	infrastructure (linear	4/ 230
				feet)	
				·	
	1473	IMP-78 PAVEMENT REHAB	Roadway Rehabilitation (2R)	Lane mile(s)	15
	1474	PAVEMENT REHABILITATION OPERATIONAL IMPROVEMENTS	Roadway Rehabilitation (2R) Operational Improvements	Lane mile(s) Daily vehicle hour(s) of	23.9 204
	1470	OF EIGHTOTAL IN ROYEMENTS	operational improvements	delay (DVHD)	204
11	1477	PAVEMENT REHAB	Pavement Preservation (CAPM)	Lane mile(s)	76.9
	1478	BIOLOGICAL MONITORING FOR 42650	SHOPP - Sustainability and Miscellaneous	Location(s)	0
		SD-15 PAVEMENT REHAB SD-5 MOBILITY TMS	Pavement Preservation (CAPM) Transportation Management Systems	Lane mile(s) Field element(s)	95.1 16
		I-5 BRIDGE REHAB	Bridge Rehabilitation and Replacement	Bridge(s)	4
		DRAINAGE RESTORATION ON ROUTE 163	Drainage System Restoration	Culvert(s) (ea)	11
		IMP-8 STORM DAMAGE	Major Damage (Emergency Restoration)	Location(s)	37
	1488	DO - KAY STORM DAMAGE	Major Damage (Emergency Restoration)	Location(s)	
	1493 1494	SD-805 DO PALOMAR STREET Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
	1495	11-43176X - DO - REMOVE ADL SOIL & REPLACE W/IMPORTED BORROW	Major Damage (Permanent Restoration)	Location(s)	i
11	1496	DO - REPAIR WASHOUT	Major Damage (Emergency Restoration)	Location(s)	1
		DO - REMOVE BOULDERS AND DEBRIS	Major Damage (Emergency Restoration)	Location(s)	4
11	1501	SAN DIEGO TRASH CAPTURE DEVICES AT VARIOUS LOCATIONS	Storm Water Mitigation	Acre(s)	50
11	1502	Blank	Major Damage (Emergency Restoration)	treated/pollutant Location(s)	1
		DO - REPLACE CULVERTS	Major Damage (Emergency Restoration)	Location(s)	6
	1504	DO - REPLACE SINKHOLE	Major Damage (Emergency Restoration)	Location(s)	1
	1505 1514	Blank Blank	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
	1514	SD-15 HIGH TENSION CABLE BARRIER	Safety Improvements	Annual fatal and serious	0.28
	1010	SO TO THE THE TOTAL OF BLE STRINGEN	carery improvements	injury collision(s)	0.20
	1518	DO - REPAIR RAMP PAVEMENT	Major Damage (Emergency Restoration)	Location(s)	63
11	1520 1539	DO - 5/163 SEP BRIDGE DECK REHABILITATION DO - REMOVE TREES	Major Damage (Emergency Restoration)	Location(s)	124
	1542	DO - REMOVE ROLLDERS AND REPAIR ROADWAY	Major Damage (Emergency Restoration)	Location(s)	4
11	1543	DO - TO REPAIR STORM DAMAGE	Major Damage (Emergency Restoration)	Location(s)	4
11		DO - EMERGENCY - REPLACE PUMP	Major Damage (Emergency Restoration)	Location(s)	1
	1580 1581	DO - EMERGENCY - REPAIR FAILED CULVERT DO - EMERGENCY - REPAIR STORM DAMAGE	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s) Location(s)	1
	1583	DO - EMERGENCY - REPAIR STORM DAMAGE DO - EMERGENCY - REPAIR STORM DAMAGE	Major Damage (Emergency Restoration) Major Damage (Emergency Restoration)	Location(s)	26
11	1584	DO - REPAIR FAILED CULVERT	Major Damage (Emergency Restoration)	Location(s)	1
	1585	DO - REPAIR SINKHOLES	Major Damage (Emergency Restoration)	Location(s)	2
	1586 1587	DO - REPAIR STORM DAMAGE DO - EMERGENCY - SECURITY MEASURES	Major Damage (Emergency Restoration) Maintenance Facilities	Location(s) Location(s)	<u>5</u> 10
		DO - REPAIR STORM DAMAGE	Major Damage (Emergency Restoration)	Location(s)	2
	1588			Field element(s)	251
11	1203	12-0Q690 detection system rehab.	Transportation Management (TMC's & Field	rield elefficiti(3)	
11 12	1203	12-0Q690 detection system rehab.	Equipment)		
11 12 12	1203	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133	Equipment Bridge Preventative Maintenance	Bridge(s)	25
11 12 12 12	1203	12-0Q690 detection system rehab.	Equipment)		25 47 6
11 12 12 12 12 12	1204 1205 1207 2208A	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte. Var. Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure	Eauipmentl Bridae Preventative Maintenance Maior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps	Bridge(s) Location(s) Location(s) Curb ramp(s)	<u>6</u> 8
11 12 12 12 12 12 12	1204 1205 1207 2208A 2209A	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project	Equipment1 Bridge Preventative Maintenance Major Domage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements	Bridge(s) Location(s) Curb ramp(s) Location(s)	6 8 24
11 12 12 12 12 12 12 12	1203 1204 1205 1207 2208A 2209A 2246	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades	Equipment1 Bridge Preventative Maintenance Major Domage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM)	Bridge(s) Location(s) Location(s) Curb ramp(s) Location(s) Lane mile(s)	6 8 24 15.6
11 12 12 12 12 12 12 12 12	1204 1205 1207 2208A 2209A	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project	Equipment1 Bridge Preventative Maintenance Major Domage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements	Bridge(s) Location(s) Curb ramp(s) Location(s)	6 8 24 15.6 9.5
11 12 12 12 12 12 12 12 12 12 12	1203 1204 1205 1207 2208A 2209A 2246 2246A 2246B 2255	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA upgrades 12-0H151 CAPM combined with ADA EA 0P690 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Upgrade ADA	Eauioment1 Stidae Preventative Maintenance Maior Damaae (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s)	6 8 24 15.6 9.5 10.8
11 12 12 12 12 12 12 12 12 12 12 12	1203 1204 1205 1207 2208A 2209A 2246 2246A 2246B 2255 2257	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0G990 PCH SB-1 Multi Asset Project 12-0H950 PCH Laguna Beach Rehabilitate Pavement & ADA upgrades 12-0H151 CAPM combined with ADA EA 0P690 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Upgrade ADA 12-0P690 Rte 1 Upgrade ADA curb ramps, widen sidewalk	Eauioment1 Bridge Preventative Maintenance Maior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps ADA - New Curb Ramps	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Curb ramp(s)	6 8 24 15.6 9.5 10.8 53
11 12 12 12 12 12 12 12 12 12 12 12 12	1203 1204 1205 1207 2208A 2209A 2246 2246A 2246B 22255 2257 2257	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03530, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte. Var. Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P890 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk	Equipment1 Bridge Preventative Maintenance Major Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM)	Bridge(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Lane mile(s)	6 8 24 15.6 9.5 10.8 53 53
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 2208A 2209A 2246 2246A 2246B 2255 2257 2257 2279	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-00990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laquna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P690 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laquna Beach Uparade ADA 12-0P69U RCP Laquna Beach Uparade ADA 12-0P69U Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P69U Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P69U Rte 10 Uparade FOADA Standards & CAPM	Eauloment1 Stidae Preventative Maintenance Maior Damaae [Emergency Openina] Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrostructure	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lone mile(s) Lone mile(s) Lone mile(s) Lorb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Lone mile(s)	6 8 24 15.6 9.5 10.8 53 53 9.5
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 2208A 2209A 2246 2246A 2246A 2255 2257 2279 2279 2285	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03530, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte. Var. Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P890 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk	Equipment1 Bridge Preventative Maintenance Major Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM)	Bridge(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Curb ramp(s) Lane mile(s) Lane mile(s)	6 8 24 15.6 9.5 10.8 53 53 9.5 83 10.8
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 2208A 2209A 2246 2246A 2246B 2257 2257 2279 2279 2279 2279 2279 2279	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laquana Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P690 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laquana Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P69U Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M820 Rte 001 Uparade to ADA Standards & CAPM 12-0M820 Rte 001 Uparade to ADA Standards & CAPM 12-0M820 Rte 001 Uparade to ADA Standards & CAPM 12-0M970 PCH/Broadway Culvert Bridge	Eauioment1 Bridae Preventative Maintenance Maior Damaae (Emergency Openina) Maintenance Facilities ADA - New Curb Romps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Rehabilitation ADA - New Curb Ramps Pavement Rehabilitation ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Bridae Rehabilitation	Bridge(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Lane mile(s) Lane mile(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Lane mile(s) Corb ramp(s) Lane mile(s) Corb ramp(s) Lane mile(s) Collision(s) reduced Bridge(s)	6 8 24 15.6 9.5 10.8 53 53 9.5 83 10.8
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 2208A 2209A 2246 2246A 2245 2255 2257 2279 2279 2279 2279 2279 2279 2279 2279 2285 2300	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03530, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0Pk90 12-0H151 CAPM combined with ADA EA 0Pk90 12-0H50 APM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0R170 Laguna Beach Route 1 @ Cress St. Modify Signals & ADA	Equipment1 Bridge Preventative Maintenance Moior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Bridge Rehabilitation Safety Improvements Bridge Rehabilitation ADA - Pedestrian Infrastructure	Bridge(s) Location(s) Location(s) Location(s) Curb ramp(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Curb ramp(s) Corb ramp(s) Corb ramp(s) Lane mile(s) Corb ramp(s) Lane mile(s) Corb ramp(s) Corb ramp(s) Corb ramp(s) Corb ramp(s) Corb ramp(s) Corb ramp(s)	6 8 24 15.6 9.5 10.8 53 53 9.5 83 10.8
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 2208A 2246 2246A 2246B 2255 2257 2279 227	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03530, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA upgrades 12-0H151 CAPM combined with ADA EA 0P690 12-0H153 CAPM Combined with ADA EA 0P690 12-0H59 PCH Laguna Beach Upgrade ADA 12-0P69U Rte 1 Upgrade ADA curb ramps, widen sidewalk 12-0P69U Rte 1 Upgrade ADA curb ramps, widen sidewalk 12-0M62U Rte 001 Upgrade to ADA Standards & CAPM 12-0R170 Laguna Beach Route 1 @ Cress St. Modify Signals & ADA 12-0M990 PCH/Broadway Culvert Bridge 12-0M62C Rte 001 Upgrade to ADA Standards & CAPM 12-0M82C Rte 001 Upgrade To ADA Standards & CAPM	Eauloment1 Stidae Preventative Maintenance Malor Damaae [Emergency Openina] Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Sridae Rehabilitation ADA - Pedestrian Infrastructure Pavement Rehabilitation ADA - Pedestrian Infrastructure Raidae Rehabilitation ADA - Pedestrian Infrastructure Maior Damaae (Emergency Openina)	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Curb ramp(s) Lune mile(s) Curb ramp(s) Lone mile(s) Curb ramp(s) Location(s)	6 8 8 24 15.6 9.5 10.8 533 10.8 16 16 18 18 18 18 18 18 18 18 18 18 18 18 18
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 2208A 2209A 2246 2246A 2245 2255 2257 2279 2279 2279 2279 2279 2279 2279 2279 2285 2300	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03530, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0Pk90 12-0H151 CAPM combined with ADA EA 0Pk90 12-0H50 APM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0R170 Laguna Beach Route 1 @ Cress St. Modify Signals & ADA	Equipment1 Bridge Preventative Maintenance Moior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Bridge Rehabilitation Safety Improvements Bridge Rehabilitation ADA - Pedestrian Infrastructure	Bridge(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Lane mile(s) Collision(s) reduced Bridge(s) Collision(s) Location(s) Location(s) Location(s)	6 8 8 24 15.6 9.5 10.8 533 10.8 16 16 18 18 18 18 18 18 18 18 18 18 18 18 18
11 12 12 12 12 12 12 12 12 12	1203 1204 1205 1207 2208A 2209A 2246 2246B 2245 2255 2257 2279 2285 2279 2280 2300 2320A 2322B	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS Gap Closure 12-0G990 PCH S8-1 Multi Asset Project 12-0G990 PCH S8-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P690 12-0H153 CAPM Combined with ADA EA 0M820 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 RCH Laguna Beach Uparade ADA 12-0P690 Ret 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0R170 Laguna Beach Route 1 @ Cress St. Modify Sianals & ADA 12-0M990 PCH/Broadway Culvert Bridge 12-0M82C Rte 001 Uparade to ADA Standards & CAPM 12-0M820 Rte 001 Uparade to ADA Standards & CAPM 12-0M820 Rte 001 Uparade to ADA Standards & CAPM 12-0M820 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM	Equipment1 Stidge Preventative Maintenance Maior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety (Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps ADA - New Curb Ramps ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Bridge Rehabilitation ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Preservation (CAPM) Safety Pedestrian Infrastructure Parement Rehabilitation Safety Pedestrian Infrastructure Maior Damage (Emergency Opening) Storm Water Mitigalion	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lone mile(s) Lone mile(s) Curb ramp(s) Curb ramp(s) Lone mile(s) Location(s) Acre(s) Location(s) Location(s) Location(s)	6 8 24 15.6.6 9.5.5 10.8 53 9.5.5 83 10.8 16 1 1 9
11 12 12 12 12 12 12 12 12 12	1203 1204 1205 1207 2208A 2209A 2246A 2246A 2246S 2255 2257 2279 2279 2279 2279 2279 2293 2300 2320A 2322B	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-03530, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS, Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P890 12-0H151 CAPM combined with ADA EA 0P890 12-0H151 CAPM Cambined with ADA EA 0M820 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0R170 Laguna Beach Route 1 @ Cress St. Modify Signals & ADA 12-0M990 PCH/Broadway Culvert Bridge 12-0M82C Rte 001 Uparade to ADA Standards & CAPM 12-0M10 Rte 10 Uparade to ADA Standards & CAPM 12-0M10 Rte 001 Uparade to ADA Standards & CAPM 12-0M10 Rte 001 Uparade to ADA Standards & CAPM 12-0M10 Rte 001 Uparade to ADA Standards & CAPM 12-0M10 Rte 001 Uparade to ADA Standards & CAPM 12-0M10 Rte 001 Uparade to ADA Standards & CAPM 12-0M10 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M80 Rte 001 Uparade to ADA Standards & CAPM 12-0M60 Rt 1 Stabilize bioswales	Equipment1 Bridge Preventative Maintenance Maior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps ADA - New Curb Ramps Pavement Rehabilitation ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Bridge Rehabilitation Safety Demage Rehabilitation ADA - Pedestrian Infrastructure Maior Damage (Emergency Opening) Storm Water Mitigation Transportation Management (TMC's & Field Equipment)	Bridge(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Lane mile(s) Collision(s) reduced Bridge(s) Collision(s) Location(s) Location(s) Location(s)	6 8 8 24 15.6. 15.
11 12 12 12 12 12 12 12 12 12	1203 1204 1205 1207 1208A 2209A 2246A 2246A 2246B 2255 2257 2279 2279 2279 2279 2285 2293 2300 2320A 2330A	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0G990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P690 12-0H53 CAPM Combined with ADA EA 0P690 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M990 PCH/Broadway Culvert Bridge 12-0M62C Rte 001 Uparade to ADA Standards & CAPM 12-0M160 Rte, I PCH Slope Embankment Repair 12-0P660 Rt 1 Stabilize bioswales 12-0P68U Upgrade Traffic Signal	Equipment1 Stidge Preventative Maintenance Maior Damage [Emergency Opening] Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Sridge Rehabilitation ADA - Pedestrian Infrastructure Pavement Rehabilitation ADA - Pedestrian Infrastructure Maior Damage (Emergency Opening) Storm Water Mitigation Iransportation Management (TMC's & Field Equipment) Pavement Preservation (CAPM)	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Lune mile(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Location(s) Acre(s) treated/pollutant Field element(s) Lane mile(s)	6 8 8 24 15.6 9.5 10.8 533 10.8 16 16 17 18 18 19 19 19 19 19 11 19 11 14.9
11 12 12 12 12 12 12 12 12 12	1203 1204 1205 1205 1207 2208A 2209A 2246A 2246A 2246B 2255 2257 2279 2279 2279 2279 2285 2293 2300 2322B 2330A 2330A	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte. Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Dohenv Park CS, Gap Closure 12-0Q990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P890 12-0H151 CAPM Combined with ADA EA 0P890 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P691 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P691 Rte 01 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M870 Laguna Beach Route 1 @ Cress St. Modify Signals & ADA 12-0M980 PCH/Broadway Culvert Bridge 12-0M88C Rte 001 Uparade to ADA Standards & CAPM 12-0U160 Rte. 1 PCH Slope Embankment Repair 12-0P680 Upgrade Traffic Signal 12-0P680 Upgrade Traffic Signals, Resurface Lanes, ADA 12-0P68U, Rte 1, Uparade Traffic Signals, Resurface Lanes, ADA	Equipment1 Bridge Preventative Maintenance Maior Damage (Emergency Opening) Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Rehabilitation ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrion Infrastructure Pavement Rehabilitation Safety Improvements Bridge Rehabilitation ADA - Pedestrion Infrastructure Maior Damage (Emergency Opening) Storm Water Mitigation Transportation Management (TMC's & Field Equipment) Pavement Preservation (CAPM) Transportation Management Systems	Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lane mile(s) Location(s) Acre(s) Ireated/loollutant Field element(s) Field element(s)	6 8 8 24 15.6 9.5 10.8 53 10.8 16.8 16.8 17.9 19.9 19.9 19.9 14.9 19.9 19.9 19.9 19
11 12 12 12 12 12 12 12 12 12 12 12 12 1	1203 1204 1205 1207 1208A 2209A 2246A 2246A 2246B 2255 2257 2279 2279 2279 2279 2285 2293 2300 2320A 2330A	12-0Q690 detection system rehab. 12-0Q930 Bridge Project on Route 5 and 133 12-0S350, Rte VAR, PSPS Retro-reflective Traffic Signal Head 12-0V200 Rte, Var, Security Measures at Maintenance Stations 12-0S750 Rte 1 Doheny Park CS Gap Closure 12-0G990 PCH SB-1 Multi Asset Project 12-0H150 PCH Laguna Beach Rehabilitate Pavement & ADA uparades 12-0H151 CAPM combined with ADA EA 0P690 12-0H53 CAPM Combined with ADA EA 0P690 12-0P690 PCH Laguna Beach Uparade ADA 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0P690 Rte 1 Uparade ADA curb ramps, widen sidewalk 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M82U Rte 001 Uparade to ADA Standards & CAPM 12-0M990 PCH/Broadway Culvert Bridge 12-0M62C Rte 001 Uparade to ADA Standards & CAPM 12-0M160 Rte, I PCH Slope Embankment Repair 12-0P660 Rt 1 Stabilize bioswales 12-0P68U Upgrade Traffic Signal	Equipment1 Stidge Preventative Maintenance Maior Damage [Emergency Opening] Maintenance Facilities ADA - New Curb Ramps Roadside Safety Improvements Pavement Preservation (CAPM) Pavement Rehabilitation Pavement Rehabilitation Pavement Rehabilitation ADA - New Curb Ramps ADA - New Curb Ramps Pavement Preservation (CAPM) ADA - Pedestrian Infrastructure Pavement Rehabilitation Safety Improvements Sridge Rehabilitation ADA - Pedestrian Infrastructure Pavement Rehabilitation ADA - Pedestrian Infrastructure Maior Damage (Emergency Opening) Storm Water Mitigation Iransportation Management (TMC's & Field Equipment) Pavement Preservation (CAPM)	Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Lone mile(s) Lane mile(s) Lane mile(s) Curb ramp(s) Lune mile(s) Curb ramp(s) Lane mile(s) Curb ramp(s) Location(s) Acre(s) treated/pollutant Field element(s) Lane mile(s)	6 8 24 15,6,6 9,5,5 10.8 53 9,5,5 83 10,8 16 1 1 9

12 2403A	T			
	12-0N930 PCH Clean and Rehab RCB 12-0Q830 PCH at Superior & at Beach Upgrade signals & ADA	Drainage System Restoration Safety Improvements	Culvert(s) (ea) Collision(s) reduced	14
12 2403B 12 2470A	12-0Q830 PCH at Superior & at Beach upgrade signals & ADA 12-0Q280 PCH Install Outer Seperation Barrier	Safety Improvements Safety Improvements	Collision(s) reduced	
12 2499A	12-0P590 Resurface 14.9 Iane miles	Pavement Rehabilitation	Lane mile(s)	14.
12 2527	12-0N850 PCH Modify Signal, Safety lighting	Safety Improvements	Collision(s) reduced	4
12 2530N	12-0R200 Interstate 5 Pavement Rehabilitation Project	Roadway Rehabilitation (2R)	Lane mile(s)	12.
12 2531H 12 2563	12-0R970 I-5 Multi Asset Project 12-0P700 Rt 5, Drainage restoration Segunda Deshecha Channel	Pavement Preservation (CAPM) Drainage System Restoration	Lane mile(s) Culvert(s) (ea)	21.
12 2564B	12-08170 Rte. 5 Safety Project. median barrier & safety light, upgrade	Safety Improvements	Collision(s) reduced	11
12 2590A	12-0S051, Rte 5, Multi Asset from I-405 to Yale Ave. OC	Pavement Preservation (CAPM)	Lane mile(s)	51.:
12 2590B	12-0S052, Rte5, Multi Asset Project from Yale Ave OC to SR55	Pavement Preservation (CAPM)	Lane mile(s)	55.
12 2591	12-0R670 SR 55 Add Safety Lighting, Barrier & Striping	Safety Improvements	Collision(s) reduced	60.
12 2603	Rte 5, Slope Stabilization	Major Damage (Emergency Opening)	Location(s)	
12 2613 12 2627	12-0T280 Rte.I-5 Multi Asset Maintenance Facility 12-0S280 I-5 Safety Project at SR -74 SB off ramp.	Maintenance Facilities Safety Improvements	Location(s) Collision(s) reduced	47
12 2632A	12-0P090 Rt 5/133 Install Stormwater Control Items	Storm Water Mitigation	Acre(s)	
		-	treated/pollutant	
12 2676A	12-0S380, Rte 5, RT 74 to RT 405 Multi-Asset Project	Pavement Preservation (CAPM)	Lane mile(s)	136.4
12 2750	12-0T950, Rte 5, I-5 HOV Operational Improvements	Operational Improvements	Daily vehicle hour(s) of	400
12 2753B	12-0H028 Rt 5 CCTV, fiber opt. upgrade	Transportation Management (TMC's & Field	delav (DVHD) Field element(s)	
12 27 335	12 01020 KI 3 CC17, libel opt. opgrade	Equipment)	ricia cierricin(s)	•
12 2786	12-0S100 Rte 5, Safety Project	Safety Improvements	Collision(s) reduced	10
12 2819	12-0S310 Rte. 5 Safety Project	Safety Improvements	Collision(s) reduced	1
12 2823	12-0R470 Rt 5 Safety Lighting Project at Redhill	Safety Improvements	Collision(s) reduced	1.
12 2833C 12 2833C	Interstate 5 (I-5) Managed Lanes Multimodal Operational Improvements. Interstate 5 (I-5) Managed Lanes Multimodal Operational Improvements.	HOV/HOT mainline constructed Operational Improvements	Miles Daily vehicle hour(s) of	725
12 20000	intersiale 3 (1-3) Managea Earles Monthhodar Operational Improvements.	Operational improvements	delay (DVHD)	7230
12 2834A	12-0Q820 I-5 HFST, delineation, loop detectors and safety devices	Safety Improvements	Collision(s) reduced	16
12 2834B	12-0S500, Rte 5, Multi Asset Project 55 to LA County	Roadway Rehabilitation (3R)	Lane mile(s)	150.9
12 2839	Directors Orders - Concrete Curtain Wall Panel	Major Damage (Emergency Opening)	Location(s)	
12 2841 12 2859B	12-0N510 Rt 5 Roadside Worker Safety Project 12-0P42U I-5, SR57, & SR 91 ICM123 Project combined with ICM 1,2, & 3	Roadside Safety Improvements Transportation Management Systems	Location(s) Field element(s)	30 20
12 2859B 12 2859C	12-0P420 1-5, SR57, & SR 91 ICM123 Project combined with ICM 1,2, & 3 12-0P671 Integrated Corridor Mamt on 3 State Route	Transportation Management Systems Transportation Management Systems	Field element(s)	204
12 2859D	12-0P672 Integrated Corridor Mgmt on 3 State Route	Transportation Management (TMC's & Field	Field element(s)	468
		Equipment)	.,	
12 2860F	12-0R750, Rte 5, Safety Traffic Control Device Modification	Safety Improvements	Collision(s) reduced	7
12 2860N	12-0P900 Rte 5 Roadside Worker Safety Project	Roadside Safety Improvements	Location(s) Collision(s) reduced	40
12 2860P	12-0Q850 I-5 Polyester concrete on 3 bridges 12-0R510 I-5 Safety Project - Cold plane, place RHMA & HSFT	Safety Improvements		102
12 2860U 12 2860V	12-0K510 1-5 Safety Project - Cold plane, place RHMA & HSFI 12-0S690 Rte.5 Pavement Delineation Modifications	Safety Improvements Safety Improvements	Collision(s) reduced Collision(s) reduced	35
12 2860Z	12-0S840, NB I-5 On-ramp at Anaheim Blvd Intersect	Safety Improvements	Annual fatal and serious	0.03
			injury collision(s)	
12 2861E	12-0P910 Rte 5 Roadside Worker Safety Project	Roadside Safety Improvements	Location(s)	40
12 2861F 12 2861Z	12-0Q300 Rt 5 Harbor BI. Surface treatment 12-0P920 Rt 5 Roadside Worker Safety Project	Safety Improvements Roadside Safety Improvements	Collision(s) reduced Location(s)	38
12 2862G	12-05390 Rte. 5 Apply HFST at NB off-ramp to Magnolia St.	Safety Improvements	Collision(s) reduced	14
12 2862H	12-0P930 Rte 5 Roadside Worker Safety Project	Roadside Safety Improvements		80
12 2862L	Rte 5, D.O. Joint Seal Assembly Unit Failures	Major Damage (Emergency Opening)	Location(s)	
12 2862N	12-0S320, Rte 5, Orangethorpe Overcrossing/Overhead Bridge	Major Damage (Emergency Opening)	Location(s)	
12 2862O	12-0S710 Rte 5 Orangethorpe Bridge Repairs	Major Damage (Emergency Opening)	Location(s)	
12 2862P 12 2869B	12-0T850 Rte, I-5 Bridge Repairs 12-0S110 Rte,22 Safety Lighting Project	Major Damage (Emergency Opening) Safety Improvements	Location(s) Collision(s) reduced	513
12 2870A	12-01020, Rte 22, Extend and Add Aux Lane at Valley View Off	Safety Improvements	Annual fatal and serious injury collision(s)	0.14
12 2873B	12-0Q650 WB Rte 22 Valley View Off-Ramp Signal, lighting and ADA	Safety Improvements	Collision(s) reduced	28
12 2916	12-0R290, Rte 22, HFST and Safety Devices Project	Safety Improvements	Collision(s) reduced	13
12 2930	12-0P980 WB Rte 22 Euclid onramp.OGAC,drainage,delineat'n,ADA	Safety Improvements	Collision(s) reduced	12
12 2947	12-0S700, Rte 22, Apply HFST GG/Haster	Safety Improvements	Annual fatal and serious injury collision(s)	0.18
12 2948 12 2962	12-0N920 WB Rte 22 Haster Off - Uparade Drainage 12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp	Drainage System Restoration Safety Improvements	Culvert(s) (ea) Annual fatal and serious injury collision(s)	0.38
12 2962	12-05520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp	Safety Improvements	Annual fatal and serious injury collision(s)	0.33
12 2962 12 2970A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0Q320 Rte 22 Safety Lighting	Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced	0.33
12 2962 12 2970A 12 2977	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0Q320 Rte 22 Safety Lighting 12-0S190 WB Rte. 22 Safety Improvement	Safety Improvements Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced	0.35 120 156
12 2962 12 2970A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0Q320 Rte 22 Safety Lighting	Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s)	0.33
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte 22 Safety Lightina 12-0S520 Rte 22 Safety Limprovement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22, Mointenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s)	0.38 120 150 30
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte 22 Safety Lighting 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22, Maintenance Facility & TMS 12-0G980 SR 241 S8-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage [Emergency Openina]	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s)	0.38 120 156 36
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0Q320 Rte 22 Safety Lighting 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22, Maintenance Facility & TMS 12-0Q980 SR 241 SB-1 Bridae, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify signals, add safety, ADA & refresh striping.	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Maior Damage (Emeraency Opening) Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced	0.38 120 156 36 13
12 2970A 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22, Mointenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify signals, add safety, ADA & refresh striping. 12-0T180, Rte 39, Modify Traffic Signals	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s)	0.39 120 156 36 10 2 14 0.19
12 2970A 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S908 Rte 22, Maintenance Facility & TNS 12-0G980 SR 241 SR-1 Bridges TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify signals, add safety, ADA & refresh striping. 12-0T140, Rte 39, Modify Traffic Signals	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s)	0.33 122 155 36 11 2 14 0.15
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22, Maintenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-01290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 Rs 39790 Modify signals, acid safety, ADA & refresh striping. 12-0T160, Rte 39, Modify Traffic Signals 12-0Q440 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinguishment	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage [Emercency Opening) Safety Improvements Safety Improvements Safety Improvements Relinquishments	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s)	0.3 12: 15: 3: 1: 14 0.1:
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 12 3302A 12 3302A 12 3302A	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22, Maintenance Facility & TMS 12-0G980 SP. 241 SB-1 Bridge, TMS & Roadside 12-01290 Rte., 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Traffic Signals 12-0G440 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced	0.33 120 15: 34 0.13 14 0.13 3 1.3 3
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 12 3202A 12 3202A 12 3309A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0S320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S980 Rte 22. Maintenance Facility & TMS 12-0S980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T990 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0T9010 SR 39/90 Modify signals, add safety, ADA & refresh stripina. 12-0T160, Rte 39, Modify Traffic Signals 12-0Q400 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R740 Rte 39 Signal modification, Ped. Lighting, and Traffic Census 12-0P740 Rte 39 Signal modification, Ped. Lighting, and Traffic Census	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Collision(s) reduced	0,3 12 15, 3, 11, 14 0,1, 3 1,; 3
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 12 3202A 12 3202A 12 32307 12 32307	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22 & Mointenance Facility & IMS 12-0G980 SR 241 SB-1 Birdae, IMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR 39790 Modify sianals, add safety, ADA & refresh striping, 12-0T160, Rte 39, Modify Traffic Signals 12-0G40 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinausishment 12-0R740 Rte 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R570 SR-39 Drainage and ADA	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM)	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced	0.3 12 15 3 1: 14 0.1: 3 1. 3 1. 55 55 55
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 12 3202A 12 3202A 12 3309A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0S320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S980 Rte 22. Maintenance Facility & TMS 12-0S980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T990 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0T9010 SR 39/90 Modify signals, add safety, ADA & refresh stripina. 12-0T160, Rte 39, Modify Traffic Signals 12-0Q400 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R740 Rte 39 Signal modification, Ped. Lighting, and Traffic Census 12-0P740 Rte 39 Signal modification, Ped. Lighting, and Traffic Census	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Malor Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinguishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centertine mile(s) Collision(s) reduced Culvert(s) reduced	0.38 120 156 36 13
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3202A 12 3307 12 32307 12 32307 12 32307 12 3402B 12 3402B	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Lightina 12-0P520 Rte 22 & Rte 57 Install Safety Lighting 12-0P520 Rte 22 & Rte 57 Install Safety Lighting 12-0S980 Rte 22, Mointenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR 39/90 Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte 39, Modify Traffic Signals 12-0G440 SR 39 Signals, safety Lighting, crosswalk 12-0R400 SR 39 Relinauishment 12-0R740 Rte 39 Signal modification, Ped, Lighting, and Traffic Census 12-0R740 Rte 39 Signal powement and drainage upgrades 12-0G290 Signal Modification 12-0R320 Rte 55 Multi-Asset Project 12-0R520 Rte 55 multi-Asset Project 12-0R520 Rte 55 multi-Asset Project	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced	0.33 122 1554 1554 161 17 11 14 14 1.13 1.14 1.15 1.15 1.15 1.15 1.15 1.15 1.15
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 13 3007 12 3230A 12 3237 12 34078 12 34078 12 34078	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0G320 Rte. 22 Safety Lightina 12-0F320 Rte. 22 Safety Improvement 12-0F320 Rte. 23 Sinkhole Repair & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0F1010 SR 39/90 Modify signals, add safety, ADA & refresh stripina. 12-0T160, Rte. 39, Modify Traffic Signals 12-0R400 SR 39 Relinquishment 12-0R400 SR 39 Relinquishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0F370 SR-39 Drainage and ADA 12-0R360 SR 39 Class II pavement and drainage upgrades 12-0R320 Rte. 55 Multi-Asset Project 12-0R320 Rte. 55 Multi-Asset Project 12-0R300 Rt. 55 dr. Hospital Rd. Safety Lighting & Signals 12-0Q490 St. 55 dr. Hospital Rd. Safety Lighting & Signals	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Maior Damage (Emeraency Opening) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced	0.3 12 15b 15b 3 3 1. 14 0.1. 3 3 1. 1. 5 5 5 2 2 686
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3202A 12 3207 12 32301 12 3279 12 34028 12 3407A 12 3450A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22 & Rte 57 Install Safety Lighting 12-0S080 Rte 22 & Rte 57 Install Safety Lighting 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR 39790 Modify sianals, add safety, ADA & refresh striping, 12-0T160, Rte 39, Modify Traffic Signals 12-0G40 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinausishment 12-0R740 Rte 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R570 SR-39 Drainage and ADA 12-0R340 SR 39 Class II powement and drainage upgrades 12-0R290 Signal Modification 12-0R350 Rt 55 Multi-Asset Project 12-0R500 Rt 55 at Hospital Rd. Safety Lighting & Signals 12-0Q840 In Costa Mesa on SB SR-55 Modify End of Freeway Signs	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Centertine mile(s) Collision(s) reduced Culver(s) reduced Culver(s) reduced Culver(s) reduced Culver(s) reduced Culsion(s) reduced Collision(s) reduced	0.3 122 155 157 144 0.1: 3 3 1.1: 2.2 2.6 68.1 44
12 2962 12 2970A 12 2981 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 12 3302A 12 3302A 12 3307 12 3237 12 3237 12 3424A 12 3458A	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0G320 WB Rte. 22 Safety Limprovement 12-0F520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0G980 SR 241 SR-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Traffic Signals 12-0G440 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R408 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0F70 SR-39 Drainage and ADA 12-0R360 SR 39 Class II pavement and drainage upgrades 12-0G290 Signal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R300 Rt. 55 at Hospital Rd. Safety Lighting & Signals 12-0G440 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G390 Bridge Seismic Restoration	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Bridge Seismic Restoration Roadway Rehabilitation	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lollision(s) reduced Lollision(s) reduced Collision(s) reduced Collision(s) reduced Bridae(s) Lane mile(s)	0.3 121 151 3.3 11 14 0.1: 3.3 1.1 55.6 68.68.1 4.4
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3300A 12 3307 12 3277 12 3474 12 3450A 12 3450A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F520 Rte 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 Maintenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repoir & Culvert Pipe Replacement 12-0P10 SR. 39790 Modify sianals, acid safety, ADA & refresh stripina. 12-0T160, Rte. 39, Modify Traffic Signals 12-0G440 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R740 Rte. 39 Sianal modification, Ped. Lighting, and Traffic Census 12-0R300 SR 39 Class Il pavement and drainage upgrades 12-0R300 SR 39 Class Il pavement and drainage upgrades 12-0R290 Sianal Modification 12-0R300 Rt 55 at Hospital Rt. Safety Lighting & Signals 12-0Q390 Bridge Seismic Restoration 12-0Q390 Bridge Seismic Restoration 12-0Q460 SR 55 to SR 405 connector, Replace Slab	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Malor Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainae System Restoration Pavement Preservation (CAPM) Safety Improvements Safety Improvements Drainae System Restoration Pavement Preservation (CAPM) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridae Seismic Restoration Roadway Rehabilitation Auxiliary Inancostructed	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Cutvert(s) feat Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Bridae(s) Lane mile(s) Lane mile(s)	0.3 122 155 156 3 3 11 14 0.1 3 3 11 15 5 5 6 6 8 1 4 4 0 0
12 2962 12 2970A 12 2981 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 13 302A 12 3302A 12 3302A 12 3302A 12 3327 12 3302A 12 3424A 12 3452A 12 3458A 12 3474 12 3474	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lighting 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22. Maintenance Facility & TMS 12-0G980 St. 241 SB-1 Bridge. TMS & Roadside 12-01290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90. Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Traffic Signals 12-0Q640 SR 39, Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R400 SR 39 Relinquishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0P30 SR-39 Drainage and ADA 12-0R300 SR 39 Class II powement and drainage upgrades 12-0Q290 Signal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R320 Rte. 55 at Hospital Rd. Safety Lighting & Signals 12-0Q340 In Costa Meso an SB SR-55 Modify End of Freeway Signs 12-0Q390 Bridge Seismic Restoration 12-0G390 Bridge Seismic Restoration 12-0G390 Bridge Seismic Restoration 12-0G340 SB 55 to SB 405 connector, Replace Slab 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Padement Preservation (CAPM) Safety Improvements Bridae Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed HOV/HOT mainline constructed	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lollision(s) reduced Lollision(s) reduced Collision(s) reduced Collision(s) reduced Bridae(s) Lane mile(s)	0.3 121 155 3.3 1: 14 0.1: 3.3 1.1: 55.6 68: 44 40 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 13 3182 12 3202A 12 33207 12 32307 12 32307 12 32307 12 32404 12 3450A 12 3450A 12 3458A 12 3474	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0F520 Rte. 22 Safety Lightina 12-0F520 Rte. 22 Safety Improvement 12-0F520 Rte. 23 Sinkhole Repair & Culvert Pipe Replacement 12-0G980 SR. 24 I SB-1 Bridge, TMS. 8 Roadside 12-0T90 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR. 39/90 Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Traffic Signals 12-0G440 SR. 39 Signals, safety lighting, crosswalk 12-0G440 SR. 39 Signals, safety lighting, crosswalk 12-0R400 SR. 39 Relinguishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R340 SR. 39 Class II povement and drainage upgrades 12-0G290 Signal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R350 Rt. 55 Multi-Asset Project 12-0G340 In Costa Mesa on SB. SR-55 Modify End of Freeway Signs 12-0G460 SB. 55 to SB. 405 connector, Replace Slab 12-0J340 Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emercency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Redge Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s)	0.3 12 15:5 3:1 14 0.1 3:1 1. 55:6 68. 1 4 0.0 0.0 4. 5.
12 2962 12 2970A 12 2981 12 2981 12 2982 12 3102A 12 3167 12 3172A 12 3182 13 302A 12 3302A 12 3302A 12 3302A 12 3327 12 3302A 12 3424A 12 3452A 12 3458A 12 3474 12 3474	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lighting 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22. Maintenance Facility & TMS 12-0G980 St. 241 SB-1 Bridge. TMS & Roadside 12-01290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90. Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Traffic Signals 12-0Q640 SR 39, Signals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R400 SR 39 Relinquishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0P30 SR-39 Drainage and ADA 12-0R300 SR 39 Class II powement and drainage upgrades 12-0Q290 Signal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R320 Rte. 55 at Hospital Rd. Safety Lighting & Signals 12-0Q340 In Costa Meso an SB SR-55 Modify End of Freeway Signs 12-0Q390 Bridge Seismic Restoration 12-0G390 Bridge Seismic Restoration 12-0G390 Bridge Seismic Restoration 12-0G340 SB 55 to SB 405 connector, Replace Slab 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridage Rehabilitation and Replacement Malor Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Safety Improvements Bridage Seismic Restoration Roadway Rehabilitation Auxiliary Inanconstructed HOV/HOT mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerfine mile(s) Collision(s) reduced Culvert(s) lead Lane mile(s) Collision(s) reduced Culvert(s) fead Lane mile(s) Collision(s) reduced Culvert(s) fead Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Bridae(s) Lane mile(s) Lane mile(s) Collision(s) reduced Bridae(s) Lane mile(s) Lane mile(s) Lane mile(s) Velice Hour(s) of delay (DVHD) Daily Vehicle Hour(s) of	0.3 12 15 3 1 14 0.1 3 3 1, 15 5.5 2 4 4 4 0.0 0.4 4 5,5 7 115
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 13 3182 13 3202A 12 3207 12 3230A 12 33237 12 3279 12 3402B 12 3450A 12 3450A 12 3474 12 3474 12 3474	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0F520 Rte. 22 Safety Lightina 12-0F520 Rte. 22 Safety Improvement 12-0F520 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0G980 SR. 241 SB-1 Bridge, TMS. & Roadside 12-0T180, Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR. 39 Syn Modify Israffic Signals 12-0T180, Rte. 39, Modify Israffic Signals 12-0G440 SR. 39 Signals, safety lighting, crosswalk 12-0R400 SR. 39 Signals, safety lighting, crosswalk 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R340 SR. 39 Class II povement and drainage upgrades 12-0G290 Signal Modification 12-0G290 Signal Modification 12-0G290 Signal Modification 12-0G240 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G340 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G460 SB 55 to SB 405 connector, Replace Slab 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emercency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Bridge Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed HOV/HOT mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Cutertine mile(s) Collision(s) reduced Cutertine mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Miles Miles Miles Miles Miles Daily vehicle hour(s) of Delay (IDVHD) Daily Vehicle Hour(s) of	0.3 12 15 15 3 1 14 0.1 3 1. 3 1 1 4 4 0.1 15 55. 2 4 4 4 11 115
12 2962 12 2970A 12 2981 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3202A 12 3302 12 3302 12 3302 12 3307 12 3230A 12 3230A 12 3424A 12 3450A 12 3474 12 3474 12 3474 12 3474	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22, Maintenance Facility & TMS 12-0G980 St. 241 SB-1 Bridge. TMS & Roadside 12-01290 Rte., 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify sianals, add safety, ADA & refresh stripina, 12-0R160, Rte. 39, Modify Traffic Signals 12-0Q480 SR 39 Sianals, safety lighting, crosswalk 12-0R400 SR 39 Relinquishment 12-0R40 SR 39 Sianals, safety lighting, crosswalk 12-0R400 SR 39 Class II pavement 12-0R306 SR 39 Class II pavement and drainage upgrades 12-0G290 Sianal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R300 Rt. 55 at Hospital Rd. Safety Lighting & Signals 12-0G390 Bridge Seismic Restoration 12-0G390 Bridge Seismic Restoration 12-0G390 Bridge Seismic Restoration 12-0G340 Rt. 55 Sc. 56 Sc.	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Maior Damage (Emercency Opening) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Bridae Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed HOV/HOT mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Dunced Collision(s) reduced Collision(s) reduced Ridae(s) Miles Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced	0.3 12 15 3 1 1 14 0.1 3 1, 1, 55 68, 44 0.0 44, 45 115
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3202A 12 3207 12 32301 12 3307 12 3237 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474 12 3474	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 Maintenance Facility & TMS 12-0G980 SR. 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR. 39790 Modify signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Traffic Signals 12-0G400 SR. 39 Signals, safety lighting, crosswalk 12-0R400 SR. 39 Relinguishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R790 SR-39 Drainage and ADA 12-0R340 SR. 39 Class II powement and drainage upgrades 12-0R290 Signal Modification 12-0R320 Rt. 55 Multi-Asset Project 12-0R500 Rt. 55 Multi-Asset Project 12-0R500 Rt. 55 Multi-Asset Project 12-0G460 SR. 55 to SR. 405 connector, Replace Slab 12-0Q460 SR. 55 to SR. 405 connector, Replace Slab 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0G950 Rte. 55 NB Aux lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Safety Improvements Bridge Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed Mixed flow mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Roadside Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Location(s)	0.3 12 15 15 3 3 1 14 0.1 3 3 1, 4 4 0.1 55 5.5 2 68,8 1 1 4 5.5 5.5 11 11 11 13
12 2962 12 2970A 12 2981 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3202A 12 3302 12 3302 12 3302 12 3307 12 3230A 12 3230A 12 3424A 12 3450A 12 3474 12 3474 12 3474 12 3474	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0C980 St. 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR 39/90 Modify Signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39 Singals, safety lighting, crosswalk 12-0R400 SR 39 Signals, safety lighting, crosswalk 12-0R400 SR 39 Signals safety lighting, crosswalk 12-0R400 SR 39 Signals modification, Ped. Lighting, and Traffic Census 12-0P770 SR-39 Drainage and ADA 12-0R340 SR 39 Class II powement and drainage upgrades 12-0Q290 Signal Modification 12-0R530 Rte. 55 Multi-Asset Project 12-0R540 Rt. 55 at Hospital Rd. Safety Lighting & Signals 12-0Q340 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0Q340 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0Q340 Rt. 55 Sconstruct additional HOV. GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV. GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Maior Damage (Emercency Opening) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Safety Improvements Pavement Preservation (CAPM) Safety Improvements Bridae Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed HOV/HOT mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Dunced Collision(s) reduced Collision(s) reduced Ridae(s) Miles Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced	0.3 12 155 3 1 14 0.1 3 3 1, 1, 3 1 1 4 4 11 5 5 5 7 1 11 11 13 3 3 3
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 13 3202A 12 3207 12 3230A 12 32307 12 32307 12 3230A 12 3474	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0F520 Rte. 22 Safety Lightina 12-0F520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0F520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0G980 Rte. 22 Mointenance Facility & TMS 12-0G980 SR. 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR. 39/PO. Modify signals, add safety, ADA & refresh striping, 12-0T180, Rte. 39, Modify Traffic Signals 12-0T180, Rte. 39, Modify Traffic Signals 12-0G440 SR. 39 Signals, safety lighting, crosswalk 12-0R400 SR. 39 Signals, safety lighting, crosswalk 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R340 SR. 39 Class II pavement and drainage upgrades 12-0G290 Signal Modification 12-0R340 Rt. 55 Multi-Asset Project 12-0R340 Rt. 55 Multi-Asset Project 12-0G460 SR. 55 to SR. 40S connector, Replace Slab 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J340 Rte. 0SS Construct additional HOV, GP and Aux Lane 12-0J3530 Rt. 55 Roadside Worker Safety Project 12-0NS30 Rt. 55 Roadside Worker Safety Project 12-0R370, Rte. 57 Multi-Asset Project, Bridge Health anchor. 12-0S330 Rt. 55 Roadside Worker Safety Project 12-0R370, Rte. 57 Add inshing a replace pavement delineation	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridage Rehabilitation and Replacement Maior Damage (Emergency Openina) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Bridage Seismic Restoration Roadway Rehabilitation Auxiliary lane constructed HOV/HOT mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Safety Improvements Safety Improvements	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Cutvert(s) (ea) Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s)	0.3 12 15 3 1. 14 0.1 3. 1. 55. 2 68. 1 0. 5, 7, 7, 115 115 115
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3202A 12 3307 12 3202A 12 3307 12 3230A 12 3237 12 3424A 12 3450A 12 3474 12 3535 12 3542A 12 3636B 12 3747B	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0G190 WB Rte. 22 Safety Improvement 12-0F520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0G80 Rte. 22 & Rote St. Install Safety Lighting 12-0G80 Rte. 23 Sinkhole Repair & Culvert Pipe Replacement 12-0G10 SR. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0F10 SR. 39/90 Modify Signals, add safety, ADA & refresh striping. 12-0G440 SR. 39 Signals, safety lighting, crosswalk 12-0R400 SR. 39 Signals, safety lighting, ped Lighting, and Traffic Census 12-0R308 SR. 39 Class II pavement and drainage upgrades 12-0R300 Rt. 39 Signals Modification 12-0R300 Rt. 55 at Hospital Rd. Safety Lighting & Signals 12-0Q340 In Costa Mesa on SB SR. 55 Modify End of Freeway Signs 12-0Q340 In Costa Mesa on SB SR. 55 Modify End of Freeway Signs 12-0Q340 Ridge Seismic Restoration 12-0R340 Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridage Rehabilitation and Replacement Maior Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Safety Improvements Bridage Seismic Restoration Roadway Rehabilitation Auxiliary Iane constructed HOV/HOT mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Safety Improvements Roadside Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Safety Improvements Bridage Preventative Maintenance	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Lane mile(s) Miles Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Daily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Bridae(s) Collision(s) reduced Bridae(s)	0.3 12 15 3 1. 14 0.1 3. 1. 55. 2 68. 1 0. 5, 7, 7, 115 115 115
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3202A 12 3207 12 32301 12 3307 12 3237 12 3474 12 3542A 12 3542A 12 3542A 12 3759A	12-0S520 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 Safety Lighting 12-0S080 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0G290 SR. 241 SB-1 Bridge, TMS & Roadside 12-0T160, Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P10 SR. 39 Signals, safety lighting, crosswalk 12-0T160, Rte. 39, Modify Traffic Signals 12-0R400 SR. 39 Signals, safety lighting, crosswalk 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0P70 SR. 39 Drainage and ABA 12-0R360 SR. 39 Class il powement and drainage upgrades 12-0R390 SR 39 Class il powement and drainage upgrades 12-0R390 SR 55 at Hospital Rd. Safety Lighting & Signals 12-0R390 SR 55 at Hospital Rd. Safety Lighting & Signals 12-0R400 SR 55 SMUIt-Saset Project 12-0R390 Bridge Seismic Restoration 12-0G460 SR 55 to SR 405 connector, Replace Slab 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 0S5 Construct additional HOV, GP and Aux Lane 12-0J350 Rte. 55 NB Aux lane 12-0R370, Rte. 57 Natli-Saset Project 12-0R50 SR 55 St. Add lighting & Sprace St. Bridge Health anchor, 12-0R370, Rte. 57 Add lighting & replace powement delineation 12-0T120 Deck Spail repairs and polyester concrete overlay Director Order - Overhead Sign Structive	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridge Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Safety Improvements Safety Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridge Rehabilitation and Replacement Safety Improvements Bridge Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Curvert(s) reduced Culvert(s) reduced Culvert(s) reduced Cultision(s) reduced Collision(s)	0.3 122 155 3.3 11: 144 0.1. 3.3 3.1: 555.2 2.0 4.4 4.5 155 1155 1155 1155 1151 1151 11
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3202A 12 3307 12 32307 12 32307 12 32307 12 3240A 12 3450A 12 3474 12 3474 12 3483 12 3510 12 3512 12 3528 12 35474 12 33474 12 3483 12 3510 12 3535 12 3542A 12 33584 12 337478 12 33748 12 33748 12 33748 12 33748 12 33759A 12 3759A	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Lightina 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0G980 Rte. 22, Mointenance Facility & TMS 12-0G980 St. 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR. 39/90 Modify Signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Iraffic Signals 12-0G440 SR. 39 Signals, safety Lighting, crosswalk 12-0R400 SR. 39 Signals, safety Lighting, crosswalk 12-0R400 SR. 39 Signals, safety Lighting, crosswalk 12-0R400 SR. 39 Pelinauishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R308 SR. 39 Class II powement and drainage upgrades 12-0G290 Signal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R300 Rt. 55 at Hospital Rd. Safety Lighting & Signals 12-0G290 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G290 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G290 Signal Rd. Safety Lighting & Signals 12-0G460 SB 55 to SB 405 connector, Replace Slab 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J350 Rt. 55 Roadside Worker Safety Project 12-0R350 Rt. 55 Roadside Worker Safety Project 12-0R350 Rt. 55 Roadside Worker Safety Project 12-0R370, Rte. 57, Multi-Asset Project, Bridge Health anchor. 12-0R370, Rte. 57, Multi-Asset Project, Bridge Health anchor. 12-0R370, Rte. 57, Multi-Asset Project, Bridge Health anchor. 12-0C450 Cord Responsed Langer	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridage Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Bridage Seismic Restoration Roadway Rehabilitation Auxiliary Ione constructed Mixed flow mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Safety Improvements Bridage Rehabilitation and Replacement Safety Improvements Bridage Preventative Maintenance Major Damage (Emergency Opening)	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Miles Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Doily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Bridae(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	0.38 12(1) 15: 15: 11 14 0.18 3 3 1 15: 22 28: 68:8.
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3302A 12 3307 12 3307 12 3207 12 3307 12 3307 12 3474 12 3479 12 3759A 12 3759A	12-0S320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0S320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F320 Rte 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Maintenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repoir & Culvert Pipe Replacement 12-0P10 SR 39790 Modify sianals, acid safety, ADA & refresh stripina. 12-0T160, Rte. 39, Modify Traffic Signals 12-0T160, Rte. 39, Modify Traffic Signals 12-0R400 SR 39 Relinauishment 12-0R740 Rte. 39 Sianals, safety lighting, crosswalk 12-0R340 SR 39 Class Il pavement and drainage upgrades 12-0R340 SR 39 Class Il pavement and drainage upgrades 12-0R340 SR 39 Class Il pavement and drainage upgrades 12-0R340 Rte. 55 Multi-Asset Project 12-0R500 Rt. 55 Mth. Asset Project 12-0R500 Rt. 55 Mth. Asset Project 12-0R340 Bridge Seismic Restoration 12-0Q340 Bridge Seismic Restoration 12-0Q340 Bridge Seismic Restoration 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Malor Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Brades Seismic Restoration Roadway Rehabilitation Auxiliary Iana Constructed HOV/HOT mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Roadside Safety Improvements Safety Improvements Safety Improvements Safety Improvements Roadside Rehabilitation and Replacement Safety Improvements Bridae Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridae(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Centertine mile(s) Collision(s) reduced Cutvert(s) (ea) Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Collision(s) reduced Bridae(s) Lane mile(s) Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Doily Vehicle Hour(s) of delay (DVHD) Collision(s) reduced Location(s) reduced Location(s) reduced Location(s) reduced Location(s) reduced Location(s) Collision(s) reduced Location(s) Location(s) Location(s) Location(s) Location(s) Location(s)	0.3 122 155 3.3 11 14 0.1. 3.3 1.1: 555 688. 1.1 4.4 4.5 55.5 1.1 115.5
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3202A 12 3307 12 32307 12 32307 12 32307 12 3240A 12 3450A 12 3474 12 3474 12 3483 12 3510 12 3512 12 3528 12 35474 12 33474 12 3483 12 3510 12 3535 12 3542A 12 33584 12 337478 12 33748 12 33748 12 33748 12 33748 12 33759A 12 3759A	12-0G320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0G320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Lightina 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0P520 Rte. 22 & Rte. 57 Install Safety Lighting 12-0G980 Rte. 22, Mointenance Facility & TMS 12-0G980 St. 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repair & Culvert Pipe Replacement 12-0P010 SR. 39/90 Modify Signals, add safety, ADA & refresh striping. 12-0T160, Rte. 39, Modify Iraffic Signals 12-0G440 SR. 39 Signals, safety Lighting, crosswalk 12-0R400 SR. 39 Signals, safety Lighting, crosswalk 12-0R400 SR. 39 Signals, safety Lighting, crosswalk 12-0R400 SR. 39 Pelinauishment 12-0R740 Rte. 39 Signal modification, Ped. Lighting, and Traffic Census 12-0R308 SR. 39 Class II powement and drainage upgrades 12-0G290 Signal Modification 12-0R320 Rte. 55 Multi-Asset Project 12-0R300 Rt. 55 at Hospital Rd. Safety Lighting & Signals 12-0G290 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G290 In Costa Mesa on SB SR-55 Modify End of Freeway Signs 12-0G290 Signal Rd. Safety Lighting & Signals 12-0G460 SB 55 to SB 405 connector, Replace Slab 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J350 Rt. 55 Roadside Worker Safety Project 12-0R350 Rt. 55 Roadside Worker Safety Project 12-0R350 Rt. 55 Roadside Worker Safety Project 12-0R370, Rte. 57, Multi-Asset Project, Bridge Health anchor. 12-0R370, Rte. 57, Multi-Asset Project, Bridge Health anchor. 12-0R370, Rte. 57, Multi-Asset Project, Bridge Health anchor. 12-0C450 Cord Responsed Langer	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridage Rehabilitation and Replacement Major Damage (Emergency Opening) Safety Improvements Safety Improvements Safety Improvements Relinauishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Bridage Seismic Restoration Roadway Rehabilitation Auxiliary Ione constructed Mixed flow mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Bridage Rehabilitation and Replacement Safety Improvements Bridage Rehabilitation and Replacement Safety Improvements Bridage Preventative Maintenance Major Damage (Emergency Opening)	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Location(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Centerline mile(s) Collision(s) reduced Culvert(s) (ea) Lane mile(s) Collision(s) reduced Lane mile(s) Collision(s) reduced Collision(s) reduced Lane mile(s) Miles Miles Miles Miles Miles Daily vehicle hour(s) of delay (DVHD) Doily Vehicle Hour(s) of Delay (DVHD) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Bridae(s) Location(s)	0.3 122 155 3.3 11: 144 0.1. 3.3 3.1: 555.2 2.0 4.4 4.5 155 1155 1155 1155 1151 1151 11
12 2962 12 2970A 12 2977 12 2981 12 2982 12 3102A 12 3105 12 3167 12 3172A 12 3182 12 3302A 12 3307 12 3307 12 3207 12 3307 12 3307 12 3474 12 3479 12 3759A 12 3759A	12-0S320 Rte. 22 Apply HSFT at WB La Veta Ave On-Ramp 12-0S320 Rte. 22 Safety Lightina 12-0S190 WB Rte. 22 Safety Improvement 12-0F320 Rte 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Rte. 57 Install Safety Lighting 12-0S080 Rte. 22 & Maintenance Facility & TMS 12-0G980 SR 241 SB-1 Bridge, TMS & Roadside 12-0T290 Rte. 39 Sinkhole Repoir & Culvert Pipe Replacement 12-0P10 SR 39790 Modify sianals, acid safety, ADA & refresh stripina. 12-0T160, Rte. 39, Modify Traffic Signals 12-0T160, Rte. 39, Modify Traffic Signals 12-0R400 SR 39 Relinauishment 12-0R740 Rte. 39 Sianals, safety lighting, crosswalk 12-0R340 SR 39 Class Il pavement and drainage upgrades 12-0R340 SR 39 Class Il pavement and drainage upgrades 12-0R340 SR 39 Class Il pavement and drainage upgrades 12-0R340 Rte. 55 Multi-Asset Project 12-0R500 Rt. 55 Mth. Asset Project 12-0R500 Rt. 55 Mth. Asset Project 12-0R340 Bridge Seismic Restoration 12-0Q340 Bridge Seismic Restoration 12-0Q340 Bridge Seismic Restoration 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane 12-0J34U Rte. 055 Construct additional HOV, GP and Aux Lane	Safety Improvements Safety Improvements Safety Improvements Safety Improvements Safety Improvements Transportation Management Systems Bridae Rehabilitation and Replacement Malor Damage (Emeraency Openina) Safety Improvements Safety Improvements Safety Improvements Relinquishments Safety Improvements Drainage System Restoration Pavement Preservation (CAPM) Safety Improvements Pavement Preservation (CAPM) Safety Improvements Brades Seismic Restoration Roadway Rehabilitation Auxiliary Iana Constructed HOV/HOT mainline constructed Mixed flow mainline constructed Operational Improvements Non-Capacity Increasing Operational Improvements Safety Improvements Roadside Safety Improvements Safety Improvements Safety Improvements Safety Improvements Roadside Rehabilitation and Replacement Safety Improvements Bridae Rehabilitation and Replacement	Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Collision(s) reduced Collision(s) reduced Field element(s) Bridge(s) Location(s) Collision(s) reduced Annual fatal and serious injury collision(s) Collision(s) reduced Collision(s) reduced Centertine mile(s) Collision(s) reduced Cutvert(s) (ea) Lane mile(s) Collision(s) reduced Cutvert(s) (ea) Lane mile(s) Collision(s) reduced Bridge(s) Lane mile(s) Miles Miles Miles Miles Miles Miles Collision(s) reduced Location(s) Collision(s) reduced Location(s) Collision(s) reduced Bridge(s) Collision(s) reduced Bridge(s) Collision(s) reduced Bridge(s) Location(s) Collision(s) reduced Bridge(s) Location(s) Location(s) Location(s) Location(s) Location(s)	0.3 122 155 3.3 11 14 0.1. 3.3 1.1: 555 688. 1.1 4.4 4.5 55.5 1.1 115.5

12 3846B	12-0Q270 Slope Stabilizing at Tonner Cyn	Storm Water Mitigation	Acre(s) treated/pollutant	29.
12 3959	12-0R560 VAR Connector Rehab project.	Pavement Preservation (CAPM)	Lane mile(s)	19.
12 4051A	12-0N720 Rte. 73 Upgrade Safety Devices	Collision Severity Reduction	Collision(s) reduced	11
12 4060	12-01740 Rte, 73 Oso Creek Channel Slope Embankment Repairs	Major Damage (Emergency Restoration)		
12 4080	12-0R340 RT 73 bridge decks and rehab approach slabs	Bridge Rehabilitation	Bridge(s)	1
12 4096P	12-0N840 Resurface and Restripe Roadway	Safety Improvements	Collision(s) reduced	5
12 4096R	12-0N860 Modifying the Existing Lane at MacArthur	Safety Improvements	Collision(s) reduced	8
12 4097C	12-0M090 SR-74 ADA	ADA - New Curb Ramps	Curb ramp(s)	4
12 4097D	12-0R990 SR-74 Multi Asset Project	Payement Preservation (CAPM)	Lane mile(s)	4
12 4124B	12-0L722 Rt 74 Mitigation Plant Establishment for 0L720	Safety Improvements	Collision(s) reduced	
12 4133	12-0U570, Rte 074, Cable Netting-Emergency Director's Order	Major Damage (Emergency Restoration)	Location(s)	
12 4218	12-0P030 Rte. 74 Super Elevation Correction.	Safety Improvements	Collision(s) reduced	16
12 4218B	12-0P031 Rte. SR 74 Landscape and Plant Establishment	Safety Improvements	Collision(s) reduced	
12 4325	12-0R180 Rte 90 New signals, safety lighting, ADA, & striping	Safety Improvements	Collision(s) reduced	6
12 4337	12-0P580 Rte 90 CAPM	Pavement Rehabilitation	Lane mile(s)	11.
12 4364	12-0R920 Rt 90 Safety Improvements SB 57 Off Ramp & at Kraemer	Safety Improvements	Collision(s) reduced	5
12 4373	12-0Q420 Rte 90/Berry St Signals, lighting, pavement delineation	Safety Improvements	Collision(s) reduced	2
12 4506F	12-0R311 State Route 91 Multi-Asset Project	Pavement Preservation (CAPM)	Lane mile(s)	51.
12 4506G	12-0R312, Rte 091, Multi-Asset Project	Pavement Preservation (CAPM)	Lane mile(s)	13.
12 4506H	12-0R313, Rte 091, Multi-Asset Project	Pavement Preservation (CAPM)	Lane mile(s)	17.
12 45061	12-0R314, Rte 091, Multi-Asset Project	Transportation Management Systems	Field element(s)	1
12 4506J	12-0R315, Rte 091, Multi-Asset Project	Transportation Management Systems	Field element(s)	7
12 4507C	12-0R730 Rte 91 Overhead sign structure with high reflective panel.	Safety Improvements	Collision(s) reduced	23
12 4518A	12-0U420 Rte. 91Brookhurst Avenue Off-Ramp Sinkhole & Damage	Major Damage (Emergency Opening)	Location(s)	
12 4532A	12-0Q310 SR 91 overhead sign structure	Safety Improvements	Collision(s) reduced	25
12 4533A	12-0Q040 Rte 91 EB on ramp resurfacing & GR	Safety Improvements	Collision(s) reduced	1
12 4560	12-0R190 SR 91 Install new guide sign structures.	Safety Improvements	Collision(s) reduced	4
12 4570B	12-0S240, Rte 91, Repair Bridge Girder	Major Damage (Emergency Opening)	Location(s)	
12 4609B	12- 0N320 Rte 91 Pvmt Rehab, Rte55 to Riv CL	Pavement Rehabilitation	Lane mile(s)	9
12 4642A	12-0N490 RTE 91 EB-Upgrade Weigh Station	Weight Stations & Weight-In-Motion Facilities	Location(s)	
12 4662A	12-0U410, Rte 091/241 MSE Wall Repairs	Major Damage (Emergency Opening)	Location(s)	
12 4769	12-0N870 Extend NB merge lane at Canyon Acres.	Safety Improvements	Collision(s) reduced	3
12 4792	12-0Q360 Drainage System Restoration	Drainage System Restoration	Culvert(s) (ea)	
12 4793	12-0N060 Rte133-Widening	Safety Improvements	Collision(s) reduced	6
12 4794	12-0P94U SR-133 Widening and Drainage Improvement	Drainage System Restoration	Culvert(s) (ea)	
12 4794	12-0P94U SR-133 Widening and Drainage Improvement	Safety Improvements	Collision(s) reduced	6
12 4795A	12-0N660 Rte 133 Replace Damaged and Outdated MBGR	Safety Enhancements	Collision(s) reduced	6
12 4836	12-0S060 Rte 133, Multi Asset Project	Bridge Rehabilitation and Replacement	Bridge(s)	
12 4846	12-0N890 Construct a new auxiliary lane to improve traffic flow	Operational Improvements	Daily vehicle hour(s) of delay (DVHD)	271.
12 4926F	12-0Q130 Install Double Thrie Beam Median Barrier	Safety Improvements	Collision(s) reduced	
12 4956A	12-0H045 SB 405 Aux Univ. to Sand Cyn. & SR-133	Non-Capacity Increasing Operational Improvements	Daily Vehicle Hour(s) of Delay (DVHD)	100
12 4984	12-0P400 I-405 at Culver Modify Signal & Upgrade ADA	Safety Improvements	Collision(s) reduced	4
12 4995A	12-0P220 Rte 405 Upgrade Median Barrier to Type 60M	Safety Improvements	Collision(s) reduced	4
12 4999D	12-0N520 Rt 405 Roadside Worker Safety Project	Roadside Safety Improvements	Location(s)	2
12 5005	12-01320 Kt 403 Kodaside Worker Safety Project 12-01840 Rte.405 MacArthur Blvd. Median Concrete Barrier Hit	Maior Damage (Emergency Opening)	Location(s)	
12 5040B	12-0R330, Rte 405 Multi-Objective Asset Management Project	Pavement Preservation (CAPM)	Lane mile(s)	59.
12 5040B	12-0Q970 Rte 405 (S.) Asset Management	Pavement Preservation (CAPM)	Lane mile(s)	9
12 5094C	12-0R570 RT 405 Multi-Asset Project	Pavement Preservation (CAPM)	Lane mile(s)	79.
12 5095B	12-0R570 Rt 405 Mont-Asset Holect 12-0R570 Rte. 405 Reh pvmt, Indscpng-install WIM-add stations	Pavement Preservation (CAPM)	Lane mile(s)	139.
12 5242A	12-0R680, I-605, Install Safety Lighting	Safety Improvements	Collision(s) reduced	6
12 5380A	12-0N730 Rt 142 335 Program Sediment Issue/control	Storm Water Mitigation	Acre(s)	1.
12 5490B	12-0S680, Rte 241, District 12 Silverado Fire Restoration	Major Damage (Emergency Opening)	treated/pollutant Location(s)	
12 5490B	12-03860, Rie 241, District 12 stiverado Fire Restoration 12-0T270, Rte 241, Multi Asset Project	Pavement Preservation (CAPM)	Lane mile(s)	58.
12 5490C	12-01270, Rie 241, Molii Assel Project 12-05250 Profile grind and raise depressed areas of asphalt pavement.	Major Damage (Emergency Opening)	Location(s)	
12 5495C	12-07240 Rte 133/241, Silverado Landscape Permanent Restoration	Major Damage (Permanent Restoration)	Location(s)	
12 5498	12-01730, Rte 241/133, Silverado Fire Remaining Features	Major Damage (Permanent Restoration)	Location(s)	1
12 5502	12-0H047 SR 241, Capital Preventive Maintenance Project	Pavement Preservation (CAPM)	Lane mile(s)	20.
12 5505B	12-08150 Rte, 241 Jump Out Ramp	Major Damage (Permanent Restoration)	Location(s)	20.