

District 5 2016/2017 Maintenance Workplan										
FY	Program	Dist	Project ID	Co.	Rte.	Prefix	Beg PM	Prefix	End PM	Project Description
2016/17	HM1-Base	05	0514000079 1F960_	SB	1, 246		19.3		20.6	Digouts
2016/17	HM1-Base	05	0516000072 1H420_	SB	192, 154		2.8 32.5		6.97 32.8	Digouts with RHMA Overlay (Includes Calle Real -Rte 101 to Rte 154 Connector)
2016/17	HM1-Base	05	0516000066 1H370_	SLO	58		0.0		0.7	Grind & Replace
2016/17	HM1-Base	05	0516000069 1H390_	SCr	35		0.0		1.48	Digouts with RHMA Overlay
2016/17	HM1-122	05	0515000058 1G650_	Mon	146		1.48		10.2	RAC Overlay
2016/17	HM1-122	05	05051500005 0 1G580_	SB	135		11.7		13.3	RAC Overlay
2016/17	HM1-122	05	0516000082 1H500_	SB	246		26.3		28.6	Slurry Seal
2016/17	HM124	05	0516000070 1H400_	SLO	101		46.1		50.7	RHMA - OG
2016/17	HM 2	05	0514000069 1F860_	SCr	1;129	R	0.04		L0.34	Repair/Replace Fence (R0.04/0.72 SB; R0.04/L0.34 NB) Access Control
2016/17	HM 2	05	0516000065 1H350_	SLO	1		40.9		48.3	Repair/Replace Fence (40.94/41.45 NB; 41.45/43.25 Both, 47.80/48.27 Both) R/W Delineation
2016/17	HM-251	05	0516000050 1H260_	MO N	1		12.6		13.14	Replace culverts
2016/17	HM-251	05	0516000049 1H250_	SB	1	R	5.33	R	5.33	Invert pave culvert
2016/17	HM315	05	0516000021 1H0801_	Mon, SLO	1,41,58, 101		Var		Var	In Monterey and San Luis Obispo Counties at 11 Locations, Methacrylate Deck Seal, Polyester Concrete Overlay
2016/17	HM315	05	0516000019 1H0701_	Mon, SBt, SCr	9,25, 68,101, 129, 156		Var		Var	In Monterey, San Benito and Santa Cruz counties. 9 Bridges at 8 Locations.
2016/17	HM315	05	0516000014 1H0301_	SB	101, 166		Var		Var	In Santa barbara County on Route 101 and 166 at five locations. Methacrylate Deck Seals-5 bridges, Replace Bearing pads-1 Bridge
2016/17	HM4	05	0516000168 1H830_	Mon Scr	Var		Var		Var	Replace pavement markers - North Region
2016/17	HM4	05	0516000169 1H840_	SB SLO	Var		Var		Var	Replace pavement markers - South Region