Priority (Lowest Number	County	Implementing	Bridge number from	Local Agency		Feature		Sufficiency	SD/FO		Request	ted PF ner	Deck Area	Total Particip.	Unit Cost	Federal	Running Fed	Local	Running Local
Is Top Priority)	Location	Agency	Inspection Report	Bridge ID	Facility Carried	Intersected	Location	Rating	Status	Work Description		oject	(ft <sup>2</sup> )	Cost	(\$/ft <sup>2</sup> )	Share	Summary	Share	Share
							0.1 Mi. Easot of			Treat bridge deck with Methacrylate, repair									
1	Sutter	Sutter	18C0041	18C0041	Ensley Road	Robbins Canal	Reclamantion Road	97.0	SD	scour countermeasures	\$	65,000.00	5,085.08	\$ 118,919.00	23	105,279	\$ 118,919.00	13,640	\$ 105,278.99
							0.4 Mi. North of Bear River			Treat bridge deck with Methacrylate,									
2	Sutter	Sutter	18C0009	18C0009	Pleasant Grove Road	Bear River	Drive	84.4	Blank	replace joint seals	\$	75,000.00	20,279.78	\$ 210,000.00	10	185,913	\$ 328,919.00	24,087	\$ 291,191.99
						Sutter Bypass	1.1 Mil West of State Route			Treat bridge deck with Methacrylate,									
3	Sutter	Sutter	18C0025	18C0025	Sacramento Road	East Channel	99	89.8	SD	replace joint seals	\$	70,800.00	5,520.00	\$ 123,800.00	22	109,600	\$ 452,719.00	14,200	\$ 400,792.13
		o				Sutter Bypass	2.9 Mi. East of State Route				e.								
4	Sutter	Sutter	18C0080	18C0080	Kirksville Road	West Canal	113	94.8	SD	Treat bridge deck with Methacrylate	Þ	33,000.00	2,571.13	\$ 61,308.00	24	54,276	\$ 514,027.00	7,032	\$ 455,068.10
_	0.44	0.44	4000047	4000047	Coles Road	\\\4-:- - O	0.5 mi. East of Cranmore	96.0	Disasta	Treat bridge deck with Methacrylate, place RSP		04.000.00	0.040.00	¢ 07,000,00	0.5	50.045	£ 504.007.00	7.005	<b>6</b> 544,000,00
5	Sutter	Sutter	18C0047	18C0047	Coles Road	Westside Canal	Road  16.1 Mi. North of Riego	96.0	Biank	Replace missing tie bolts, repair scour	\$	34,000.00	2,640.00	\$ 67,000.00	25	59,315	\$ 581,027.00	7,685	\$ 514,383.20
6	Sutter	Sutter	18C0073	18C0073	Pleasant Grove Road	Yankee Slough	Road	97.1	Dlank	countermeasures	•	75.000.00	3 707 30	\$ 148.000.00	40	131.024	\$ 729,027.00	16.976	\$ 645,407,60
0	Sullei	Sutter	1000073	1000073	Fleasailt Glove Road	Cross Canal	Road	97.1	DIATIK	Treat bridge deck with Methacrylate, place	\$	75,000.00	3,707.30	φ 140,000.00	40	131,024	\$ 729,027.00	10,970	φ 045,407.00
7	Sutter	Sutter	18C0001	18C0001	Garden Highway	(Verona Bridge)	Sankey Road	97.7	Blank	RSP	\$	75,000.00	17,514.78	\$ 252,000.00	14	223,096	\$ 981,027.00	28,904	\$ 868,503.20
						( renew = mege)					Ψ	127.800.00	,	s 981.027.00			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,	<b>*</b>
											\$ -	+21,000.00		\$ 901,027.00					
											PE	Costs							
										Previous allocated amount (E76) =		106,000.00							
							\$321,669 is	s Additional Co	unty Cost	\$321,669 + \$106,000 =	= \$ 4	127,669.00							
							Construction Costs			\$427669 - (75K x 3) =	\$ 2	202,669.00	Distribute be	tween other 4 brid	dges				
							\$ 53,919.00	(Rem. Approach	Roadway)	18C0041	\$	65,160.26	0.32						
							\$ 135,000.00			18C0009	\$	75,000.00	Max Amoun	nt Posible (LAPG E	Exhibit 6-D)				
							\$ 53,000.00			18C0025	-	70,733.33	0.35						
								(Rem. Approach	Roadway)	18C0080		32,946.42	0.16						
							\$ 33,000.00			18C0047		33,828.98	0.17		<u> </u>				
							\$ 73,000.00			18C0073				t Posible (LAPG E					
							\$ 177,000.00			18C0001	•	-,	Max Amoun	t Posible (LAPG E	xnibit 6-D)				
											\$ 4	127,669.00			<u> </u>	<u> </u>			

1/25/2016 Page 1 of 1