## COUN

Priority Ranking***	State# 57C-	County Bridge #	Roadway	Crossing	Location	SR	SD/FO Status	Work Recommended by Caltrans ABME in BIR (Work Recommended by County or previous BPM report)	Proposed Work / Remarks	Bridge Deck Width (FT)	Bridge Deck Length (FT)	Bridge Deck Area (SF)	Unit cost Methacryl ate* (\$ / SF)	Plan	Joint Repair Quantity (LF)	Unit Cost Joint Repair (\$ / LF)	Patch Bridge Deck (SF)	Unit Cost Patch Bridge Deck	Paint Structural Steel Area	Unit Cost Paint Structural Steel	Scour Mitigation Study (LS)	Replace Bridge Deck (LS)	Replace Bridge Railing (LS)		Soft Cost (Design, Contingen cy, & CE)	Total Participating Cost	Federal Share (88.12%)	Running Total Federal Share		
1	259	F08-7-225-B2	Japatul Rd	Peterson Canyon	2.3 miles e/o Tavem Road	83.6		Repair potholes & level AC approaches     Remove portion of trees growing over shoulder on southeast corner	Already completed by County forces     Already completed by County forces     Seal deck cracks with methacrylate	40	82	3280	Maria Control	\$10,000		(4.57	275	(\$ / SF) \$200	(SF)	(\$/SF)	\$0	\$0	1		\$73,445	\$214,685	\$189,180	\$189,180	\$25,505	\$25,505
2	396	A31-A-407-B1	Via De Santa Fe	San Dieguito River	0.7 mile s/c Via De La Valle	79.0	None	Seal deck cracks with methacrylate     Clear excessive vegetation in the channel     (2. Repair deck spalls - voids on deck surface	Scheduled to be completed by County forces     Repair deck spalls	40	405	16200	\$8	\$10,000	0		1,620	\$200	0		\$0	\$0	\$0	\$50,000	\$267,072	\$780,672	\$687,928	\$877,108	\$92,744	\$118,248
3	440	E02-0-260-B1	Willow Rd	San Vicente Creek	0.2 mile n/o SR67	96.6		maybe too deep to fill with mathacrylate) (3. Seal deck with methacrylate)  1. Patch spalls at deck joint edge with polyester concrete	Seal deck with methacrylate     Completed by County contract in 2009     Replace pourable joint seals at Abutments.	40	210	8400			80	\$150	0		0		\$0	\$0	\$0	\$50,000	\$32,240	\$94,240	\$83,044	\$960,153	\$11,196	\$129,444
4	145	77500-398-B1	Seventh St	Santa Maria Creek	0.2 mile n/o SR78	55.3	FO	Replace pourable joint seals at the two abutment joints     Repair spalls	1. Repair spalls	26	134	3484	\$8	\$10,000	26	\$150	350	\$200	0		\$0	\$0	\$0	\$50,000	\$84,121	\$245,893	\$216,681	\$1,176,834	\$29,212	\$158,656
5	237	F53-0-465-B3	Buckman Springs Rd	Cottonwood Creek	0.2 mile s/o Old HWY 80	94.6		Methacrylate Deck     (3. Remove bridge deck AC @ south approach)     Seal deck cracks with methacrylate	Methacrylate deck     Remove deck AC     Seal deck cracks with methacrylate	40	108	4320	\$8	\$10,000	0		350	\$200	0		\$0	\$0	\$0	\$50,000	\$85,571	\$250 131	\$220.416	\$1,397,250	\$29.716	\$188,372
4,500								(2. Replace approach AC for 5ft length each side of bridge)	2. To be completed by County																					
			Billy Mitchell Dr	Forrester Creek Channel	300' ± w/o Marshal Avenue			Clean and seal deck with methacrylate     Repair spalls at eastbound joint	Clean and seal deck with methacrylate     Spalls already repaired by County forces	68				\$10,000			-0.073**	\$200			\$0			1,820018,2002	\$116,122	10.000000000000000000000000000000000000		\$1,696,359		XXXIII
		D24-0-020-B1	Potrero Valley Rd	Sweetwater River Potrero Creek- W Crossing	0.2 mile s/o Sweetwater Road 1.1 miles ne/o SR94			Seal deck crack by methacrylate or equivalent material     Seal the deck cracks	Seal deck with methacrylate     Seal deck with methacrylate	83		41500 2070		\$10,000 \$10,000			200	\$200	0		\$0 \$0	\$0 \$0		\$50,000	\$203,840 \$60,611	25	\$525,054 \$156,123	22 85	\$70,786 \$21,048	16
9		B33-0-022-B2		Moosa Canyon Creek	0.3 mile se/o Camino Del rey			(2. Replace north approach AC)  1. Trim Tree branches	To be completed by County      Trees trimmed by County forces	42	111100	6426	•••	\$10,000			200	Ψ200	Ů		-	•••		400,000	\$0	\$0	\$0	\$2,377,537	\$0	\$320,530
					,			(2. Remove and replace approach AC per previous BPM report) (3. Clean deck surface and seal deck with methacrylate per previous BPM report)																						,
10	371	E11-0-090-B1	Riverside Dr	Sweetwater River	1.6 miles n/o SR79	53.5		None per Caltrans (1. Clean deck and seal surface with methacrylate) (2. Remove bridge deck AC) (3. Petch spalled AC and build-up to compensate for settlement of about 1/2" - bridge deck near south approach has been overlaid with AC, should remove AC on bridge deck and re-do south approach)	Clean deck and seal surface with methacrylate     Remove deck AC     To be completed by County	23	184	4232													\$0	\$0	\$0	\$2,377,537	\$0	\$320,530
11	656	B39-0-022-B1	Camino Del Rey (Lilac Rd)	San Luis Rey River	0.2 mile e/o SR76	93.5		Repair 5 failed sawcut deck spalls in the middle of the bridge (2. Negative moment crackings at center pier) (3. Methacrylate deck per County inspection)	Repair deck spalls in middle of bridge     Seal deck cracks with methacrylate     Methacrylate deck	40	400	16000	\$8	\$10,000	0		1,600	\$200	0		\$0	\$0	\$0	\$50,000	\$264,160	\$772,160	\$680,427	\$3,057,964	\$91,733	\$412,263
12	323	48500-335-B1	Pankey Rd - North	Horse Ranch Creek	0.1 mile n/a SR76	92.9		None per Caltrans (1. Seal deck cracks near south abutment per previous BFM report) (2. Fill soour hole at toe of south abutment slope per previous BFM report) (3. Extend rip-rap to toe of south abutment slope per previous BFM report) (4. Grout rip-rap per previous BFM report)	Seal deck cracks with methacrylate     To be addressed by County     To be addressed by County     To be addressed by County	40	105	4200			0		450	\$200	0		\$O	\$0	\$0	\$50,000	\$72,800	\$212,800	\$187,519	\$3,245,483	\$25,281	\$437,544
13	531	B39-0-022-B4 (	Camino Del Rey	Moosa Canyon Creek	2.1 miles e/o West Lilac Road (S/o Via Mariposa)	96.6		None per Caltrans (1. Clean deck surface and seal with methacrylate per previous BPM report)	Clean deck surface and seal with methacrylate	36	158	5688	\$8	\$10,000	0		575	\$200	0		\$0	\$0	\$0	\$50,000	\$114,662	\$335,166	\$295,348	\$3,540,832	\$39,818	\$477,361
14	637	15000-403-B1	Camino San Bernardo	Camion Del Norte	0.5 mile s/o Rancho Bernardo Road	79.0	None	Clean joint at abutment #3     (2. Clean and seal deck with methacrylate)	Already completed by County forces     Cleen and seal deck with methacrylate	70	189	13230	\$8	\$10,000	0		1,100	\$200	0		\$0	\$0	\$0	\$50,000	\$200,637	\$586,477	\$516,803	\$4,057,635	\$69,673	\$547,035
15	647	A23-0-407-B1	Rancho Santa Fe Rd	Escondido Creek	e/o Rancho Santa Fe Road/Manchester Avenue	92.2		None per Caltrans (1. Repair Deck Spalls) (2. Clean deck surface and seal with methacrylate per previous BPM report) (3. Seal cracks in approach slabs per previous BPM report. Note that there are voids on deck surface which seem too deep to fill with methacrylate)	Repair Deck Spalls     Clean deck surface and seal with methacrylate     Repair Deck Spalls     Part of the process to methacrylate deck	36	416	14976	\$10	\$10,000	0		1,500	\$200	0		\$O	\$0	\$0	\$50,000	\$265,075	\$774,835	\$682,785	\$4,740,420	\$92,050	\$639,085
16	649	C01-B-515-B1	Guejito Rd	Escondido Creek	0.1 mile s/o Lake Wohford Road	82.6	None	None per Caltrans (1. Clean and seal deck with methacrylate)	Clean and seal deck with Methacrylate.	32	92	2944	\$8	\$10,000	0		250	\$200	0		\$0	\$0	\$0	\$50,000	\$69,447	\$202,999	\$178,883	\$4,919,303	\$24,116	\$663,201
17	666	J42-0-465-B9	Old Highway 80	Kitchen Creek	1.9 miles e/o Buckman Springs Road	98.9	100000	None per Caltrans (1. Methacrylate deck per previous BPM report) (2. Add short Type A AC dike at south east corner to get drainage into overside drain and flume) (3. Repair erosion)	Melhacrylate deck     To be addressed by County     To be addressed by County	32	273	8736	\$8	\$10,000	0		700	\$200	0		\$0	\$0	\$0	\$50,000	\$140,342	\$410,230	\$361,494	\$5,280,797	\$48,735	\$711,937
		68200-180-B1		Mount Helix Dr (OC)	0.4 ± mile s/o Fuerte Drive			Clean & paint rusted spots	Clean & Paint Structural Steel	23	37				0		0		1,215	\$165	\$0	\$0	\$0	\$50,000	\$130,247	\$380,722	2	\$5,616,289		(2)
19	253	F64-0-090-B1	Wildwood Glen Ln	Sweetwater River	500' west of SR79			Remove trees & vegitation     Remove rust, spot blast, clean and paint structural steel	Already completed by County forces     Clean & Paint Structural Steel	82	47	3854													\$0	\$0	\$0	, -, - · -, - · -	\$0	\$757,167
20	2	F47-0-090-B1	Los Terrinitos Rd	Sweetwater River	0.1 mile west of SR79	79.3	None	Replace existing concrete bridge railing found to be in poor condition during BPM construction	Replace existing concrete bridge railing	21	138	2898			0		0		0		\$0	\$0	\$100,000	\$80,000	\$93,600	\$273,600	\$241,096	\$5,857,386	\$32,504	\$789,670

San Diego County	 Date
County	

TOTAL PARTICIPATING COST = TOTAL FEDERAL SHARE = TOTAL LOCAL SHARE = \$6,647,056 \$5,857,386 \$789,670