## Contra Costa County Public Works Federal Fiscal Year 2024/2025 Bridge Preventive Maintenance Program (2024/2025)

Priority (Lowest Number Is Top Priority)		Bridge Number from Inspection Report		Feature Intersected	Location	Sufficiency Rating	Paint Condition Index (PCI)	Work Description	Deck Area (ft²)	Unit Cost (\$/ft²)	Federal Share	Local Share	Total Particip. Cost	Breakdown of CON Costs	Calculated CON Cost <sup>1</sup>	PE Requested <sup>2</sup> or Spent <sup>5</sup>	R/W Requested <sup>3</sup>	CE Requested <sup>4</sup>	CON + CE
1	Contra Costa County	28C-0480	Contra Costa Canal	Contra Costa	0.05 mile south of	88.9		(1) Clean and repaint all areas where epoxy paint is failing on metal deck arch exterior including providing lead compliance plan; (Includes 100% containment system to prevent discharge into the waterway, lead compliance plan, construction area signs and traffic control.)	2425	\$50	\$107,284	\$13,900	\$121,184	\$43,280	\$86,560	\$21,640		\$12,984	\$99,544
	County		Bridge on Pomo Street	Canal	Riverside Dr.	33.3		(2) Clean corroded interior bolts and repaint with the specified coating system(Includes 100% containment system to prevent discharge into the waterway, lead compliance plan, construction area signs and traffic control.)						\$43,280					
2	Contra Costa County	28C-0382	San Pablo Creek Bridge on La Honda Road	San Pablo Creek	0.1 mile north of San Pablo Dam Rd.	69.4		<ul> <li>(1) Replace rotten diagonal timber bracings at Bents 2 &amp; 3; (Includes Construction areas signs &amp; Traffic Control.)</li> <li>(2) Stengthen existing timber cap beam at Bent 2 by installing steel bracket to support cap beam overhang.(Includes Construction areas signs &amp; Traffic Control.)</li> <li>(3) Resurface settled AC approach pavement at both abutments.</li> </ul>	1657	\$21	\$31,227	\$4,046	\$35,273	\$12,077 \$13,117	\$25,195	\$6,299		\$3,779	\$28,974
3	Contra Costa County	28C-0227	Bear Creek Bridge on Bear Creek Road	Bear Creek	0.4 mile north of Happy Valley Road	62.1		(1) Replace pourable joint seals at both piers. (includes traffic control & construction area signs)  (2) Fill in the erosion gully in the embankment below Abutment 1 and reinforce the Span 1 slope as necessary.	3751	\$11	\$35,323	\$4,576	\$39,899	\$28,500 \$0	\$28,500	\$7,125		\$4,275	\$32,775
4	Contra Costa County	28C-0082	Rock Slough Bridge on Delta Road	Rock Slough	3 miles east of Knightsen	92.2 (per 7.21.2020 BIR per 5.4.2020 UWI test with 8% CISS section loss)(Was 81.9 per 7.16.2018 BIR)		(1) Replace joint seals at abutments and bents; (includes traffic control & construction area signs)  (2) Patch potholes and seal_cracks in deck AC overlay.  (3) Replace damaged HMA over longitudinal joints, sawcut a joint into the new HMA, fill joint with crack sealant.	5174	\$22	\$99,306	\$12,866	\$112,173	\$80,123 \$0 \$0	\$80,123	\$20,031		\$12,019	\$92,142
5	Contra Costa County	28C-0144	Marsh Creek Bridge on Marsh Creek Road	Marsh Creek	6.8 miles east of Morgan Territory Road	90.9		<ul> <li>(1) Replace joint seals at abutments; (Includes traffic control &amp; construction area signs)</li> <li>(2) Patch pothole in AC approach roadway near Abutment 3.</li> <li>(3) Clean and treat the bridge deck with methacrylate(Includes traffic control &amp; construction area signs)</li> <li>(4) Remove and replace AC approach adjacent to Abutment 3</li> </ul>	3297	\$50	\$145,046	\$18,792	\$163,838	\$43,962 \$0 \$73,065	\$117,027	\$29,257		\$17,554	\$134,581
6	Contra Costa County	28C-0230	Unimin/Frisk Creek Bridge on Vasco Road	Unimin/Frisk Creek	3.4 miles south of Walnut Blvd.	83.9		<ul><li>(1) Replace joint seals at abutments; (includes traffic control &amp; construction area signs)</li><li>(2) Patch edge spalls in deck and approach slabs along the joints at abutments.</li></ul>	8284	\$13	\$96,199	\$12,464	\$108,662	\$77,616 \$0	\$77,616	\$19,404		\$11,642	\$89,258
7	Contra Costa County	28C-0077	Contra Costa Canal Bridge on Bailey Road	Contra Costa Canal	At SR 4	95.5		(1) Replace Abutment 1 & 2 joint seals in northbound and southbound lanes. (Includes traffic control & construction area signs)	4645	\$23	\$94,320	\$12,220	\$106,540	\$76,100	\$76,100	\$19,025		\$11,415	\$87,515
Removed from BPMP	Contra Costa County	28C-0175	Kellogg Creek Bridge on Hoffman Lane	Kellogg Creek	1.0 mile south of Marsh Creek Rd	51.1		(1) Replace broken timber block braces between girders at 2-location; (Includes traffic control & construction area signs)  (2) Place a shim between Girder 10 and the Abutment 2 timber sill-plate; (3) Replace damaged horizontal bolt connection between timber-curb and metal beam bridge rail at Abutment 2 (Includes traffic-centrol & construction area signs)  (4) Replace the timber spacer block for the bridge rail at Abutment 2 (Includes traffic control & construction area signs)  (5) Tighten all railing hardware where needed (Includes traffic control & construction area signs)					\$10,000			\$10,000			
Removed from	Contra Costa	222 222	San Pablo Creek Bridge on Appian Way	Com Dally Co.	ALCON Della Da Tal	70.5		(1) Clean and paint steel columns 3 through 5 at Bent 2 near ground-level (including providing lead compliance plan, traffic control & construction area signs);  (2) Install concrete jacket encasement around painted area to-prevent further corrosion;  (3) Replace abutment joint seals;					440.000			<b>#40.000</b>			
BPMP	County	28C-0329	Appian Way	San Pablo Creek	At San Pablo Dam Rd.	70.5		(4) Place erosion protection on the right/widened Abutment 1 embankment per 2018 BIR work recommendation and County 9.12.2019 field review work recommendation.					\$10,000			\$10,000			

## Contra Costa County Public Works Federal Fiscal Year 2024/2025 Bridge Preventive Maintenance Program (2024/2025)

Priority (Lowest Number Is Top Priority)		Bridge Number from Inspection Report	Facility Carried	Feature Intersected	Location	Sufficiency Rating	Paint Condition Index (PCI)	Work Description	Deck Area	unit Cost	Federal Share	Local Share	Total Particip Cost	. Breakdown of CON Costs	Calculated CON Cost <sup>1</sup>	PE Requested <sup>2</sup> or Spent <sup>5</sup>	R/W Requested <sup>3</sup>	CE Requested⁴	CON + CE
								(5) Resurface the AC approach pavement in the southbound lanes- adjacent to Abutment 4 to conform to existing bridge deck.											
			Delta-Mendota Canal (@	5 "				(1) Replace joint seals at Bents 2, 4, 6, and 11; (2) Replace any rotten or broken timber blockings between timber							-				
Removed from BPMP	Contra Costa County	28C-0402	CPM 0.33) Bridge on Lindemann Road	Delta-Mendota Canal	100 feet south of Herdlyn Road	28.0		girders;  (3) Chip out and patch unsound concrete on deck surface at all spans and along Bent 11 joint.	1				\$1,000		_	\$1,000			
Removed from BPMP Removed from	Contra Costa County	28C-0043	Eckley Slide Bridge on Carquinez Scenic Drive	Eckley Slide	2.1 miles East of I-80 in Crocket	48.9		(1) Clean and paint exposed rebars on the soffit and right side of Abutment 1 with rust inhibitor paint; (2) Replace the missing timber spacer block for the second post on the left approach metal beam guardrail near Abutment 3 per 2016 -					\$1,000			\$1,000			
BPMP Removed from BPMP	Contra Costa County	28C-0171	Nichols Road Overhead Bridge on Nichols Road	UPRR/BNSF/AMT RAK	0.3 mile north of Port Chicago HY	79.2		New approach slabs to protect both Abutment 1 and Abutment 4.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0251	Kellogg Creek Bridge on Newport Drive	Kellogg Creek	0.6 mile north of SR 4	80.2		Remove all delaminated concrete from bridge rails and paint exposed rebars with a rust inhibitor paint to prevent further corrosion.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0250	Frisk Creek Bridge on Clipper Drive	Frisk Creek	0.1 mile east of Newport Drive	85.6		Remove all delaminated concrete from bridge rails and paint exposed rebars with a rust inhibitor paint to prevent further corrosion.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0207	Del Monte Drive Overhead Bridge on Del Monte Drive	BNSF RW		47.8	41.3 < 65	This bridge is being programed under HBP for future replacement to address all deficiencies and it is no longer BPMP eligible.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0389	Las Trampas Creek Bridge on Freeman Road	Las Trampas Creek		68.7	51.2 < 65	This bridge is being programmed under HBP for cleaning and painting all structural steel members due to PCI <65 and it is no longer BPMP eligible.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0495	Briones Valley Creek Bridge on Briones Valley Road	Briones Valley Creek		45.2	51.3 < 65	This bridge is being programmed under HBP for cleaning and painting all structural steel members due to PCI <65 and it is no longer BPMP eligible.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0398	Marsh Creek Bridge on Concord Avenue	Marsh Creek		72.2	N/A	Based on 7/19/2018 BIR, "the current 0.5" separation between wingwall and Abutment 2 has not changed since 2012", no BPMP repair is needed at this time.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0150	Peyton Slough Bridge on Waterfront Road	Peyton Slough		53.7	N/A	Based on 2018 BIR, no BPMP work is needed at this time.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0122	Kellogg Creek Bridge on Byron Hwy	Kellogg Creek		59.5	N/A	Per 7-18-2019 field review, the subject timber wingwall was recently restored by third party. No BPMP work is needed at this time.					\$1,000			\$1,000			
Removed from BPMP	Contra Costa County	28C-0396	Contra Costa Canal Bridge on Golf Club Road	Contra Costa Canal		74.0	N/A	No BPMP work is needed per 2018 BIR recommendation.					\$250			\$250			
Removed from BPMP	Contra Costa County	28C-0059	Garrity Creek Bridge on San Pablo Avenue	Garrity Creek		78.3	N/A	No BPMP work is needed per 2018 BIR recommendation.					\$250			\$250			
<u>Notes:</u>	<u>.</u>								Grand	Total =	\$ 608,706	\$ 78,864	\$ 719,070	\$ 491,121	\$ 491,121	\$154,280	\$ -	\$ 73,668	\$ 564,7
1)	) 10% Mobiliz		Contingency are includ							ed Grand tal =	\$ 675,298	\$ 87,492	\$ 762,789	\$ 491,121	\$ 491,121	\$ 198,000	\$ -	\$ 73,668	\$ 564,78
	4		ain required outside ag		non-participating and no ent permits	t included in funding re	equest totals								\$			762,789	
5)	PE expendi	ture up to when	the bridge was determi	ined not BPMP el	igible.														
6)	) Alternate Pl	E Funding Break  1. Consultant								-									
				MGE Engineerigi	n Inc. for design service	s, signed 3/15/21	\$171,709												
		2. County Ove	rsight of Consultant (1	5%)			\$25,756												
						Total: Rounded Total:	\$197,465 <b>\$198,00</b> 0												
Explanation	for remov	al of individiu	al bridges from Bl	PMP															
Bridge:	Caltrans Cor	mment:							County A	Action:									
28C-0043								nsidered routine maintenance.			item from BPN								
28C-0171									Noted and removed item from BPMP.  Noted and removed item from BPMP.										
28C-0251 28C-0250								onsidered routine maintenance. onsidered routine maintenance.	1		item from BPN item from BPN								
28C0402:					ed to 28.0 and the cond				The bridg	ge has be	en removed fr	rom the list.							
	our unders	standing that the	bridge is no longer co	nsidered to be in	fair to good condition ar	nd therefore no longer	eligible for BPN	IP funding.											Page 2 of 3

## Contra Costa County Public Works Federal Fiscal Year 2024/2025 Bridge Preventive Maintenance Program (2024/2025)

Priority (Lowest Number Is Top Priority)	Agency Location	Bridge Number from Inspection Report	Facility Carried	Feature Intersected	Location	Sufficiency Rating	Paint Condition Index (PCI)	Work Description	Deck Area Unit Cost (\$/ft²)	Federal Share Local Share	Total Particip. Cost	Breakdown of CON Costs	Calculated CON Cost <sup>1</sup>	PE Requested <sup>2</sup> or Spent <sup>5</sup>	R/W Requested <sup>3</sup>	CE Requested⁴	CON + CE
	Following a meeting with Caltrans D4 Cultural, it was determined that the time and cost to prepare the Cultural studies required to perform the work on Bridge 28C-0329 exceeds the value of the repairs and has therefore been removed from the BPMP plan.									en removed from the list.							
	on Briage 28	C-0329 exceeds	the value of the repail	rs and has therefo	ore been removed from	the BPMP plan.											
28C-0175	In the process	of repairing the bridg	je due to multiple vehicle s	strikes, the work item	s for this bridge were comple	eted by County forces.											
Other:																	
"Develop Future ye	ear BPMP" remo	ved from list per em	ail from Karen Nguyen dat	ites 9/15/22													