

TEES 2009 Errata 1
Release Notes Ver. 1.1

Item	Description of Item	Section
Model 2070 Controller		
1	Limits Sp8 baud rate to 153.6 Kbps	A9-7
2	Adds additional necessary spec to Ver Module	9.2.7.6.4
3	Renames Model 2070L to Model 2070E and Model 2070LC to Model 2070EC	9.1.1
4	Makes corrections to 2070-9x Modem Spec	10.6.2.1, 10.8.2.1
5	Adds Model 2070-7G GPS Universal Time Base Module	Section 10.9 and A10-9
Model 170 Controller		
6	Removes protective cover requirements for the Model 400N Ethernet Module	Section 2.5, Details A2-7
Model 332L Cabinet		
7	Adds 24V DC Controlled Voltage Circuit	Chapter 6, Details A6-7, A6-15, A6-17, A6-24

TEES 2009 Errata 1
Release Notes Ver. 1.1

Model 336L Cabinets

8	Modifies Model 336L Cabinet to accommodate SPA	Chapter 6, Details A6-1, A6-2, A6-3, A6-4, A6-5
Model 206L Power Supply		
9	Updates drawing with missing details	A3-6
Harnesses		
10	Moves Harness Drawings to Chapter 3	A3-5, 7 and 8
11	Connector Detail -M14 (A1-2) becomes C2 Modem Harness (A3-5)	A3-5
12	Adds new C11 Harness	A3-7
13	Connector Detail -M14S (A1-4) becomes C2 Serial Harness (A3-8)	A3-8
Sensors and Isolators		
14	Detail A3-5 merges into A5-1(Sensor Unit and Isolator Details)	A5-1
Battery Back-Up System, Chapter #4		
15	AC Connection, allows quick disconnect plug	Section 4.2.10.1