


Exhibit 13-A Process Flowchart – High-Risk (Formerly “Major”) ITS Projects
 (FHWA Full Oversight Projects)



Note:

- This flow chart process does not apply to the earmarked ITS Deployment Projects (QT80 projects).
- This 2-phased PE procedure requires FHWA review of the SERF and approval of the SEMP.
- FHWA Full Oversight for PE phases on all major ITS projects.
- FHWA Full Oversight for E-76 purposes.
- For simplicity, the right of way phase is not shown in this chart. If right of way is involved, refer to Chapter 13, "Right of Way," of the LAPM for information and procedures.
- For FHWA list of criteria for full oversight projects, refer to Section 2.4 of Chapter 2 of the LAPM

This page intentionally left blank