



Table of Contents

Revision and Approval

Revision	Date	Nature of Changes	Approved By
0	01/15/2005	New/Updated	Dolores Valls
1	11/16/2018	Removed 160-2.0, 160-3.0, 160-4.0, 160-5.0, and 160-6.0	Steve Altman

MEMO NO	ISSUE DATE	TITLE
160-1.0	01/15/2005	Broken or Slipped Prestress Strands
160-2.0		Blank. Moved to BCM 50-1.03B, Attachment 1, <i>Patching Concrete Under Prestress Bearing Plates</i> , 11/16/18
160-3.0		Deleted 11/16/18
160-4.0		Deleted 11/16/18
160-5.0		Blank. Moved to BCM 50-1.03A, Attachment 1, <i>Electric Welding of Prestress Strand</i> , 11/16/18
160-6.0		Blank. Moved to BCM 50 – 1.01C, <i>Prestressing Concrete – General – Submittals</i> , 11/16/18