

**2020 SHOPP As of March 2022 Close-Out
(\$1,000)**

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Vote | Vote Date | Fund Type | PA & ED | PS & E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|--------|-------|-----------------|--|-------|------|------------|-----------|-------|-------|----------|----------|-----------|-----------|---------|---------|---------|---------|-----------------|-------------------|---------------------|-----------------------------|
| 02 | Lassen | 36 | | In Lassen County, on Routes 36, 44, and 139 at various locations. Repair fire damaged guardrail, fences, signs, and markers, and remove hazardous trees. | 1J900 | 3808 | 0221000007 | 201.130 | 20-21 | \$100 | \$2,000 | \$2,000 | 8/17/20 | NH | \$0 | \$0 | \$0 | \$600 | \$2,700 | 1 | Location(s) | |
| 02 | Lassen | 139 | 54.000/58.500 | Near Susanville, from 0.1 mile north of Hayden Hill Road to 0.7 mile north of Willow Creek Ranch Road at various locations. Replace culverts, repair drainage channels, install sediment control devices, and remove hazardous trees in fire damaged areas. | 2J120 | 3811 | 0221000030 | 201.130 | 20-21 | \$30 | \$2,750 | \$2,750 | 10/7/20 | NH | \$0 | \$0 | \$0 | \$750 | \$3,530 | 13 | Location(s) | |
| 02 | Lassen | 395 | 31.000/51.000 | Near Doyle, from 1.1 miles north of Garnier Road to 0.7 mile north of Hicks Road. Remove hazardous trees, place erosion control, and replace guardrails, signs and fencing. | 3J390 | 3860 | 0222000041 | 201.130 | 21-22 | \$25 | \$950 | \$950 | 10/26/21 | NH | \$0 | \$0 | \$0 | \$200 | \$1,175 | 40 | Location(s) | |
| 02 | Modoc | 139 | R3.500/30.300 | Near Canby, from 1.3 miles north of Howards Gulch Bridge to 0.1 mile south of Clear Lake Road, at various locations. Improve drainage facilities by repairing or replacing culverts. | 0H570 | 3589 | 0215000052 | 201.151 | 21-22 | \$71 | \$3,045 | \$0 | | RMRA | \$890 | \$360 | \$250 | \$700 | \$5,316 | 8 | Culvert(s) (ea) | |
| 02 | Plumas | 70 | 0.000/29.900 | Near Pulga, from the Butte County line to 3.1 miles west of Route 89 at various locations. Repair Rock Slope Protection (RSP) and stabilize roadway embankment. | 4H440 | 3723 | 0218000119 | 201.131 | 20-21 | \$347 | \$17,160 | \$17,086 | 6/23/21 | NH | \$1,030 | \$1,110 | \$70 | \$2,686 | \$22,403 | 8 | Location(s) | |
| 02 | Plumas | 70 | 1.000 | Near Storrie, at Elephant Butte Tunnel No. 09-0024. Remove rockfall, and repair damaged hangers and steel structure. | 3J150 | 3853 | 0222000013 | 201.130 | 21-22 | \$0 | \$1,000 | \$1,000 | 8/4/21 | NH | \$0 | \$0 | \$0 | \$300 | \$1,300 | 1 | Location(s) | |
| 02 | Plumas | 70 | 4.000/45.000 | Near Pulga and Quincy, from Rock Creek Powerhouse Overcrossing to Fairgrounds Road. Repair culverts, remove hazardous trees, rocks and debris, and replace guardrails and signs. | 3J120 | 3852 | 0222000010 | 201.130 | 21-22 | \$100 | \$2,000 | \$2,000 | 7/28/21 | NH | \$0 | \$0 | \$0 | \$600 | \$2,700 | 1 | Location(s) | |
| 02 | Plumas | 70 | 36.700/56.700 | Near Quincy, at various locations from 0.3 mile west of Butterfly Valley Road to 1.5 miles west of Gill Ranch Road/Sloat Road; also on Route 89 near Greenville, from 0.9 mile to 1.1 miles north of Wolf Creek Road (PM 25.1/25.3). Upgrade rock fall fence to reduce maintenance and highway worker exposure. | 1H790 | 3639 | 0216000043 | 201.235 | 20-21 | \$40 | \$1,760 | \$1,731 | 5/12/21 | NH | \$350 | \$450 | \$20 | \$450 | \$3,070 | 6 | Location(s) | |
| 02 | Plumas | 70 | 58.200/R78.400 | In and near Cromberg and Portola, from Gill Ranch Road to 0.2 mile west of Big Grizzly Creek Bridge. Rehabilitate roadway, repair or replace culverts, upgrade guardrail, upgrade bridge railing at Humbug Creek Bridge No. 09-0022, and make pedestrian facilities Americans with Disabilities Act (ADA) compliant. (G13 Contingency) | 1H580 | 3619 | 0216000024 | 201.120 | 21-22 | \$911 | \$0 | \$0 | | NH | \$3,490 | \$2,620 | \$1,120 | \$0 | \$8,141 | 45.1 | Lane mile(s) | Dec-2021/SHOPP-P-2122-03B |
| 02 | Plumas | 70 | | In Plumas, Lassen, and Sierra Counties on Routes 70 and 395 at various locations. Replace guardrail, signs, and fencing, repair pavement, reconstruct wildlife escape ramps, remove hazardous trees, and install erosion control measures. | 2J060 | 3809 | 0221000024 | 201.130 | 20-21 | \$100 | \$2,850 | \$2,850 | 10/14/20 | NH | \$0 | \$0 | \$0 | \$600 | \$3,550 | 2 | Location(s) | |
| 02 | Plumas | 284 | 0.000/8.300 | Near Chilcoot, from Route 70 to Frenchman Lake Dam. Repair culverts and pavement, remove hazardous trees, and replace guardrails, fencing, delineation, and signs. | 3J100 | 3854 | 0222000008 | 201.130 | 21-22 | \$30 | \$1,000 | \$1,000 | 8/20/21 | NH | \$0 | \$0 | \$0 | \$250 | \$1,280 | 17 | Location(s) | |
| 02 | Shasta | 5 | R38.000/R40.000 | Near Lakehead, from 0.9 mile north of Upper Salt Creek Undercrossing to Antlers Bridge. Remove hazardous trees, replace damaged fence, repair drainage systems, and place erosion control. | 3J090 | 3857 | 0222000007 | 201.130 | 21-22 | \$20 | \$1,130 | \$1,130 | 9/28/21 | NH | \$0 | \$0 | \$0 | \$340 | \$1,490 | 2 | Location(s) | |
| 02 | Shasta | 5 | R38.000/R40.000 | Near Lakehead, from 0.9 mile north of Upper Salt Creek Undercrossing to Antlers Bridge. Remove hazardous trees, replace damaged fence, repair drainage systems, and place erosion control. | 3J660 | 3867 | 0222000070 | 201.130 | 21-22 | \$0 | \$600 | \$600 | 1/24/22 | NH | \$0 | \$0 | \$5 | \$200 | \$805 | 2 | Location(s) | |
| 02 | Shasta | 5 | R54.600 | Near Lakehead, at 1.3 miles north of Gibson Road Overcrossing. Remove destabilized slope material, enlarge catchment area, and restore drainage facilities. | 1J720 | 3804 | 0220000121 | 201.130 | 20-21 | \$20 | \$1,700 | \$1,700 | 7/31/20 | NH | \$0 | \$0 | \$0 | \$450 | \$2,170 | 1 | Location(s) | |

**2020 SHOPP As of March 2022 Close-Out
(\$1,000)**

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Vote | Vote Date | Fund Type | PA & ED | PS & E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|----------|-------|-----------------|---|-------|------|------------|-----------|-------|---------|----------|---------|-----------|-----------|---------|---------|---------|---------|-----------------|-------------------|----------------------|-----------------------------|
| 02 | Shasta | 89 | 29.100/29.400 | Near Burney, at Lake Britton Bridge No. 06-0052. Replace the damaged bridge railing and concrete curb. | 2J160 | 3820 | 0221000035 | 201.130 | 20-21 | \$10 | \$1,140 | \$1,140 | 2/8/21 | NH | \$0 | \$0 | \$0 | \$330 | \$1,480 | 1 | Location(s) | |
| 02 | Shasta | 273 | 14.900/15.700 | In Redding, from 0.1 mile north of South Redding Underpass to 0.1 mile north of California Street. Construct Americans with Disabilities Act (ADA) compliant ramps and sidewalks. | 1H720 | 3626 | 0216000033 | 201.378 | 21-22 | \$402 | \$2,400 | \$2,833 | 12/8/21 | NH | \$0 | \$1,200 | \$750 | \$1,050 | \$5,802 | 19 | Curb ramp(s) | |
| 02 | Shasta | 299 | R1.000/R1.600 | Near Lewiston, from 0.7 mile east to 1.3 miles east of Hoadley Peak Road. Improve material disposal sites and construct culverts. | 0J680 | 3761 | 0219000149 | 201.131 | 21-22 | \$0 | \$760 | \$737 | 12/8/21 | NH | \$132 | \$345 | \$20 | \$255 | \$1,512 | 1 | Location(s) | |
| 02 | Shasta | 299 | 44.300/44.900 | Near Redding, from 1.9 miles west to 1.3 miles west of Du Bois Road. Curve improvement. | 4H930 | 3742 | 0219000027 | 201.010 | 21-22 | \$230 | \$6,835 | \$0 | | STP | \$1,310 | \$1,290 | \$280 | \$1,990 | \$11,935 | 38 | Collision(s) reduced | |
| 02 | Shasta | 299 | 67.800/77.800 | Near Burney, from 2.6 miles east of Carberry Flat Road to 0.3 mile east of Burney Mountain Power Road. Rehabilitate pavement, upgrade guardrail, improve drainage, reconstruct sidewalks, and make curbs Americans with Disabilities Act (ADA) compliant. | 1H570 | 3618 | 0216000036 | 201.121 | 21-22 | \$436 | \$14,800 | \$0 | | NH | \$1,430 | \$1,300 | \$1,020 | \$2,430 | \$21,416 | 21.3 | Lane mile(s) | |
| 02 | Shasta | Var | | In Shasta and Tehama Counties, on Routes 5, 44, 273, and 299 at various locations. Install new retroreflective pavement markers. | 2J550 | 3824 | 0221000105 | 201.130 | 20-21 | \$0 | \$380 | \$380 | 3/22/21 | NH | \$0 | \$0 | \$0 | \$125 | \$505 | 4 | Location(s) | |
| 02 | Siskiyou | 3 | 38.000/38.600 | Near Fort Jones, from 0.3 mile south to 0.3 mile north of West Moffett Creek Road at Moffett Creek Bridge No. 02-0042. Bridge replacement. | 4G440 | 3546 | 0214000013 | 201.110 | 20-21 | \$237 | \$6,990 | \$5,746 | 1/27/21 | HBRR-S | \$1,340 | \$700 | \$80 | \$1,540 | \$10,887 | 1 | Bridge(s) | |
| 02 | Siskiyou | 3 | R46.800/R48.000 | In Yreka, from 0.4 mile north of Laura Lane to Juniper Drive; also on Route 263, from Route 3 to 1.0 mile south of Long Gulch Road (PM 49.07/49.41). Reconstruct pavement structural section, replace sidewalk, driveways, curb ramps and pedestrian signals to meet current Americans with Disabilities Act (ADA) standards, designate bikeways with new signage and pavement delineation. This is a Construction Manager/General Contractor (CMGC) project. (G13 Contingency) | 1H520 | 3643 | 0217000009 | 201.120 | 21-22 | \$1,482 | \$0 | \$0 | | NH | \$1,830 | \$2,200 | \$5,880 | \$0 | \$11,392 | 11.1 | Lane mile(s) | Aug-2020/SHOPP-P-2021-01B |
| 02 | Siskiyou | 5 | 2.500/3.000 | In Dunsmuir, from Central Dunsmuir Undercrossing to 0.1 mile north of Siskiyou Avenue at Sacramento River Bridge and Overhead No. 02-0002. Replace southbound bridge deck. This is a Construction Manager/General Contractor (CMGC) project. (G13 Contingency) | 1H480 | 3614 | 0216000019 | 201.110 | 21-22 | \$269 | \$0 | \$0 | | HBRR-S | \$1,440 | \$2,660 | \$450 | \$0 | \$4,819 | 1 | Bridge(s) | |
| 02 | Siskiyou | 5 | 2.700/R15.900 | In and near Dunsmuir and Mt. Shasta, from Sacramento River Bridge Overhead to Black Butte Overhead. Roadway rehabilitation. This is a Construction Manager/General Contractor (CMGC) project. (G13 Contingency) | 3H320 | 3685 | 0217000097 | 201.122 | 21-22 | \$135 | \$0 | \$0 | | NH | \$1,620 | \$5,090 | \$80 | \$0 | \$6,925 | 27.8 | Lane mile(s) | May-2021/SHOPP-P-2021-06B |
| 02 | Siskiyou | 5 | R8.300 | Near Mount Shasta, at Azalea Road Overcrossing No. 02-0126. Rehabilitate bridge. | 1H400 | 3631 | 0216000042 | 201.110 | 20-21 | \$50 | \$1,851 | \$2,180 | 1/27/21 | HBRR-S | \$320 | \$750 | \$40 | \$710 | \$3,721 | 1 | Bridge(s) | |
| 02 | Siskiyou | 5 | R9.900/R68.100 | In and near Mount Shasta, Weed, and Yreka, at various locations from 0.2 mile north of Ream Avenue Overcrossing to 0.2 mile south of Hill Road Overcrossing. Enhance traffic safety by improving the roadside clear recovery zone. | 4F520 | 3507 | 0213000002 | 201.015 | 21-22 | \$95 | \$3,540 | \$4,203 | 8/18/21 | STP | \$1,000 | \$1,000 | \$200 | \$1,250 | \$7,085 | 5 | Collision(s) reduced | |
| 02 | Siskiyou | 5 | R25.400/R25.900 | Near Weed, from 0.2 mile south to 0.3 mile north of Weed Airport Safety Roadside Rest Area (SRRRA). Upgrade wastewater and water systems. | 2H130 | 3657 | 0216000114 | 201.235 | 20-21 | \$11 | \$1,663 | \$1,570 | 12/2/20 | NH | \$260 | \$770 | \$30 | \$680 | \$3,414 | 2 | Location(s) | |
| 02 | Siskiyou | 5 | | In Siskiyou County, on Routes 5 and 97 at various locations. Construct paved turn-arounds, install Changeable Message Signs (CMS), and relocate chain installation area. | 2J700 | 3850 | 0221000126 | 201.130 | 21-22 | \$100 | \$3,880 | \$3,880 | 8/3/21 | NH | \$0 | \$0 | \$0 | \$1,200 | \$5,180 | 14 | Location(s) | |

**2020 SHOPP As of March 2022 Close-Out
(\$1,000)**

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Vote | Vote Date | Fund Type | PA & ED | PS & E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|----------|-------|----------------|---|-------|------|------------|-----------|-------|-------|----------|----------|-----------|-----------|---------|---------|--------|---------|-----------------|-------------------|----------------------|-----------------------------|
| 02 | Siskiyou | 96 | 33.100 | Near Happy Camp, at 0.8 mile west of Slippery Creek Falls Road. Stabilize slope, install erosion control, and replace guardrail, signs, and pavement. | 2J460 | 3819 | 0221000080 | 201.130 | 20-21 | \$30 | \$1,500 | \$1,500 | 2/19/21 | NH | \$0 | \$0 | \$0 | \$300 | \$1,830 | 1 | Location(s) | |
| 02 | Siskiyou | 96 | 36.900/37.300 | Near Happy Camp, from 1.9 miles west to 1.5 miles west of Benjamin Creek Road. Remove slide material, stabilize slope, and install erosion control and drainage. | 2J510 | 3821 | 0221000086 | 201.130 | 20-21 | \$5 | \$4,000 | \$4,000 | 3/1/21 | NH | \$0 | \$0 | \$0 | \$800 | \$4,805 | 1 | Location(s) | |
| 02 | Siskiyou | 96 | 37.000/37.300 | Near Happy Camp, from 1.8 miles west to 1.5 miles west of Forest Road 17N16. Remove and dispose of slope material from the roadway. | 3J690 | 3866 | 0222000073 | 201.130 | 21-22 | \$5 | \$1,000 | \$1,000 | 12/30/21 | NH | \$0 | \$0 | \$0 | \$250 | \$1,255 | 1 | Location(s) | |
| 02 | Siskiyou | 96 | 37.000/R52.000 | Near Happy Camp, from 3.3 miles west of Lower Airport Road to 0.5 mile west of Thompson Creek Bridge. Replace culverts to increase hydraulic capacity, install erosion control and sediment capturing devices, and remove hazardous trees. | 2J110 | 3810 | 0221000029 | 201.130 | 20-21 | \$30 | \$4,570 | \$4,570 | 11/18/20 | NH | \$0 | \$0 | \$0 | \$600 | \$5,200 | 1 | Location(s) | |
| 02 | Siskiyou | 97 | 5.400/7.600 | Near Weed, from 1.0 mile north of Big Springs Road to 0.3 mile north of Juniper Valley Drive; also from 1.0 mile north of Tennant-Bray Road to 0.4 mile south of Ball Mountain Road (PM 28.7/35.8). Remove hazardous trees, repair pavement, and replace guardrails, fencing, delineation, signs, and culverts. | 3J040 | 3851 | 0222000001 | 201.130 | 21-22 | \$30 | \$3,000 | \$3,000 | 7/13/21 | NH | \$0 | \$0 | \$0 | \$750 | \$3,780 | 2 | Location(s) | |
| 02 | Tehama | 5 | 36.300/41.600 | Near Red Bluff, from Nine Mile Hill Overcrossing to 0.1 mile north of Bowman Road Overcrossing. Improve median clear recovery zone and widen inside shoulder to make standard for enhanced errant vehicle safety. | 1H470 | 3632 | 0216000044 | 201.015 | 20-21 | \$470 | \$4,530 | \$5,295 | 5/12/21 | STP | \$930 | \$800 | \$40 | \$1,030 | \$7,800 | 7 | Collision(s) reduced | |
| 02 | Tehama | 5 | 39.000/41.900 | Near Red Bluff, from 0.3 mile north of Snively Road Overcrossing to 0.4 mile north of Bowman Road Overcrossing. Upgrade southbound Cottonwood Commercial Vehicle Enforcement Facility (CVEF). | 1H680 | 3611 | 0216000010 | 201.321 | 21-22 | \$35 | \$16,350 | \$0 | | ST-CASH | \$450 | \$2,170 | \$50 | \$2,320 | \$21,375 | 1 | Location(s) | |
| 02 | Tehama | 5 | 41.983 | Near Cottonwood, at Cottonwood Creek Bridge No.06-0204. Replace all bridge joint assemblies and reconstruct adjoining concrete sections. | 3J640 | 3865 | 0222000068 | 201.130 | 21-22 | \$0 | \$3,000 | \$3,000 | 12/22/21 | NH | \$0 | \$0 | \$0 | \$500 | \$3,500 | 1 | Location(s) | |
| 02 | Tehama | 99 | 9.000/9.300 | Near Los Molinos, at Champlin Slough Bridge No. 08-0006. Replace bridge to correct scour critical conditions. | 1H510 | 3642 | 0216000148 | 201.111 | 21-22 | \$90 | \$4,370 | \$4,311 | 8/18/21 | HBRR-S | \$850 | \$1,170 | \$90 | \$990 | \$7,560 | 1 | Bridge(s) | |
| 02 | Tehama | Var | | In Tehama, Plumas, and Lassen Counties, on Routes 32, 36, 44, 89, 147 at various locations. Repair culverts, remove hazardous trees, place erosion control, and replace guardrails and signs. | 3J220 | 3855 | 0222000021 | 201.130 | 21-22 | \$100 | \$5,000 | \$5,000 | 8/19/21 | NH | \$0 | \$0 | \$0 | \$1,250 | \$6,350 | 156 | Location(s) | |
| 02 | Trinity | 3 | | In Trinity County, at Dobbins Gulch Bridge No. 05-0042 (PM 0.6), Stuart Fork Bridge No. 05-0055 (PM 43.9) and Mule Creek Bridge No. 05-0056 (PM 48.5); also on Route 299, at Grass Valley Creek Bridge No. 05-0013 (PM 65.5). Repair unsound concrete, replace bearings and joint seals, repair bridge decks, and install barrier and approach slabs. | 1H500 | 3633 | 0216000045 | 201.119 | 21-22 | \$206 | \$6,300 | \$0 | | HBRR-S | \$900 | \$1,030 | \$230 | \$2,060 | \$10,726 | 4 | Bridge(s) | |
| 02 | Trinity | 36 | 0.000/R29.000 | Near Mad River, from Humboldt County line to 0.4 mile east of Route 3. Replace culverts to increase hydraulic capacity, repair drainage channels, install sediment control devices, repair guardrail, signs, and earth retaining structures, and remove hazardous trees that could interfere with the travel way. | 2J140 | 3813 | 0221000032 | 201.130 | 20-21 | \$300 | \$17,000 | \$17,000 | 10/15/20 | NH | \$0 | \$0 | \$0 | \$3,400 | \$20,700 | 1 | Location(s) | |
| 02 | Trinity | 36 | 20.700 | Near Forest Glen, at 0.3 mile east of Upper Rattlesnake Creek Bridge. Stabilize slope, install steel wire mesh, improve the catchment area, and repair pavement. | 2J470 | 3818 | 0221000081 | 201.130 | 20-21 | \$50 | \$5,000 | \$5,000 | 2/8/21 | NH | \$0 | \$0 | \$0 | \$800 | \$5,850 | 1 | Location(s) | |

**2020 SHOPP As of March 2022 Close-Out
(\$1,000)**

| <u>Dist</u> | <u>County</u> | <u>Route</u> | <u>Post Miles</u> | <u>Location/Description</u> | <u>EA</u> | <u>PPNO</u> | <u>Project ID</u> | <u>Prog Code</u> | <u>FY</u> | <u>RW</u> | <u>Con</u> | <u>Vote</u> | <u>Vote Date</u> | <u>Fund Type</u> | <u>PA & ED</u> | <u>PS & E</u> | <u>RW Sup</u> | <u>Con Sup</u> | <u>Total Cap & Sup</u> | <u>Performance Value</u> | <u>Performance Measure</u> | <u>Approved Baseline Agreement</u> |
|-------------|---------------|--------------|-------------------|--|-----------|-------------|-------------------|------------------|-----------|-----------|------------|-------------|------------------|------------------|--------------------|-------------------|---------------|----------------|----------------------------|--------------------------|----------------------------|------------------------------------|
| 02 | Trinity | 299 | 0.000/43.400 | Near Salyer, Burnt Ranch, and Junction City, from the Humboldt County line to 0.1 mile west of Canyon Creek Road at various locations. Repair culverts and retaining walls, remove hazardous trees and rock slide debris, and replace guardrails and signs. | 3J190 | 3856 | 0222000018 | 201.130 | 21-22 | \$100 | \$2,000 | \$2,000 | 8/19/21 | NH | \$0 | \$0 | \$0 | \$700 | \$2,800 | 43 | Location(s) | |
| 02 | Trinity | 299 | 1.600/45.200 | Near Salyer and Junction City, at various locations from 0.2 mile east of Madrone Street to 0.4 mile west of Slattery Pond Road. Rehabilitate culverts. | 2H810 | 3668 | 0217000012 | 201.151 | 21-22 | \$137 | \$3,940 | \$3,091 | 12/8/21 | NH | \$930 | \$980 | \$330 | \$760 | \$7,077 | 20 | Culvert(s) (ea) | |
| 02 | Trinity | 299 | 11.200 | Near Burnt Ranch, at 0.3 mile west of Burnt Ranch School Road. Remove slide material, repair the support cables and wire mesh drapery, and install erosion control. | 2J530 | 3822 | 0221000088 | 201.130 | 20-21 | \$5 | \$1,000 | \$1,000 | 3/11/21 | NH | \$0 | \$0 | \$0 | \$300 | \$1,305 | 1 | Location(s) | |
| 02 | Trinity | 299 | 64.600/72.100 | Near Douglas City, at various locations from 1.1 miles east of Lewiston Road to 0.1 mile west of Shasta County line. Perform storm water mitigation improvements at twelve locations to meet statewide National Pollutant Discharge Elimination System (NPDES) permit mandate goals. | 1H700 | 3637 | 0216000049 | 201.335 | 21-22 | \$58 | \$2,580 | \$0 | | NH | \$860 | \$1,200 | \$380 | \$773 | \$5,851 | 108.0 | Acre(s) treated/pollutant | |