

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|----------|-------|---------------|---|-------|-------|------------|-----------|-------|---------|----------|----------|-----------|-----------|-------|-------|--------|----------|-----------------|-------------------|---------------------|-----------------------------|
| 05 | Monterey | 1 | 0.000/20.900 | Near Gorda, from San Luis Obispo County Line to Limekiln State Park; also in San Luis Obispo County, from Ragged Point Inn to Monterey County line (PM 72.8/74.324). Repair storm damage, including slopes, drainage systems, guardrail, and pavement. | 1Q760 | 3144 | 0523000073 | 201.130 | 22-23 | \$100 | \$18,350 | \$18,350 | 3/30/23 | NH | \$0 | \$300 | \$50 | \$5,000 | \$23,800 | 30.00 | Location(s) | |
| 05 | Monterey | 1 | 7.200/9.200 | Near Gorda, from 0.1 mile north to 2.1 miles north of Villa Creek Bridge. Restore and repair access routes, repair Rock Slope Protection (RSP) revetment, and replace damaged gabion baskets. | 1R190 | 3174 | 0523000167 | 201.130 | 23-24 | \$200 | \$51,000 | \$51,000 | 2/8/24 | NH | \$0 | \$0 | \$0 | \$15,300 | \$66,500 | 2.00 | Location(s) | |
| 05 | Monterey | 1 | 20.900/42.200 | Near Big Sur, from Limekiln State Park to 0.9 mile south of Castro Canyon Bridge. Repair storm damage, including slide mitigation, restoring rockfall barrier systems, and replacing culverts. | 1Q770 | 3145 | 0523000074 | 201.130 | 22-23 | \$100 | \$45,600 | \$45,600 | 3/13/23 | NH | \$0 | \$0 | \$0 | \$10,000 | \$55,700 | 25.00 | Location(s) | |
| 05 | Monterey | 1 | 22.000 | Near Lucia, at 0.5 mile north of Pitkins Curve Bridge; also at 0.3 mile north of Big Creek Bridge (PM 28.4); also in Monterey, at 0.1 mile south of Soledad Drive (PM R75.9). Clean out catchment, repair rockfall barrier, and line culvert and repair sinkhole. | 1Q050 | 3098 | 0522000145 | 201.130 | 22-23 | \$10 | \$800 | \$800 | 12/14/22 | NH | \$0 | \$0 | \$0 | \$250 | \$1,060 | 3.00 | Location(s) | |
| 05 | Monterey | 1 | 27.800 | Near Lucia, at 0.3 mile south of Big Creek Bridge. Remove slide material from top down, haul off slide material, restore roadway, and install rockfall protection and provide erosion control. | 1R640 | 3208 | 0524000098 | 201.130 | 23-24 | \$200 | \$31,000 | \$31,000 | 3/28/24 | NH | \$0 | \$0 | \$0 | \$9,000 | \$40,200 | 1.00 | Location(s) | |
| 05 | Monterey | 1 | 29.500 | Near Lucia, at 1.4 miles north of Big Creek Bridge. Remove slide material, restore roadway, and install rockfall netting. | 1R630 | 3207 | 0524000097 | 201.130 | 23-24 | \$25 | \$1,800 | \$1,800 | 3/18/24 | NH | \$0 | \$0 | \$0 | \$540 | \$2,365 | 1.00 | Location(s) | |
| 05 | Monterey | 1 | 44.700/69.800 | Near Big Sur, from 0.9 mile south of Sycamore Canyon Road to 0.1 mile north of Corona Road. Repair storm damage, including clearing or repairing culverts, restoring slopes, and clearing debris. | 1Q800 | 3146 | 0523000090 | 201.130 | 22-23 | \$40 | \$25,400 | \$25,400 | 3/30/23 | NH | \$0 | \$0 | \$0 | \$7,000 | \$32,440 | 11.00 | Location(s) | |
| 05 | Monterey | 1 | 45.400/45.600 | Near Big Sur, at the Pfeiffer Canyon Bridge No. 44-0060. Environmental mitigation (utility relocation) for project EA 1J130. | 1K081 | 2855X | 0522000107 | 201.131 | 23-24 | \$1,600 | \$0 | \$0 | | NH | \$0 | \$0 | \$110 | \$0 | \$1,710 | 0.00 | Location(s) | |
| 05 | Monterey | 1 | 47.800 | Near Big Sur, at 0.2 mile south of Juan Higuera Creek Bridge. Divert river to dewater the toe, remove existing concrete wall, construct Rock Slope Protection (RSP) revetment, and restore site. | 1R210 | 3176 | 0523000169 | 201.130 | 23-24 | \$50 | \$7,500 | \$7,500 | 2/14/24 | NH | \$0 | \$0 | \$0 | \$1,950 | \$9,500 | 1.00 | Location(s) | |
| 05 | Monterey | 1 | 60.000 | Near Notleys Landing, at 0.2 mile south of Rocky Creek Bridge. Stabilize slope due to rock slide. | 1S040 | 3222 | 0524000162 | 201.130 | 23-24 | \$100 | \$9,400 | \$9,400 | 4/23/24 | NH | \$0 | \$0 | \$0 | \$2,820 | \$12,320 | 1.00 | Location(s) | |
| 05 | Monterey | 1 | 60.000 | Near Notleys Landing, at 0.2 mile south of Rocky Creek Bridge. Construct sidehill viaduct. | 1S160 | 3229 | 0524000176 | 201.130 | 23-24 | \$200 | \$21,000 | \$21,000 | 6/17/24 | NH | \$0 | \$0 | \$0 | \$6,000 | \$27,200 | 1.00 | Location(s) | |
| 05 | Monterey | 1 | R78.900 | In the city of Monterey, at Cabrillo Highway; also near the city of Monterey, from 0.2 mile west of Scenic Drive to Scenic Drive. Reconstruct slopes and repair culverts and sinkhole damage. | 1R130 | 3168 | 0523000148 | 201.130 | 22-23 | \$0 | \$700 | \$700 | 5/24/23 | NH | \$0 | \$0 | \$0 | \$200 | \$900 | 4.00 | Location(s) | |
| 05 | Monterey | 1 | 96.400/96.600 | Near Moss Landing, at Elkhorn Slough Bridge No. 44-0074. Regrade site, install anchors to restrain the abutment and sheet pile wall, install Rock Slope Protection (RSP), and fencing. | 1P390 | 3084 | 0522000037 | 201.130 | 22-23 | \$20 | \$750 | \$750 | 10/13/22 | NH | \$0 | \$0 | \$0 | \$250 | \$1,020 | 1.00 | Location(s) | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|------------|-------|----------------|--|-------|-------|------------|-----------|-------|---------|----------|----------|-----------|-----------|---------|---------|---------|---------|-----------------|-------------------|----------------------|-----------------------------|
| 05 | Monterey | 25 | | In Monterey and San Benito counties on route 25, 101, and 198 at various locations. Repair storm damage, including drainage systems, embankments, and roadway. | 1Q810 | 3147 | 0523000076 | 201.130 | 22-23 | \$10 | \$2,800 | \$2,800 | 3/9/23 | NH | \$0 | \$200 | \$10 | \$590 | \$3,610 | 8.00 | Location(s) | |
| 05 | Monterey | 68 | 0.200/15.700 | In and near the city of Monterey, from 0.1 mile west of Sunset Drive to 0.1 mile west of Toro Park Undercrossing. Rehabilitate drainage systems and lighting, and install Transportation Management System (TMS) elements. | 1J880 | 2787 | 0518000083 | 201.151 | 23-24 | \$992 | \$7,600 | \$9,564 | 8/15/25 | RMRA | \$1,900 | \$2,600 | \$2,300 | \$1,950 | \$17,342 | 33.00 | Culvert(s) (ea) | |
| 05 | Monterey | 101 | R6.700 | Near Paso Robles, at San Antonio River Bridge No 44-0141L/R. Environmental mitigation monitoring for project EA 1F820. | 1F821 | 2565A | 0520000070 | 201.113 | 23-24 | \$0 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$20 | \$20 | 0.00 | Bridge(s) | |
| 05 | Monterey | 101 | R41.900/49.800 | Near King City, from Jolon Road to Lagomarsino Avenue. Rehabilitate pavement, drainage systems, and lighting, and install Transportation Management System (TMS) elements. This project will extend the pavement service life and improve ride quality. | 1K440 | 2900 | 0518000208 | 201.121 | 23-24 | \$156 | \$27,571 | \$29,751 | 8/15/25 | NH | \$1,151 | \$2,021 | \$224 | \$4,157 | \$35,280 | 28.00 | Lane mile(s) | |
| 05 | Monterey | 101 | 98.800/100.300 | Near Prunedale, from 0.4 mile north of Crazy Horse Canyon Road to 1.1 miles south of San Juan Road. Rehabilitate drainage culverts. | 1H691 | 2679X | 0521000065 | 201.407 | 23-24 | \$521 | \$5,017 | \$6,451 | 8/16/24 | NH | \$1,000 | \$1,606 | \$875 | \$1,809 | \$10,828 | 35.00 | Culvert(s) (ea) | |
| 05 | Monterey | 101 | 99.000 | Near Salinas, at 0.4 mile north of Echo Valley Road; also in San Benito County near San Juan Batista on Route 156 at Route 101 (PM 0.0). Repair storm damaged facilities, including washed out embankments, drainage systems, and dikes. | 1Q900 | 3156 | 0523000096 | 201.130 | 22-23 | \$0 | \$950 | \$950 | 3/14/23 | NH | \$0 | \$0 | \$0 | \$280 | \$1,230 | 2.00 | Location(s) | |
| 05 | Monterey | 183 | R2.100/R8.300 | Near Salinas and Castroville, from 0.2 mile north of South Davis Road to 0.1 mile south of Del Monte Avenue. Rehabilitate pavement and lighting, replace sign panels, and install Transportation Management System (TMS) elements. This project will extend the pavement service life and improve ride quality. | 1K430 | 2899 | 0518000207 | 201.121 | 22-23 | \$13 | \$6,950 | \$6,696 | 8/17/23 | NH | \$634 | \$1,430 | \$43 | \$1,308 | \$10,378 | 12.70 | Lane mile(s) | |
| 05 | Monterey | 183 | R8.300/9.980 | In Castroville, from 0.1 mile south of Del Monte Avenue to Route 183/Route 1 Junction, a multi-objective Asset Management Pilot Project. Rehabilitate pavement, repair bridge, construct storm drainage system improvements, construct Transportation Management System (TMS) elements, improve pedestrian, bicycle, and Americans with Disabilities Act (ADA) facilities. | 1H650 | 2678 | 0516000118 | 201.999 | 22-23 | \$2,300 | \$21,300 | \$21,221 | 8/16/24 | ST-CASH | \$2,600 | \$3,000 | \$6,600 | \$4,200 | \$40,000 | 1.00 | Location(s) | |
| 05 | Monterey | 198 | 20.800 | Near Parkfield Junction, at 1.8 miles west of North Fork Road. Remove and reconstruct the damaged roadway with a reinforced structural section and construct a v-ditch. | 1R150 | 3170 | 0523000151 | 201.130 | 22-23 | \$0 | \$3,000 | \$3,000 | 5/24/23 | NH | \$0 | \$0 | \$0 | \$900 | \$3,900 | 1.00 | Location(s) | |
| 05 | Monterey | Var | | In Monterey, San Benito, and Santa Cruz Counties, at four maintenance stations. Replace perimeter fencing and gates, and install security camera systems to improve security. This project will utilize the Emergency Limited Bid contract method. | 1S290 | 3231 | 0524000189 | 201.352 | 23-24 | \$0 | \$615 | \$615 | 5/17/24 | ST-CASH | \$0 | \$0 | \$0 | \$67 | \$682 | 4.00 | Location(s) | |
| 05 | San Benito | 25 | 53.700/54.300 | Near Hollister, at the intersection of Route 25 and Route 156 (R11.1/R11.7). Environmental mitigation landscape and monitoring for project EA 1J480. | 1J481 | 2746Y | 0521000064 | 201.010 | 22-23 | \$0 | \$200 | \$394 | 8/17/23 | STP | \$0 | \$442 | \$0 | \$458 | \$1,100 | 0.00 | Collision(s) reduced | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|-----------------|-------|----------------|--|-------|-------|------------|-----------|-------|---------|----------|----------|-----------|-----------|---------|---------|--------|---------|-----------------|-------------------|---------------------|-----------------------------|
| 05 | San Benito | 101 | R4.000 | Near San Juan Bautista, at 0.2 mile south of Anzar Road Undercrossing. Repair damaged pavement. | 1Q040 | 3097 | 0522000142 | 201.130 | 22-23 | \$0 | \$650 | \$650 | 9/28/22 | NH | \$0 | \$0 | \$0 | \$130 | \$780 | 1.00 | Location(s) | |
| 05 | San Benito | 101 | R4.240 | Near San Juan Bautista, at Anzar Road. Line culverts, backfill sinkhole, replace guardrail, and repair drainage inlet. | 1S140 | 3227 | 0524000174 | 201.130 | 23-24 | \$0 | \$650 | \$650 | 5/28/24 | NH | \$0 | \$0 | \$0 | \$150 | \$800 | 2.00 | Location(s) | |
| 05 | San Luis Obispo | 1 | 0.000/0.300 | Near Guadalupe, at the Santa Maria River Bridge No. 49-0042; also in Santa Barbara County (PM 50.3/50.6). The bridge is scour critical and needs to be replaced. The existing bridge will be used for traffic handling during construction and then demolished. The highway will need to be realigned as a result of the new bridge location. The new bridge will provide standard lane and shoulder widths and include a protected walkway. | 1H440 | 2650 | 0516000074 | 201.116 | 22-23 | \$1,030 | \$32,640 | \$61,334 | 1/31/25 | BFP | \$2,294 | \$3,517 | \$455 | \$9,660 | \$49,596 | 1.00 | Bridge(s) | Mar-2021 / SHOPP-P-2021-05B |
| 05 | San Luis Obispo | 1 | R12.600 | Near Oceano, at Oceano Overhead No. 49-0012. Replace bridge damper blocks, restore eroded void and shoulder, install concrete wedges, and pave slope. | 1Q060 | 3099 | 0522000146 | 201.130 | 22-23 | \$10 | \$700 | \$700 | 1/9/23 | NH | \$0 | \$0 | \$0 | \$200 | \$910 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 1 | 32.600 | In Morro Bay, at Toro Creek Bridge. Environmental mitigation (biological monitoring) for project EA 0L721. | 0L724 | 0072C | 0519000054 | 201.110 | 23-24 | \$9 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$37 | \$46 | 0.00 | Bridge(s) | |
| 05 | San Luis Obispo | 1 | 34.500 | In Morro Bay, at Old Creek Bridge No. 49-0070R. Environmental mitigation (biological monitoring) for project EA 0L722. | 0L725 | 0072D | 0519000055 | 201.110 | 23-24 | \$9 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$37 | \$46 | 0.00 | Bridge(s) | |
| 05 | San Luis Obispo | 1 | 64.000/R67.200 | Near San Simeon, from north of Piedras Blancas Road to north of the Arroyo de la Cruz Bridge. Planting, wetland and California Red-Legged Frog mitigation at Toro Preserve for PPNO 05-4928A. | 49286 | 4928R | 0522000106 | 201.150 | 23-24 | \$3,300 | \$7,040 | \$6,674 | 12/7/23 | NH | \$0 | \$730 | \$150 | \$2,300 | \$13,520 | 0.00 | Location(s) | |
| 05 | San Luis Obispo | 1 | 71.800 | Near Ragged Point, at 0.5 mile north of San Carpoforo Creek. Install drainage system, remove slide material, and install drapery mesh and erosion control. | 1Q650 | 3138 | 0523000060 | 201.130 | 22-23 | \$100 | \$4,100 | \$4,100 | 2/14/23 | NH | \$0 | \$0 | \$25 | \$700 | \$4,925 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 41 | 3.100 | Near Morro Bay, 3.1 miles north of Route 1. Environmental mitigation for parent project EA 1K720 for biological monitoring. | 1K721 | 2927X | 0522000134 | 201.131 | 23-24 | \$17 | \$0 | \$0 | | NH | \$0 | \$0 | \$21 | \$133 | \$171 | 0.00 | Location(s) | |
| 05 | San Luis Obispo | 41 | 6.700/13.000 | In and near Atascadero, from 0.5 mile south of Cerro Alto Road to 0.4 mile north of Old Morro Road; also on Route 101 in the city of San Luis Obispo from 0.3 mile north of Prado Road to Marsh Street (PM 27.0/28.0). Repair storm damage, including slide and debris removal, roadway restoration, and revetment construction and repair. | 1Q970 | 3162 | 0523000107 | 201.130 | 22-23 | \$15 | \$3,800 | \$3,800 | 4/3/23 | NH | \$0 | \$0 | \$0 | \$750 | \$4,565 | 7.00 | Location(s) | |
| 05 | San Luis Obispo | 46 | R4.800/R5.200 | Near Cambria, from 2.4 miles to 2.8 miles east of North Green Valley Road. Repair roadway, reconstruct slope, construct retaining wall, and place asphalt curb dike. | 1P400 | 3085 | 0522000038 | 201.130 | 22-23 | \$0 | \$900 | \$900 | 10/13/22 | NH | \$0 | \$0 | \$0 | \$300 | \$1,200 | 2.00 | Location(s) | |
| 05 | San Luis Obispo | 46 | 29.800/32.200 | In Paso Robles, from Route 101 to east of Airport Road. Rehabilitate pavement, replace roadside signs and sign panels, install Transportation Management System (TMS) elements, and upgrade facilities to Americans with Disabilities Act (ADA) standards. This project will extend the pavement service life and improve ride quality. | 1K460 | 2903 | 0518000210 | 201.121 | 22-23 | \$124 | \$7,550 | \$8,583 | 3/23/23 | NH | \$477 | \$1,424 | \$75 | \$1,693 | \$11,343 | 8.20 | Lane mile(s) | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|-----------------|-------|---------------|--|-------|-------|------------|-----------|-------|-------|----------|----------|-----------|-----------|---------|---------|--------|---------|-----------------|-------------------|----------------------|-----------------------------|
| 05 | San Luis Obispo | 58 | 1.800/6.900 | Near Santa Margarita, from I Street to Route 229. Rehabilitate pavement and drainage, replace sign panels, and install Transportation Management System (TMS) elements. This project will extend the pavement service life and improve ride quality. | 1J970 | 2845 | 0518000095 | 201.121 | 23-24 | \$856 | \$7,762 | \$8,901 | 8/16/24 | NH | \$1,622 | \$2,253 | \$968 | \$2,103 | \$15,564 | 11.70 | Lane mile(s) | |
| 05 | San Luis Obispo | 58 | 3.100 | Near Santa Margarita, at Trout Creek Bridge. Environmental mitigation (biological monitoring) for project EA 0L723. | 0L726 | 0072E | 0519000056 | 201.110 | 23-24 | \$9 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$37 | \$46 | 0.00 | Bridge(s) | |
| 05 | San Luis Obispo | 101 | 7.800/16.500 | In and near Pismo Beach, Arroyo Grande, and Nipomo, from Los Berros Road to south of Hinds Avenue Overcrossing. Rehabilitate pavement, drainage systems, enhance highway worker safety, designate bikeways with pavement delineation, add bike lanes and curb ramps, and install Transportation Management System (TMS) elements. This project will extend the pavement service life and improve ride quality. | 1J860 | 2778 | 0518000081 | 201.121 | 23-24 | \$206 | \$34,632 | \$36,595 | 8/16/24 | NH | \$1,610 | \$3,209 | \$655 | \$4,426 | \$44,738 | 34.70 | Lane mile(s) | |
| 05 | San Luis Obispo | 101 | 28.600/29.600 | In the city of San Luis Obispo, from 0.1 mile south of Broad Street to 0.2 mile north of California Boulevard. Improve sight distance at gores by placing contrasting surface treatment and vegetation control, relocate guide signs, and widen shoulders. This project will improve safety and reduce the number and severity of collisions. | 1N340 | 3039 | 0520000168 | 201.010 | 23-24 | \$480 | \$2,024 | \$2,616 | 10/18/24 | STP | \$0 | \$1,475 | \$114 | \$930 | \$5,023 | 163.00 | Collision(s) reduced | |
| 05 | San Luis Obispo | 101 | 32.600 | Near the city of San Luis Obispo, at 0.2 mile south of Old Stage Coach Road. Extend rockfall drapery system, stabilize slopes, and place erosion control. | 1S150 | 3228 | 0524000175 | 201.130 | 23-24 | \$10 | \$900 | \$900 | 5/31/24 | NH | \$0 | \$0 | \$0 | \$160 | \$1,070 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 101 | 56.900 | In Paso Robles, at 13th Street. Upgrade pumps and electrical system. | 1Q890 | 3155 | 0523000095 | 201.130 | 22-23 | \$20 | \$1,300 | \$1,300 | 2/7/23 | NH | \$0 | \$0 | \$0 | \$450 | \$1,770 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 101 | | In San Luis Obispo and Santa Barbara Counties, on Routes 1, 41, 46, 101, and 135 at various locations. Improve safety by constructing centerline and edge line rumble strips and re-stripe with high visibility striping and markings. This project will reduce the number and severity of collisions. | 1M740 | 3026 | 0520000058 | 201.010 | 22-23 | \$0 | \$2,510 | \$2,796 | 8/30/22 | STP | \$0 | \$827 | \$25 | \$834 | \$4,196 | 111.00 | Collision(s) reduced | |
| 05 | San Luis Obispo | 101 | | In San Luis Obispo County, in and near Santa Maria, Santa Margarita, Atascadero at various locations; also in Monterey County at North Bradley Undercrossing No. 44-0142R (PM R7.94). Apply polyester concrete overlay and replace joint seals. (Bridge Deck Preservation) | 1P230 | 3078 | 0522000002 | 201.119 | 22-23 | \$0 | \$2,218 | \$1,431 | 3/23/23 | RMRA | \$75 | \$330 | \$10 | \$650 | \$3,283 | 6.00 | Bridge(s) | |
| 05 | San Luis Obispo | 101 | | In San Luis Obispo, at the Caltrans District 5 Office at 50 Higuera Street. Repair electrical systems damaged by basement flood. | 1Q840 | 3150 | 0523000079 | 201.130 | 22-23 | \$0 | \$400 | \$400 | 3/1/23 | NH | \$0 | \$0 | \$0 | \$160 | \$560 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 101 | | In San Luis Obispo, at the Caltrans District 5 Office at 50 Higuera Street. Repair or replace servers and networking equipment damaged by basement flood. | 1Q850 | 3151 | 0523000080 | 201.130 | 22-23 | \$0 | \$4,036 | \$4,036 | 3/1/23 | NH | \$0 | \$0 | \$0 | \$900 | \$4,936 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 101 | | In San Luis Obispo, at the Caltrans District 5 Office at 50 Higuera Street. Reconstruct flooring, drywall, doors, and HVAC systems damaged by basement flood. | 1Q860 | 3152 | 0523000081 | 201.130 | 22-23 | \$0 | \$1,800 | \$1,800 | 3/30/23 | NH | \$0 | \$0 | \$0 | \$360 | \$2,160 | 1.00 | Location(s) | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|-----------------|-------|----------------|---|-------|-------|------------|-----------|-------|---------|----------|----------|-----------|-----------|---------|---------|---------|---------|-----------------|-------------------|--|-----------------------------|
| 05 | San Luis Obispo | 101 | | In San Luis Obispo, at the Caltrans District 5 Office at 50 Higuera Street. Remove and dispose of drywall, flooring, and furniture damaged by basement flood. | 1Q880 | 3154 | 0523000094 | 201.130 | 22-23 | \$0 | \$1,250 | \$1,250 | 3/1/23 | NH | \$0 | \$0 | \$0 | \$300 | \$1,550 | 1.00 | Location(s) | |
| 05 | San Luis Obispo | 227 | R6.800 | Near Edna, at 0.1 mile north of Corbett Canyon Road; also on Route 46 near Harmony at 0.1 mile west and 2.1 mile east of South Green Valley Road (PM 3.3, 5.5). Replace culverts, place Rock Slope Protection (RSP), and restore roadway and embankments. | 1Q070 | 3101 | 0522000147 | 201.130 | 22-23 | \$10 | \$650 | \$650 | 1/9/23 | NH | \$0 | \$0 | \$0 | \$160 | \$820 | 3.00 | Location(s) | |
| 05 | San Luis Obispo | | | In San Luis Obispo County, on routes 1, 41, 58, 101, and 229 at various locations. Repair storm damage, including clearing debris, repairing damaged drainage systems, and restoring roadway damage. | 1Q820 | 3148 | 0523000077 | 201.130 | 22-23 | \$25 | \$3,300 | \$3,300 | 2/16/23 | NH | \$0 | \$0 | \$0 | \$650 | \$3,975 | 15.00 | Location(s) | |
| 05 | Santa Barbara | 1 | 16.000 | Near Lompoc, at 1.8 miles south of Santa Rosa Road. Construct revetment to restore slope, shoulder, and lane and reconstruct barrier. | 1Q910 | 3157 | 0523000097 | 201.130 | 22-23 | \$20 | \$5,100 | \$5,100 | 3/28/23 | NH | \$0 | \$0 | \$0 | \$1,100 | \$6,220 | 1.00 | Location(s) | |
| 05 | Santa Barbara | 1 | R36.300/49.200 | Near Orcutt and Guadalupe, from Solomon Road to Route 166 Junction. Widen shoulders, install rumble strips, upgrade guardrails and relocate objects from within the clear recovery zone. This project will improve safety and reduce the number and severity of collisions. | 1H610 | 2667 | 0516000097 | 201.015 | 23-24 | \$2,362 | \$18,848 | \$21,607 | 10/17/25 | STP | \$1,736 | \$1,942 | \$1,237 | \$3,948 | \$30,073 | 0.38 | Annual fatal and serious injury collision(s) | |
| 05 | Santa Barbara | 1 | 49.200/50.400 | In Guadalupe, from Route 166 (West Main Street) to 0.1 mile south of Santa Maria River Bridge; also on Route 166, from Route 1 to Obispo Street (PM 0.0/0.2). Upgrade curb ramps and other facilities to Americans with Disabilities Act (ADA) standards, construct new sidewalks, buffered bike lanes, bulb outs, and install flashing beacons as complete streets elements. | 1E030 | 2466 | 0513000026 | 201.361 | 23-24 | \$1,284 | \$6,192 | \$10,833 | 10/17/25 | NH | \$1,229 | \$2,233 | \$2,963 | \$1,447 | \$15,348 | 21.00 | Curb ramp(s) | |
| 05 | Santa Barbara | 1 | | In Santa Barbara County on Routes 1, 101, 135, 166, and 246 at various locations. Repair storm damage, including debris removal, embankment restoration, and repair bridge rail. | 1Q870 | 3153 | 0523000093 | 201.130 | 22-23 | \$20 | \$3,000 | \$3,000 | 3/27/23 | NH | \$0 | \$0 | \$0 | \$650 | \$3,670 | 19.00 | Location(s) | |
| 05 | Santa Barbara | 101 | 2.600/R4.800 | In Carpinteria, from Casitas Pass Overcrossing to 0.5 mile south of South Padaro Lane. Environmental mitigation (biological monitoring) for EA 1C821. | 1C8A2 | 2426X | 0520000053 | 201.120 | 23-24 | \$7 | \$0 | \$0 | | NH | \$0 | \$0 | \$0 | \$33 | \$40 | 0.00 | Lane mile(s) | |
| 05 | Santa Barbara | 101 | 4.400/R7.700 | Near Summerland, from 0.9 mile south of South Padaro Lane Undercrossing to 0.6 mile north of Padaro Lane Overcrossing. Landscape and environmental mitigation (highway planting) for EA 1C822. | 1C8B1 | 2427Y | 0520000063 | 201.120 | 22-23 | \$0 | \$2,250 | \$2,650 | 10/18/24 | NH | \$0 | \$400 | \$0 | \$600 | \$3,250 | 0.00 | Lane mile(s) | |
| 05 | Santa Barbara | 101 | 4.400/R7.700 | Near Summerland, from 0.9 mile south of South Padaro Lane Undercrossing to 0.6 mile north of Padaro Lane Overcrossing. Environmental mitigation (biological monitoring) for EA 1C822. | 1C8B2 | 2427X | 0520000064 | 201.120 | 23-24 | \$5 | \$0 | \$0 | | NH | \$0 | \$0 | \$0 | \$35 | \$40 | 0.00 | Lane mile(s) | |
| 05 | Santa Barbara | 101 | R5.300/10.500 | Near the city of Santa Barbara, from South Padaro Lane Undercrossing to East Olive Mill Road Overcrossing. Clear rocks, sediment, and debris from creek beds at bridges and restore shoulder backing. | 1Q750 | 3143 | 0523000072 | 201.130 | 22-23 | \$10 | \$750 | \$750 | 2/17/23 | NH | \$0 | \$0 | \$0 | \$180 | \$940 | 5.00 | Location(s) | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement | |
|------|---------------|-------|-----------------|---|-------|-------|------------|-----------|-------|-------|----------|----------|-----------|-----------|---------|---------|--------|----------|-----------------|-------------------|--|-----------------------------|--|
| 05 | Santa Barbara | 101 | R7.300/9.200 | Near Summerland, from 0.2 mile north of Padaro Lane Overcrossing to 0.2 mile north of Sheffield Avenue. Environmental mitigation (biological monitoring) for EA 1C823. | 1C8C2 | 2429X | 0520000147 | 201.120 | 23-24 | \$5 | \$0 | \$0 | | | NH | \$0 | \$0 | \$0 | \$35 | \$40 | 0.00 | Lane mile(s) | |
| 05 | Santa Barbara | 101 | 9.200/9.700 | Near the city of Santa Barbara, from 0.2 mile north of Sheffield Drive to 0.3 mile south of San Ysidro Road. Upgrade median barrier, enhance highway worker safety, rehabilitate drainage systems and pavement, and install Transportation Management System (TMS) elements. This is a Construction Manager/General Contractor (CMGC) project. [Local contribution: \$966,000 PA&ED, \$3,433,000 PS&E, and \$156,000 R/W Support as part of STIP project EA 0N70B.] | 1C824 | 2426D | 0519000053 | 201.015 | 22-23 | \$0 | \$12,935 | \$12,935 | 3/22/24 | STP | \$0 | \$0 | \$0 | \$4,600 | \$17,535 | 0.12 | Annual fatal and serious injury collision(s) | | |
| 05 | Santa Barbara | 101 | 31.000/67.000 | Near Las Cruces, from 0.9 mile north of Dos Pueblos Creek Undercrossing to 1.8 miles south of Alisos Canyon Road. Repair storm damage, such as clearing debris, restoring drainage systems, and reconstructing embankments. | 1Q670 | 3140 | 0523000062 | 201.130 | 22-23 | \$20 | \$5,500 | \$5,500 | 3/23/23 | NH | \$0 | \$0 | \$0 | \$1,300 | \$6,820 | 13.00 | Location(s) | | |
| 05 | Santa Barbara | 101 | R36.000/R37.000 | Near Goleta, from 0.6 mile south and 0.4 mile north of Refugio Road Undercrossing No. 51-0215L/R and Canada del Refugio No. 51-0030S. Replace two bridges and upgrade bridge railing on one bridge. | 1C950 | 2448 | 0513000018 | 201.110 | 22-23 | \$622 | \$40,900 | \$49,771 | 10/19/23 | HBRR-S | \$2,200 | \$6,260 | \$320 | \$11,200 | \$61,502 | 3.00 | Bridge(s) | Jun-2021 / SHOPP-P-2021-07B | |
| 05 | Santa Barbara | 101 | 46.500/48.000 | Near Gaviota, from 0.1 mile north of Gaviota Beach Road to 0.8 mile south of Route 1. Clear rocks and debris and replace and repair damaged rockfall systems. | 1Q660 | 3139 | 0523000061 | 201.130 | 22-23 | \$0 | \$1,700 | \$1,700 | 2/16/23 | NH | \$0 | \$0 | \$0 | \$400 | \$2,100 | 3.00 | Location(s) | | |
| 05 | Santa Barbara | 101 | 46.700/48.000 | Near Gaviota, from 0.3 mile north of Gaviota Beach Road to 0.8 mile south of Route 1. Clear catchment areas and repair rockfall fences. | 1S020 | 3220 | 0524000160 | 201.130 | 23-24 | \$0 | \$600 | \$600 | 3/28/24 | NH | \$0 | \$0 | \$0 | \$150 | \$750 | 1.00 | Location(s) | | |
| 05 | Santa Barbara | 101 | 47.000/47.300 | Near Gaviota, from 1.8 to 1.5 miles south of Route 1. Construct secant pile wall and restore roadway. | 1R140 | 3169 | 0523000150 | 201.130 | 22-23 | \$25 | \$15,000 | \$15,000 | 5/11/23 | NH | \$0 | \$0 | \$0 | \$3,700 | \$18,725 | 1.00 | Location(s) | | |
| 05 | Santa Barbara | 101 | R52.300/R56.100 | Near Buellton, from Old Coast Highway to south of Santa Rosa Road Overcrossing. Rehabilitate pavement and drainage systems. This project will extend the pavement service life and improve ride quality. | 1K450 | 2902 | 0518000209 | 201.121 | 23-24 | \$188 | \$15,773 | \$18,074 | 8/16/24 | NH | \$1,312 | \$1,963 | \$189 | \$2,388 | \$21,813 | 14.40 | Lane mile(s) | | |
| 05 | Santa Barbara | 101 | 54.850 | Near Buellton, at Nojoqui Creek Bridge No. 51-0074R. Repair bridge railing. | 1R200 | 3175 | 0523000168 | 201.130 | 23-24 | \$0 | \$600 | \$600 | 2/29/24 | NH | \$0 | \$0 | \$0 | \$120 | \$720 | 1.00 | Location(s) | | |
| 05 | Santa Barbara | 101 | 55.660 | Near Buellton, at Nojoqui Creek No. 51-0019R. Reconstruct bridge railing. | 1S120 | 3225 | 0524000172 | 201.130 | 23-24 | \$0 | \$550 | \$550 | 4/30/24 | NH | \$0 | \$0 | \$0 | \$100 | \$650 | 1.00 | Location(s) | | |
| 05 | Santa Barbara | 101 | 55.900/R56.200 | Near Buellton, from 0.1 mile south of Nojoqui Creek Bridge No. 51-0018L/R to 0.3 mile south of Santa Rosa Road Overcrossing. Environmental mitigation for bridge rail replacement and widening project EA 1F790. | 1F791 | 2561A | 0520000139 | 201.112 | 22-23 | \$10 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$123 | \$133 | 0.00 | Linear feet rail | | |
| 05 | Santa Barbara | 101 | 65.000/84.100 | Near Los Alamos and Orcutt, from 1.8 miles north of Route 154 to 0.2 mile south of South Santa Maria Undercrossing. Rehabilitate drainage systems and lighting, and install Transportation Management System (TMS) elements. | 1K510 | 2918 | 0518000215 | 201.407 | 23-24 | \$464 | \$4,523 | \$4,582 | 8/16/24 | NH | \$1,478 | \$1,900 | \$214 | \$1,629 | \$10,208 | 13.00 | Culvert(s) (ea) | | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|---------------|-------|----------------|--|-------|------|------------|-----------|-------|-------|----------|----------|-----------|-----------|---------|---------|--------|---------|-----------------|-------------------|---------------------|-----------------------------|
| 05 | Santa Barbara | 101 | 82.200 | Near Santa Maria, at Clark Avenue Overcrossing No. 51-0232. Replace and repair damaged bridge girders and provide traffic control. | 1R160 | 3171 | 0523000152 | 201.130 | 22-23 | \$0 | \$1,900 | \$1,900 | 6/23/23 | NH | \$0 | \$0 | \$0 | \$500 | \$2,400 | 1.00 | Location(s) | |
| 05 | Santa Barbara | 101 | | In Santa Barbara County, on Routes 101, 144, 150, and 192 at various locations. Repair storm damage including clearing debris deposits, restoring hydraulic capacity in impacted channels, and repair bridge scour damage. | 1Q830 | 3149 | 0523000078 | 201.130 | 22-23 | \$50 | \$3,600 | \$3,600 | 3/13/23 | NH | \$0 | \$0 | \$50 | \$800 | \$4,500 | 15.00 | Location(s) | |
| 05 | Santa Barbara | 135 | | In Santa Barbara County, on Routes 1, 135, and 246 at various locations. Repair storm damage, including drainage systems, slopes, and roadway. | 1R120 | 3167 | 0523000147 | 201.130 | 22-23 | \$20 | \$2,200 | \$2,200 | 4/11/23 | NH | \$0 | \$0 | \$0 | \$550 | \$2,770 | 16.00 | Location(s) | |
| 05 | Santa Barbara | 154 | R0.000/32.800 | In Santa Barbara County, at various locations. Rehabilitate drainage systems and install Transportation Management System (TMS) elements. | 1K520 | 2919 | 0518000216 | 201.151 | 23-24 | \$317 | \$12,979 | \$19,037 | 10/17/25 | RMRA | \$1,926 | \$2,044 | \$558 | \$2,342 | \$20,166 | 27.00 | Culvert(s) (ea) | |
| 05 | Santa Barbara | 154 | 2.000/R31.500 | Near the city of Santa Barbara, from 0.4 mile west of Foxen Canyon Road to Route 192 (Foothill Road); also on Route 246 in Solvang at Alamo Pintado Road (PM 30.3). Repair storm damage, including debris removal, drainage system repair, and roadway restoration. | 1Q680 | 3141 | 0523000063 | 201.130 | 22-23 | \$50 | \$7,400 | \$7,400 | 3/13/23 | NH | \$0 | \$0 | \$0 | \$1,500 | \$8,950 | 12.00 | Location(s) | |
| 05 | Santa Barbara | 154 | 26.000/30.200 | Near Santa Barbara, from 0.7 mile west of San Marcos/Painted Cave Road to San Antonio Creek Bridge at various locations. Clear catchment areas, repair rockfall fences, repair downdrain, clear landslides, and stabilize slopes. | 1R650 | 3209 | 0524000099 | 201.130 | 23-24 | \$100 | \$4,200 | \$4,200 | 3/28/24 | NH | \$0 | \$0 | \$0 | \$900 | \$5,200 | 4.00 | Location(s) | |
| 05 | Santa Barbara | 192 | 5.100 | In the city of Santa Barbara, at 0.9 mile west of Route 144. Construct a retaining wall and concrete barrier, modify drainage systems, and reconstruct the roadway. | 1S030 | 3221 | 0524000161 | 201.130 | 23-24 | \$50 | \$3,800 | \$3,800 | 4/19/24 | NH | \$0 | \$0 | \$0 | \$950 | \$4,800 | 1.00 | Location(s) | |
| 05 | Santa Barbara | 192 | | In Santa Barbara county, on Routes 192 and 144 at various locations. Replace failed drainage system, repair slopes and slipouts, clear debris and rocks, repair rockfall fence, and clear creek debris. | 1R620 | 3206 | 0524000096 | 201.130 | 23-24 | \$25 | \$2,500 | \$2,500 | 3/8/24 | NH | \$0 | \$0 | \$0 | \$550 | \$3,075 | 12.00 | Location(s) | |
| 05 | Santa Barbara | 246 | 10.910/R19.380 | Near Lompoc, from 0.9 mile east of Sweeney Road to 0.8 mile east of Drum Canyon Road. Establish roadside ditch, reconstruct downdrain, clear sediment in box culvert, construct Rock Slope Construction (RSP) pad, and provide erosion control. | 1R660 | 3210 | 0524000100 | 201.130 | 23-24 | \$5 | \$550 | \$550 | 3/11/24 | NH | \$0 | \$0 | \$0 | \$100 | \$655 | 3.00 | Location(s) | |
| 05 | Santa Barbara | Var | | In Santa Barbara and San Luis Obispo Counties, at six maintenance stations. Replace perimeter fencing and gates, and install security camera systems to improve security. This project will utilize the Emergency Limited Bid contract method. | 1S280 | 3230 | 0524000188 | 201.352 | 23-24 | \$0 | \$2,090 | \$2,090 | 5/17/24 | ST-CASH | \$0 | \$0 | \$0 | \$228 | \$2,318 | 6.00 | Location(s) | |
| 05 | Santa Cruz | 1 | 0.000/R1.000 | In and near Watsonville, from Monterey County line to Beach Street and at Pajaro River Bridge No. 44-0069; also in Monterey County, from 0.5 mile south of Salinas Road to Santa Cruz County line (PM 100.5/R102.031). Repair bridge scour, remove debris, and rebuild abutment slope. | 1Q960 | 3161 | 0523000106 | 201.130 | 22-23 | \$50 | \$1,850 | \$1,850 | 4/3/23 | NH | \$0 | \$0 | \$0 | \$700 | \$2,600 | 1.00 | Location(s) | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|------------|-------|---------------|--|-------|-------|------------|-----------|-------|-------|---------|----------|-----------|-----------|---------|---------|---------|---------|-----------------|-------------------|---------------------------|-----------------------------|
| 05 | Santa Cruz | 1 | R0.000/R7.900 | In and near Watsonville, from Monterey County line to 0.2 mile north of Larkin Valley Road; also in Monterey County (PM R101.53). Rehabilitate drainage systems and lighting, install Transportation Management System (TMS) elements, pave areas behind the gore and construct Maintenance Vehicle Pullouts (MVPs) to reduce maintenance and enhance highway worker safety. | 1K640 | 2926 | 0518000239 | 201.407 | 23-24 | \$296 | \$5,869 | \$3,703 | 8/16/24 | NH | \$1,570 | \$2,456 | \$43 | \$1,813 | \$12,047 | 16.00 | Culvert(s) (ea) | |
| 05 | Santa Cruz | 1 | R5.000/8.200 | Near Aptos, from 0.9 mile north of Buena Vista Drive to 0.1 mile south of Freedom Boulevard. Widen shoulders and install rumble strips. This project will improve safety and reduce the number and severity of collisions. | 1P180 | 3074 | 0521000181 | 201.010 | 23-24 | \$29 | \$4,482 | \$5,291 | 6/21/24 | STP | \$0 | \$2,173 | \$37 | \$1,319 | \$8,040 | 64.00 | Collision(s) reduced | |
| 05 | Santa Cruz | 1 | 8.200/10.600 | Near Capitola, from 0.2 mile south of Freedom Boulevard to State Park Drive. Upgrade concrete barrier, rehabilitate drainage systems, enhance highway worker safety, and replace highway lighting. | 1J961 | 2843A | 0523000185 | 201.015 | 23-24 | \$0 | \$9,051 | \$0 | | STP | \$0 | \$0 | \$0 | \$3,191 | \$12,242 | 9.00 | Collision(s) reduced | |
| 05 | Santa Cruz | 1 | 8.200/26.000 | In and near the cities of Capitola and Santa Cruz, from north of Larkin Valley Road Undercrossing to Laguna Road; also in Monterey County (PM R101.53). Rehabilitate drainage systems, enhance highway worker safety, replace lighting and install Transportation Management System (TMS) elements. | 1J960 | 2843 | 0518000093 | 201.151 | 23-24 | \$212 | \$0 | \$0 | | RMRA | \$2,206 | \$3,264 | \$779 | \$0 | \$6,461 | 0.00 | Culvert(s) (ea) | |
| 05 | Santa Cruz | 1 | 13.300 | In Capitola, at Soquel Creek Bridge No. 36-0013. Landscape and plant establishment for parent project EA 1H480. | 1H481 | 2736Y | 0521000112 | 201.119 | 22-23 | \$0 | \$300 | \$355 | 8/17/23 | RMRA | \$0 | \$150 | \$0 | \$400 | \$850 | 0.00 | Bridge(s) | |
| 05 | Santa Cruz | 1 | 13.300 | In Capitola, at Soquel Creek Bridge No. 36-0013. Biological monitoring for parent project EA 1H480. | 1H482 | 2736X | 0522000017 | 201.119 | 22-23 | \$25 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$40 | \$65 | 0.00 | Bridge(s) | |
| 05 | Santa Cruz | 1 | 31.900/35.700 | Near Davenport, from 1.4 miles north of Swanton Road to 0.6 mile south of Waddell Creek. Environmental mitigation biological monitoring for project EA 0J200. | 0J201 | 1967X | 0522000010 | 201.151 | 22-23 | \$10 | \$0 | \$0 | | RMRA | \$0 | \$0 | \$0 | \$100 | \$110 | 0.00 | Culvert(s) (ea) | |
| 05 | Santa Cruz | 1 | 33.000 | Near Swanton, at 2.6 miles north of Swanton Road. Restore storm damaged slope. | 1Q940 | 3159 | 0523000104 | 201.130 | 22-23 | \$0 | \$450 | \$450 | 4/11/23 | NH | \$0 | \$0 | \$0 | \$180 | \$630 | 1.00 | Location(s) | |
| 05 | Santa Cruz | 9 | 8.500/25.500 | Near Ben Lomond, from Holiday Lane to 4.7 miles north of the northern junction of Routes 236/9. Replace failed culverts systems and construct energy dissipaters. | 1G950 | 2627 | 0516000005 | 201.407 | 22-23 | \$328 | \$7,179 | \$8,503 | 8/16/24 | NH | \$1,445 | \$2,377 | \$1,078 | \$2,025 | \$14,432 | 15.40 | Acre(s) treated/pollutant | |
| 05 | Santa Cruz | 9 | 9.330 | In the community of Ben Lomond, at Hillside Avenue; also at Jacobson Lane (PM 10.04). Replace culverts, reconstruct slope, reconstruct roadway, reset guardrail, and replace traffic delineation. | 1R170 | 3172 | 0523000165 | 201.130 | 23-24 | \$0 | \$1,410 | \$1,410 | 9/28/23 | NH | \$0 | \$0 | \$0 | \$420 | \$1,830 | 2.00 | Location(s) | |
| 05 | Santa Cruz | 9 | | In Santa Cruz County, on Routes 9, 17, 35, and 236 at various locations. Clear fallen or hazardous trees, remove debris, and stabilize slopes. | 1Q930 | 3158 | 0523000103 | 201.130 | 22-23 | \$0 | \$1,200 | \$1,200 | 3/28/23 | NH | \$0 | \$0 | \$0 | \$360 | \$1,560 | 15.00 | Location(s) | |

2022 SHOPP As of January 2026 Close-Out

(x\$1,000)

| Dist | County | Route | Post Miles | Location/Description | EA | PPNO | Project ID | Prog Code | FY | RW | Con | Con Vote | Vote Date | Fund Type | PA&ED | PS&E | RW Sup | Con Sup | Total Cap & Sup | Performance Value | Performance Measure | Approved Baseline Agreement |
|------|------------|-------|--------------|---|-------|------|------------|-----------|-------|-------|----------|----------|-----------|-----------|---------|---------|---------|---------|-----------------|-------------------|----------------------|-----------------------------|
| 05 | Santa Cruz | 17 | 3.200/11.270 | In and near Scotts Valley, from 0.2 mile south of Mount Hermon Road to 0.6 mile north of Glenwood Drive. Grind pavement, place Hot Mix Asphalt (HMA), and apply High Friction Surface Treatment (HFST) and contrasting surface treatment to improve safety. This project will reduce the number and severity of collisions. | 1M730 | 3025 | 0520000055 | 201.010 | 22-23 | \$0 | \$6,923 | \$6,644 | 5/8/23 | STP | \$0 | \$1,049 | \$31 | \$560 | \$8,563 | 856.00 | Collision(s) reduced | |
| 05 | Santa Cruz | 17 | 7.880 | Near Scotts Valley, at Jarvis Road. Remove and replace failed culverts. | 1S050 | 3223 | 0524000163 | 201.130 | 23-24 | \$0 | \$740 | \$740 | 5/9/24 | NH | \$0 | \$0 | \$0 | \$200 | \$940 | 1.00 | Location(s) | |
| 05 | Santa Cruz | 35 | 3.000 | Near Lexington Hills, at 0.3 mile north of Zayante Road. Install soldier pile wall, restore slope, roadway, and shoulder, and place erosion control. | 1Q690 | 3142 | 0523000064 | 201.130 | 22-23 | \$20 | \$2,750 | \$2,750 | 2/28/23 | NH | \$0 | \$50 | \$50 | \$700 | \$3,570 | 1.00 | Location(s) | |
| 05 | Santa Cruz | 129 | 10.000/0.600 | In and near Watsonville, from Route 1 to 0.1 mile east of Blackburn Street; also on Route 152 (West Lake Avenue) from Main Street to Wagner Avenue (PM T2.8/1.33). Rehabilitate pavement and lighting, replace sign panels, install Transportation Management System (TMS) elements, construct new sidewalk, curb ramps, high visibility crosswalks, flashing beacons, and Class II and Class III bike lanes as complete streets elements. This project will extend the pavement service life and improve ride quality. | 1J830 | 2775 | 0518000078 | 201.121 | 23-24 | \$943 | \$8,440 | \$11,554 | 8/15/25 | NH | \$1,143 | \$2,616 | \$2,022 | \$1,904 | \$17,068 | 6.80 | Lane mile(s) | |
| 05 | Santa Cruz | 129 | | In Santa Cruz County, on Routes 129 and 152 at various locations. Clear slide debris and clear culverts. | 1Q950 | 3160 | 0523000105 | 201.130 | 22-23 | \$10 | \$2,900 | \$2,900 | 5/10/23 | NH | \$0 | \$0 | \$0 | \$850 | \$3,760 | 34.00 | Location(s) | |
| 05 | Santa Cruz | 236 | 5.400 | Near Boulder Creek, at 0.6 mile south of Lodge Road. Construct retaining wall to stabilize slope, widen shoulder, repair pavement, improve drainage systems and install erosion control. | 1M450 | 3017 | 0519000153 | 201.131 | 22-23 | \$8 | \$2,521 | \$2,184 | 10/12/22 | NH | \$0 | \$1,450 | \$45 | \$831 | \$4,855 | 1.00 | Location(s) | |
| 05 | Santa Cruz | | | Near Scotts Valley and Felton, on Routes 1, 9, 17, and 236 at various locations. Repair storm damage, including slope restoration, culvert replacement, roadway reconstruction, and debris removal. | 1Q080 | 3102 | 0522000148 | 201.130 | 22-23 | \$100 | \$14,300 | \$14,300 | 3/1/23 | NH | \$0 | \$300 | \$50 | \$3,920 | \$18,670 | 13.00 | Location(s) | |