PM00129

COUNTY of YUBA Preventative Maintenance Program

County Location	Bridge No.	Facility Carried	Feature Intersected	Location	Sufficiency Rating	SD / FO Status	Work Description	Deck Area (sq ft)	Total Participation Cost	Unit Cost (\$ / sq ft)	Federal Share	Running Federal Summary	Local Share	Running Local Summary
YUBA	Develop next years BPMP						Develop next years BPMP plan	1	\$8,900.00	\$8,900.00	\$7,879.17	\$7,879.17	\$1,020.83	\$1,020.83
YUBA	16C0001	Simpson Lane	Yuba River	0.5 Mi SE of 10th Street	85.9		1 .	16682	\$686,416.00	\$41.15	\$607,684.08	\$615,563.25	\$78,731.92	\$79,752.75
YUBA	16C0050	Ridge Road	Oregon Creek	0.1 Mi E of S.R. 49	92.9		a proper structural expansion. Partial polyester concrete overlay. Treat the deck w/methacrylate to seal deck	4958	\$188,416.00	\$38.00	\$166,804.68	\$782,367.94	\$21,611.32	\$101,364.06
YUBA	16C0031	Woodruff Lane	Jack Slough	0.5 Mi East Jack Slough Rd	75.5		Clean & treat deck with methcrylate to seal cracks.	2837	\$109,416.00	\$38.57	\$96,865.98	\$879,233.92	\$12,550.02	\$113,914.08
YUBA	16C0051	Peoria Road	Dry Creek	1.7 Mi North of S.R. 20	83.7	,	, i	4852	\$131,417.00	\$27.09	\$116,343.47	\$995,577.39	\$15,073.53	\$128,987.61
	YUBA YUBA YUBA YUBA	Location Develop next years BPMP YUBA 16C0001 16C0050 YUBA YUBA 16C0031	Develop next years YUBA BPMP YUBA 16C0001 Simpson Lane 16C0050 Ridge Road YUBA YUBA 16C0031 Woodruff Lane	Develop next years BPMP YUBA 16C0001 Simpson Lane Yuba River 16C0050 Ridge Road Oregon Creek YUBA 16C0031 Woodruff Lane Jack Slough	Develop next years BPMP YUBA 16C0001 Simpson Lane Yuba River 0.5 Mi SE of 10th Street 16C0050 Ridge Road Oregon Creek 0.1 Mi E of S.R. 49 YUBA 16C0031 Woodruff Lane Jack Slough 0.5 Mi East Jack Slough Rd	Develop next years YUBA BPMP	Location Rating Status Develop next years YUBA Develop next years BPMP 0.5 Mi SE of 10th Street 85.9 SD YUBA 16C0001 Simpson Lane Yuba River 0.5 Mi SE of 10th Street 85.9 SD YUBA 16C0050 Ridge Road Oregon Creek 0.1 Mi E of S.R. 49 92.9 SD YUBA 16C0031 Woodruff Lane Jack Slough 0.5 Mi East Jack Slough Rd 75.5	Develop next years BPMP YUBA 16C0001 Ridge Road Oregon Creek YUBA 16C0031 Woodruff Lane Jack Slough TUBA Rating Status Develop next years BPMP plan Develop next years BPMP plan Replace AC deck with polyester concrete overlay. Reconstruct expansion joints @ all joint locations. Reconstruct expansion joints @ both abutments to allow a proper structural expansion. Partial polyester concrete overlay. Treat the deck w/methacrylate to seal deck cracks from futher water penetration. YUBA 16C0031 Woodruff Lane Jack Slough Dry Creek 1.7 Mi North of S.R. 20 83.7 Clean & treat deck with methcrylate to seal cracks.	Develop next years BPMP YUBA 16C0001 Simpson Lane Yuba River 0.5 Mi SE of 10th Street 85.9 SD Reconstruct expansion joints @ all joint locations. 16682 Reconstruct expansion joints @ all joint locations. 16682 Reconstruct expansion joints @ both abutments to allow a proper structural expansion. Partial polyester concrete overlay. Treat the deck w/methacrylate to seal deck yUBA 16C0031 Woodruff Lane Jack Slough Rd 75.5 Clean & treat deck with methorylate to seal cracks. 2837	Develop next years BPMP	Develop next years BPMP Status Develop next years BPMP Develop next years ye	Develop next years BPMP Develop next years BPMP plan Simpson Lane Yuba River O.5 Mi SE of 10th Street Street	Develop Develop Public Develop Public Develop Public Develop Public Publi	Develop next years BPMP Develop next years Develop next years BPMP Develop next years Develop next years

Revised November 17, 2021