## California Department of Parks and Recreation Federal Fiscal Year- 2017/2018 Bridge Preventative Maintenance Program - Sorted By County & District District 1

Note 1: Not Applicable

Note 2: This bridge is flagged as Structurally Deficient (SD) in the most recent Local Agency Bridge List. However, the most recent BIRIS Report lists a Sufficiency rating of 85.8 without noting a SD flag.

Note 3: Not Applicable

Priority (Lowest Number Is Top Priority)		Distri ct	Impleme nting Agency	Bridge number from Inspection Report	Facility Carried	Feature Intersected	Location	Sufficiency Rating	SD/FO Status	HBP Eligibility	Work Description	Deck Area (ft²)	Total Particip. Cost		Federal Share	State Share	Local Share
1	Del Norte	1	CA State Parks	01P0019	CHILD'S HILL ROAD	JANE CREEK	10.3 MI SE OF HAMILTON RD	61.7			Replace timber decking. Replace missing transverse struts on upstream RR car and repair damaged struts on both RR cars.Install bank protection measures at Abut 1.	1,145	339,051	296	300,162	38,889	0
2	Humboldt	1	CA State Parks	04P0001	BRICELAND ROAD	REDWOOD CREEK (REDWAY)	WHITTEMORE STATE PARK	79.6			Replace decaying timber rail @ both ends of bridge. Clean and replace exp joint seal @ both Abuts. PCC Deck Overlay. Fix Drainage/New Appr. Slab Constr. Replace Abutment Crib Walls w/Ret Walls. Place concrete under exposed A1 footing. RSP at Pier 3 Footings.	2,035	902,190	443	798,709	103,481	0
3	Mendocino	1	CA State Parks	10P0002	STATE PARK ROAD	LITTLE RIVER	VAN DAMME STATE PARK	54.9	FO	REHAB	Replace decayed timber rails. Replace timber retaining wall at downstream side of north abut. Remove and patch cracked concrete at bot of SW abut corner. Install RSP at upstream and downstream ends of aprons.	788	119,819	152	106,075	13,743	0
4	Humboldt	1	CA State Parks	04P0004	MATTOLE RD	BULL CREEK	5.3 MI W/O RTE 101	83.9			PC Deck Overlay. New Appr. Slab Constr. Scour protection at Abut 1.	2,043	208,031	102	184,170	23,861	0
5	Del Norte	1	CA State Parks	01P0005	BREEN MEMORIAL RD	MILL CREEK	JEDEDIAH SMITH STATE PARK	59.8	FO	REHAB	Replace missing timber rail @ NE abut corner. Replace timber rail cap and facing members. PCC Deck Overlay. Fix Drainage/New Appr. Slab Constr.	3,342	228,358	68	202,165	26,193	0
6	Mendocino	1	CA State Parks	10P0006	RG STATE PARK ROAD	RUSSIAN GULCH	RUSSIAN GULCH STATE PARK	42.6	FO	REPLACE	Replace timber lagging at abut and embankment walls. Place RSP at Abut 1.	293	287,502	982	254,526	32,977	0
7	Mendocino	1	CA State Parks	10P0005	RG STATE PARK ROAD	RUSSIAN GULCH	RUSSIAN GULCH STATE PARK	49.9	FO	REPLACE	Place RSP at both abutments.	463	65,475	141	57,965	7,510	0

3/15/2018 Page 1 of 2

## California Department of Parks and Recreation Federal Fiscal Year- 2017/2018 Bridge Preventative Maintenance Program - Sorted By County & District District 1

Note 1: Not Applicable

Note 2: This bridge is flagged as Structurally Deficient (SD) in the most recent Local Agency Bridge List. However, the most recent BIRIS Report lists a Sufficiency rating of 85.8 without noting a SD flag.

Note 3: Not Applicable

Priority (Lowest Number Is Top Priority)	1	Distri ct	Impleme nting Agency	Bridge number from Inspection Report	Facility Carried	Feature Intersected	Location	Sufficiency Rating	SD/FO Status	HBP Eligibility	Work Description	Deck Area (ft²)	Total Particip. Cost		Federal Share	State Share	Local Share
8	Humboldt	1	CA State Parks	04P0007	MATTOLE RD	HARPER CREEK	4.3 MI W/O RTE 101	73.8			Replace log curbs. PC Deck Overlay. Fix drainage at corner of Abut 3. Repair spalls in leading edge of pier wall support Add RSP protection for upstream and downstream aprons.	. 460	414,441	902	366,904	47,536	0
9	Del Norte	1	CA State Parks	01P0021	CHILD'S HILL ROAD	EAST FORK MILL CREEK	5.3 MILES EAST OF US 101	64.9			Replace log bridge rails. Scour protection at both abutments. Replace crib wall abutments.	794	517,522	651	458,162	59,360	0
10	Mendocino	1	CA State Parks	10P0003	STATE PARK ROAD	LITTLE RIVER	VAN DAMME STATE PARK	83.2	FO		Replace decayed timber rails.	788	85,290	108	75,507	9,783	0
11	Humboldt	1	CA State Parks	04P0011	ALBEE CK CAMP	ALBEE CREEK	HUMBOLDT REDWOOD ST. PK.	53.5			New Appr. Slab Constr. Scour protection at Abutments.	426	88,316	207	78,186	10,130	0
12	Del Norte	1	CA State Parks	01P0020	CHILD'S HILL ROAD	ROCK CREEK	8.8 MI SE OF HAMILTON RD	46.9			Replace missing and damaged transverse struts. Replace crib abutments.	1,598	398,837	250	353,090	45,747	0
13	Del Norte	1	CA State Parks	01P0018	CHILD'S HILL ROAD	BUMMER LAKE CREEK	4.5 MI EAST OF US 101	79.9			Scour protection at upstream side of south abutment.	1,248	193,462	155	171,272	22,190	0
14	Mendocino	1	CA State Parks	10P0007	RG STATE PARK ROAD	RUSSIAN GULCH	RUSSIAN GULCH STATE PARK	49.0			Place RSP at Abut 1.	293	48,457	166	42,899	5,558	0
15	Lake	1	CA State Parks	14P0001	BOAT LAUNCH RMP RD	COLE CREEK	CLEAR LAKE STATE PARK	80.7	SD		PC Deck Overlay. See Note 2	1,017	60,861	60	53,880	6,981	0

Grand

Total = \$ 3,957,611

\$ 3,503,673 \$ 453,938 \$

3/15/2018 Page 2 of 2