						<u></u>								T		
Priority (Lowest		Bridge Number													Total	
Number Is Top	Agency	from Inspection				Sufficiency SD/FO		Deck Area		Federal	Local		Construction		articip.	
Priority)	Location	Report	Facility Carried	Feature Intersected		Rating Status	Work Description	(ft <sup>2</sup> )	(\$/ft <sup>2</sup> )	Share	Share PE	Costs	Costs		Cost	Final HBP Comments
1	Tulare County	460030	AVE 56	FRIANT-KERN CANAL	0.45 MI WEST OF ROAD 192	79.4 FO	1. Clean the debris out of the joint and install a ioint seal	3,513	28	78,400	19,600	24,500	73 500	¢	98,000	
1		4000039	AVE 50	FRIANT-KERN	0.2 MINORTH OF AVE	79.4 FO	1. Remove AC and dirt from the expansion joint	3,513	20	78,400	19,000	24,300	73,500	φ	96,000	
2	Tulare County	46C0180	ROAD 216	CANAL	264	91.4	over Pier 2 and replace the Joint seal	2,537	30	60,000	15,000	18,750	56.250	\$	75,000	
L							1. Remove the AC from Spans 1 and 4 and treat	_,			,	,		+	,	
				FRIANT-KERN			the deck with methacrylate									
3	Tulare County	46C0236	AVE 328	CANAL	0.3 MI WEST OF SR 245	56.2	2. Clean out the joints and place new joint seals	3,984	43	136,000	34,000	42,500	127,500	\$	170,000	
				FRIANT-KERN												
4	Tulare County	/ 46C0237	AVE 322		0.1 MI WEST OF SR 245	70.5	1. Clean out the joint and replace the seal	2,282	33	60,000	15,000	18,750	56,250	\$	75,000	
5	Tuloro Count	4600240	AVE 282 (WIRHT)	FRIANT-KERN CANAL	0.2 MI EAST OF ROAD 206	62.2	1. Remove AC and dirt from the expansion joint over Pier 2. Replace joint seal.	1,962	38	60,000	15,000	18,750	56 250	¢	75,000	
	Tulare County	4000240		FRIANT-KERN	0.3 MI EAST OF ROAD	02.2	1. Clean out the joint opening and place a suitable		30	00,000	15,000	16,750	50,250	φ	75,000	
6	Tulare County	46C0241	AVE 280	CANAL	204	54.6	ioint seal.	2,481	30	60,000	15,000	18,750	56 250	\$	75,000	
	rulare eeung			0, 11, 12		0.110	1. Clean out the joint and replace with a suitable	2,.01			10,000	10,100	00,200	÷	. 0,000	
							joint seal									
				FRIANT-KERN	0.1 MI EAST OF ROAD		2. Remove residual AC and treat the deck with									
7	Tulare County	46C0244	AVE 248	CANAL	224	51.0	methacrylate	1,874	57	84,800	21,200	26,500	79,500	\$	106,000	
-				FRIANT-KERN	0.35 MI EAST OF ROAD		1. Clean out the joint and place a suitable joint									
8	Tulare County	/ 46C0247	AVE 228	CANAL	228	56.7	seal	2,537	30	60,000	15,000	18,750	56,250	\$	75,000	
0	Tulara Count	4600050	AVE 220	FRIANT-KERN CANAL	0.25 MI EAST OF ROAD 228	EQ 4	1. Clean out the joint and place neuroble joint and	2 270	22	60,000	15 000	10 750	56.050	¢	75.000	
9	Tulare County	4600250	(WADDELL)	CANAL	228	58.1	<ol> <li>Clean out the joint and place pourable joint seal</li> <li>Remove the fiber board from the joint opening</li> </ol>	2,370	32	60,000	15,000	18,750	56,250	\$	75,000	
							and place a pourable joint seal									
				FRIANT-KERN	0.25 MI EAST OF ROAD		2. Place a 1 inch layer of polyester concrete									
10	Tulare County	46C0251	AVE 216 (CITRUS)		228	51.2	overlay on the entire deck surface.	2,370	84	160,000	40.000	50,000	150.000	\$	200.000	
						-	1. Remove residual AC and treat the deck with	,		,	.,	,	,			
				FRIANT-KERN	0.25 MI WEST OF ROAD		methacrylate									
11	Tulare County	/ 46C0253	AVE 208 (5TH AVE)	-	232	57.7	2. Replace joint seal at Pier 2	2,370	52	98,400	24,600	30,750	92,250	\$	123,000	
				FRIANT-KERN	0.25 MI EAST OF ROAD											
	Tulare County	/ 46C0254	AVE 204 (6TH AVE)		228	60.2	1. Clean the expansion joint and install a seal	2,370	32	60,000	15,000	18,750	56,250	\$	75,000	
	Tulare County	4600055		FRIANT-KERN	0.25 MI WEST OF ROAD 232	60.4	1. Clean debris from joint and install new joint seal.	2,564.63	29	60,000	15,000	18,750	56 050	¢	75,000	
	Tulare County	4000200	AVE 200 (7TH AVE)	FRIANT-KERN	232	00.4	1. Install a proper joint seal at Pier 2	2,304.03	29	60,000	15,000	16,750	50,250	Э	75,000	
14	Tulare County	46C0257	AVE 194 (8TH AVE)		AT ROAD 234	55.3	2. Treat the deck surface with methacrylate.	2851.631	46	104,800	26,200	32,750	98 250	\$	131,000	
		1000201		FRIANT-KERN	0.1 MI WEST OF ROAD	00.0	1. Clean out the open joint at Pier 2 and insall a	2001.001	10	101,000	20,200	02,100	00,200	Ŷ	101,000	
	Tulare County	46C0259	AVE 188 (OLIVE)	CANAL	232	53.6	joint seal	2,370.20	32	60,000	15,000	18,750	56,250	\$	75,000	
				FRIANT-KERN	AT DRIVE 232/NEWCOMB		-									
16	Tulare County	46C0260	AVE 184	CANAL	ST	58.4	1. Clean out the joint and install a joint seal	2,370.20	32	60,000	15,000	18,750	56,250	\$	75,000	
			AVE 170 (N	FRIANT-KERN	0.25 MI EAST OF ROAD		1. Clean the AC out of the joint at Pier 2 and									
17	Tulare County	/ 46C0264	GRAND)	CANAL	224	49.9	install a new seal	3,024.38	25	60,000	15,000	18,750	56,250	\$	75,000	
40	Tuloro Court	4600222		FRIANT-KERN		72.0	1. Clean joint and install suitable joint and	2 060 04	20	60.000	15 000	10 750		¢	75.000	
18	Tulare County	4000322	AVE 8	CANAL FRIANT-KERN	AT ROAD 176 0.5 MI WEST OF ROAD	73.3	<ol> <li>Clean joint and install suitable joint seal</li> <li>Clean out the expansion joint at Pier 2 and</li> </ol>	2,260.21	33	60,000	15,000	18,750	56,250	\$	75,000	
19	Tulare County	46C0323	AVE 16	CANAL	184	79.7	install a suitable joint seal	2,260.21	33	60,000	15,000	18,750	56 250	\$	75,000	
10	. siere oounty			FRIANT-KERN	0.05 MI WEST OF ROAD		1. Clean out the expansion joint at Pier 2 and	2,200.21		50,000	,	,	00,200	Ψ	,	
20	Tulare County	46C0324	AVE 24	CANAL	184	67.8	install a suitable joint seal	2,260.21	33	60,000	15,000	18,750	56,250	\$	75,000	
-	,			FRIANT-KERN	0.1 MI SOUTH OF		1. Clean out the joint at Pier 2 and install a									
21	Tulare County	46C0363	ROAD 184	CANAL	AVENUE 40	58.1	suitable joint seal	3,349.03	22	60,000	15,000	18,750	56,250	\$	75,000	
22				FRIANT-KERN	0.05 MI EAST OF ROAD											
	Tulare County	46C0364	AVE 40	CANAL	184	74.9	1. Clean out the joint and install a new seal	2,287.54	33	60,000	15,000	18,750	56,250	\$	75,000	
							1. Clean out the joint and install a suitable joint									
							seal at Pier 2									
22	Tulare Count	4600365				73.0		2 360 81	55	104 800	26 200	32 750	08 250	¢	131 000	
23					דטו	15.8										
23	Tulare County	/ 46C0365	AVE 48	FRIANT-KERN CANAL	0.1 MI EAST OF ROAD 184	73.9	2. Remove the existing AC overlay and treat the deck with methacrylate.	2,369.81 Gra		104,800 <b>\$ 1,727,200</b>		32,750 <b>539,750</b>			131,000 2 <b>,159,000</b>	