High Point Curve Correction Project - 10-19-12

Project view from the North.

High Point Curve Correction Project - 10-19-12

Project view from the North.

High Point Curve Correction Project - 10-19-12

Piles and temporary retaining wall B.

High Point Curve Correction Project - 10-19-12

Piles and temporary retaining wall B.

High Point Curve Correction Project - 10-19-12

Piles for wall B

High Point Curve Correction Project - 10-19-12

Piles for wall B

High Point Curve Correction Project - 10-19-12

Temporary retaining wall B

High Point Curve Correction Project - 10-19-12

Temporary retaining wall B

High Point Curve Correction Project - 10-19-12

Piles and temporary retaining wall B.

High Point Curve Correction Project - 10-19-12

High Point Curve Correction Project - 10-19-12

Wall A - backfilling

High Point Curve Correction Project - 10-19-12

Wall A - wall in the process of being built and backfilled.

High Point Curve Correction Project - 10-19-12

Lake side of Wall A.

High Point Curve Correction Project - 10-19-12

Lake side of Wall A.

High Point Curve Correction Project - 10-19-12

Wall A

Wall A - wall in the process of being built and backfilled.

High Point Curve Correction Project - 10-19-12

Wall A - wall in the process of being built and backfilled.

High Point Curve Correction Project - 10-19-12

View of covered slope

High Point Curve Correction Project - 10-19-12

Anchored wire mesh installed.

High Point Curve Correction Project - 10-19-12

Anchored wire mesh installed.

High Point Curve Correction Project - 10-19-12

Anchored wire mesh installed.

High Point Curve Correction Project - 10-19-12

Anchored wire mesh installed.

High Point Curve Correction Project - 10-19-12