High Point Curve Correction Project - 9-20-12

Wall A - Retaining Wall is being built and back filled.

High Point Curve Correction Project - 9-20-12

Closer View of Wall A

High Point Curve Correction Project - 9-20-12

Wall A - View of the wall and black paper liner.

High Point Curve Correction Project - 9-20-12



High Point Curve Correction Project - 9-20-12

Wall A - Outside view

High Point Curve Correction Project - 9-20-12

Wall A -Current view of the outside

High Point Curve Correction Project - 9-20-12

Hillside partially covered.

High Point Curve Correction Project - 9-20-12

Uncovered hillside

High Point Curve Correction Project - 9-20-12

Topaz Lake to the south.