

## **Appendix D: Example Problems**

## **Table of Contents**

Example Problem	Date Issued	Subject
1	04/2020	
-		Clearances at Falsework Openings
2	04/2020	Falsework Beam – Bi-Axial Bending – Canted ≤ 2 %
3	04/2020	<u>Falsework Beam – Bi-Axial Bending – Canted &gt; 2%</u>
4	08/2021	Wind Loads on Conventional Falsework
5	04/2020	Horizontal Design Load on Heavy Duty Falsework
6	04/2020	Stability of Conventional Falsework in Longitudinal Direction
7	04/2020	Stability of Shoring Towers
8	04/2020	Stability of Towers with Discontinuous Legs
9	04/2020	Effect of Overturning on Post Loads
10	04/2020	Bolted Joints – Single Shear
11	04/2020	Bolted Joints – Double Shear
12	04/2020	Multiple Fastener Connection – Single Shear
13	04/2020	Multiple Fastener Connection – Double Shear
14	04/2020	<u>Diagonal Bracing of Single Tier Framed Bent – Nailed</u> <u>Connections</u>
15	04/2020	<u>Diagonal Bracing of Single Tier Framed Bent – Bolted</u> <u>Connections</u>
16	04/2020	<u>Diagonal Bracing of Multi-Tiered Framed Bents – Two</u> <u>Posts</u>
17	04/2020	<u>Diagonal Bracing of Multi-Tiered Framed Bents – Multiple</u> <u>Posts</u>
18	08/2021	Cable Bracing – Bents
19	04/2020	Individual Falsework Pads – Symmetrical Loading
20	04/2020	Individual Falsework Pads – Asymmetrical Loading
21	04/2020	Continuous Pads – Individual Corbels
22	04/2020	Continuous Pads – Two or More Corbels
23	04/2020	Soil Bearing Load Test

Example	Date	
<b>Problem</b>	<u>Issued</u>	<u>Subject</u>
24	04/2020	<u> Timber Pile Bents – Type I Bent</u>
25	04/2020	<u> Timber Pile Bents – Type II Bent</u>
26	04/2020	<u> Timber Pile Bents – Type III Bent</u>
27	04/2020	Pile Penetration Failure – Type I Bent
28	04/2020	Pile Penetration Failure – Type II Bent
29	04/2020	<u>Short Poured-In-Place Concrete Piles – Sample</u>
		<u>Calculations</u>
30	04/2020	Short Poured-In-Place Concrete Piles
31	04/2020	Falsework Removal with Winches