

City of San Diego

Priority (Lowest Number Is Top Priority)	Agency Location	Bridge Number from Inspection Report	Facility Carried	Feature Intersected	Location	Sufficiency Rating	SD/FO Status	Work Description	Deck Area (ft ²)	Unit Cost (\$/ft ²)	Federal Share	Local Share	Total Particip. Cost
1	San Diego	57C-0157	Beyer Blvd	Otay River	0.5 mi N of Palm Ave	92.7	-	Repair N + S median curb; Repair Barrier, Sidewalk, & Median Spalling; Repair Cracking on Approach and Deck; Repair Anchorage Spalling and Railing	24,022	\$3.56	\$75,690.00	\$9,804.00	\$85,494.00
2	San Diego	57C-0676	Montezuma Rd	Fairmount Ave/ Montezuma Ave Sep	0.5 mi S of I-8	90.3	-	Repair Sidewalk Barrier Spalling and Exposed Rebar; Repair Cracking at Abut Face; Replace Joint Seals; Repair Spalling & Unsound Concrete at NW Shear Key; Repair Cracking on Deck, Abutment, & Sidewalk; Repair Sidewalk Spalling	12,920	\$7.23	\$82,690.00	\$10,709.00	\$93,399.00
3	San Diego	57C-0626L	Sorrento Valley WB	Lopez Canyon	1.0 mi E of I-805	89.2	-	Repair Barrier Wall Spalling & Exposed Rebar; Repair Deck Cracking; Replace Joint Seals; Repair Spalling on Approach, Sidewalk, & Joints	4,129	\$6.89	\$25,210.00	\$3,256.00	\$28,466.00
4	San Diego	57C-0311	Ingraham St over FB	Fisherman's Channel	1.1 mi N of West Mission Bay Dr	88.3	-	Repair/Replace NB Inside Lane Joint Seal; Repair Spalling & Exposed Rebar on Deck; Repair Cracked & Spalled Curtain Wall; Add concrete Ditch Along SW Side of Bridge to Mitigate for Soil Erosion at Slope Paving; Repair Spalling on Soffit & Wing Wall; Repair AC Paving on Approach; Repair/ Replace Pickets; Abutment Slope Paving	77,420	\$11.06	\$758,370.00	\$98,251.00	\$856,621.00
5	San Diego	57C-0594	Qualcomm Way	San Diego River	0.25 mi N of I-8	94.2	-	Seal Deck & Slope Wall/Headwall with Methacrylate; Repair Cracking on Deck, Slope, Wall, Barriers, and Approach	10,318	\$7.00	\$63,980.00	\$8,278.00	\$72,258.00
6	San Diego	57C-0068	Bandy Canyon Rd	Santa Maria Creek	6.7 mi E of I-15	97.0	-	Replace WB Abut 6 Approach Slabs; Repair abut WW Cracks; Replace all Joint Seals; Repair Cracking in Abut Wall; Repair Approach Cracking & Spalling; Repair Deck Spalling	6,206	\$13.44	\$73,870.00	\$9,566.00	\$83,436.00
7	San Diego	57C-0577	Pomerado Rd	Caarrol Canyon Creek	0.4 mi E of I-15	89.9	-	Repair Cracking of SW Corner Headwall; Repair Spalling on Abut 1; Repair Cracking & Spalling of Pier Walls; Repair Settling & Damage Slope Paving	2,808	\$6.77	\$16,830.00	\$2,173.00	\$19,003.00
8	San Diego	57C-0310R	Ingraham St NB	Mission Bay Channel	0.5 mi NW of Mission Bay	92.6	-	Replace Joint Seals; Repair Cracking & Spalling on Deck; Grind & Repave South AC Approach Edge; Methacrylate Overlay North Approach Slab; Replace Spalling Approach Edge; Repair AC Paving on Approach	52,228	\$9.51	\$439,760.00	\$56,967.00	\$496,727.00
9	San Diego	57C-0607	Carmel Country Rd	Carmel Valley Creek	500' S of SR-56	N/A	-	Repair Cracking at Abut Face; Repair Spalling at Concrete Curb; Repair/Replace Gabion Units; Replace Joint Seals; Repair Cracking at Barrier Railing; Repair Cracking at Abutment, Deck, Slope Paving; Repair Spalling of Sidewalk & Barrier	20,790	\$8.14	\$149,870.00	\$19,406.00	\$169,276.00
10	San Diego	57C-0414	32nd St	Chollas Creek	0.4 mi S of I-5	96.6	-	Clean and Seal Deck & Approach Slab with Methacrylate; Repair Spalling & Cracking on Deck, Approach, & Sidewalk; Repair Abutment Slopes	8,363	\$10.16	\$75,200.00	\$9,733.00	\$84,933.00
11	San Diego	57C-0472	Ward Rd	San Diego River	100' N of Camino Del Rio N	96.3	-	Seal Deck with Methacrylate; Repair Deck Cracking; Repair Approach AC Paving	7,427	\$5.25	\$34,540.00	\$4,464.00	\$39,004.00
12	San Diego	57C-0627R	Camino Santa Fe NB	Lopez Canyon	0.5 mi N of Mira Mesa Blvd	95.0	-	Repair Spalling on Sidewalk Barrier & Median Barrier; Repair Spalling on Deck; Repair Approach Cracking; Repair AC Pavement	18,594	\$0.79	\$13,040.00	\$1,682.00	\$14,722.00
13	San Diego	57C-0428	Sorrento Valley Rd	Los Penasquitos Creek	2.1 mi S of Carmel Valley Rd	90.5	-	Replace Joints Seals; Repair Spalling at Curb, WW, Abut Face, Sidewalk, & Hangers; Repair Cracking at Superstructure; Repair Cracking on Deck; Repair Approach AC Paving	17,640	\$3.20	\$49,900.00	\$6,460.00	\$56,360.00
14	San Diego	57C-0310L	Ingraham St SB	Mission Bay Channel	0.5 mi NW of Mission Bay	90.5	SD	Repair Cracking at Abut Face; Replace Spalls on Deck; Repair Barrier Spalling at Light Post; Replace Joint Seals; Repair Spalling in Wing Wall, Barriers & Abutment; Repair/Replace Pickets; Replace AC Paving on Approach	52,228	\$7.10	\$328,230.00	\$42,516.00	\$370,746.00
15	San Diego	57C-0580	Mission Center Rd	San Diego River	0.4 mi N of I-8	66.9	SD	Repair Spalling & Cracking on Deck, WW, Slope Wall, Approach, & Sidewalk; Seal Deck with Methacrylate; Replace Joint Seal	9,786	\$15.10	\$130,840.00	\$16,951.00	\$147,791.00
16	San Diego	57C-0595	Camino Del Este	San Diego River	0.3 mi S of Friars Rd	73.0	FO	Repair Rusted Post Pockets; Repair Wing Wall Spalling; Replace Joint Seals; Repair Deck Cracking	6,336	\$11.54	\$64,750.00	\$8,385.00	\$73,135.00
Grand Total =											\$ 2,382,770	\$ 308,601	\$ 2,691,371