Stanislaus County

		•		
Federal Fiscal Year 2017/2018	Bridge	Preventive	Maintenance	Program

Priority

Priority (Lowest		Bridge Number	I .				22/52		Dook	Unit Cost			
Number Is Top Priority)	Agency Location	from Inspection Report	Facility Carried	Feature Intersected	Location	Sufficiency Rating	SD/FO Status	Work Description	Deck Area (ft ²)	(\$/ft²)	Federal Share	Local Share	Total Particip. Cost
	pairs (West County)	•	<u>-</u>				<u> </u>		······································				
1	1	38C0098	Crows Landing Road	TID Lower Lateral	0.5 mi N of W. Main St	70.1		Repair concrete slab (main structural member)	784	28.1	\$19,477	\$2,523	\$22,000
2	Stanislaus County	38C0124	Carpenter Road	TID Lateral #1	Just N of Whitmore Ave	77.1		Repair concrete slab (main structural member)	1,221	22.9	\$24,788	\$3,212	\$28,000
3	Stanislaus County	38C0208	5th Street	CCID Main Canal	Jct at Armstrong Rd	63.0		Repair concrete slab (main structural member)	1,216	23.0	\$24,788	\$3,212	\$28,000
4	Stanislaus County	38C0226	Covert Road	MID Lateral #6	0.4 mi W of Toomes Rd	80.2		Repair concrete T-beams	1,198	23.4	\$24,788	\$3,212	\$28,000
5	Stanislaus County	38C0304	Beckwith Road	MID Lateral #7	0.4 mi W of Dakota Rd	78.9		Repair concrete slab (main structural member)	1,097	23.7	\$23,018	\$2,982	\$26,000
6	Stanislaus County	38C0181	Moorehead Road	CCID Main Canal	Just W of Draper Rd	62.7		Repair concrete T-beams	1,363	22.0	\$26,559	\$3,441	\$30,000
7	Stanislaus County	38C0203	Draper Road	CCID Main Canal	0.25 mi S of Orestimba Rd	77.8		Repair concrete T-beams	1,924	20.3	\$34,527	\$4,473	\$39,000
8	Stanislaus County	38C0116	Paradise Road	MID Lateral #5	0.9 mi NW of Shiloh Rd	64.8		Repair concrete T-beams and slab**	1,231	22.7	\$24,788	\$3,212	\$28,000
9	Stanislaus County	38C0242	W. Stanislaus Road	W. Stanislaus ID Lateral #4	200 ft W of Hamilton Rd	61.9		Repair concrete T-beams, slab, and abutments	544	40.4	\$19,477	\$2,523	\$22,000
										Subtotal =	\$222,210	\$28,790	\$251,000
Structural Re	pairs (East County)	-	T	_	_					T	·	·····	
10	Stanislaus County	38C0258	Cooperstown Road	Johnson Creek	1.5 mi NW of La Grange Rd	92.1		Repair concrete T-beams and slab	728	28.8	\$18,591	\$2,409	\$21,000
11	Stanislaus County	38C0259	Cooperstown Road	Dry Creek	0.8 mi NW of La Grange Rd	71.7		Repair large crack in Abutment 3 and wingwall and in pierwall	526	28.5	\$13,280	\$1,721	\$15,000
12	Stanislaus County	38C0165	Tully Road	MID Main Canal	0.1 N of Thieman Ave	65.5		Repair concrete T-beams and slab	1,164	24.1	\$24,788	\$3,212	\$28,000
13	Stanislaus County	38C0251	Langworth Road	MID Main Canal	3.0 mi N of Milnes Rd	92.2		Repair concrete T-beams, slab, and pierwall	2,698	18.5	\$44,265	\$5,735	\$50,000
14	Stanislaus County	38C0286	Church Street	MID Lateral #2	1.0 mi N of SR132	71.5		Repair concrete slab (main structural member)	859	26.8	\$20,362	\$2,638	\$23,000
15	Stanislaus County	38C0292	Blossom Road	MID Main Canal	0.5 mi N of SR132	54.8	FO	Repair concrete T-beams, slab, and pier cap	1,471	21.8	\$28,330	\$3,670	\$32,000
16	Stanislaus County	38C0091	Hickman Road	TID Main Canal	1.2 mi N of Whitmore Ave	94.3		Repair concrete bent caps and columns	2,758	13.4	\$32,756	\$4,244	\$37,000
17	Stanislaus County	38C0125	Hatch Road	Ceres Main Spillway	Just W of Faith Home Rd	98.4		Repair concrete abutments, pier walls and columns	1,947	20.5	\$35,412	\$4,588	\$40,000
18	Stanislaus County	38C0230	Milnes Road	MID Main Canal	0.2 mi E of Langworth Rd	79.4		Repair concrete pierwalls	1,702	17.6	\$26,559	\$3,441	\$30,000
Methacrylate,	Joint Seals and App	proach Repairs (E	East County)							Subtotal =	\$244,343	\$31,65 7	\$276,000
19	Stanislaus County	38C0001	Orange Blossom Rd	Stanislaus River	0.2 mi SW of Jct Rodden Rd	82.8		Replace the joint seal at the hinges in Span 2 and 5 & treat bridge deck with methacrylate	17,966	7.6	\$121,286	\$15,714	\$137,000
20	Stanislaus County	38C0055	Oakdale-Waterford Hwy	Dry Creek	1.8 mi NW of SR132	67.2		Replace pourable joint seals	11,818	8.3	\$86,759	\$11,241	\$98,000
21	Stanislaus County	38C0114	Claribel Road	MID Main Canal	0.1 mi W of Terminal Ave	80.4		Repair cracks and potholes in both AC approaches at bridge joints	3,614	8.3	\$26,559	\$3,441	\$30,000
22	Stanislaus County	38C0145	La Grange Road	Tuolumne River	0.25 mi N of SR132	84.3		Replace modular expansion joint seal assemblies	19,950	2.3	\$39,839	\$5,162	\$45,000
23	Stanislaus County	38C0044	Mitchell Road	Tuolumne River	0.55 mi S of Finch Rd	84.0		Treat bridge deck and approach slabs with methacrylate	57,780	8.3	\$424,944	\$55,056	\$480,000
24	Stanislaus County	38C0079	Valley Home Road	SSJID Canal	0.1 mi NW Cleveland Ave	91.9		Replace AC overlay**	1,164	21.5	\$22,133	\$2,868	\$25,000
25	Stanislaus County	38C0147	Wellsford Road	MID Main Canal	0.4 mi N of Parker Rd	90.8		Install joints at piers** & repair AC at pier joints**	4,780	5.2	\$22,133	\$2,868	\$25,000
26	Stanislaus County	38C0161	Santa Fe Avenue	TID Main Canal	0.1 mi S of Monte Vista Ave	94.7		Remove AC overlay and treat bridge deck with methacrylate**	1,507	16.6	\$22,133	\$2,868	\$25,000
27	Stanislaus County	38C0223	Clinton Road	TID Ceres Main Canal	50 ft S of Hatch Rd	74.7		Treat bridge deck with methacrylate**	1,475	14.9	\$19,477	\$2,523	\$22,000
28	Stanislaus County	38C0291	Hopper Road	MID Main Canal	0.5 mi N of SR132	70.7		Treat bridge deck with methacrylate** & repair settlement at bridge in both AC approaches	1,558	19.3	\$26,559	\$3,441	\$30,000
29	Stanislaus County	38C0319	Frankenheimber Road	S. San Joaquin Main Canal	2.5 mi S of Sonora Rd	97.9		Replace joint seals**	1,567	14.0	\$19,477	\$2,523	\$22,000
										Subtotal =	\$831,297	\$107,703	\$939,000

Stanislaus County Federal Fiscal Year 2017/2018 Bridge Preventive Maintenance Program

Priority												
(Lowest	Bridge N	mber										
Number Is	from Insp	ection			Sufficiency	SD/FO		Deck	Unit Cost			Total Particip.
Top Priority)	Agency Location Repo	t Facility Carried	Feature Intersected	Location		Status	Work Description	Area (ft ²)	(\$/ft ²)	Federal Share	Local Share	Cost

op Priority	Agency Location	Report	Facility Carried	Feature Intersected	Location	Rating	Status	Work Description	Area (ft²)	(\$/ft²)	Federal Share	Local Share	Cost
ethacrylate	, Joint Seals and Ap	proach Repairs	s (West County)		Т		Т				тт		
30	Stanislaus County	38C0043	River Road	Orestimba Creek	0.6 mi SE of Crows Lndg Rd	95.8	<u> </u>	Remove AC overlay and treat bridge deck with methacrylate**	2,788	11.8	\$29,215	\$3,785	\$33,000
31	Stanislaus County	38C0186	Morgan Road	TID Lateral #5	Jct at Harding Ave	79.3	<u> </u>	Repair AC deck & repair spalls in girders	697	43.0	\$26,559	\$3,441	\$30,000
32	Stanislaus County	38C0096	Crows Landing Road	CCID Main Canal	0.5 mi E of SR33	94.6	3	Repair AC deck and AC approach	2,052	19.5	\$35,412	\$4,588	\$40,000
33	Stanislaus County	38C0185	Sycamore Avenue	Patterson ID Main Canal	0.6 mi S of Las Palmas Ave	62.5	5	Repair AC approach at bridge joint at Abutment 2 & repair crack on wingwall at Abutment 1	526	60.8	\$28,330	\$3,670	\$32,000
34	Stanislaus County	38C0306	Faith Home Road	TID Upper Lateral #3	Just S of Barnhart Rd	71.2	2	Remove AC deck and treat bridge deck with methacrylate & repair spalls and cracks in soffit	799	42.6	\$30,100	\$3,900	\$34,000
35	Stanislaus County	38C0218	Frank Cox Road	Westley Wasteway	0.3 mi SW of SR33	72.1		Repair cracks in AC both approaches at the bridge & remove AC deck overlay and treat bridge deck with methacrylate**	1,729	24.9	\$38,068	\$4,932	\$43,000
	•							Repair sinkhole on the AC approach at Abutment 4 & repair					
36	Stanislaus County	38C0204	Orestimba Road	CCID Main Canal	0.1 mi E of Draper Rd	75.5	<u> </u>	concrete girders	1,786	37.5	\$59,315	\$7,685	\$67,000
37	Stanislaus County	38C0215	Rogers Road	Del Puerto Creek	0.5 mi N of Zacharias Rd	95.8	<u> </u>	Remove AC overlay and treat bridge deck with methacrylate**	2,259	12.4	\$24,788	\$3,212	\$28,000
38	Stanislaus County	38C0053	Sperry Avenue	California Aqueduct	0.1 mi E of I5	85.6	<u> </u>	Repair AC approaches at both abutments	5,636	5.3	\$26,559	\$3,441	\$30,000
39	Stanislaus County	38C0094	Fink Road	California Aqueduct	0.43 mi E of 15	95.0	<u> </u>	Replace joint seal at Bent 2	5,731	2.6	\$13,280	\$1,721	\$15,000
40	Stanislaus County	38C0095	Fink Road	Delta-Mendota Canal	2.0 mi E of 15	65.7	<u>'</u>	Repair potholes in AC approaches at Abutment 4	3,109	8.0	\$22,133	\$2,868	\$25,000
41	Stanislaus County	38C0118	Howard Road	Delta-Mendota Canal	1.5 mi E of I5	65.0		Repair AC approach & AC deck surface	2,997	10.0	\$26,559	\$3,441	\$30,000
42	Stanislaus County	38C0200	Sullivan Road	California Aqueduct	1.68 mi W of Eastin Rd	90.3	3	Repair AC approaches at both abutments & AC deck surface	4,806	8.3	\$35,412	\$4,588	\$40,000
43	Stanislaus County	38C0207	Orestimba Road	California Aqueduct	1.1 mi W of I5	96.9		Remove AC in joint and replace joint seal at Pier 2	4,817	3.1	\$13,280	\$1,721	\$15,000
44	Stanislaus County	38C0209	Davis Road	Delta-Mendota Canal	0.6 mi N of Fink Rd	86.7	,	Repair AC deck surface	3,212	7.8	\$22,133	\$2,868	\$25,000
45	Stanislaus County	38C0211	Oak Flat Road	California Aqueduct	0.4 mi W of Ward Ave	97.0		Remove AC overlay and treat bridge deck with methacrylate**	4,930	10.1	\$44,265	\$5,735	\$50,000
46	Stanislaus County	38C0212	Marshall Road	Delta-Mendota Canal	0.4 mi E of Ward Ave	77.6	5	Repair AC approach and AC deck surface	3,025	9.9	\$26,559	\$3,441	\$30,000
47	Stanislaus County	38C0296	Diehl Road	Delta-Mendota Canal	0.5 mi W of Bell Rd	78.5	SD	Treat bridge deck with methacrylate	2,997	10.0	\$26,559	\$3,441	\$30,000
48	Stanislaus County	38C0332	Shields Road	Delta-Mendota Canal	1.5 mi W of Eastin Rd	86.9	,	Treat bridge deck with methacrylate & repair vertical offset at both approaches	4,270	12.2	\$46,036	\$5,964	\$52,000
49	Stanislaus County	38C0016	Grayson Road	San Joaquin River	0.2 mi NE of Cox Rd	87.7	,	Repair settlement at AC approaches at both abutments	7,374	4.1	\$26,559	\$3,441	\$30,000
50	Stanislaus County	38C0027	Grayson Road	Laird Slough	3.1 mi NE of SR33	90.8	3	Repair settlement at AC approaches at both abutments**	13,390	2.2	\$26,559	\$3,441	\$30,000
51	Stanislaus County	38C0031	Stuhr Road	CCID Main Canal	1.0 mi W of SR33	93.4	ļ.	Repair crackign and potholes in AC approaches at both abutments	1,886	15.9	\$26,559	\$3,441	\$30,000
52	Stanislaus County	38C0064	Briggsmore Road	UPRR & Brink Avenue	At SPRR & 9th St	78.0	SD	Treat bridge deck with methacrylate	9,974	9.0	\$79,677	\$10,323	\$90,000
53	Stanislaus County		Beckwith Road	UPRR	Just W of SR99	86.2		Repair NW sidewalk transition** & treat bridge deck with methacrylate	10,994	8.2		\$10,323	\$90,000
					•			•		ubtotal =	\$813,591	\$105,409	\$919,000
									_		.	, ,	¥1.11,000
alida Bloule	evard - Paint	1	1		T		Т		, , , , , , , , , , , , , , , , , , , 			T	
54	Stanislaus County	38C0069	Salida Boulevard	MID Lateral #6	0.4 mi S of Broadway	77.7	FO	Clean and paint exposed steel girders (no PI)	1,028	214.0	\$194,766	\$25,234	\$220,000
			1			1	1	Panair analla in aaffit**	1 000	25.2	l 622 040l	¢2 002	¢26 000

Salida Bloule	Salida Bloulevard - Paint											
54	Stanislaus County	38C0069	Salida Boulevard	MID Lateral #6	0.4 mi S of Broadway	77.7 FO	Clean and paint exposed steel girders (no PI)	1,028	214.0	\$194,766	\$25,234	\$220,000
							Repair spalls in soffit**	1,028	25.3	\$23,018	\$2,982	\$26,000
									Subtotal =	\$217,784	\$28,216	\$246,000

1/16/2018 Page 2 of 3

Stanislaus County

Federal Fiscal Year 2017/2018 Bridge Preventive Maintenance Program

PM00185

\$4,015

\$35,000

Priority (Lowest Number Is Top Priority)	Agency Location	Bridge Number from Inspection Report		Feature Intersected	Location	Sufficiency Rating	SD/FO Status	Work Description	Deck Area (ft²)	Unit Cost (\$/ft ²)	Federal Share	Local Share	Total Particip. Cost
Golden State	Boulevard												
55	Stanislaus County	38C0141	Golden State Blvd	UPPR	0.1 mi N of Merced Co Line	61.5		Repair AC approach	71,414	0.6	\$39,839	\$5,162	\$45,000
								Repair deck spalls on concrete headers at the hinge joints	71,414	1.6	\$101,810	\$13,191	\$115,000
								Remove AC deck overlay and treat bridge deck with methacrylate**	71.414	5.8	\$367.400	\$47.601	\$415.000

Repair cracks in abutments**

NOTE: ** Indicates work items that are not listed in the BIRS but are maintenance items that need to be completed based on site inspections

	Subtotal =	\$540,033	\$69,967	\$610,000
	Grand Total =	\$ 2,869,257	\$ 371,743	\$ 3,241,000
ſ	FFY BEYOND	\$2.869.257	\$371.743	 \$3.241.000

\$30,986

0.5

71,414