



**DEPARTMENT OF FORESTRY AND FIRE
PROTECTION**
OFFICE OF THE STATE FIRE MARSHAL
Fire and Life Safety Division - North
2251 Harvard Street, Suite 130, Sacramento, CA 95815
(916) 568-3826

SPOT INSPECTION REPORT

LOCATION INFORMATION

Building Name: VAN MATRE LUMBER

Street Address: EMBARADERO X 5TH AVENUE

County: Alameda

City, State, Zip code: OAKLAND , CA, 94606

Lot Number:

Suite Number:

Floor Number:

Agency: Transportation Dept. (CalTrans) (59900)

SFM File No.: 14-01-91-0407-10001

INSPECTION INFORMATION

Inspection Number : 152356

Inspection Type: Spot Inspection

Inspection Date : 11/21/2023

Inspection Status : Failed

Inspector: Terence Liszewski

Inspection Hours : 2

Inspector Signature:

Travel Hours : 2

Inspection Comments:

A Fire and Life Safety Inspection was conducted at CALTRANS Airspace ALA880-0057, on Tuesday, November 21, 2023, by Supervising Deputy State Fire Marshal David Nye and Deputy State Fire Marshal Terence Liszewski. This inspection is for fire and panic safety, and code compliance within the California Department of Transportation (CALTRANS) right-of-way property use. I was accompanied by CALTRANS Staff. The location is an open lot; currently being leased by a lumber supplier for product storage. The following deficiencies were noted and shall be correct. See deficiency list.

Discussed With: Jim Bozionelos

Title: District Branch Chief

Accompanied By:

Jim Bozionelos

Title: District Branch Chief

Signed:

COMMENTS OR QUESTIONS ABOUT INSPECTION SERVICES
Please contact Life Safety North at (916) 568-3826 for assistance.



**DEPARTMENT OF FORESTRY AND FIRE
PROTECTION**
OFFICE OF THE STATE FIRE MARSHAL
Fire and Life Safety Division - North
2251 Harvard Street, Suite 130, Sacramento, CA 95815
(916) 568-3826

SPOT INSPECTION REPORT

Violation # 697624

Description: 510571

Violation Code: Title 24 CFC 2022-Code

Comments: 2022 CFC 315.7.6 Pile separation distances.
In addition to the other requirements of this section, pallet stacks and piles shall be separated in accordance with Sections 315.7.6.1.

The separation distant between wood pallet stacks and building shall be greater than 90 feet.



Comments:

Violation # 697641

Description: 510571

Violation Code: Title 24 CFC 2022-Code

Comments: Combustible Storage Height. Lumber storage height, as identified as combustible class III commodities, shall not exceed 12 feet in storage height. As per CFC 3205.1: Storage layout plan maintenance.
The approved storage layout shall be verified and evaluated annually in accordance with Section 3201.3.2. Modifications or changes to the provisions of the approved storage layout shall not be made without the prior approval of the fire code official.



Comments:

COMMENTS OR QUESTIONS ABOUT INSPECTION SERVICES
Please contact Life Safety North at (916) 568-3826 for assistance.



**DEPARTMENT OF FORESTRY AND FIRE
PROTECTION**
OFFICE OF THE STATE FIRE MARSHAL
Fire and Life Safety Division - North
2251 Harvard Street, Suite 130, Sacramento, CA 95815
(916) 568-3826

SPOT INSPECTION REPORT

Violation # 697641

Description: 510571

Violation Code: Title 24 CFC 2022-Code

Comments: Combustible Storage Height. Lumber storage height, as identified as combustible class III commodities, shall not exceed 12 feet in storage height. As per CFC 3205.1: Storage layout plan maintenance.
The approved storage layout shall be verified and evaluated annually in accordance with Section 3201.3.2. Modifications or changes to the provisions of the approved storage layout shall not be made without the prior approval of the fire code official.



Comments: