



**DEPARTMENT OF FORESTRY AND FIRE
PROTECTION**

OFFICE OF THE STATE FIRE MARSHAL
Fire and Life Safety Division - North
2251 Harvard Street, Suite 130, Sacramento, CA 95815
(916) 568-3826

SPOT INSPECTION REPORT

LOCATION INFORMATION

Building Name: Truck Parking

Street Address: 6th, MLK, 7th and Castro

County: Alameda

City, State, Zip code: Oakland, CA, 94612

Lot Number: ALA980-0002

Suite Number:

Floor Number:

Agency: Transportation Dept. (CalTrans) (59900)

SFM File No.: 14-01-91-0406-10001

INSPECTION INFORMATION

Inspection Number : 152349

Inspection Type: Spot Inspection

Inspection Date : 11/21/2023

Inspection Status : Failed

Inspector: Andrew McSorley

Inspection Hours : 5.25

Inspector Signature: 

Travel Hours : 2.25

Inspection Comments: A Fire and Life Safety Inspection was conducted at CALTRANS Airspace ALA980-0002, on Tuesday, November 21, 2023, by Deputy State Fire Marshals Andrew McSorley and Ray Stockton. This inspection is for fire and panic safety, and code compliance within the California Department of Transportation (CALTRANS) right-of-way property use. I was accompanied by CALTRANS Staff. The location is at 6th Street and Castro Street, 7th Street and MLK Way. The property is being used for private lease commercial semi-truck parking. The following deficiencies were noted and shall be correct. See deficiency list. End of Report.

Discussed With: Ryan Ciero

Title: Right of Way Agent - Airspace

Accompanied By: 

Title: District Branch Chief

Jim Bozionelos

Signed: 11/22/2023

COMMENTS OR QUESTIONS ABOUT INSPECTION SERVICES
Please contact Life Safety North at (916) 568-3826 for assistance.



**DEPARTMENT OF FORESTRY AND FIRE
PROTECTION**
OFFICE OF THE STATE FIRE MARSHAL
Fire and Life Safety Division - North
2251 Harvard Street, Suite 130, Sacramento, CA 95815
(916) 568-3826

SPOT INSPECTION REPORT

Violation # 697617

Description: 511336

Violation Code: Title 24 CFC 2022-304.1

Comments: Used/waste oil in 5 gallon containers noted behind column to the left of the entrance. All used/waste oil storage shall be removed and properly disposed.



Comments: Oil at Column

Violation # 697618

Description: 511345

Violation Code: Title 24 CFC 2022-304.1.1

Comments: Remove combustible trash in wooden box at column near portable toilet.



Comments:



**DEPARTMENT OF FORESTRY AND FIRE
PROTECTION**
OFFICE OF THE STATE FIRE MARSHAL
Fire and Life Safety Division - North
2251 Harvard Street, Suite 130, Sacramento, CA 95815
(916) 568-3826

SPOT INSPECTION REPORT

Violation # 697619

Description: 510822

Violation Code: Title 24 CFC 2022-304.2

Comments: All combustible storage behind locked gate at southeast corner of property shall be removed. This was noted to be from previous tenant.



Comments: Cumbustible Storage Southeast Corner

Violation # 697620

Description: 510833

Violation Code: Title 24 CFC 2022-304.1.2

Comments: Remove all combustible vegetation and trash/rubbish along fence at 7th Street and Martin Luther King Jr. Way.



Comments: Trash and Dead Vegetation 7th Street

COMMENTS OR QUESTIONS ABOUT INSPECTION SERVICES
Please contact Life Safety North at (916) 568-3826 for assistance.